

delay in effective date for these same reasons.

List of Subjects in 10 CFR Part 431

Administrative practice and procedure, Confidential business information, Energy conservation, Household appliances, Imports, Intragovernmental relations, Reporting and recordkeeping requirements, and Small businesses.

Accordingly, part 431 of chapter II, subchapter D, of title 10 of the Code of Federal Regulations, is corrected by making the following correcting amendments:

PART 431—ENERGY EFFICIENCY PROGRAM FOR CERTAIN COMMERCIAL AND INDUSTRIAL EQUIPMENT

■ 1. The authority citation for part 431 continues to read as follows:

Authority: 42 U.S.C. 6291–6317.

■ 2. Section 431.156 of subpart I is revised to read as follows:

§ 431.156 Energy and water conservation standards and effective dates.

(a) Each commercial clothes washer manufactured between January 1, 2007, and January 8, 2013, shall have—

(1) A modified energy factor of at least 1.26; and

(2) A water consumption factor of not more than 9.5.

(b) Each commercial clothes washer manufactured on or after January 8, 2013, shall have a modified energy factor no less than and a water factor no greater than:

Equipment class	Modified energy factor, cu. ft./kWh/cycle	Water factor, gal./cu. ft./cycle
Top-Loading	1.60	8.5
Front-Loading ...	2.00	5.5

Issued in Washington, DC, on November 1, 2011.

Kathleen B. Hogan,

Deputy Assistant Secretary for Energy Efficiency, Energy Efficiency and Renewable Energy.

[FR Doc. 2011–28920 Filed 11–7–11; 8:45 am]

BILLING CODE 6450–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2007–27747; Directorate Identifier 2007–CE–030–AD; Amendment 39–16782; AD 2009–10–09 R2]

RIN 2120–AA64

Airworthiness Directives; Cessna Aircraft Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; correction.

SUMMARY: The FAA is correcting an airworthiness directive (AD) that published in the *Federal Register*. That AD applies to certain Cessna Aircraft Company (Cessna) Models 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, F150F, F150G, F150H, F150J, F150K, F150L, F150M, FA150K, FA150L, FRA150L, FA150M, FRA150M, 152, A152, F152, and FA152 airplanes. There is an error in the compliance instructions. This document corrects that error. In all other respects, the original document remains the same.

DATES: This final rule; correction, is effective November 8, 2011. The effective date for AD 2009–10–09 R2 remains September 12, 2011.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (*phone:* (800) 647–5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Ann Johnson, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209; *phone:* (316) 946–4105; *fax:* (316) 946–4107; *email:* ann.johnson@faa.gov.

SUPPLEMENTARY INFORMATION: Airworthiness Directive 2009–10–09 R2, Amendment 39–16782 (76 FR 53308, August 26, 2011), currently requires either installing a placard prohibiting spins and other acrobatic maneuvers in the airplane or replacing the rudder stop, the rudder stop bumper, and the attachment hardware with a new rudder

stop modification kit for certain Cessna Models 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, F150F, F150G, F150H, F150J, F150K, F150L, F150M, FA150K, FA150L, FRA150L, FA150M, FRA150M, 152, A152, F152, and FA152 airplanes.

As published, the text in the Procedures column of Table 2 in paragraph (g)(1) of this AD incorrectly states “* * * fabricate the placard required in paragraph (g)(1)(i) of this AD * * *”, and the text should refer to paragraph (g)(1)(ii).

No other part of the preamble or regulatory information has been changed; therefore, only the changed portion of the final rule is being published in the *Federal Register*.

The effective date of this AD remains September 12, 2011.

Correction of Regulatory Text

§ 39.13 [Corrected]

In the *Federal Register* of August 26, 2011, on page 53311, in the 3rd column, Procedures, paragraph (g)(1), Table 2—Actions, Compliance and Procedures, of AD 2009–10–09 R2 is corrected to read as follows:

* * * * *

A person authorized to perform maintenance as specified in 14 CFR 43.3 of the Federal Aviation Administration Regulations (14 CFR 43.3) is required to make the AFM and POH changes, fabricate the placard required in paragraph (g)(1)(ii) of this AD, and make an entry into the aircraft logbook showing compliance with the portion of the AD per compliance with 14 CFR 43.9.

* * * * *

Issued in Kansas City, Missouri, on November 2, 2011.

John R. Colomy,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2011–28861 Filed 11–7–11; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2010–1301; Directorate Identifier 2010–SW–008–AD; Amendment 39–16851; AD 2011–22–08]

RIN 2120–AA64

Airworthiness Directives; MD Helicopters, Inc. Model MD900 Helicopters

AGENCY: Federal Aviation Administration, DOT.

ACTION: Final rule.

SUMMARY: This amendment supersedes an existing airworthiness directive (AD) that applies to MD Helicopters, Inc. (MDHI) Model MD900 helicopters. That AD currently requires turning ON both Vertical Stabilizer Control System (VSCS) switches and turning OFF the autopilot (AP/SAS) switch; pulling certain AP/SAS circuit breakers; installing a placard near the AP/SAS master switch; installing an airspeed limitation placard on the instrument panel; and making changes to the Rotorcraft Flight Manual (RFM). This amendment retains those requirements and provides an option of replacing each affected tube adapter with a newly-designed tube adapter, which provides terminating action for the unsafe condition. This amendment is prompted by the manufacturer introducing an improved, newly-designed tube adapter. The actions specified by this AD are intended to prevent loss of yaw control and subsequent loss of control of the helicopter.

DATES: Effective December 13, 2011.

ADDRESSES: You may get the service information identified in this AD from MD Helicopters, Inc., *Attn:* Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615, Mesa, AZ 85215-9734, telephone 1-(800) 388-3378, fax (480) 346-6813, or at <http://www.mdhelicopters.com>.

Examining the Docket: You may examine the docket that contains this AD, any comments, and other information on the Internet at <http://www.regulations.gov>, or at the Docket Operations office, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

FOR FURTHER INFORMATION CONTACT: Eric D. Schrieber, FAA, Los Angeles Aircraft Certification Office, Aviation Safety Engineer, Airframe Branch, 3960 Paramount Blvd., Lakewood, California 90712, telephone (562) 627-5348, fax (562) 627-5210.

SUPPLEMENTARY INFORMATION:

Discussion

On December 28, 2010, we issued a proposal to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) to include an AD that would apply to all MDHI Model MD900 helicopters with a VSCS tube adapter, part number 500N7218-1, installed. This proposal was published in the **Federal Register** as a notice of proposed rulemaking (NPRM) on January 14, 2011 (76 FR 2607). The NPRM proposed to supersede AD 2008-22-53 (73 FR 73165, December 2, 2008), retain the current requirements, and require

continuing operations at a reduced speed until each tube adapter is replaced with an improved tube adapter.

We provided the public the opportunity to participate in developing this AD. We received no comments on the proposal or on the determination of the cost to the public. We have determined that air safety and the public interest require adopting the AD as proposed.

We estimate that this AD will affect 39 helicopters of U.S. registry. It will take about 5.5 hours to install the newly designed tube adapters and 0.5 hours for all other required modifications at an average labor rate of \$85 per work hour. Required parts will cost about \$244 for 2 tube adapters. Based on these figures, we estimate the total cost impact of this AD on U.S. operators is \$29,406, assuming both tube adapters are replaced on the entire fleet of helicopters.

Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and
3. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD. See the AD docket to examine the economic evaluation.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations

for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the Federal Aviation Administration amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Amendment 39-15756 (73 FR 73165, December 2, 2008), and adding the following new AD:

2011-22-08 MD Helicopters, Inc. Model MD900 Helicopters: Amendment 39-16851; Docket No. FAA-2010-1301; Directorate Identifier 2010-SW-008-AD. Supersedes AD 2008-22-53, Amendment 39-15756 (73 FR 73165, December 2, 2008), Directorate ID 2008-SW-61-AD.

Applicability

Model MD900 helicopters with a Vertical Stabilizer Control System (VSCS) tube adapter, part number (P/N) 500N7218-1, installed, certificated in any category.

Compliance

Required before further flight, unless accomplished previously.

To prevent loss of yaw control and subsequent loss of control of the helicopter, do the following:

- (a) Turn ON both VSCS switches.
- (b) If installed, de-energize the autopilot (AP/SAS) as follows:

- (1) Determine if the AP/SAS trim actuators are centered. If the AP/SAS trim actuators are not centered, center them.

- (2) After the AP/SAS trim actuators are centered:

- (i) Turn the AP/SAS MSTR switch to the OFF position.

- (ii) Pull the following AP circuit breakers located on the A601 Essential Bus Circuit Breaker Panel, mounted in the cockpit console, and install a plastic cable tie on each circuit breaker to prevent accidental energizing of the circuit:

- (A) AP/SAS CMPTR (CB28),
- (B) AP/SAS DISC (CB29), and
- (C) AP/SAS ACCEL (CB30).

(3) Install a placard next to the AP Mode Select panel that contains the AP/SAS MSTR switch stating "AP/SAS DEACTIVATED."

(c) Install a placard on the instrument panel as close as practicable to the airspeed indicator that states:

"AIRSPEED LIMIT 100 KIAS or V_{NE} , WHICHEVER IS LESS. VFR FLIGHT ONLY, AUTOPILOT OFF."

(d) Make pen and ink changes or insert a copy of this AD into the Limitations section of the rotorcraft flight manual (RFM) to revise the limitations as follows: " V_{NE} is limited to 100 KIAS or less as determined by referring to the airspeed V_{NE} placard already installed on the helicopter. VFR Flight Only, Autopilot OFF."

(e) Make pen and ink changes or insert a copy of this AD into the Limitations section of the RFM to revise the emergency procedures as follows: "If you experience an anti-torque system malfunction, turn both VSCS switches to OFF during final approach for a run-on landing."

(f) Instead of complying with paragraphs (a) through (e) of this AD, you may replace both VSCS tube adapters, P/N 500N7218-1, with airworthy VSCS tube adapters, P/N 900C2010303-101. If you install VSCS tube adapters, P/N 900C2010303-101, and previously have complied with AD 2008-22-53 (73 FR 73165, December 2, 2008), return the helicopter to its normal configuration by returning the switches and circuit breakers to their normal operating position, operationally testing the auto-pilot system, removing the two placards, and removing the revisions to the RFM pertaining to the airspeed limitation. Replacing both VSCS tube adapters, P/N 500N7218-1, with airworthy VSCS tube adapters, P/N 900C2010303-101, and returning the helicopter to its normal operating configuration constitutes terminating action for the requirements of this AD.

Note: MD Helicopters Service Bulletin SB900-110R1, dated December 3, 2008, which is not incorporated by reference, contains additional information about the subject of this AD. Copies of this service information may be obtained from MD Helicopters, Inc., *Attn:* Customer Support Division, 4555 E. McDowell Rd., Mail Stop M615, Mesa, Arizona 85215-9734, telephone 1-(800) 388-3378, fax (480) 346-6813, or on the Web at <http://www.mdhelicopters.com>. This service information may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

(g) To request a different method of compliance or a different compliance time for this AD, follow the procedures in 14 CFR 39.19. Contact the Manager, Los Angeles Aircraft Certification Office, FAA, *Attn:* Eric D. Schrieber, Aviation Safety Engineer, Airframe Branch, 3960 Paramount Blvd., Lakewood, California 90712, telephone (562) 627-5348, fax (562) 627-5210, for information about previously approved alternative methods of compliance.

(h) The Joint Aircraft System/Component (JASC) Code is 6720: Tail Rotor Control System.

(i) This amendment becomes effective on December 13, 2011.

Issued in Fort Worth, Texas, on October 18, 2011.

Lance T. Gant,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2011-28897 Filed 11-7-11; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 73

[Docket No. FAA-2010-0693; Airspace Docket No. 11-ASO-29]

RIN 2120-AA66

Amendment of Restricted Areas R-2104A, B, C, D and E; Huntsville, AL

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action changes the using agency name for Restricted Area R-2104 A through E, Huntsville, AL to read "Commander, U.S. Army Garrison, Redstone, Redstone Arsenal, AL." There are no changes to the boundaries; designated altitudes; time of designation; or activities conducted within the affected restricted areas.

DATES: Effective date 0901 UTC, February 9, 2012.

FOR FURTHER INFORMATION CONTACT: Paul Gallant, Airspace, Regulations and ATC Procedures Group, Office of Airspace Services, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: (202) 267-8783.

SUPPLEMENTARY INFORMATION:

Background

The Base Realignment and Closure Commission directed the merger of the "Army Missile Command" and the "Aviation and Troop Command" to form the "Aviation and Missile Command." As a result, the current using agency organizational name is no longer accurate. Therefore, the U.S. Army requested that the FAA change the name of the using agency for Restricted Areas R-2104A through E to "Commander, U.S. Army Garrison, Redstone Arsenal, AL."

The Rule

This action amends Title 14 Code of Federal Regulations (14 CFR) part 73 by amending the using agency name for Restricted Areas R-2104A, B, C, D and E, in Huntsville, AL, from "Commanding General, U.S. Army Missile Command, Redstone Arsenal,

AL" to "Commander, U.S. Army Garrison Redstone, Redstone Arsenal, AL." This is an administrative change to update the title of the using agency. It does not affect the boundaries, designated altitudes, or activities conducted within the restricted area; therefore, notice and public procedures under 5 U.S.C. 553(b) are unnecessary.

Section 73.21 of Title 14, CFR part 73 was republished in FAA Order 7400.8T, effective February 16, 2011.

The FAA has determined that this action only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. Therefore, this regulation: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that will only affect air traffic procedures and air navigation, it is certified that this rule, when promulgated, will not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority.

This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as amends the description of Restricted Areas R-2104A, B, C, D and E, Huntsville, AL.

Environmental Review

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1E, Environmental Impacts: Policies and Procedures, paragraph 311d. This airspace action is an administrative change to the descriptions of the affected restricted area to update the using agency name. It does not alter the dimensions, altitudes, or times of designation of the airspace; therefore, it is not expected to cause any potentially significant