

missing latch pin retention bolts of the latch pin fittings of the lower sill of the forward large cargo door, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777-52A0038, Revision 1, dated June 24, 2010, except as provided by paragraph (h) of this AD. Do all applicable related investigative and corrective actions at the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-52A0038, Revision 1, dated June 24, 2010. Repeat the inspection thereafter at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 777-52A0038, Revision 1, dated June 24, 2010, except as specified in paragraph (j) of this AD.

#### (h) Repair

If any cut, crack, or damage is found during any inspection required by this AD, and Boeing Alert Service Bulletin 777-52A0038, Revision 1, dated June 24, 2010, specifies to contact Boeing for appropriate action: Before further flight, repair the cut, crack, or damage in accordance with a method approved by the Manager, Seattle, Aircraft Certification Office (ACO), FAA. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (i) Exception to Compliance Time

Where Boeing Alert Service Bulletin 777-52A0038, Revision 1, dated June 24, 2010, specifies a compliance time after the date on that service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

#### (j) Optional Terminating Action for Repetitive Inspections

Replacing latch pin retention bolts made of titanium with new Inconel bolts, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 777-52A0038, Revision 1, dated June 24, 2010, terminates the repetitive inspections required by paragraph (g) of this AD at Stations 509.10, 522.75, 537.50, 554.30, 562.90, 579.70, 591.25, and 604.90, latch pin fittings No. 1 through No. 8.

#### (k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (l) Related Information

For more information about this AD, contact Ana Martinez Hueto, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6592; fax: 425-917-6590; email: [ana.m.hueto@faa.gov](mailto:ana.m.hueto@faa.gov).

#### (m) Material Incorporated by Reference

(1) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference (IBR) of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51 of the following service information:

(i) Boeing Alert Service Bulletin 777-52A0038, Revision 1, dated June 24, 2010.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; email [me.boecom@boeing.com](mailto:me.boecom@boeing.com); Internet <https://www.myboeingfleet.com>.

(3) You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 4, 2012.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012-11463 Filed 5-16-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2012-0218; Directorate Identifier 2012-CE-003-AD; Amendment 39-17051; AD 2012-10-02]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Hawker Beechcraft Corporation Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Hawker Beechcraft Corporation Models

58 and G58 airplanes. This AD was prompted by installation of oversized clamps on fuel vapor return and/or fuel vent lines in the outboard sections of the left and right wings. This AD requires inspecting for oversized or deformed fuel hose clamps and replacing as necessary. We are issuing this AD to correct the unsafe condition on these products.

**DATES:** This AD is effective June 21, 2012.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of June 21, 2012.

**ADDRESSES:** For service information identified in this AD, contact Hawker Beechcraft Corporation, B091-A04, 10511 E. Central Ave., Wichita, Kansas 67206; telephone: (800) 429-5372 or (316) 676-3140; fax: (316) 676-8027; email: [tmcdc@hawkerbeechcraft.com](mailto:tmcdc@hawkerbeechcraft.com); or Internet: [http://www.hawkerbeechcraft.com/customer\\_support/technical\\_and\\_field\\_support/](http://www.hawkerbeechcraft.com/customer_support/technical_and_field_support/). You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

#### **Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

#### **FOR FURTHER INFORMATION CONTACT:**

Thomas Teplik, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Room 100, Wichita, Kansas 67209; phone: (316) 946-4196; fax: (316) 329-4090; email: [thomas.teplik@faa.gov](mailto:thomas.teplik@faa.gov).

#### **SUPPLEMENTARY INFORMATION:**

##### **Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM published in the **Federal Register** on March 2, 2012 (77 FR 12757). That NPRM proposed to require

inspection for oversized or deformed fuel hose clamps and replacement as necessary because of reports we have received of installation of oversized clamps on fuel vapor return and/or fuel vent lines in the outboard sections of the left and right wings. This condition, if not corrected, could result in leakage of fuel or vapor in areas where electrical wiring and other potential ignition sources are present, which could lead to an inflight fire.

**Comments**

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

**Conclusion**

We reviewed the relevant data and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (77 FR 12757, March 2, 2012) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (77 FR 12757, March 2, 2012).

**Costs of Compliance**

We estimate that this AD affects 244 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Defueling, inspection of the fuel hose clamps, and refueling.	3.5 work-hours × \$85 per hour = \$297.50.	Not applicable .....	\$297.50	\$72,590

We estimate the following costs to do any necessary replacements that would

be required based on the results of the inspection. We have no way of

determining the number of aircraft that might need these replacements:

**ON-CONDITION COSTS**

Action	Labor cost	Parts cost	Cost per product
Replacement of fuel hose clamps (Cost represents replacement of a maximum of 20 clamps depending on airplane configuration).	3 work-hours × \$85 per hour = \$255 .....	\$20	\$275

According to the manufacturer, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2012–10–02 Hawker Beechcraft**

**Corporation:** Amendment 39–17051; Docket No. FAA–2012–0218; Directorate Identifier 2012–CE–003–AD.

**(a) Effective Date**

This AD is effective June 21, 2012.

**(b) Affected ADs**

None.

**(c) Applicability**

(1) This AD applies to the following Hawker Beechcraft Corporation airplanes that are certificated in any category:

- (i) Model 58, serial numbers TH–1931 through TH–2124, and

(ii) Model G58, serial numbers TH-2125 through TH-2281, TH-2283, and TH-2284.

**(d) Subject**

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 28; fuel.

**(e) Unsafe Condition**

This AD was prompted by installation of oversized clamps on fuel vapor return and/ or fuel vent lines in the outboard sections of the left and right wings. We are issuing this AD to correct the unsafe condition on these products.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Inspection**

Within the next 50 hours time-in-service after June 21, 2012 (the effective date of this AD) or within the next 6 calendar months after June 21, 2012 (the effective date of this AD), whichever occurs first, inspect the fuel hose clamps for oversized or deformed clamps following Hawker Beechcraft Mandatory Service Bulletin No. SB 28-4039, Revision 1, dated October 2011.

**Note 1 to paragraph (g) of this AD:** If you have a scheduled inspection before the compliance time of this AD, the FAA recommends you comply with this AD at that time.

**(h) Replacement**

If any oversized or deformed clamps are found during the inspection required in paragraph (g) of this AD, before further flight, replace the clamps following Hawker Beechcraft Mandatory Service Bulletin No. SB 28-4039, Revision 1, dated October 2011.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

**(j) Related Information**

For more information about this AD, contact Thomas Teplik, Aerospace Engineer, Wichita ACO, FAA, 1801 Airport Road, Room 100, Wichita, Kansas 67209; phone: (316) 946-4196; fax: (316) 329-4090; email: [thomas.teplik@faa.gov](mailto:thomas.teplik@faa.gov).

**(k) Material Incorporated by Reference**

(1) You must use Hawker Beechcraft Mandatory Service Bulletin No. SB 28-4039, Revision 1, dated October 2011, to do the actions required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference (IBR) under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) For service information identified in this AD, contact Hawker Beechcraft Corporation, B091-A04, 10511 E. Central Ave., Wichita, Kansas 67206; telephone: (800) 429-5372 or (316) 676-3140; fax: (316) 676-8027; email: [tmdc@hawkerbeechcraft.com](mailto:tmdc@hawkerbeechcraft.com); or Internet: [http://www.hawkerbeechcraft.com/customer\\_support/technical\\_and\\_field\\_support/](http://www.hawkerbeechcraft.com/customer_support/technical_and_field_support/).

(3) You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on May 9, 2012.

**Earl Lawrence,**

*Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012-11812 Filed 5-16-12; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF HEALTH AND HUMAN SERVICES**

**Food and Drug Administration**

**21 CFR Parts 510, 520, 522, and 558**

**[Docket No. FDA-2012-N-0002]**

**New Animal Drugs; Ceftiofur Sodium; Lincomycin Powder; Naracin; Tylosin**

**AGENCY:** Food and Drug Administration, HHS.

**ACTION:** Final rule.

**SUMMARY:** The Food and Drug Administration (FDA) is amending the animal drug regulations to reflect approval actions for new animal drug applications (NADAs) and abbreviated new animal drug applications (ANADAs) during March 2012. FDA is also informing the public of the availability of summaries of the basis of approval and of environmental review documents, where applicable.

**DATES:** This rule is effective May 17, 2012.

**FOR FURTHER INFORMATION CONTACT:**

George K. Haibel, Center for Veterinary Medicine (HFV-6), Food and Drug Administration, 7519 Standish Pl., Rockville, MD 20855, 240-276-9019, email: [george.haibel@fda.hhs.gov](mailto:george.haibel@fda.hhs.gov).

**SUPPLEMENTARY INFORMATION:** FDA's Center for Veterinary Medicine (CVM) is adopting use of a monthly **Federal Register** document to codify approval actions for NADAs and abbreviated ANADAs. CVM will no longer publish a separate rule for each action. This approach will allow a more efficient use of available resources.

In this document, FDA is amending the animal drug regulations to reflect the original and supplemental approval actions during March 2012, as listed in table 1 of this document. FDA is also informing the public of the availability of environmental review documents required under the National Environmental Policy Act (NEPA), where applicable. For actions requiring review of safety or effectiveness data, summaries of the basis of approval (FOI Summaries) under the Freedom of Information Act (FOIA) may be seen in the Division of Dockets Management (HFA-305), Food and Drug Administration, 5630 Fishers Lane, rm. 1061, Rockville, MD 20852, between 9 a.m. and 4 p.m., Monday through Friday.