

altitude above effective translational lift is 13,000 ft PA," or comply with paragraph (e)(2)(iii) of this AD. The term "hovering" as used in this placard includes both IGE and OGE hovering.

(B) Revise the Altitude Limitations section of the RFM in accordance with paragraph A.2.3. on page 10 and paragraph 2.8. on page 11 of Eurocopter Alert Service Bulletin No. MBB BK117 C-2-71A-003, Revision 3, dated December 11, 2007 (ASB003).

(ii) Within 50 hours TIS, unless accomplished previously:

(A) Revise the RFM as required by paragraph (e)(2)(i)(B) of this AD; and

(B) Affix a placard as required by paragraph (e)(2)(i)(A) of this AD or comply with paragraph (e)(2)(iii) of this AD.

(iii) At intervals not to exceed 600 hours TIS:

(A) Before operating between 16,000 ft PA and 18,000 ft PA, perform the "MAX N1 CHECK" by following the Accomplishment Instructions, paragraph 3.A.(1) (on pages 4 and 5), of ASB003. If the OEI rating is not reached, either affix a placard as required by paragraph (e)(2)(i)(A) or comply with paragraph (e)(2)(iii)(B) or (e)(2)(iii)(C) of this AD.

(B) Before operating between 13,000 ft PA and 16,000 ft PA, perform the "MAX N1 CHECK" by following the Accomplishment Instructions, paragraph 3.A.(1) (on pages 5 and 6) of ASB003.

(1) If the OEI rating is reached, affix a placard to the instrument panel in plain view of the pilot(s), which states: "Maximum operating altitude is 16,000 ft PA."

(2) If the OEI rating is not reached, either affix a placard as required by paragraph (e)(2)(i)(A) or comply with paragraph (e)(2)(iii)(C) of this AD.

(C) Before operating between 10,000 ft PA and 13,000 ft PA, perform the "MAX N1 CHECK" by following the Accomplishment Instructions, paragraph 3.A.(1) (on page 7) of ASB003.

(1) If the OEI rating is reached, affix a placard to the instrument panel in plain view of the pilot(s), which states: "Maximum operating altitude is 13,000 ft PA."

(2) If the OEI rating is not reached, affix a placard as required by paragraph (e)(2)(i)(A) of this AD.

(3) If an engine, FCU, engine module 2, or engine module 3 is replaced, before any flight operation at or above a PA of 10,000 feet, comply with the requirements of paragraph (e)(1) of this AD for the Model MBB-BK 117 C-1 helicopter or paragraph (e)(2) of this AD for the Model MBB-BK 117 C-2 helicopter.

(4) Modifying both engines with Turbomeca Modification TU 358 in accordance with Turbomeca Groupe SAFRAN (Turbomeca) Service Bulletin No. 292 73 0358, dated October 2, 2007, is optional terminating action for the requirements of this AD. This AD does not require returning any parts to Turbomeca nor does it require that you perform the modification at a specific location. After modifying both engines, remove from the helicopter any placard required by this AD and remove from the RFM the revised altitude limitations and the revised performance pages required by this AD.

#### (f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Ed Cuevas, Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email [ed.cuevas@faa.gov](mailto:ed.cuevas@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

#### (g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (Germany) AD No. 2008-0061, dated March 27, 2008.

#### (h) Subject

Joint Aircraft Service Component (JASC) Code: 1100, Placards and Markings.

#### (i) Material Incorporated by Reference

(1) You must use the specified portions of the following service information to do the specified actions required by this AD. The Director of the Federal Register approved the incorporation by reference of the following service information under 5 U.S.C. 552(a) and 1 CFR part 51:

(i) Eurocopter Alert Service Bulletin No. ASB-MBB-BK117-60-121, Revision 4, dated December 11, 2007; and

(ii) Eurocopter Alert Service Bulletin No. MBB BK117 C-2-71A-003, Revision 3, dated December 11, 2007.

(2) You must use the specified portions of Turbomeca Groupe SAFRAN Service Bulletin No. 292 73 0358, dated October 2, 2007 to do the optional terminating action in this AD. The Director of the Federal Register approved the incorporation by reference of this service information under 5 U.S.C. 552(a) and 1 CFR part 51.

(3) For the Eurocopter service information identified in this AD, contact American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005; telephone (800) 232-0323; fax (972) 641-3710; or at <http://www.eurocopter.com>. For the Turbomeca Groupe SAFRAN service information identified in this AD, contact SAFRAN Turbomeca, 2709 N. Forum Drive, Grand Prairie, Texas 75052; telephone (800) 662-6322; or at <http://www.turbomeca-usa.com>.

(4) You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137 or at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call (202) 741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html)

Issued in Fort Worth, Texas, on May 2, 2012.

**Carlton N. Cochran,**

*Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.*

[FR Doc. 2012-12672 Filed 6-1-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2012-0324; Directorate Identifier 2012-CE-008-AD; Amendment 39-17060; AD 2012-10-11]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Burkhart GROB Luft- und Raumfahrt GmbH Powered Sailplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all Burkhart GROB Luft- und Raumfahrt GmbH Models GROB G 109 and GROB G 109B powered sailplanes. This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as excessive corrosion on the nose plate in the vertical stabilizer, which could cause the vertical stabilizer nose plate to fail. We are issuing this AD to require actions to address the unsafe condition on these products.

**DATES:** This AD is effective July 9, 2012.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of July 9, 2012.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

For service information identified in this AD, contact Grob Aircraft AG, Lettenbachstrasse 9, D-86874 Tussenhausen-Mattsies, Germany; telephone: +49 (0) 8268 998139; fax: +49 (0) 8268 998200; email: [productsupport@grob-aircraft.com](mailto:productsupport@grob-aircraft.com); Internet: <http://www.grob-aircraft.eu/>. You may review copies of the

referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

**FOR FURTHER INFORMATION CONTACT:** Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: [jim.rutherford@faa.gov](mailto:jim.rutherford@faa.gov).

#### SUPPLEMENTARY INFORMATION:

#### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM was published in the **Federal Register** on March 23, 2012 (77 FR 16968). That NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

Occurrences have been reported of finding heavily corroded nose plates, part number (P/N) 109-2160.01, in the vertical stabiliser of some Grob G 109 powered sailplanes.

The investigation results concluded that the affected aeroplanes were based and operated near the seaside and therefore exposed to a salty environment, causing the excessive corrosion.

This condition, if not detected and corrected, could lead to failure of the vertical stabilizer nose plate, which functions as a horizontal stabiliser fitting, to support limit loads and consequent loss of control of the aeroplane.

For the reasons described above, this AD requires repetitive inspections and, depending on findings, replacement of the nose plate.

You may obtain further information by examining the MCAI in the AD docket.

#### Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (77 FR 16968, March 23, 2012) or on the determination of the cost to the public.

#### Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting the AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (77 FR 16968, March 23, 2012) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (77 FR 16968, March 23, 2012).

#### Costs of Compliance

We estimate that this AD will affect 59 products of U.S. registry. We also estimate that it will take about 6 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$424 per product.

Based on these figures, we estimate the cost of the AD on U.S. operators to be \$55,106, or \$934 per product.

In addition, we estimate that any necessary follow-on actions will take about 12 work-hours and require parts costing \$243, for a cost of \$1,263 per product. We have no way of determining the number of products that may need these actions.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify this AD:*

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM (77 FR 16968, March 23, 2012), the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

**2012-10-11 Burkhart GROB Luft- und Raumfahrt GmbH:** Amendment 39-17060; Docket No. FAA-2012-0324; Directorate Identifier 2012-CE-008-AD.

#### (a) Effective Date

This airworthiness directive (AD) becomes effective July 9, 2012.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Burkhart GROB Luft- und Raumfahrt GmbH Models GROB G 109 and GROB G 109B powered sailplanes, all serial numbers, certificated in any category.

#### (d) Subject

Air Transport Association of America (ATA) Code 55, Stabilizer.

#### (e) Reason

This AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as excessive corrosion on the nose plate in the vertical stabilizer. We are issuing this AD to detect and correct corrosion and flaking on the nose

plate, which could cause the vertical stabilizer nose plate to fail and result in loss of control of the sailplane.

#### (f) Actions and Compliance

Unless already done, do the following actions:

(1) Within 3 months after July 9, 2012 (the effective date of this AD):

(i) Inspect, from the top, the front and rear side of the nose plate, part number (P/N) 109-2160.01, in the vertical stabilizer for corrosion and flaking following Part A of the Accomplishment Instructions in Grob Aircraft Service Bulletin No. MSB817-58, dated November 24, 2011. Repetitively thereafter inspect at intervals not to exceed 12 months.

(ii) Install an access panel on the left side of the vertical stabilizer following Grob Aircraft Repair Instruction Doc. No. RI 817-010/1, issue date December 20, 2011, as specified in Grob Aircraft Service Bulletin No. MSB 817-060, dated November 24, 2011.

(iii) Through the access panel installed as required in paragraph (f)(1)(ii) of this AD, inspect, from below, the nose plate, P/N 109-2160.01, for corrosion and flaking following Part B of the Accomplishment Instructions in Grob Aircraft Service Bulletin No. MSB817-58, dated November 24, 2011. Repetitively thereafter inspect at intervals not to exceed 12 months.

(2) If any corrosion or flaking is found on the nose plate, P/N 109-2160.01, during any inspection required in paragraphs (f)(1)(i) or (f)(1)(iii) of this AD, replace P/N 109-2160.01 with a serviceable part. Do the replacement following Grob Aircraft Repair Instruction Doc. No. RI 817-009, issue date November 17, 2011, as specified in Grob Aircraft Service Bulletin No. MSB817-58, dated November 24, 2011. After replacement, continue with the repetitive inspections required in paragraphs (f)(1)(i) and (f)(1)(iii) of this AD.

#### (g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: [jim.rutherford@faa.gov](mailto:jim.rutherford@faa.gov). Before using any approved AMOC on any sailplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(3) *Reporting Requirements*: For any reporting requirement in this AD, a federal

agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

#### (h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No. 2012-0027, dated February 14, 2012; Grob Aircraft Service Bulletin No. MSB817-58 and Grob Aircraft Service Bulletin No. MSB 817-060, both dated November 24, 2011; Grob Aircraft Repair Instruction Doc. No. RI 817-009, issue date November 17, 2011; and Grob Aircraft Repair Instruction Doc. No. RI 817-010/1, issue date December 20, 2011, for related information.

#### (i) Material Incorporated by Reference

(1) You must use the following service information to do the actions required by this AD, unless the AD specifies otherwise. The Director of the Federal Register approved the incorporation by reference (IBR) under 5 U.S.C. 552(a) and 1 CFR part 51 of the following service information on July 9, 2012:

- (i) Grob Aircraft Service Bulletin No. MSB817-58, dated November 24, 2011;
- (ii) Grob Aircraft Service Bulletin No. MSB 817-060, dated November 24, 2011;
- (iii) Grob Aircraft Repair Instruction Doc. No. RI 817-009, issue date November 17, 2011; and
- (iv) Grob Aircraft Repair Instruction Doc. No. RI 817-010/1, issue date December 20, 2011.

(2) For service information identified in this AD, contact Grob Aircraft AG, Lettenbachstrasse 9, D-86874 Tussenhausen-Mattsies, Germany; telephone: +49 (0) 8268 998139; fax: +49 (0) 8268 998200; email: [productsupport@grob-aircraft.com](mailto:productsupport@grob-aircraft.com); Internet <http://www.grob-aircraft.eu/>.

(3) You may review copies of the service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

(4) You may also review copies of the service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at an NARA facility, call 202-741-6030, or go to [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

Issued in Kansas City, Missouri, on May 16, 2012.

**Earl Lawrence,**

*Manager, Small Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2012-12409 Filed 6-1-12; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2011-1320; Directorate Identifier 2011-NM-208-AD; Amendment 39-17066; AD 2012-11-03]**

**RIN 2120-AA64**

#### **Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all The Boeing Company Model 777 airplanes. This AD was prompted by four reports of retaining cross bolt hardware not fully engaged into the fuse pins of the forward trunnion lower housing of the main landing gear (MLG), which could result in an incorrect MLG emergency landing break-away sequence. This AD requires a detailed inspection of the fuse pin cross bolts and fuse pins of the left and right MLG forward trunnion lower housing to verify that the cross bolts are correctly installed and that there are no missing fuse pins, and replacement of the fuse pins if necessary. We are issuing this AD to prevent an incorrect emergency landing MLG break-away sequence, which could result in puncturing of the wing box and consequent fuel leaks and an airplane fire. Failure of the fuse pins could also result in a possible landing gear collapse causing a runway excursion during take-off or landing.

**DATES:** This AD is effective July 9, 2012.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of July 9, 2012.

**ADDRESSES:** For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, Washington 98124-2207; phone: 206-544-5000, extension 1; fax: 206-766-5680; email: [me.boecom@boeing.com](mailto:me.boecom@boeing.com); Internet: <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA,