

We are issuing this AD to detect and correct discrepancies in the aft attach lugs for the elevator tab control mechanism, which could result in elevator and tab vibration. Consequent structural failure of the elevator or horizontal stabilizer could result in loss of structural integrity and loss of airplane control.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Group 1 Airplanes

For Group 1 airplanes as identified in Boeing Alert Service Bulletin 737-27A1302, dated April 24, 2012: Within 1,500 flight cycles or 2,000 flight hours after the effective date of this AD, whichever occurs first, inspect the left and right elevator tab control mechanisms, and repair or replace as applicable, in accordance with a method approved by the Manager, Seattle Aircraft Certification Office (ACO), FAA. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(h) Inspection for Group 2 Airplanes

For Group 2 airplanes as identified in Boeing Alert Service Bulletin 737-27A1302, dated April 24, 2012: Within 1,500 flight cycles or 2,000 flight hours after the effective date of this AD, whichever occurs first, do a detailed inspection for any discrepancies of the inboard and outboard aft attach lugs of the left and right elevator tab control mechanisms, in accordance with Boeing Alert Service Bulletin 737-27A1302, dated April 24, 2012. Repeat the detailed inspection thereafter at intervals not to exceed 1,500 flight cycles or 2,000 flight hours, whichever occurs first.

(i) Corrective Actions for Paragraph (h) of This AD

If any discrepancy is found during any inspection required by paragraph (h) of this AD, before further flight, replace the discrepant elevator tab control mechanism with a non-discrepant mechanism by doing the actions specified in paragraphs (i)(1) and (i)(2) of this AD.

(1) Do a detailed inspection for discrepancies of the replacement elevator tab control mechanism; and, if no discrepancy is found, before further flight, install the replacement elevator tab control mechanism; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737-27A1302, dated April 24, 2012. If any discrepancy is found in that mechanism, then that mechanism may not be installed.

(2) Repeat the inspection on the installed replacement elevator tab control mechanism in accordance with the requirements of paragraph (h) of this AD.

(j) Inspection Report

Submit a report of the findings (both positive and negative) of the initial inspection required by paragraph (h) of this AD to Boeing Commercial Airlines Group, Attention: Manager, Airline Support, email: rse.boecom@boeing.com; at the applicable time specified in paragraph (j)(1) or (j)(2) of

this AD. The report must include the inspection results, a description of any discrepancies found, the airplane serial number, and the number of landings and flight hours on the airplane.

(1) If the inspection was done after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was accomplished prior to the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(k) Parts Installation Limitations

As of the effective date of this AD, no person may install an elevator tab control mechanism assembly, part number 65-79425-2, -3, -4, -5, or -6, on any airplane, unless the assembly has been inspected in accordance with paragraph (i) of this AD both before and after installation.

(l) Paperwork Reduction Act Burden Statement

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(m) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(n) Related Information

(1) For more information about this AD, contact Kelly McGuckin, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: (425) 917-6490; fax: (425) 917-6590; email: Kelly.McGuckin@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate; 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on July 23, 2012.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012-18614 Filed 7-31-12; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2012-0728; Directorate Identifier 2012-NM-050-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model MD-90-30 airplanes. This proposed AD was prompted by reports of fatigue cracks found in Stringer 11 at the outboard flap, inboard drive hinge at Station Xrs=164.000. This proposed AD would require repetitive inspections for cracks in Stringer 11, and a splice repair if necessary; and repetitive post-repair inspections, and repair if necessary. We are proposing this AD to detect and correct such cracking, which could result in the wing structure not supporting the limit load condition, which could lead to loss of the structural integrity of the wing.

DATES: We must receive comments on this proposed AD by September 17, 2012.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations,

M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

• **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, California 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Roger Durbin, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, California 90712-4137; phone: (562) 627-5233; fax: (562) 627-5210; email: roger.durbin@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2012-0728; Directorate Identifier 2012-NM-050-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We received reports of fatigue cracks found in Stringer 11 at the outboard flap, inboard drive hinge at Station Xrs=164.000 on Model MD-80 airplanes. Model MD-90 airplanes share the same structure design as the MD-80, and are also susceptible to cracking. The cracking occurred at the end fastener of the wing bulkhead clip attachment to the stringer. If undetected, a crack in the stringer may grow until the stringer severs, initiating a crack in the wing lower skin. This condition, if not corrected, could result in the wing structure not supporting the limit load condition, which could lead to loss of the structural integrity of the wing.

Relevant Service Information

We reviewed Boeing Alert Service Bulletin MD90-57A030, dated February 14, 2012. The service information describes procedures for repetitive in-

tank eddy current high frequency (ETHF) inspections for cracks in Stringer 11 at the outboard flap, inboard drive hinge at Station Xrs=164.000 on the left and right wings, and a splice repair if necessary; and repetitive post-repair inspections, and repair if necessary.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of this same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under "Differences Between the Proposed AD and the Service Information."

Differences Between the Proposed AD and the Service Information

The service bulletin specifies to contact the manufacturer for instructions on how to repair certain conditions, but this proposed AD would require repairing those conditions in one of the following ways:

- In accordance with a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) whom we have authorized to make those findings.

Costs of Compliance

We estimate that this proposed AD affects 52 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	13 work-hours × \$85 per hour = \$1,105 per inspection cycle.	None	\$1,105 per inspection cycle	\$57,460 per inspection cycle.
Post-repair inspection.	13 work-hours × \$85 per hour = \$1,105.	None	\$1,105	\$57,460.

We estimate the following costs to do any necessary repairs that would be

required based on the results of the proposed inspection. We have no way of

determining the number of aircraft that might need these repairs:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Splice repair per wing	93 work-hours × \$85 per hour = \$7,905	\$28,126	\$36,031

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions of the post-repair inspection specified in this proposed AD.

Authority for this Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2012–0728; Directorate Identifier 2012–NM–050–AD.

(a) Comments Due Date

We must receive comments by September 17, 2012.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model MD–90–30 airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin MD90–57A030, dated February 14, 2012.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports of fatigue cracks found in Stringer 11 at the outboard flap, inboard drive hinge at Station Xrs=164.000. We are issuing this AD to detect and correct such cracking, which could result in the wing structure not supporting the limit load condition, which could lead to loss of the structural integrity of the wing.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections

Before the accumulation of 14,000 total flight cycles, or within 9,470 flight cycles after the effective date of this AD: Whichever occurs later, do an in-tank eddy current high frequency (ETHF) inspection for cracks in Stringer 11 at the outboard flap, inboard drive hinge at Station Xrs=164.000 of the left and right wings, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD90–57A030, dated February 14, 2012. If no cracking is found, repeat the inspection thereafter at intervals not to exceed 31,000 flight cycles.

(h) Splice Repair

If any cracking is found during the inspection required by paragraph (g) of this AD: Before further flight, do a splice repair, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD90–57A030, dated February 14, 2012.

(i) Post-Repair Inspection

Within 42,000 flight cycles after doing the splice repair specified in paragraph (h) of this

AD: Do an ETHF inspection for cracks in Stringer 11 at the outboard flap, inboard drive hinge at Station Xrs=164.000, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD90–57A030, dated February 14, 2012. Repeat the inspection thereafter at intervals not to exceed 31,000 flight cycles. If any crack is found: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by The Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and 14 CFR 25.571, Amendment 54, and the approval must specifically refer to this AD.

(k) Related Information

(1) For more information about this AD, contact Roger Durbin, Airframe Branch, ANM–120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, California 90712–4137; phone: (562) 627–5233; fax: (562) 627–5210; email: roger.durbin@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800–0019, Long Beach, California 90846–0001; telephone 206–544–5000, extension 2; fax 206–766–5683; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on July 23, 2012.

Kalene C. Yanamura,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2012–18616 Filed 7–31–12; 8:45 am]

BILLING CODE 4910–13–P