

(d) For propeller critical parts, applicants must meet the prescribed integrity specifications of § 35.16. These instances must be stated in the safety analysis.

\* \* \* \* \*

■ 3. Add § 35.16 to subpart B to read as follows:

**§ 35.16 Propeller Critical Parts.**

The integrity of each propeller critical part identified by the safety analysis required by § 35.15 must be established by:

(a) A defined engineering process for ensuring the integrity of the propeller critical part throughout its service life,

(b) A defined manufacturing process that identifies the requirements to consistently produce the propeller critical part as required by the engineering process, and

(c) A defined service management process that identifies the continued airworthiness requirements of the propeller critical part as required by the engineering process.

Issued in Washington, DC, on January 8, 2013.

**Michael P. Huerta,**

*Acting Administrator.*

[FR Doc. 2013-01041 Filed 1-17-13; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

[Docket No. FAA-2011-0724; Directorate Identifier 2010-NM-181-AD; Amendment 39-17299; AD 2012-26-04]

**RIN 2120-AA64**

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are superseding an existing airworthiness directive (AD) for certain The Boeing Company Model 757-200, -200PF, and -200CB series airplanes powered by Rolls-Royce engines. That AD currently requires repetitive inspections of the shim installation between the drag brace fitting vertical flange and bulkhead, and repair if necessary; for certain airplanes, an inspection for cracking of the four critical fastener holes in the horizontal flange, and repair if necessary; and, for airplanes without conclusive records of previous inspections, performing the existing actions. This new AD reduces

the repetitive inspection interval; adds repetitive detailed inspections for cracking of the bulkhead, and repair if necessary; allows an extension of the repetitive intervals for certain airplanes by also doing repetitive ultrasonic inspections for cracking of the bulkhead, and repair if necessary; and provides an option for a high frequency eddy current inspection for cracking of the critical fastener holes, and repair if necessary. This action also adds a terminating action for certain repetitive inspections. This AD was prompted by reports of loose fasteners and cracks at the joint common to the aft torque bulkhead and strut-to-diagonal brace fitting, and one report of such damage occurring less than 3,000 flight cycles after the last inspection. We are issuing this AD to detect and correct cracks, loose and broken bolts, and shim migration in the joint between the aft torque bulkhead and the strut-to-diagonal brace fitting, which could result in damage to the strut and consequent separation of the strut and engine from the airplane.

**DATES:** This AD is effective February 22, 2013.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of February 22, 2013.

The Director of the Federal Register approved the incorporation by reference of a certain other publication listed in this AD as of August 24, 2007 (72 FR 44753, August 9, 2007).

**ADDRESSES:** For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; phone: 206-544-5000, extension 1; fax: 206-766-5680; Internet: <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building

Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:**

Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM-120S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone 425-917-6440; fax 425-917-6590; email: [Nancy.Marsh@faa.gov](mailto:Nancy.Marsh@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 to supersede airworthiness directive (AD) 2008-05-10, Amendment 39-15404 (73 FR 11347, March 3, 2008). (AD 2008-05-10 superseded AD 2007-16-13, Amendment 39-15152 (72 FR 44753, August 9, 2007); and AD 2007-16-13 superseded AD 2005-12-04, Amendment 39-14120 (70 FR 34313, June 14, 2005).) AD 2008-05-10 applies to the specified products. The SNPRM published in the **Federal Register** on June 21, 2012 (77 FR 37332). The original NPRM (76 FR 52901, August 24, 2011) proposed to continue to require repetitive inspections of the shim installation between the engine strut vertical flange and bulkhead, and repair if necessary. That NPRM also proposed to continue to require, for certain airplanes, inspecting for cracking of the four critical fastener holes in the horizontal flange, and repair if necessary; and, for airplanes without conclusive records of previous inspections, performing the existing actions. Additionally, that NPRM proposed to reduce the repetitive inspection interval, add repetitive detailed inspections for cracking of the bulkhead, and repair if necessary; extend the repetitive intervals for certain airplanes by also doing repetitive ultrasonic inspections for cracking of the bulkhead, and repair if necessary; and add an option for a high frequency eddy current inspection for cracking of the critical fastener holes, and repair if necessary. The SNPRM proposed to add a terminating action for certain repetitive inspections.

**Comments**

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the proposal (77 FR 37332, June 21, 2012) and the FAA's response to each comment.

**Support for the SNPRM (77 FR 37332, June 21, 2012)**

United Airlines (United) stated that it has 41 Model 757–200 airplanes affected by the SNPRM (77 FR 37332, June 21, 2012). United stated that, in general, it concurs with the SNPRM to mandate the inspections and modifications described in Boeing Alert Service Bulletin 757–54A0047, Revision 5, dated June 9, 2011.

UPS stated that it concurs with the reduced inspection interval specified in the SNPRM (77 FR 37332, June 21, 2012), as it provides additional opportunity beyond that required by AD 2008–05–10, Amendment 39–15404 (73 FR 11347, March 3, 2008), to find and correct any damage.

**Request To Change Compliance Time**

United requested that we remove the 54-month compliance time in favor of only a 9,000 airplane-cycle limit for the modification specified in paragraph (o) of the SNPRM (77 FR 37332, June 21, 2012). United stated that the 54-month compliance time does not align with current 72-month heavy check intervals at United. United stated that it understands the related bulkhead cracking to be a fatigue related failure, thus negating the need for a calendar driven modification limit. United stated it believes that the currently mandated repetitive inspection limits, in conjunction with a 9,000-airplane-cycle mandated modification limit only, would provide a safe program that would allow for a controlled implementation that minimizes the negative financial impact to operators.

We disagree with the request to change the specified compliance time. We have determined that the 54-month compliance time (grace period), as specified in Boeing Alert Service Bulletin 757–54A0047, Revision 5, dated June 9, 2011, is necessary to adequately address the identified unsafe condition. This structure has been the subject of AD 2008–05–10, Amendment 39–15404 (73 FR 11347, March 3, 2008); which superseded AD 2007–16–13, Amendment 39–15152 (72 FR 44753, August 9, 2007); which superseded AD 2005–12–04, Amendment 39–14120 (70 FR 34313, June 14, 2005). In each of these ADs, the results from the new inspection found more damage than

anticipated, and more frequent and complicated inspections were needed.

In developing an appropriate compliance time for the modification specified in paragraph (o) of this AD, we considered the safety implications, the time necessary to design an acceptable modification, and normal maintenance schedules for timely accomplishment of the modification. In light of these items, we have determined that a 54-month compliance time (grace period) is appropriate. However, under the provisions of paragraph (q) of this AD, we will consider requests for approval of an extension of the compliance time if sufficient data are submitted to substantiate that the extension would provide an acceptable level of safety. We have not changed the AD in this regard.

**Request To Change Terminating Action**

UPS requested that the terminating action proposed in the SNPRM (77 FR 37332, June 21, 2012) be optional in lieu of continued reduced interval inspections, and the terminating action be required only if the reduced interval inspections find cracks or other damage at the fitting.

We do not agree to change the required terminating action specified in this AD because this portion of the Model 757 pylon has been the subject of AD 2008–05–10, Amendment 39–15404 (73 FR 11347, March 3, 2008); which superseded AD 2007–16–13, Amendment 39–15152 (72 FR 44753, August 9, 2007); which superseded AD 2005–12–04, Amendment 39–14120 (70 FR 34313, June 14, 2005). In each of these ADs, results from the new, more frequent, and more complicated inspections showed more damage than anticipated. Under the provisions of paragraph (q) of this AD, we will consider requests for approval of alternative methods of compliance (AMOC) if sufficient data are submitted to substantiate that continued inspections without the terminating action can mitigate the identified unsafe condition. We have not changed the AD in this regard.

**Request To Specify Certain Section of Service Information**

Boeing requested that we specifically call out Part V of the Accomplishment

Instructions of Boeing Alert Service Bulletin 757–54A0047, Revision 5, dated June 9, 2011, in paragraph (o) of the SNPRM (77 FR 37332, June 21, 2012) to prevent misinterpretation in that paragraph because it is different than all other locations in the SNPRM.

We agree to specify Part V in paragraph (o) of this AD, as requested by Boeing, since doing so will help prevent misinterpretation. We have changed paragraph (o) of this AD to specify PART V of the Accomplishment Instructions of Boeing Alert Service Bulletin 757–54A0047, Revision 5, dated June 9, 2011.

**Request To Change Paragraph Header**

Boeing requested that we revise the header of paragraph (g) of the SNPRM (77 FR 37332, June 21, 2012), by deleting “With Reduced Repetitive Intervals and New Optional Inspection Method.” Boeing stated that there are no repetitive inspection requirements in paragraph (g) of the SNPRM.

We agree to modify the specified header, since the repetitive inspection is specified in paragraph (h) of this AD. We have removed the words “Reduced Repetitive Intervals and New Optional Inspection Interval” from the header of paragraph (g) of this AD.

**Conclusion**

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting the AD with the changes described previously—and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the SNPRM (77 FR 37332, June 21, 2012) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the SNPRM (77 FR 37332, June 21, 2012).

We also determined that these changes will not increase the economic burden on any operator or increase the scope of the AD.

**Costs of Compliance**

We estimate that this AD affects 309 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Part I inspection on fasteners and shims—vertical flange [retained actions from AD 2008–05–10, Amendment 39–15404 (73 FR 11347, March 3, 2008)].	28 work-hours × \$85 per hour = \$2,380 per inspection cycle.	\$0	\$2,380 per inspection cycle.	\$735,420 per inspection cycle.

## ESTIMATED COSTS—Continued

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Part II inspection on fasteners—horizontal flange [retained actions from AD 2008–05–10, Amendment 39–15404 (73 FR 11347, March 3, 2008)].	6 work-hours × \$85 per hour = \$510 per inspection cycle.	0	\$510 per inspection cycle.	\$157,590 per inspection cycle.
Part IV inspection on critical fasteners—horizontal flange [retained action from AD 2008–05–10, Amendment 39–15404 (73 FR 11347, March 3, 2008)].	6 work-hours × \$85 per hour = \$510 per inspection cycle.	0	\$510 per inspection cycle.	\$157,590 per inspection cycle.
Part II additional inspection on fasteners—horizontal flange [new action].	10 work-hours × \$85 per hour = \$850 per inspection cycle.	0	\$850 per inspection cycle.	\$262,650 per inspection cycle.
Part IV inspection on critical fasteners—horizontal flange [new action].	8 to 22 work-hours × \$85 per hour = \$680 to \$1,870 per inspection cycle.	0	\$680 to \$1,870 per inspection cycle.	\$210,120 to \$577,830 per inspection cycle.
Part V fastener replacement flange [new action]	Up to 37 work-hours × \$85 per hour = \$3,145 per strut.	750	Up to \$3,895 per strut ..	Up to \$1,203,555 per strut.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this AD.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

*For the reasons discussed above, I certify that this AD:*

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing airworthiness directive (AD) 2008–05–10, Amendment 39–15404 (73 FR 11347, March 3, 2008), and adding the following new AD:

**2012–26–04 The Boeing Company:**  
Amendment 39–17299; Docket No. FAA–2011–0724; Directorate Identifier 2010–NM–181–AD.

#### (a) Effective Date

This airworthiness directive (AD) is effective February 22, 2013.

#### (b) Affected ADs

This AD supersedes AD 2008–05–10, Amendment 39–15404 (73 FR 11347, March 3, 2008).

#### (c) Applicability

This AD applies to The Boeing Company Model 757–200, –200PF, and –200CB series airplanes; certificated in any category; line numbers 1 through 1048 inclusive; powered by Rolls-Royce engines.

#### (d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 54, Nacelles/Pylons.

#### (e) Unsafe Condition

This AD was prompted by reports of loose fasteners and cracks at the joint common to the aft torque bulkhead and strut-to-diagonal brace fitting, and one report of such damage occurring less than 3,000 flight cycles after the last inspection. We are issuing this AD to detect and correct cracks, loose and broken bolts, and shim migration in the joint between the aft torque bulkhead and the strut-to-diagonal brace fitting, which could result in damage to the strut and consequent separation of the strut and engine from the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Retained One-Time Inspection and Repair With Optional Inspection Method

This paragraph restates the one-time inspection and repair required by paragraph (g) of AD 2008–05–10, Amendment 39–15404 (73 FR 11347, March 3, 2008), with optional inspection method and revised service information. For airplanes identified in paragraphs (g)(1) and (g)(2) of this AD: Within 90 days after August 24, 2007 (the effective date of AD 2007–16–13, Amendment 39–15152 (72 FR 44753, August 9, 2007)), do a high frequency eddy current (HFEC) inspection for cracking of the four critical fastener holes in the horizontal flange and, before further flight, do all applicable repairs, in accordance with Part IV of the Accomplishment Instructions of Boeing Alert Service Bulletin 757–54A0047, Revision 3, dated June 27, 2007; Boeing Alert Service

Bulletin 757-54A0047, Revision 4, dated June 24, 2010; or Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011; except as required by paragraph (i)(3) of this AD. As of the effective date of this AD, only Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011, may be used to accomplish the actions required by this paragraph. Doing an ultrasonic inspection for cracking of the fasteners, in accordance with Part IV of the Accomplishment Instructions of Boeing Alert Service Bulletin 757-54A0047, Revision 4, dated June 24, 2010; or Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011; is an acceptable method of compliance with the HFEC inspection requirement of this paragraph.

(1) Airplanes on which findings on the horizontal or vertical fasteners or the shims led to a rejection of any fastener during the actions specified in Boeing Alert Service Bulletin 757-54A0047, dated November 13, 2003; or Boeing Service Bulletin 757-54A0047, Revision 1, dated March 24, 2005.

(2) Airplanes that had equivalent findings prior to the actions specified in Boeing Alert Service Bulletin 757-54A0047, dated November 13, 2003, except for findings on airplanes identified as Group 1, Configuration 2, in Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007, that were prior to the incorporation of Boeing Service Bulletin 757-54-0035.

#### **(h) Retained Repetitive Inspection and Repair With Reduced Interval**

This paragraph restates the repetitive inspections and repair required by paragraph (h) of AD 2008-05-10, Amendment 39-15404 (73 FR 11347, March 3, 2008), with reduced repetitive intervals and revised service information. At the applicable initial times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007, except as required by paragraphs (i)(1) and (i)(2) of this AD: Do the inspections specified in paragraphs (h)(1), (h)(2), and (h)(3) of this AD, and, before further flight, do all the applicable related investigative actions and repairs, by doing all the actions specified in Parts I and II of the Accomplishment Instructions of Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007; or by doing all the actions specified in Part I, and in Step 2 of Part II, of the Accomplishment Instructions of Boeing Alert Service Bulletin 757-54A0047, Revision 4, dated June 24, 2010, or Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011, except as required by paragraph (i)(3) of this AD. As of the effective date of this AD, only Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011, may be used to accomplish the actions required by this paragraph. Repeat the inspections required by this paragraph at the times specified in paragraph (h)(4) of this AD.

(1) Do detailed inspections of the shim installations between the vertical flange and bulkhead to determine if there are signs of movement.

(2) Do detailed inspections of the four fasteners in the vertical flange to determine

if there are signs of movement or if there are gaps under the head or collar.

(3) Do detailed inspections of the fasteners that hold the strut to the horizontal flange of the strut-to-diagonal brace fitting to determine if there are signs of movement or if there are gaps under the head or collar.

(4) Repeat the inspections required by paragraph (h) of this AD at the earlier of the times specified in paragraphs (h)(4)(i) and (h)(4)(ii) of this AD. Thereafter, repeat the inspections at intervals not to exceed the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011.

(i) At intervals not to exceed the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007.

(ii) At intervals not to exceed the applicable intervals specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011, or within 90 days after the effective date of this AD, whichever occurs later.

#### **(i) Retained Exceptions To Alert Service Bulletin Procedures**

This paragraph restates the exceptions to alert service bulletin procedures specified in paragraphs (i), (j), and (k) of AD 2008-05-10, Amendment 39-15404 (73 FR 11347, March 3, 2008), with revised service information.

(1) Where Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007, specifies a compliance time relative to "the date on this service bulletin," this AD requires compliance within the corresponding specified time relative to the effective date of AD 2007-16-13, Amendment 39-15152 (72 FR 44753, August 9, 2007).

(2) Where Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007, specifies a compliance time relative to the "date of issuance of airworthiness certificate," this AD requires compliance within the corresponding time relative to the date of issuance of the original standard airworthiness certificate or the date of issuance of the original export certificate of airworthiness.

(3) If any crack is found during any inspection required by this AD, and Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007; Boeing Alert Service Bulletin 757-54A0047, Revision 4, dated June 24, 2010; or Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011; specifies to contact Boeing for appropriate action: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (q) of this AD.

#### **(j) Retained Inspection/Repair for Airplanes for Which There Are No Conclusive Inspection Records**

This paragraph restates the inspection and repair requirements for airplanes for which there are no conclusive inspection records, as required by paragraph (l) of AD 2008-05-10, Amendment 39-15404 (73 FR 11347, March

3, 2008), with revised service information. For airplanes for which there are no conclusive records showing no loose or missing fasteners during previous inspections done in accordance with the requirements of AD 2007-16-13, Amendment 39-15152 (72 FR 44753, August 9, 2007); or AD 2005-12-04, Amendment 39-14120 (70 FR 34313 June 14, 2005); Do the actions specified in paragraphs (j)(1) and (j)(2) of this AD, at the times specified in those paragraphs, as applicable.

(1) Within 90 days after March 18, 2008 (the effective date of AD 2008-05-10, Amendment 39-15404 (73 FR 11347, March 3, 2008)), do the actions specified in paragraph (g) of this AD, except as required by paragraph (i)(3) of this AD.

(2) At the applicable initial times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007, do the actions specified in paragraph (h) of this AD, except as required by paragraphs (i)(2) and (k) of this AD. And, before further flight, do all applicable related investigative actions and repairs, by doing all the actions specified in Parts I and II of the Accomplishment Instructions of Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007; or in Part 1 and in Step 2 of Part II of the Accomplishment Instructions of Boeing Alert Service Bulletin 757-54A0047, Revision 4, dated June 24, 2010, or Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011; except as required by paragraph (i)(3) of this AD. As of the effective date of this AD, only Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011, may be used to accomplish the actions required by this paragraph. Repeat the actions specified in paragraph (h) of this AD at the times specified in paragraph (h)(4) of this AD.

#### **(k) Retained Additional Exception To Alert Service Bulletin Procedures**

This paragraph restates the exception to alert service bulletin procedures required by paragraph (m) of AD 2008-05-10, Amendment 39-15404 (73 FR 11347, March 3, 2008). Where Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007, specifies a compliance time relative to "the date on this service bulletin," this AD requires compliance within the corresponding specified time relative to March 18, 2008 (the effective date of AD 2008-05-10).

#### **(l) Retained Acceptable Method of Compliance with Certain Requirements of AD 2004-12-07, Amendment 39-13666 (69 FR 33561 June 16, 2004)**

This paragraph restates an acceptable method of compliance with certain requirements of AD 2004-12-07, Amendment 39-13666 (69 FR 33561 June 16, 2004), specified by paragraph (p) of AD 2008-05-10, Amendment 39-15404 (73 FR 11347, March 3, 2008). Accomplishing the actions specified in paragraphs (g) and (h) of this AD terminates the requirements specified in paragraphs (b) and (d) of AD 2004-12-07.

**(m) New Repetitive Inspections and Repair**

At the applicable initial compliance times specified in paragraph (n) of this AD: Do the applicable actions specified in paragraph (m)(1) or (m)(2) of this AD, in accordance with Step 3 of Part II of the Accomplishment Instructions of Boeing Alert Service Bulletin 757-54A0047, Revision 4, dated June 24, 2010; or Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011. If no cracking is found, repeat the inspections thereafter at intervals not to exceed the applicable intervals specified in paragraph 1.E., "Compliance," of the Accomplishment Instructions of Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011. If any crack is found during any inspection required by this paragraph, before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (q) of this AD.

(1) For Group 1, Configuration 1 airplanes identified in Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011: Do the actions specified in paragraph (m)(1)(i) or (m)(1)(ii) of this AD.

(i) Do a detailed inspection for cracking of the bulkhead in the area around the access door cutout and around the critical fasteners in the horizontal flange.

(ii) Do a detailed inspection for cracking of the bulkhead in the area around the access door cutout and around the critical fasteners in the horizontal flange, and do an ultrasonic inspection for cracking of the bulkhead around the fasteners in the horizontal flange. Doing the actions in this paragraph extends the repetitive intervals of the inspections required by paragraph (n) of this AD.

(2) For Group 1, Configuration 2 airplanes; and Group 2 airplanes; identified in Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011: Do a detailed inspection for cracking of the bulkhead in the area around the access door cutout and around the critical fasteners in the horizontal flange.

**(n) New Compliance Times for Paragraph (m) of This AD**

At the applicable times specified in paragraphs (n)(1) and (n)(2) of this AD, do the actions required by paragraph (m) of this AD.

(1) For Group 1, Configuration 1 airplanes identified in Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011: At the later of the times specified in paragraph (n)(1)(i) or (n)(1)(ii) of this AD.

(i) Within 1,800 flight cycles after accomplishing the most recent inspection required by paragraph (h) or (j) of this AD.

(ii) Within 90 days after the effective date of this AD.

(2) For Group 1, Configuration 2 airplanes; and Group 2 airplanes; identified in Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011: At the later of the times specified in paragraph (n)(2)(i) or (n)(2)(ii) of this AD.

(i) Within 3,000 flight cycles after accomplishing the most recent inspection required by paragraph (h) or (j) of this AD.

(ii) Within 90 days after the effective date of this AD.

**(o) New Terminating Action for Certain Airplanes: Fastener Replacement**

For Group 1, Configuration 2 airplanes; and Group 2 airplanes; as identified in Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011: Within 9,000 flight cycles or 54 months after the effective date of this AD, whichever occurs first, replace the horizontal and vertical flange fasteners in the strut-to-diagonal brace fitting on the number 1 and number 2 struts with new fasteners, and do all related investigative and applicable corrective actions, in accordance with PART V of the Accomplishment Instructions of Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011, except where Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011, specifies to contact Boeing for repair instructions, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (q) of this AD. Do all related investigative and corrective actions before further flight. Accomplishment of the actions required in paragraph (o) of this AD terminates the inspection requirements of paragraphs (g), (h), (j), and (m) of this AD for Group 1, Configuration 2 airplanes; and Group 2 airplanes; as identified in Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011.

**(p) Credit for Previous Actions**

(1) Except for the actions specified in paragraphs (j), (m), and (o) of this AD, this paragraph provides credit for the actions required by paragraphs (g) and (h) of this AD, if those actions were performed before March 18, 2008 (the effective date of AD 2008-05-10, Amendment 39-15404 (73 FR 11347, March 3, 2008), using Boeing Service Bulletin 757-54A0047, Revision 1, dated March 24, 2005; or Boeing Alert Service Bulletin 757-54A0047, Revision 2, dated January 31, 2007 (which are not incorporated by reference in this AD).

(2) This paragraph provides credit for the initial inspection required by paragraph (h) of this AD, if that inspection was performed before June 29, 2005 (the effective date of AD 2005-12-04, Amendment 39-14120 (70 FR 34313, June 14, 2005)), using the actions required by paragraph (b) or (d), as applicable, of AD 2004-12-07, Amendment 39-13666 (69 FR 33561, June 16, 2004).

**(q) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) AMOCs approved previously in accordance with AD 2004-12-07, Amendment 39-13666 (69 FR 33561, June 16, 2004), are approved as AMOCs for the corresponding provisions of this AD.

(5) AMOCs approved previously in accordance with AD 2005-12-04, Amendment 39-14120 (70 FR 34313, June 14, 2005), are approved as AMOCs for the corresponding provisions of this AD.

(6) AMOCs approved previously in accordance with AD 2007-16-13, Amendment 39-15152 (72 FR 44753, August 9, 2007), are approved as AMOCs for the corresponding provisions of this AD.

(7) AMOCs approved previously in accordance with AD 2008-05-10, Amendment 39-15404 (73 FR 11347, March 3, 2008), are approved as AMOCs for the corresponding provisions of this AD.

**(r) Related Information**

(1) For more information about this AD, Nancy Marsh, Aerospace Engineer, Airframe Branch, ANM-120S, Seattle Aircraft Certification Office (ACO), FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-917-6440; fax: 425-917-6590; email: [Nancy.Marsh@faa.gov](mailto:Nancy.Marsh@faa.gov).

(2) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; phone: 206-544-5000, extension 1; fax: 206-766-5680; Internet: <https://www.myboeingfleet.com>.

**(s) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on February 22, 2013.

(i) Boeing Alert Service Bulletin 757-54A0047, Revision 4, dated June 24, 2010.

(ii) Boeing Alert Service Bulletin 757-54A0047, Revision 5, dated June 9, 2011.

(4) The following service information was approved for IBR on August 24, 2007, (72 FR 44753, August 9, 2007).

(i) Boeing Alert Service Bulletin 757-54A0047, Revision 3, dated June 27, 2007.

(ii) Reserved.

(5) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; phone: 206-544-5000, extension 1; fax: 206-766-5680; Internet: <https://www.myboeingfleet.com>.

(6) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton Washington, on December 17, 2012.

**Kalene C. Yanamura,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2013-00897 Filed 1-17-13; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2012-0299; Directorate Identifier 2011-NM-029-AD; Amendment 39-17295; AD 2012-25-13]

RIN 2120-AA64

#### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 747-100, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400F, and 747SR series airplanes. This AD was prompted by reports of broken and damaged latch pin retention bolts and subsequent migration of the latch pins of the main deck side cargo door (MDSCD). This AD requires various repetitive inspections of the MDSCD latch pin fittings, measuring the latch pin, and related investigative and corrective actions if necessary. This AD also requires modifying the latch pin fittings and installing new latch pins and latch pin fasteners. We are issuing this AD to prevent loss of the cargo door and rapid depressurization of the airplane.

**DATES:** This AD is effective February 22, 2013.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in the AD as of February 22, 2013.

**ADDRESSES:** For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707,

MC 2H-65, Seattle, WA 98124-2207; phone: 206-544-5000, extension 1; fax: 206-766-5680; Internet: <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Bill Ashforth, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6432; fax: 425-917-6590; email: [Bill.Ashforth@faa.gov](mailto:Bill.Ashforth@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to include an AD that would apply to the specified products. That NPRM published in the **Federal Register** on March 27, 2012 (77 FR 18137). That NPRM proposed to require various repetitive inspections of the MDSCD latch pin fittings, measuring the latch pin, and related investigative and corrective actions if necessary. That NPRM also proposed to require modifying the latch pin fittings and installing new latch pins and latch pin fasteners.

##### Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the proposal (77 FR 18137, March 27, 2012) and the FAA's response to each comment.

##### Requests To Change Applicability

Boeing and Thai Airways International PCL requested that we limit the applicability of the NPRM (77 FR 18137, March 27, 2012) to airplanes with a Boeing-certified MDSCD instead of airplanes identified in Boeing Alert

Service Bulletin 747-52A2294, Revision 1, dated August 16, 2011. The commenters requested this change to ensure that airplanes modified in the future to Model 747-400 Boeing Converted Freighter (BCF) with an MDSCD installation are inspected and modified per the intent of Boeing Alert Service Bulletin 747-52A2294, Revision 1, dated August 16, 2011.

We partially agree with changing the applicability. The AD already provides coverage for the future Model 747-400 BCF airplanes with an MDSCD installation. That is, the applicability of the AD specifies Model 747-100, 747-200B, 747-200C, 747-200F, 747-300, 747-400, 747-400F, and 747SR series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747-52A2294, Revision 1, dated August 16, 2011. This service information identifies Model 747-100, 747-200B, 747-200C, 747-200F, 747-300, 747-400, and 747-400F airplanes with an MDSCD installed in production or by a Boeing-approved modification. For clarification, per the Type Certificate Data Sheet (TCDS) for those airplanes, Model 747-400 BCF and 747-400 Special Freighter (SF) airplanes remain as Model 747-400 series airplanes for documentation purposes on the TCDS and with regard to the applicability of ADs. Where Boeing Alert Service Bulletin 747-52A2294, Revision 1, dated August 16, 2011, specifies "all" airplanes, this means past, present, and future airplanes.

However, we found that Boeing Alert Service Bulletin 747-52A2294, Revision 1, dated August 16, 2011, does not currently provide a grace period for airplanes that have been modified with an MDSCD after the initial compliance time of 6 months after the effective date of this AD. Therefore, the initial compliance time specified in paragraph (g) of this AD has been modified to add a grace period for airplanes that are modified with an MDSCD after the effective date of this AD. Additionally, the initial compliance time reference to paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-52A2294, Revision 1, dated August 16, 2011, as revised by Boeing Alert Service Bulletin 747-52A2294, Revision 2, dated December 12, 2011, has been removed from paragraph (g) of this final rule.

##### Request To Change Service Information Reference

Boeing requested that we change the service information reference in paragraphs (g), (h), (i), and (j) of the NPRM (77 FR 18137, March 27, 2012) from Boeing Alert Service Bulletin 747-52A2294, Revision 1, dated August 16,