

and qualitative information, should be included in a single release on a company's Web site, or in any other forum that is reasonably accessible to the public.

Each bank or thrift must publish a summary of its stress tests results separate from the results of stress tests conducted at the consolidated level of its parent holding company, but the company may include this summary with its holding company's public disclosure. Thus, a bank or thrift with a parent holding company that is required to conduct a company-run DFA stress test under the Federal Reserve Board's DFA stress test rules will have satisfied its public disclosures requirement when the parent holding company discloses summary results of subsidiary's annual stress test in satisfaction of the requirements of the applicable regulations of the company's primary Federal regulator, unless the company's primary regulator determines that the disclosures at the holding

company level does not adequately capture the potential impact of the scenarios on the capital of the companies.

A company must disclose, at a minimum, the following information regarding the severely adverse scenario:

- a. A description of the types of risks included in the stress test;
- b. A summary description of the methodologies used in the stress test;
- c. Estimates of—
  - Aggregate losses; PPNR; PLLL; Net income; and Pro forma regulatory capital ratios and any other capital ratios specified by the primary supervisor;
- d. An explanation of the most significant causes for the changes in regulatory capital ratios; and
- e. For bank holding companies and savings and loan holding companies: for a stress test

conducted by an insured depository institution subsidiary of the bank holding company or savings and loan holding company pursuant to section 165(i)(2) of the Dodd-Frank Act, changes in regulatory capital ratios and any other capital ratios specified by the primary Federal financial regulatory agency of the depository institution subsidiary over the planning horizon, including an explanation of the most significant causes for the changes in regulatory capital ratios.

It should be clear in the company's public disclosure that the results are conditioned on the supervisory scenarios. Items to be publicly disclosed should follow the same definitions as those provided in the confidential report to supervisors. Companies should disclose all of the required items in a single public release, as it is difficult to interpret the quantitative results without the qualitative supporting information.

DIFFERENCES IN DFA STRESS TEST REQUIREMENTS FOR HOLDING COMPANIES VERSUS BANKS AND THRIFTS

	Bank Holding Companies and Savings and Loan Holding Companies	Banks and Thrifts
Capital actions used for company-run stress tests.	Capital actions prescribed in Federal Reserve Board's DFA stress tests rules. Generally based on historical dividends, contracted payments, and no repurchases or issuances.	No prescribed capital actions. Banks and thrifts should use capital actions consistent with the scenario and their internal business practices.
Public disclosure of company-run stress tests ..	Disclosure must include information on stress tests conducted by subsidiaries subject to DFA stress tests.	Disclosure requirement met when parent company disclosure includes the required information on the bank or thrift's stress test results, unless the company's primary regulator determines that the disclosure at the holding company level does not adequately capture the potential impact of the scenarios on the capital of the company.

Dated: July 25, 2013.  
**Thomas J. Curry,**  
*Comptroller of the Currency.*  
 By order of the Board of Governors of the Federal Reserve System, July 24, 2013.  
**Robert deV. Frierson,**  
*Secretary of the Board.*  
 Dated at Washington, DC, this 30th day of July, 2013.  
 Federal Deposit Insurance Corporation.  
**Robert E. Feldman,**  
*Executive Secretary.*  
 [FR Doc. 2013-18716 Filed 8-2-13; 8:45 am]  
**BILLING CODE 4810-33-P; 6714-01-P; 6210-01-P**

**DEPARTMENT OF TRANSPORTATION**  
**Federal Aviation Administration**  
**14 CFR Part 39**  
**[Docket No. FAA-2013-0561; Directorate Identifier 2013-NE-23-AD]**  
**RIN 2120-AA64**  
**Airworthiness Directives; Thielert Aircraft Engines GmbH Reciprocating Engines**  
**AGENCY:** Federal Aviation Administration (FAA), DOT.  
**ACTION:** Notice of proposed rulemaking (NPRM).  
**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Thielert Aircraft Engines GmbH TAE 125-01 reciprocating engines. This proposed AD was prompted by a report

of engine power loss due to engine coolant contaminating the engine clutch. The design of the engine allows the crankcase assembly opening to be susceptible to contamination from external sources. This proposed AD would require applying sealant to close the engine clutch housing (crankcase assembly) opening. We are proposing this AD to prevent in-flight engine power loss, which could result in loss of control of, and damage to, the airplane.  
**DATES:** We must receive comments on this proposed AD by October 4, 2013.  
**ADDRESSES:** You may send comments by any of the following methods:  
 • *Federal eRulemaking Portal:* Go to <http://www.regulations.gov> and follow the instructions for sending your comments electronically.  
 • *Mail:* Docket Management Facility, U.S. Department of Transportation, 1200

New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.

- **Hand Delivery:** Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

- **Fax:** 202-493-2251.

For service information identified in this proposed AD, contact Thielert Aircraft Engines GmbH, Platanenstrasse 14 D-09350, Lichtenstein, Germany, phone: +49-37204-696-0; fax: +49-37204-696-55; email: [info@centurion-engines.com](mailto:info@centurion-engines.com). You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the Mandatory Continuing Airworthiness Information (MCAI), the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (phone: 800-647-5527) is the same as the Mail address provided in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

### FOR FURTHER INFORMATION CONTACT:

Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7779; fax: 781-238-7199; email: [frederick.zink@faa.gov](mailto:frederick.zink@faa.gov).

### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2013-0561; Directorate Identifier 2013-NE-23-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA

personnel concerning this proposed AD. Using the search function of the Web site, anyone can find and read the comments in any of our dockets, including, if provided, the name of the individual who sent the comment (or signed the comment on behalf of an association, business, labor union, etc.). You may review the DOT's complete Privacy Act Statement in the **Federal Register** published on April 11, 2000 (65 FR 19477-78).

### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2013-0109, dated May 22, 2013 (referred to hereinafter as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

A power loss event was reported on an aeroplane equipped with a TAE 125-01 engine. The investigation results showed that the probable cause was contamination of the engine clutch by coolant spillage during the last maintenance operation. The contamination penetrated the clutch housing through an opening located under the coolant tank that was only closed by a not fluid-tight plastic cover.

You may obtain further information by examining the MCAI in the AD docket. The design of the engine allows the crankcase assembly opening to be susceptible to contamination from external sources. We are proposing this AD to prevent in-flight engine power loss, which could result in loss of control of, and damage to, the airplane.

### Relevant Service Information

Thielert Aircraft Engines GmbH has issued Service Bulletin (SB) No. TM TAE 125-0022, dated August 8, 2012. The SB describes procedures for applying sealant to close the engine clutch housing (crankcase assembly) opening.

### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of Germany, and is approved for operation in the United States. Pursuant to our bilateral agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design. This proposed AD would require applying

sealant to close the engine clutch housing (crankcase assembly) opening.

### Costs of Compliance

We estimate that this proposed AD affects 140 engines installed on airplanes of U.S. registry. We also estimate that it would take about 2.5 hours per engine to comply with this proposed AD. The average labor rate is \$85 per hour. Required parts cost about \$110 per engine. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$45,150. Our cost estimate is exclusive of possible warranty coverage.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Thielert Aircraft Engines GmbH:** Docket No. FAA–2013–0561; Directorate Identifier 2013–NE–23–AD.

#### (a) Comments Due Date

We must receive comments by October 4, 2013.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all Thielert Aircraft Engines GmbH TAE 125–01 reciprocating engines.

#### (d) Reason

This AD was prompted by a report of engine power loss due to engine coolant contaminating the engine clutch. The design of the engine allows the crankcase assembly opening to be susceptible to contamination from external sources. We are issuing this AD to prevent in-flight engine power loss, which could result in loss of control of, and damage to, the airplane.

#### (e) Actions and Compliance

Unless already done, do the following actions.

(1) After the effective date of this AD at the next annual or 100-hour inspection, whichever comes first, apply sealant to close the engine clutch housing (crankcase assembly) opening.

(2) Thereafter, reapply sealant to the engine clutch housing (crankcase assembly) opening, whenever the sealant is found to be not liquid-tight, or is removed.

(3) Guidance on the sealant and application can be found in Thielert Aircraft Engines GmbH Service Bulletin No. TM TAE 125–0022, dated August 8, 2012.

#### (f) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs to this AD. Use

the procedures found in 14 CFR 39.19 to make your request.

#### (g) Related Information

(1) For more information about this AD, contact Frederick Zink, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781–238–7779; fax: 781–238 7199; email: [frederick.zink@faa.gov](mailto:frederick.zink@faa.gov).

(2) Refer to European Aviation Safety Agency Airworthiness Directive 2013–0109, dated May 22, 2013, for related information. You may examine the AD on the Internet at <http://ad.easa.europa.eu/ad/2013-0109>.

(3) Thielert Aircraft Engines GmbH Service Bulletin No. TM TAE 125–0022, dated August 8, 2012, which is not incorporated by reference in this AD, can be obtained from Thielert Aircraft Engines GmbH, using the contact information in paragraph (g)(4) of this AD.

(4) For service information identified in this AD, contact Thielert Aircraft Engines GmbH, Platanenstrasse 14 D–09350, Lichtenstein, Germany, telephone: +49–37204–696–0; fax: +49–37204–696–55; email: [info@centurion-engines.com](mailto:info@centurion-engines.com). You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781–238–7125.

Issued in Burlington, Massachusetts, on July 25, 2013.

**Thomas A. Boudreau,**

*Acting Assistant Manager, Engine & Propeller Directorate, Aircraft Certification Service.*

[FR Doc. 2013–18797 Filed 8–2–13; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2013–0679; Directorate Identifier 2009–SW–015–AD]

RIN 2120–AA64

#### Airworthiness Directives; Eurocopter France (Eurocopter) Model Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for Eurocopter Model AS350B, AS350BA, AS350B1, AS350B2, AS350B3, AS350C, AS350D, and AS350D1 helicopters. This proposed AD would require measuring the distance between the end of the main rotor collective pitch lever (collective) locking stud (locking stud) and the locking strip and repairing the locking stud if the clearance is insufficient. This proposed AD is

prompted by a report that insufficient distance between the locking stud and the locking strip may cause the collective to become inadvertently locked in the low pitch (low) position. The proposed actions are intended to prevent the collective from becoming inadvertently locked in the low position and subsequent loss of control of the helicopter.

**DATES:** We must receive comments on this proposed AD by October 4, 2013.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.
- *Fax:* 202–493–2251.
- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590–0001.

• *Hand Delivery:* Deliver to the “Mail” address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt. For service information identified in this proposed AD, contact American Eurocopter Corporation, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641–0000 or (800) 232–0323; fax (972) 641–3775; or at <http://www.eurocopter.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

**FOR FURTHER INFORMATION CONTACT:** Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone 817–222–5110; email [robert.grant@faa.gov](mailto:robert.grant@faa.gov).

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to participate in this rulemaking by submitting written comments, data, or views. We also