

early, the RDAP contract terminates and voucher payments to the landlord stop. To remain eligible for a new voucher after terminating tenancy, the voucher holder must meet the following requirements:

(1) If the voucher holder terminates tenancy during the lease term, the voucher holder must document landlord's consent to the termination of the lease.

(2) The voucher holder must notify the Agency immediately upon terminating tenancy.

(b) The landlord may terminate tenancy only in accordance with the provisions of the voucher holder's lease. The landlord may not terminate the tenancy or charge a penalty to the tenant or Agency if the Agency fails to pay the housing assistance payment or pays it late. Lease provisions under which the landlord may terminate tenancy include the following:

(1) Violations of the terms of lease that are substantial and repeated;

(2) Violations of Federal, State, or local law that directly relate to the occupancy or use of the unit or premises;

(3) Other causes specified in the lease.

(c) The Agency may terminate assistance to the voucher holder if he or she is subject to a court ordered eviction or if the voucher holder relinquishes the voucher and no longer participates in the program. The Agency may also terminate assistance under the following circumstances:

(1) If the voucher holder or voucher household violates any of the obligations under the program as defined in § 3560.804;

(2) If the voucher holder or voucher household commits fraud, bribery, or other corrupt or criminal acts related to any Rural Development MFH program;

(3) If the voucher holder or voucher household owes funds to the Agency in connection with the Rural Development Voucher Program; or

(4) If the voucher holder or voucher household has engaged in or threatened abusive or violent behavior to Agency representatives.

(d) The Agency may recapture any unauthorized assistance that was provided to a landlord or voucher holder. Unauthorized assistance may be the result of submission of inaccurate or false information by the landlord or voucher holder or an error by the Agency personnel. Unauthorized assistance will be processed in accordance with subpart O of this part. The Agency will provide notice to the landlord or voucher holder upon determining that unauthorized assistance was received. The notice will

specify, in detail, the reason(s) that the assistance was determined to be unauthorized, the amount of unauthorized assistance to be repaid, and the process by which a review may be requested.

(e) In making termination decisions, the Agency has discretion to consider the seriousness of the issue, the level of involvement of household members, mitigating circumstances, such as the disability of a household member, and the effects of termination on non-involved household members. The Agency may permit a voucher holder to continue receiving assistance while imposing a condition that the household member or members who engaged in wrongful activity will not reside with the voucher holder.

§ 3560.815 Monitoring and enforcement.

The Agency will monitor voucher holders and landlords participating in the Rural Development Voucher Program. The Agency or its representatives, Inspector General of the U.S Department of Agriculture and Comptroller General of the United States have full and free access to all premises and to all accounts and other records that are relevant to the Rural Development Voucher Program. Upon request, voucher holders and landlords must assist in accessing any accounts or records. The Agency, at its discretion and in accordance with Agency regulations, may pursue civil monetary penalties from the landlord or voucher holder in an attempt to remedy violations of program regulations.

§§ 3560.816–3560.849 [Reserved]

§ 3560.850 OMB control number.

The information collection requirements contained in this regulation has been forwarded to the Office of Management and Budget (OMB) for approval. Public reporting burden for this collection of information is averaged at 15 minutes response, including time reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information.

Dated: August 7, 2013.

Tammye Treviño,

Administrator, Rural Housing Service.

[FR Doc. 2013-19769 Filed 8-13-13; 8:45 am]

BILLING CODE 3410-XV-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-0693; Directorate Identifier 2013-NM-059-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 757-200 and -200PF series airplanes. This proposed AD was prompted by reports indicating that a standard access door was located where an impact-resistant access door was required, and stencils were missing from some impact-resistant access doors. This proposed AD would require an inspection of the left- and right-hand wing fuel tank access doors to determine that impact-resistant access doors are installed in the correct locations, and to replace any door with an impact-resistant access door if necessary. This proposed AD also would require an inspection for stencils and index markers on impact-resistant access doors, and application of new stencils or index markers if necessary. This proposed AD would also require revising the maintenance program to incorporate changes to the airworthiness limitations section. We are proposing this AD to prevent foreign object penetration of the fuel tank, which could cause a fuel leak near an ignition source (e.g., hot brakes or engine exhaust nozzle), consequently leading to a fuel-fed fire.

DATES: We must receive comments on this proposed AD by September 30, 2013.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the ADDRESSES section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Suzanne Lucier, Aerospace Engineer, Supulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6438; fax: 425-917-6590; email: suzanne.lucier@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the ADDRESSES section. Include "Docket No. FAA-2013-0693; Directorate Identifier 2013-NM-059-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this

proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We received reports of a standard access door located where an impact-resistant access door is required, and stencils missing from some spare impact-resistant access doors. This condition, if not corrected, could result in foreign object penetration of the fuel tank, which could cause a fuel leak near an ignition source (e.g., hot brakes or engine exhaust nozzle), consequently leading to a fuel-fed fire.

Relevant Service Information

We reviewed Boeing Service Bulletin 757-28-0118, dated January 12, 2012; and critical design configuration control limitation (CDCCL) Task 57-AWL-01, "Impact-Resistant Fuel Tank Access Doors," of Section 9, Airworthiness Limitations (AWLs) and Certification Requirements (CMRs) of Boeing 757 Maintenance Planning Data Document D622N001-9, Revision August 2012. For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for Docket No. FAA-2013-0693.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

Proposed AD Requirements

The FAA issued section 121.316 of the Federal Aviation Regulations (14 CFR 121.316) requiring that each turbine powered transport category airplane meet the requirements of section 25.963(e) of the Federal Aviation

Regulations (14 CFR 25.963(e)). Section 25.963(e) outlines the certification requirements for fuel tank access covers on turbine powered transport category airplanes.

This proposed AD would require inspecting fuel tank access doors to determine that impact-resistant access doors are installed in the correct locations and replacing any door with an impact-resistant access door if necessary; inspecting application of stencils and index markers of impact-resistant access doors and application of new stencils or index markers if necessary; and revising the maintenance program.

This proposed AD requires revisions to certain operator maintenance documents to include a new CDCCL. Compliance with CDCCLs is required by section 91.403(c) of the Federal Aviation Regulations (14 CFR 91.403(c)). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator might not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to the procedures specified in paragraph (j) of this proposed AD. The request should include a description of changes to the required actions that will ensure the continued damage tolerance of the affected structure.

After accomplishing the revision required by paragraph (h) of this AD, no alternative actions (e.g., inspections), intervals, and/or CDCCLs may be used unless the actions, intervals, and/or CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j) of this AD.

Costs of Compliance

We estimate that this proposed AD affects 86 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	8 work-hours × \$85 per hour = \$680	\$0	\$680	\$58,480
Maintenance Program Revision	1 work-hour × \$85 per hour = \$85	0	85	7,310

We estimate the following costs to do any necessary replacements that would

be required based on the results of the proposed inspection. We have no way of

determining the number of aircraft that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replacement per door	3 work-hours × \$85 per hour = \$255	\$8,000	\$8,255
Stencil and index marker	4 work-hours × \$85 per hour = \$340	0	340

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2013–0693; Directorate Identifier 2013–NM–059–AD.

(a) Comments Due Date

We must receive comments by September 30, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 757–200 and –200PF series airplanes; certificated in any category; as identified in Boeing Service Bulletin 757–28–0118, dated January 12, 2012.

(d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 28, Fuel.

(e) Unsafe Condition

This AD was prompted by reports indicating that a standard access door was located where an impact-resistant access door was required, and stencils were missing from some impact-resistant access doors. We are issuing this AD to prevent foreign object penetration of the fuel tank, which could cause a fuel leak near an ignition source (e.g., hot brakes or engine exhaust nozzle), consequently leading to a fuel-fed fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspections

Within 72 months after the effective date of this AD, do the actions specified in

paragraphs (g)(1) and (g)(2) of this AD, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 757–28–0118, dated January 12, 2012.

(1) Do a general visual inspection of the left- and right-hand wing fuel tank access doors to determine whether impact-resistant access doors are installed in the correct locations. If any standard access door is found, before further flight, replace with an impact-resistant access door, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 757–28–0118, dated January 12, 2012.

(2) Do a general visual inspection of the left- and right-hand wing fuel tank impact-resistant access doors to verify stencils and index markers are applied. If a stencil or index marker is missing, before further flight, apply stencil or index marker, as applicable, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 757–28–0118, dated January 12, 2012.

(h) Maintenance Program Revision

Within 60 days after the effective date of this AD, revise the maintenance program to incorporate critical design configuration control limitations (CDCCLs) Task 57–AWL–01, "Impact-Resistant Fuel Tank Access Doors," of Section 9, Airworthiness Limitations (AWLs) and Certification Requirements (CMRs) of Boeing 757 Maintenance Planning Data Document D622N001–9, Revision August 2012.

(i) No Alternative Actions, Intervals, and/or CDCCLs

After accomplishing the revision required by paragraph (h) of this AD, no alternative actions (e.g., inspections), intervals, and/or CDCCLs may be used unless the actions, intervals, and/or CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j) of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

(1) For more information about this AD, contact Suzanne Lucier, Aerospace Engineer, Propulsion Branch, ANM-140S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6438; fax: 425-917-6590; email: suzanne.lucier@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on August 6, 2013.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-19753 Filed 8-13-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF DEFENSE

Office of the Secretary

32 CFR Part 68

[Docket No. DOD-2013-OS-0093]

RIN 0790-AJ06

Voluntary Education Programs

AGENCY: Office of the Under Secretary of Defense for Personnel and Readiness, DoD.

ACTION: Proposed rule.

SUMMARY: In this proposed rule, the Department of Defense (DoD) discusses new policy, responsibilities, and procedures for the operation of voluntary education programs within DoD. The new policies discussed in the rule include the following.

All educational institutions providing education programs through the DoD Tuition Assistance (TA) Program will provide meaningful information to students about the financial cost and attendance at an institution so military students can make informed decisions on where to attend school; not use unfair, deceptive, and abusive recruiting

practices; and provide academic and student support services to Service members and their families. New criteria are created to strengthen existing procedures for access to military installations by educational institutions. An annual review and notification process is required if there are changes made to the uniform semester-hour (or equivalent) TA caps and annual TA ceilings. Military Departments will be required to provide their Service members with a joint services transcript (JST). The DoD Postsecondary Education Complaint System is implemented for Service members, spouses, and adult family members to register student complaints. The Military Departments are authorized to establish Service-specific TA eligibility criteria and management controls.

DATES: Comments must be received by September 30, 2013.

FOR FURTHER INFORMATION CONTACT: For general information concerning DoD Voluntary Education Programs, send a written inquiry to Ms. Carolyn Baker, at the Office of the Under Secretary of Defense (Personnel & Readiness), Military Community & Family Policy, State Liaison and Educational Opportunities, 4800 Mark Center Drive, Suite 14E08, Alexandria, Virginia 22350-2300 (Phone: 571-372-5355 or email: carolyn.baker@osd.mil).

SUPPLEMENTARY INFORMATION:

Executive Summary

This proposed rule implements Voluntary Education Programs for Military Service members. This rule includes educational programs that enable Service members to earn a degree on their off-duty time. Congress has held that men and women serving in the Armed Forces should have at least the same opportunity to advance academically as do civilians who remain outside the military.

Funding for Voluntary Education Programs is authorized by law and is subject to the availability of funds from each Service. Voluntary education programs include tuition assistance (TA) (per 10 U.S.C. 2007), which is administered uniformly across the Services. Subject to appropriations, each Service pays no more than \$250.00 per semester-unit (or equivalent) for tuition. Each Service member participating in off-duty, voluntary education is eligible for up to \$4,500.00, in aggregate, for each fiscal year. TA can only be used for courses offered by postsecondary institutions accredited by a national or regional accrediting body recognized by the U.S. Department of Education.

A March 2011 Government Accountability Office report on the DoD TA program recommended the Department take steps to enhance its oversight of schools receiving TA funds (available at <http://www.gao.gov/new.items/d11300.pdf>). As a result, a DoD Memorandum of Understanding (MOU) requirement was included in this rule, which is designated not only to improve Departmental oversight but also to account for our Service members' unique lifestyle requirements. The purpose of the DoD MOU is to establish a partnership between the Department and institutions to improve educational opportunities while protecting the integrity of each institution's core educational values. This partnership serves to ensure a quality, viable program exists that provides for our Service members to realize their educational goals, while allowing for judicious oversight of taxpayer dollars.

Background

The purpose of voluntary education programs is to provide active duty Service members with opportunities to enhance their academic achievement which in turn improves job performance and promotion potential. A final rule for DoD's Voluntary Education Programs was published in the **Federal Register** on December 6, 2012 (77 FR 72941-72956). The rule established the new requirement of a standardized memorandum of understanding (MOU) between DoD and the Institutions of Higher Learning (IHLs) prior to participating in DoD Voluntary Education Programs, such as the military tuition assistance program. As of June 25, 2013, 3,155 IHLs with a total of 4,180 sub-campuses have signed the DoD MOU.

This new proposed rule includes requirements stated in the President's Executive Order 13607, "*Establishing Principles of Excellence for Educational Institutions Servicing Service Members, Veterans, Spouses, and Other Family Members*", signed April 27, 2012 (available at <http://www.gpo.gov/fdsys/pkg/FR-2012-05-02/pdf/2012-10715.pdf>). In implementing the EO, three interagency working groups were established (information, compliance, and report), along with an aggressive timeline to ensure that the policies take effect as soon as possible. The E.O. directed DoD to coordinate with the Departments of Veterans Affairs and Education, and in consultation with the Department of Justice and the Consumer Financial Protection Bureau, to implement and promote compliance with the principles stated in the E.O. Several of these principles were covered