

paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-54A2237, dated March 14, 2013: Do a detailed inspection for cracking of the lower spar chords and web, an HFEC inspection for cracking of the lower spar chords, a lower spar chord modification, including open-hole HFEC inspections for cracking in the chord and all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-54A2237, dated March 14, 2013, except as required by paragraph (j)(2) of this AD. Do all applicable corrective actions before further flight. Doing the actions specified in this paragraph terminates the requirements of paragraph (g) of this AD for the modified strut only. The open-hole HFEC inspection for cracking must be done before the modification.

(i) Post Modification Repetitive Inspections

For airplanes on which a modification required by paragraph (g) or (h) of this AD has been done: At the compliance time specified in table 2 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-54A2237, dated March 14, 2013, do a detailed inspection for any cracking of the lower spar web and chord, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747-54A2237, dated March 14, 2013, except as required by paragraph (j)(2) of this AD. Repeat the inspection thereafter at intervals not to exceed 18 months. Do all applicable corrective actions before further flight.

(j) Exceptions

(1) Where Boeing Alert Service Bulletin 747-54A2237, dated March 14, 2013, specifies a compliance time after the original issue date on the service bulletin, this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 747-54A2237, dated March 14, 2013, specifies to contact Boeing for appropriate action: Before further flight, repair the crack using a method approved in accordance with the procedures specified in paragraph (k) of this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in the Related Information section of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the

Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(l) Related Information

(1) For more information about this AD, contact Nathan Weigand, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6428; fax: 425-917-6590; email: nathan.p.weigand@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on August 21, 2013.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-20969 Filed 8-27-13; 8:45 am]

BILLING CODE 4910-13-P

discrepancies on certain AC generator mounting adapters, and replacing discrepant adapters with serviceable ones. This proposed AD would also require revising the maintenance program to incorporate a repetitive task specified in certain temporary revisions. We are proposing this AD to detect and correct corrosion in the AC generator mounting plate, which could result in a gap between the AC generator and the generator mounting plate, and cause loss of engine oil and consequent engine failure.

DATES: We must receive comments on this proposed AD by October 15, 2013

ADDRESSES: You may send comments by any of the following methods:

- **Federal eRulemaking Portal:** Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** (202) 493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Assata Dessaline, Aerospace Engineer, Avionics and Flight Test Branch, ANE-

172, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228–7301; fax (516) 794–5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2013–0703; Directorate Identifier 2013–NM–004–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive, CF–2012–29, dated November 22, 2012 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

An incident has been reported on the DHC–8 aeroplane of a pilot commanded in-flight engine shut down in response to a[n] engine low oil pressure warning indication.

Further investigation revealed the mounting studs in the engine mounted AC generator mounting plate were pulled out of position and the threaded interface in the plate corroded. This resulted in a gap between the AC generator and the generator mounting plate, leading to the loss of engine oil and the ensuing illumination of the associated engine low oil pressure warning indication.

To ensure the integrity of the affected units, Part I of this [TCCA] AD mandates an [general visual and mechanical] inspection of the affected AC generator mounting adapters part numbers (P/N) 31708–500 or 31708–501, and, as applicable, replacement with new or serviceable mounting plates.

Part II of this [TCCA] AD mandates the incorporation of a repeat Maintenance Review Board (MRB) inspection applicable to the replacement of the AC generator mounting adapters P/Ns 31708–510 or 31708–511 only.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Bombardier has issued the following service information:

- Bombardier Service Bulletin 8–24–88, dated December 13, 2011.

• de Havilland Dash 8 Series 100 Temporary Revision MRB–153, dated July 10, 2012, Part 1 Section 2–Systems, of the de Havilland Dash 8 Series 100 Maintenance Program Manual PSM 1–8–7 MRB Report.

• de Havilland Dash 8 Series 200 Temporary Revision MRB 2–31, dated July 10, 2012, Part 1 Section 2–Systems of the de Havilland Dash 8 Series 200 Maintenance Program Manual PSM 1–82–7 MRB Report.

• de Havilland Dash 8 Series 300 Temporary Revision MRB 3–162, dated July 10, 2012, Part 1 Section 2–Systems of the de Havilland Dash 8 Series 300 Maintenance Program Manual PSM 1–83–7 MRB Report.

The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

This AD requires revisions to certain operator maintenance documents to include new actions (e.g., inspections). Compliance with these inspections is required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by these actions, the operator may not be able to accomplish the inspections described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (j)(1) of this AD. The request should include a description of changes to the required inspections that will ensure the continued operational safety of the airplane.

Costs of Compliance

Based on the service information, we estimate that this proposed AD would affect about 88 products of U.S. registry.

We also estimate that it would take about 5 work-hours per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$4,000 per product. Where the service information lists required parts costs that are covered under warranty, we have assumed that there will be no charge for these parts. As we do not control warranty coverage for affected parties, some parties may incur costs higher than estimated here. Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$389,400, or \$4,425 per product.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

Bombardier, Inc.: Docket No. FAA-2013-0703; Directorate Identifier 2013-NM-004-AD.

(a) Comments Due Date

We must receive comments by October 15, 2013.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model DHC-8-102, -103, -106, -201, -202, -301, -311, and -315 series airplanes; certificated in any category; serial numbers 019 through 672 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 24, Electrical Power.

(e) Reason

This AD was prompted by a report of a pilot commanding an in-flight engine shut down in response to a low oil pressure warning indication. Further investigation revealed the mounting studs in the engine mounted alternating current (AC) generator mounting plate were pulled out of position and the threaded interface in the plate corroded. We are issuing this AD to detect and correct corrosion in the AC generator mounting plate, which could result in a gap between the AC generator and the generator mounting plate, and cause loss of engine oil and consequent engine failure.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Inspection and Removal of AC Generator Mounting Adaptor

Within 6,000 flight hours or 36 months or when the AC generator is removed for service, whichever occurs first, after the effective date of this AD: Do a general visual inspection and a mechanical inspection for discrepancies (i.e., damage, corrosion, and failed mechanical inspection) on AC generator mounting adapters having P/N 31708-500 and P/N 31708-501, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-24-88, dated December 13, 2011. If any discrepancy (i.e., damage, corrosion, or failed mechanical inspection) is found, before further flight replace the AC generator mounting adapter with a serviceable mounting adapter having P/N 31708-510, P/N 31708-511, P/N 31708-500, or 31708-501, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 8-24-88, dated December 13, 2011.

(1) For in-service mounting adapters that have P/N 31708-500 or P/N 31708-501, repeat the general visual and mechanical inspection thereafter at intervals not to exceed 6,000 flight hours or 36 months after the most recent inspection or when the AC generator is removed for service, whichever occurs first.

(2) For airplanes having AC generator mounting adapters that have P/N 31708-500 or 31708-501: Within the later of the times specified in paragraphs (g)(2)(i) and (g)(2)(ii) of this AD, replace the AC generator mounting adapter with a new AC generator mounting adapter having P/N 31708-510 or 31708-511.

(i) Before the accumulation of 120 months on the part.

(ii) Within 12 months or 2,000 flight hours or when the generator is removed from service, whichever occurs first, after the effective date of the AD.

(h) Airplane Maintenance Program Revision

For airplanes having AC generator mounting adapters that have P/N 31708-510 or 31708-511: Within 30 days after the effective date of this AD, revise the airplane maintenance program by incorporating MRB Task 2420/14 in the applicable maintenance program manual specified in paragraph (h)(1), (h)(2), or (h)(3) of this AD. The initial compliance time for MRB Task 2420/14 is prior to the accumulation of 10,000 total flight hours or within 60 months since installation of the part, whichever occurs first.

(1) For Model DHC-8-102, -103, and -106 airplanes: de Havilland Dash 8 Series 100 Temporary Revision MRB-153, dated July 10, 2012, Part 1 Section 2—Systems, of the de Havilland Dash 8 Series 100 Maintenance Program Manual PSM 1-8-7 MRB Report.

(2) For Model DHC-8-201 and -202 airplanes: de Havilland Dash 8 Series 200 Temporary Revision MRB 2-31, dated July 10, 2012, Part 1 Section 2—Systems of the de Havilland Dash 8 Series 200 Maintenance Program Manual PSM 1-82-7 MRB Report.

(3) For Model DHC-8-301, -311, and -315 airplanes: de Havilland Dash 8 Series 300 Temporary Revision MRB 3-162, dated July 10, 2012, Part 1 Section 2—Systems of the de

Havilland Dash 8 Series 300 Maintenance Program Manual PSM 1-83-7 MRB Report.

(i) No Alternative Actions or Intervals

After accomplishing the revision required by paragraph (h) of this AD, no alternative actions (e.g., inspections) or intervals may be used, unless the actions and intervals are approved as an AMOC in accordance with the procedures specified in paragraph (j)(1) of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Airworthy Product:* For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to ensure the product is airworthy before it is returned to service.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2012-29, dated November 22, 2012, and the service information specified in paragraphs (l)(1)(i) through (l)(1)(iv) of this AD, for related information.

(i) Bombardier Service Bulletin 8-24-88, dated December 13, 2011.

(ii) de Havilland Dash 8 Series 100 Temporary Revision MRB-153, dated July 10, 2012, Part 1 Section 2—Systems, of the de Havilland Dash 8 Series 100 Maintenance Program Manual PSM 1-8-7 MRB Report.

(iii) de Havilland Dash 8 Series 200 Temporary Revision MRB 2-31, dated July 10, 2012, Part 1 Section 2—Systems of the de Havilland Dash 8 Series 200 Maintenance Program Manual PSM 1-82-7 MRB Report.

(iv) de Havilland Dash 8 Series 300 Temporary Revision MRB 3-162, dated July 10, 2012, Part 1 Section 2—Systems of the de Havilland Dash 8 Series 300 Maintenance Program Manual PSM 1-83-7 MRB Report.

(2) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com;

Internet <http://www.bombardier.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on August 21, 2013.

Stephen P. Boyd,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.
[FR Doc. 2013-20968 Filed 8-27-13; 8:45 am]

BILLING CODE 4910-13-P

PEACE CORPS

22 CFR Part 303

RIN 0420-AA29

Freedom of Information Act Administration

AGENCY: Peace Corps.

ACTION: Proposed rule; correction.

SUMMARY: The Peace Corps is correcting a typographical error in a proposed rule that appeared in the **Federal Register** of August 7, 2013. The proposed rule updates Peace Corps regulations on the Freedom of Information Act (FOIA) to implement guidance given by the President and the Attorney General regarding discretionary disclosures of records or information exempt from disclosure under the FOIA, whenever disclosure would not foreseeably harm an interest protected by a FOIA exemption. The proposed rule is based on language used by Department of Justice in its FOIA regulations. Additionally, the proposed rule deletes unnecessary and superfluous language and ensures the rule is consistent with current law.

FOR FURTHER INFORMATION CONTACT:
Anne Passmore, 202-692-2164.

Correction

In proposed rule FR Doc. 2013-19050 published on August 7, 2013 (78 FR 48083), make the following correction:

On page 48084, in the third column, third paragraph, in § 303.10(c)(2)(ii), remove “Executive Order 13525” and add “Executive Order 13526” in its place.

Dated: August 22, 2013.

Garry W. Stanberry,
Deputy Associate Director, Management.
[FR Doc. 2013-20926 Filed 8-27-13; 8:45 am]

BILLING CODE 6051-01-P

DEPARTMENT OF THE INTERIOR

Bureau of Indian Affairs

25 CFR Part 226

[BIA-2013-0003; 134/A0A511010/
AAK1001000]

RIN 1076-AF17

Leasing of Osage Reservation Lands for Oil and Gas Mining

AGENCY: Bureau of Indian Affairs, Interior.

ACTION: Proposed rule.

SUMMARY: The Bureau of Indian Affairs is proposing to revise the regulations addressing oil and gas mining on reservation land of the Osage Nation. This rule updates the leasing procedures and rental, production, and royalties requirements for oil and gas on Osage Mineral lands and is the result of a negotiated rulemaking.

DATES: Comments on this proposed rule must be received by October 28, 2013. Comments on the information collections contained in this proposed regulation are separate from those on the substance of the rule. Comments on the information collection burden should be received by September 27, 2013 to ensure consideration, but must be received no later than October 28, 2013.

ADDRESSES: You may submit comments by any of the following methods:

- Federal rulemaking portal:* The rule is listed under the agency name “Bureau of Indian Affairs” and has been assigned Docket ID “BIA-2013-0003” at <http://www.regulations.gov>.
- Email:* osageregneg@bia.gov. Include the number 1076-AF17 in the subject line of the message.
- Mail or hand-delivery:* Mr. Eddie Streeter, Designated Federal Officer, Bureau of Indian Affairs, P.O. Box 8002, Muskogee, OK 74402. Include the number 1076-AF17 on the outer envelope.

We cannot ensure that comments received after the close of the comment period (see **DATES**) will be included in the docket for this rulemaking and considered. Comments sent to an address other than those listed above will not be included in the docket for this rulemaking.

Comments on the information collections contained in this proposed regulation are separate from those on the substance of the rule. Send comments on the information collection burden to OMB by facsimile to (202) 395-5806 or email to the OMB Desk

Officer for the Department of the Interior at OIRA_submission@omb.eop.gov. Please send a copy of your comments to the person listed in the **FOR FURTHER INFORMATION CONTACT** section of this notice.

FOR FURTHER INFORMATION CONTACT: Mr. Eddie Streeter, Designated Federal Officer, Bureau of Indian Affairs, P.O. Box 8002, Muskogee, OK 74402; telephone (918) 781-4608; fax (918) 718-4604; or email osageregneg@bia.gov. Additional information on the negotiated rulemaking can be found at: <http://www.bia.gov/osageregneg>.

SUPPLEMENTARY INFORMATION:

I. Executive Summary of Rule

This rule updates the oil and gas regulations governing Osage County. It is intended to strengthen the management and administration of the Osage mineral estate for the benefit of the Osage. These provisions provide updated reporting and inspection requirements, further specify lessee obligations with respect to operations, revise royalty rate calculations and update the amounts for bonds, fines and penalties.

II. Background

On October 14, 2011, the United States and the Osage Nation (formerly known as the Osage Tribe) signed a Settlement Agreement to resolve litigation regarding alleged mismanagement of the Osage Nation’s oil and gas mineral estate, among other claims. In the Settlement Agreement, the parties agreed that it would be mutually beneficial “to address means of improving the trust management of the Osage Mineral Estate, the Osage Tribal Trust Account, and Other Osage Accounts.” The parties agreed that a review and revision of the existing regulations is warranted to better assist the Bureau of Indian Affairs (BIA) in managing the Osage Mineral Estate. The parties agreed to engage in a negotiated rulemaking for this purpose. For additional information on the negotiated rulemaking, please visit <http://www.bia.gov/osageregneg/>. The Committee submitted its report to BIA on April 25, 2013. BIA has based this proposed rule on the report.

III. Detailed Explanation of Revisions

This rule revises 25 CFR part 226 by changing all references to the “Osage Tribal Council” to the “Osage Minerals Council” because the Osage Tribal Council no longer exists and the Osage Minerals Council has the authority to make decisions regarding the Osage minerals estate. To avoid confusion in terminology, this rule changes all