

Novel or Unusual Design Features

The Model EMB-550 airplane will incorporate the following novel or unusual design features: The design of the electronic flight control system incorporates normal load factor limiting on a full-time basis that will prevent the flight crew from inadvertently or intentionally exceeding the positive or negative airplane limit load factor. This feature is considered novel and because the current regulations do not provide standards for maneuverability and controllability evaluations for such systems. Therefore, a special condition is needed to ensure adequate maneuverability and controllability when using this design feature.

Discussion

Title 14 Code of Federal Regulations (14 CFR) part 25 sections do not specify requirements or policy for demonstrating maneuver control that impose any handling qualities requirements beyond the design limit structural loads. Nevertheless, some pilots have become accustomed to the availability of this excess maneuver capacity in case of extreme emergency such as upset recoveries or collision avoidance.

As with previous fly-by-wire airplanes, the FAA has no regulatory or safety reason to prohibit a design for an electronic flight control system with load factor limiting. It is possible that pilots accustomed to this feature feel more freedom in commanding full-stick displacement maneuvers because of the following:

- Knowledge that the limit system will protect the structure,
- Low stick force/displacement gradients,
- Smooth transition from pilot elevator control to limit control.

The special conditions will ensure adequate maneuverability and controllability when using this design feature.

Applicability

As discussed above, these special conditions are applicable to the Model EMB-550 airplane. Should Embraer S.A. apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, the special conditions would apply to that model as well.

Conclusion

This action affects only certain novel or unusual design features on one model of airplanes. It is not a rule of general applicability.

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701, 44702, 44704.

The Proposed Special Conditions

Accordingly, the Federal Aviation Administration (FAA) proposes the following special conditions as part of the type certification basis for Embraer S.A. Model EMB-550 airplanes.

1. Flight Envelope Protection: Normal Load Factor (g) Limiting.

To meet the intent of adequate maneuverability and controllability required by § 25.143(a), and in addition to the requirements of § 25.143(a) and in the absence of other limiting factors, the following special conditions are proposed based on § 25.333(b):

(a) The positive limiting load factor must not be less than:

(1) 2.5g for the normal state of the electronic flight control system with the high lift devices retracted.

(2) 2.0g for the normal state of the electronic flight control system with the high lift devices extended.

(b) The negative limiting load factor must be equal to or more negative than:

(1) Minus 1.0g for the normal state of the electronic flight control system with the high lift devices retracted.

(2) 0.0g for the normal state of the electronic flight control system with high lift devices extended.

(c) Maximum reachable positive load factor wings level may be limited by the characteristics of the electronic flight control system or flight envelope protections (other than load factor protection) provided that:

(1) The required values are readily achievable in turns, and

(2) That wings level pitch up is satisfactory.

(d) Maximum achievable negative load factor may be limited by the characteristics of the electronic flight control system or flight envelope protections (other than load factor protection) provided that:

(1) Pitch down responsiveness is satisfactory, and

(2) From level flight, 0g is readily achievable or alternatively, a satisfactory trajectory change is readily achievable at operational speeds. For the FAA to consider a trajectory change as satisfactory, the applicant should propose and justify a pitch rate that provides sufficient maneuvering capability in the most critical scenarios.

(e) Compliance demonstration with the above requirements may be

performed without ice accretion on the airframe.

(f) These proposed special conditions do not impose an upper bound for the normal load factor limit, nor does it require that the limiter exist. If the limit is set at a value beyond the structural design limit maneuvering load factor n of §§ 25.333(b), 25.337(b), 25.337(c), there should be a very obvious positive tactile feel built into the controller so that it serves as a deterrent to inadvertently exceeding the structural limit.

Issued in Renton, Washington, on September 6, 2013.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-25204 Filed 10-24-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-0867; Directorate Identifier 2013-NM-115-AD]

RIN 2120-AA64

Airworthiness Directives; the Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 777-200, -200LR, -300, and -300ER series airplanes. This proposed AD was prompted by reports of severe corrosion on bonding jumpers installed on the flight control surfaces. This proposed AD would require repetitive bonding jumper inspections for corrosion, sealant disbond, and insufficient sealant coverage, and corrective actions if necessary. This proposed AD also specifies an optional action of doing an inspection for corrosion damage of the bonding brackets, and corrective actions if necessary, which would terminate the repetitive inspections. For certain airplanes, this proposed AD would also require installing certain bonding jumpers and related ground clips and fasteners to the elevators, horizontal stabilizers, rudder, and vertical fin, removing certain bonding jumpers and installing new bonding jumpers, and replacing single-tabbed brackets with two-tabbed brackets. We are proposing this AD to detect and correct corrosion

on bonding jumpers installed on the flight control surfaces, which, in the event of a lighting strike, could damage the actuator control electronics (ACEs) and result in the loss of the ability to command individual flight control surfaces or cause uncommanded motion of individual flight control surfaces.

DATES: We must receive comments on this proposed AD by December 9, 2013.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Georgios Roussos, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, Seattle Aircraft Certification Office, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-917-6482; fax: 425-917-6590; email: Georgios.Roussos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2013-0867; Directorate Identifier 2013-NM-115-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report of severe corrosion on 15 bonding jumpers on the ailerons, horizontal stabilizers, and vertical fins of six airplanes that were approximately eight years old. We also received a similar report on an airplane that was approximately seven years old. The corrosion is caused by sealant voids, which allow moisture under the sealant and then trap it inside.

The bonding jumpers are part of the lightning protection ground path for the flight control surfaces that prevent excessive lightning energy from traveling to the primary flight control actuators and then to one of the four ACEs. Corrosion damage on the bonding jumper connections creates high resistance bonding paths that could, in the event of a lightning strike, potentially expose multiple flight control system ACEs to high voltage transients. The excessive voltage could cause damage to the ACEs and result in the loss of the ability to command individual flight control surfaces or cause uncommanded motion of individual flight control surfaces.

A new category 2 fay seal method has been developed to improve the integrity of the bonding jumper connections. This new method creates a continuous layer of sealant inside and outside of all mating surfaces to keep moisture away from the bonding surfaces and prevent corrosion.

Relevant Service Information

We reviewed the following service bulletins:

- Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013

- Boeing Service Bulletin 777-55A0010, Revision 1, dated April 17, 2001
- Boeing Service Bulletin 777-55A0014, Revision 1, dated April 1, 2010

For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for Docket No. FAA-2013-0867.

Other Relevant Rulemaking

This proposed AD is related to AD 2012-08-13, Amendment 39-17030 (77 FR 24357, April 24, 2012). AD 2012-08-13 requires replacing certain single-tabbed bonding brackets in the airplane empennage with two-tabbed bonding brackets. AD 2012-08-13 also requires, for certain airplanes, installing new bonding jumpers, and measuring the resistance of the modified installation to verify resistance is within specified limits. AD 2012-08-13 refers to Boeing Service Bulletin 777-55A0010, Revision 1, dated April 17, 2001; and Boeing Service Bulletin 777-55A0014, Revision 1, dated April 1, 2010; as the appropriate sources of service information for accomplishing the required actions.

This proposed AD would require inspecting the installation of the bonding jumpers associated with AD 2012-08-13, Amendment 39-17030 (77 FR 24357, April 24, 2012).

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information identified previously, except as discussed under "Differences Between the Proposed Rule and the Service Information."

The phrase "corrective actions" might be used in this proposed AD. "Corrective actions" are actions that correct or address any condition found. Corrective actions in an AD could include, for example, repairs.

Difference Between the Proposed Rule and the Service Bulletin

Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013, specifies to contact the manufacturer for instructions on how to repair certain conditions, but this proposed AD would require repairing

those conditions in one of the following ways:

- In accordance with a method that we approve; or
- Using data that meet the certification basis of the airplane, and

that have been approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) whom we have authorized to make those findings.

Costs of Compliance

We estimate that this proposed AD affects 131 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection of bonding jumpers	Up to 67 work-hours × \$85 per hour = Up to \$5,695 per inspection cycle.	\$0	Up to \$5,695 per inspection cycle.	Up to \$746,045 per inspection cycle.
Replacement of bonding brackets	Up to 158 work-hours × \$85 per hour = Up to \$13,430.	37,928	Up to \$51,358	Up to \$6,727,898.
Concurrent cost Boeing Service Bulletin 777-55A0010, Revision 1, dated April 17, 2001.	66 work-hours × \$85 per hour = \$5,610	2,668	\$8,278	\$1,084,418.
Concurrent cost Boeing Service Bulletin 777-55A0014, Revision 1, dated April 1, 2010.	21 work-hours × \$85 per hour = \$1,785	1,235	\$3,020	\$395,620.

We estimate the following costs to do any necessary replacements that would

be required based on the results of the proposed inspection. We have no way of

determining the number of aircraft that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replacement of bonding brackets	Up to 158 work-hours × \$85 per hour = Up to \$13,430	\$37,928	Up to \$51,358.

We have received no definitive data that would enable us to provide cost estimates for certain on-condition repairs specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on

the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2013-0867; Directorate Identifier 2013-NM-115-AD.

(a) Comments Due Date

We must receive comments by December 9, 2013.

(b) Affected ADs

This AD affects AD 2012-08-13, Amendment 39-17030 (77 FR 24357, April 24, 2012).

(c) Applicability

This AD applies to the Boeing Company Model 777-200, -200LR, -300, and -300ER series airplanes, certificated in any category, as identified in Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013.

(d) Subject

Joint Aircraft System Component (JASC)/Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Unsafe Condition

This AD was prompted by reports of severe corrosion on bonding jumpers installed on the flight control surfaces. We are issuing this AD to detect and correct corrosion on bonding jumpers installed on the flight control surfaces, which, in the event of a lightning strike, could damage the actuator control electronics (ACEs) and result in the

loss of the ability to command individual flight control surfaces or cause uncommanded motion of individual flight control surfaces.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Bonding Jumper or Bracket Inspection

At the applicable compliance time specified in paragraph 1.E., "Compliance," of Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013, except as specified in paragraphs (j)(1) and (j)(2) of this AD: Do a general visual inspection or a detailed inspection using a borescope, as applicable, for corrosion, sealant disbond, and insufficient sealant coverage of bonding jumpers; and do all applicable corrective actions: in accordance with Option 1, and Option 2, as applicable, of the Accomplishment Instructions of Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013, except as required by paragraph (j)(3) of this AD. Do a detailed inspection using a borescope if the horizontal stabilizer tips have not been removed. Do all applicable corrective actions before further flight. Repeat the inspection thereafter at intervals not to exceed 48 months. Doing the actions specified in paragraph (h)(1) of this AD on a bonding jumper terminates the repetitive inspections required by this paragraph. Doing the actions specified in paragraph (h)(2) of this AD terminates repetitive inspections required by this paragraph for that bonding jumper.

(h) Optional Terminating Action and Termination of Certain Repetitive Inspections

(1) Doing a general visual inspection or a detailed inspection for corrosion damage of the bonding jumper brackets, and all applicable corrective actions; in accordance with Option 2 of the Accomplishment Instructions of Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013; terminates the repetitive inspections required by paragraph (g) of this AD. Do all applicable corrective actions before further flight.

(2) The repetitive inspections required by paragraph (g) of this AD are not required on the bonding jumpers that were removed, inspected, and replaced with new bonding jumpers and new fasteners using the new category 2 fay sealed direct standard ground stud installation method, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013.

(i) Prior and Concurrent Requirements

(1) For Group 1 airplanes, as identified in Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013: Prior to or concurrently with accomplishing the actions required by paragraph (g) of this AD, install new bonding jumpers, and do resistance measurements of the modified installation to verify resistance is within the limits specified in the Accomplishment Instructions of Boeing Service Bulletin 777-55A0010, Revision 1, dated April 17, 2001. Do the actions in accordance with the

Accomplishment Instructions of Boeing Service Bulletin 777-55A0010, Revision 1, dated April 17, 2001.

Note 1 to paragraph (i)(1) of this AD: AD 2012-08-13, Amendment 39-17030 (77 FR 24357, April 24, 2012), refers to Boeing Service Bulletin 777-55A0010, Revision 1, dated April 17, 2001, as the appropriate source of service information for accomplishing the actions specified in paragraph (h) of AD 2012-08-13.

(2) For Group 1 and Group 2 airplanes, as identified in Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013: Prior to or concurrently with accomplishing the actions required by paragraph (g) of this AD, replace certain single-tabbed bonding brackets in the airplane empennage with two-tabbed bonding brackets, in accordance with the Accomplishment Instructions of Boeing Service Bulletin 777-55A0014, Revision 1, dated April 1, 2010.

Note 2 to paragraph (i)(2) of this AD: AD 2012-08-13, Amendment 39-17030 (77 FR 24357, April 24, 2012), refers to Boeing Service Bulletin 777-55A0014, Revision 1, dated April 1, 2010, as the appropriate source of service information for accomplishing the actions specified in paragraph (g) of AD 2012-08-13.

(j) Exceptions to Service Information

(1) Where Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013, specifies a compliance time after the "Original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) The "Condition" column in paragraph 1.E., "Compliance," of Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013, refers to a condition as of the "Original Issue date of this service bulletin." This AD applies to the corresponding condition as of the effective date of this AD.

(3) If any corrosion damage is found during any inspection required by this AD, and Boeing Service Bulletin 777-27A0078, Revision 1, dated April 1, 2013, specifies to contact Boeing for appropriate action: Before further flight, repair the corrosion damage using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

(k) Credit for Previous Actions

(1) For Groups 1, 2, and 6 through 9, as identified in Boeing Alert Service Bulletin 777-27A0078, dated September 10, 2009: This paragraph provides credit for actions required by paragraph (g) of this AD and the actions specified in paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 777-27A0078, dated September 10, 2009, which is not incorporated by reference in this AD.

(2) For Groups 3 through 5, as identified in Boeing Alert Service Bulletin 777-27A0078, dated September 10, 2009: This paragraph provides credit for actions required by paragraph (g) of this AD, except for the actions required for bonding jumpers 21 and 22, if those actions were performed before the effective date of this AD using

Boeing Alert Service Bulletin 777-27A0078, dated September 10, 2009, which is not incorporated by reference in this AD. If a check of the airplane's maintenance records positively determines that bonding jumpers 21 and 22 were inspected before the effective date of this AD in accordance with Option 1 of Work Package 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 777-27A0078, dated September 10, 2009, this paragraph provides credit for the actions required by paragraph (g) of this AD for the inspected bonding jumpers.

(3) For Groups 3 through 5, as identified in Boeing Alert Service Bulletin 777-27A0078, dated September 10, 2009: This paragraph provides credit for actions specified in paragraph (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 777-27A0078, dated September 10, 2009, which is not incorporated by reference in this AD; provided that a check of the airplane's maintenance records positively determines that bonding jumpers 21 and 22 were replaced in accordance with Option 2 of Work Package 3 of the Accomplishment Instructions of Boeing Alert Service Bulletin 777-27A0078, dated September 10, 2009, or were replaced using the new Category 2 fay sealed direct ground stud installation method.

(4) This paragraph provides credit for actions required by paragraph (i)(1) of this AD if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 777-55A0010, dated October 26, 2000, which is not incorporated by reference in this AD.

(5) This paragraph provides credit for actions required by paragraph (i)(2) of this AD if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 777-55A0014, dated May 8, 2008, which is not incorporated by reference in this AD.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (m) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your Principal Maintenance Inspector or Principal Avionics Inspector, as appropriate, or lacking a principal inspector, your local Flight Standards District Office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes ODA that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(m) Related Information

(1) For more information about this AD, Georgios Roussos, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, Seattle Aircraft Certification Office, FAA, 1601 Lind Avenue SW., Renton, Washington 98057-3356; phone: 425-917-6482; fax: 425-917-6590; email: Georgios.Roussos@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on October 15, 2013.

Jeffrey E. Duven,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2013-25134 Filed 10-24-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2013-0888; Directorate Identifier 2013-CE-024-AD]

RIN 2120-AA64

Airworthiness Directives; Costruzioni Aeronautiche Tecnam srl Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Costruzioni Aeronautiche Tecnam srl Model P2006T airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as cracks of the nose landing gear (NLG) lower link. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by December 9, 2013.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow

the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Costruzioni Aeronautiche Tecnam Airworthiness Office, Via Maiorise-81043 Capua (CE) Italy; telephone: +39 0823 620134; fax: +39 0823 622899; email: m.oliva@tecnam.com or g.paduan@tecnam.com; Internet: www.tecnam.com/it-IT/documenti/service-bulletins.aspx. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Albert Mercado, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4119; fax: (816) 329-4090; email: albert.mercado@faa.gov.

SUPPLEMENTARY INFORMATION:**Comments Invited**

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2013-0888; Directorate Identifier 2013-CE-024-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will

consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No.: 2013-0134, dated July 2, 2013 (referred to after this as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

During an inspection of a P2006T, a nose landing gear (NLG) lower link was found with two cracks. The affected NLG lower link is part of NLG lower link assembly P/N 26-8-1417-000.

This condition, if not detected and corrected, could lead to NLG failure, possibly resulting in damage to the aeroplane and injury to the occupants.

To address this potential unsafe condition, Costruzioni Aeronautiche Tecnam (hereafter referred to as Tecnam) issued Service Bulletin (SB) SB-128-CS, providing inspection instructions. Tecnam also developed an improved NLG lower link assembly with P/N 26-8-8000-000, which can be installed in service by accomplishment of Tecnam SB-104-CS.

For the reasons described above, this AD requires, for aeroplanes equipped with NLG lower link assembly P/N 26-8-1417-000, a one-time inspection of the NLG lower link and, depending on findings, accomplishment of the applicable corrective action. This AD also requires installation of the improved NLG lower link assembly P/N 26-8-8000-000.

You may obtain further information by examining the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2013-0888.

Relevant Service Information

Costruzioni Aeronautiche Tecnam srl issued Service Bulletin No. SB 104-CS, Edition 2, Revision 1, dated March 28, 2013 (now superseded); Service Bulletin No. SB 128-CS, Revision 0, dated May 15, 2013; Job Card 442, Revision 1, dated February 11, 2013; Job Card 468, dated October 12, 2012; and Job Card 528, Revision 1, dated April 2, 2013. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.