

(a) Model EC120B helicopters, serial numbers up to and including 1367, with a sliding door, Part Number (P/N) C526A2370101, installed; and

(b) Model EC130B4 helicopters with a sliding door, P/N C526S1101051, installed.

(b) Unsafe Condition

This AD defines the unsafe condition as a failure of the sliding door star axle support. This condition could prevent operation of a sliding door from inside, which could delay evacuation of passengers during an emergency.

(c) Comments Due Date

We must receive comments by March 3, 2014.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within 165 hours time-in-service:

(1) Visually inspect each upper and lower locking pin control rod end fitting (control end fitting) for a bend, twist, or breakage. If a control end fitting is bent, twisted, or broken, before further flight, replace the control end fitting with an airworthy control end fitting.

(2) Clean and dye penetrant inspect the star support pin for a crack in the areas identified as Zone X and Zone Y in Figure 3 of Eurocopter Alert Service Bulletin (ASB) No. EC120-52A014 or ASB No. EC130-52A009, both Revision 1, and both dated January 25, 2013, as applicable to your model helicopter. If there is a crack in the star support pin, before further flight, replace the star support pin with an airworthy star support pin.

(3) Reinforce the sliding door star support stringer by installing three carbon fabric plies by following the Accomplishment Instructions, paragraph 3.B.2.d, of ASB No. EC120-52A014 or ASB No. EC130-52A009, as applicable to your model helicopter, except this AD does not require you to comply with paragraph 3.C.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Gary Roach, Aviation Safety Engineer, Regulations and Policy Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email gary.b.roach@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD 2013-0093, dated April 15, 2013. You may

view the EASA AD in Docket No. FAA-2013-1090 on the Internet at <http://www.regulations.gov>.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 5220, Emergency Exits.

Issued in Fort Worth, Texas, on December 18, 2013.

Lance T. Gant,

Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2013-31298 Filed 12-31-13; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2013-1068; Directorate Identifier 2013-NM-196-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model DHC-8-400 series airplanes. This proposed AD was prompted by reports of failure of the high pressure shutoff valves (HPSOVs) causing the timer and monitor unit (TMU) to become inoperative since the HPSOV and the TMU are on the same circuit breaker. This proposed AD would require a wiring modification to segregate the HPSOV power supply from the TMU. We are proposing this AD to prevent an inoperative TMU, which could result in the loss of the automatic de-icing mode, and lead to an increased workload for the flight crew and loss of control of the airplane.

DATES: We must receive comments on this proposed AD by February 18, 2014.

ADDRESSES: You may send comments by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- Fax: (202) 493-2251.

- Mail: U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- Hand Delivery: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5

p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>.

You may review copies of the referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov>; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the MCAI, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Cesar Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone (516) 228-7318; fax (516) 794-5531.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2013-1068; Directorate Identifier 2013-NM-196-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority

for Canada, has issued Canadian Airworthiness Directive CF-2013-27, dated September 25, 2013 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

There have been several in-service reports of the failure of high pressure shutoff valves (HPSOV) causing the Timer and Monitor Unit (TMU) to become inoperative since the HPSOV and TMU are on the same circuit breaker.

An inoperative TMU would result in the loss of the automatic de-icing mode and would lead to an increased workload for the flightcrew. In the case where additional failures occur during a critical flight phase, the significantly increased workload could lead to loss of control of the aeroplane.

This [TCCA] AD mandates a wiring modification to segregate the HPSOV power supply from the TMU.

You may obtain further information by examining the MCAI in the AD docket.

Relevant Service Information

Bombardier, Inc. has issued Service Bulletin 84-36-04, Revision A, dated April 17, 2013. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation

in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 78 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Wiring Modification	7 work-hours × \$85 per hour = \$595	\$0	\$595	\$46,410

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;

2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);

3. Will not affect intrastate aviation in Alaska; and

4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared a regulatory evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA-2013-1068; Directorate Identifier 2013-NM-196-AD.

(a) Comments Due Date

We must receive comments by February 18, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc. Model DHC-8-400, -401, and -402 airplanes, certificated in any category, serial numbers 4001 through 4446 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 36, Pneumatic.

(e) Reason

This AD was prompted by reports of failure of the high pressure shutoff valves (HPSOVs) causing the timer and monitor unit (TMU) to become inoperative since the HPSOV and the TMU are on the same circuit breaker. We are issuing this AD to prevent an inoperative TMU, which could result in the loss of the automatic de-icing mode, and lead to an increased workload for the flight crew and loss of control of the airplane.

(f) Compliance

You are responsible for having the actions required by this AD performed within the compliance times specified, unless the actions have already been done.

(g) Segregation of the HPSOV Power Supply From the TMU

Within 2,000 flight hours or 12 months after the effective date of this AD, whichever occurs first: Do a wiring modification to segregate the HPSOV power supply from the TMU by incorporating Bombardier ModSum 4-110595, in accordance with the Accomplishment Instructions of Bombardier

Service Bulletin 84–36–04, Revision A, dated April 17, 2013.

(h) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 84–36–04, dated March 13, 2013.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York Aircraft Certification Office (ACO), ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the New York ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516 228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) Airworthy Product: For any requirement in this AD to obtain corrective actions from a manufacturer, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they were approved by the State of Design Authority (or its delegated agent, or by the DAH with a State of Design Authority's design organization approval). For a repair method to be approved, the repair approval must specifically refer to this AD. You are required to ensure the product is airworthy before it is returned to service.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF–2013–27, dated September 25, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov>.

(2) For service information identified in this AD, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416–375–4000; fax 416–375–4539; email thd.qseries@aero.bombardier.com; Internet <http://www.bombardier.com>. You may review copies of this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on December 20, 2013.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate,
Aircraft Certification Service.

[FR Doc. 2013–31314 Filed 12–31–13; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF JUSTICE

Bureau of Prisons

28 CFR Part 527

[BOP–1165–P]

RIN 1120–AB65

Transfer of Offenders to Foreign Countries

AGENCY: Bureau of Prisons, Department of Justice.

ACTION: Notice of proposed rulemaking.

SUMMARY: In this document, the Bureau of Prisons (Bureau) proposes to streamline its regulations on transferring offenders to foreign countries by eliminating language that constitutes agency guidance to staff. Guidance language will be retained in the relevant Bureau policy.

DATES: Comments due by March 3, 2014.

ADDRESSES: Comments should be submitted to the Rules Unit, Office of General Counsel, Bureau of Prisons, 320 First Street NW., Washington, DC 20534. You may also comment via the Internet to BOP at BOPRULES@BOP.GOV or by using the www.regulations.gov comment form for this regulation. When submitting comments electronically you must include the BOP Docket No. in the subject box.

FOR FURTHER INFORMATION CONTACT: Sarah Qureshi, Office of General Counsel, Bureau of Prisons, phone (202) 307–2105.

SUPPLEMENTARY INFORMATION:

Posting of Public Comments

Please note that all comments received are considered part of the public record and are made available for public inspection online at www.regulations.gov. Such information includes personal identifying information (such as your name, address, etc.) voluntarily submitted by the commenter.

If you want to submit personal identifying information (such as your name, address, etc.) as part of your comment, but do not want it to be posted online, you must include the phrase “PERSONAL IDENTIFYING INFORMATION” in the first paragraph of your comment. You must also locate all the personal identifying information you do not want posted online in the first paragraph of your comment and identify what information you want redacted.

If you want to submit confidential business information as part of your

comment but do not want it to be posted online, you must include the phrase “CONFIDENTIAL BUSINESS INFORMATION” in the first paragraph of your comment. You must also prominently identify confidential business information to be redacted within the comment. If a comment has so much confidential business information that it cannot be effectively redacted, all or part of that comment may not be posted on www.regulations.gov.

Personal identifying information identified and located as set forth above will be placed in the agency's public docket file, but not posted online. Confidential business information identified and located as set forth above will not be placed in the public docket file. If you wish to inspect the agency's public docket file in person by appointment, please see the **FOR FURTHER INFORMATION CONTACT** paragraph.

Proposed Rule

In this document, the Bureau of Prisons (Bureau) proposes to streamline its regulations on transferring offenders to or from foreign countries by eliminating language that constitutes agency guidance to staff. Guidance language will be retained in the relevant Bureau policy. Below is an analysis of each new proposed section.

Section 527.40 Purpose and Scope

This section more concisely describes the statutory authority (18 U.S.C. 4100, et seq.) for the Bureau's procedures for transferring offenders to foreign countries and states that the purpose of this subpart is to describe those procedures. We propose to delete obsolete references to Public Law 95–144, as it has been codified as 18 U.S.C. 4100, and also propose to delete the recitation of authority which stated that “18 U.S.C. 4102 authorizes the Attorney General to act on behalf of the United States in regard to such treaties. In accordance with the provisions of 28 CFR 0.96b, the Attorney General has delegated to the Director of the Bureau of Prisons, and to designees of the Director, the authority to receive custody of, and to transfer to and from the United States, offenders in compliance with the conditions of the treaty.” This authority is stated elsewhere in regulation and in the Authority section preceding these regulations and is therefore not necessary to repeat in these regulations.

Section 527.41 Definitions

This section continues to define the terms “treaty nation,” “state prisoner,”