

**AgustaWestland S.p.A.)**  
**(AgustaWestland):** Amendment 39-17773; Docket No. FAA-2013-0643; Directorate Identifier 2012-SW-096-AD.

**(a) Applicability**

This AD applies to AgustaWestland Model A109S, AW109SP, A119, and AW119 MKII helicopters with a main rotor lag damper assembly (lag damper), part number (P/N) 109-0112-39-103, 109-0112-39-105, 109-0112-05-105, or 109-0112-05-107, installed with a rod end assembly, P/N M004-01H007-041 or M004-01H007-045, with a serial number (S/N) 84 through 132, or 4964 through 5011, certificated in any category.

**(b) Unsafe Condition**

This AD defines the unsafe condition as a crack in a rod end assembly, which could result in fracture of the rod end assembly, damage to the main rotor, and subsequent loss of control of the helicopter.

**(c) Effective Date**

This AD becomes effective April 7, 2014.

**(d) Compliance**

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

**(e) Required Actions**

- (1) Within 25 hours time-in-service, remove the rod end assembly from service.
- (2) Do not install a rod end assembly, P/N M004-01H007-041 or M004-01H007-045, with a S/N 84 through 132 or 4964 through 5011, on any helicopter.

**(f) Special Flight Permits**

Special flight permits are prohibited.

**(g) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email [robert.grant@faa.gov](mailto:robert.grant@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

**(g) Additional Information**

(1) AgustaWestland Bollettino Tecnico No. 109S-49, No. 109SP-052, and No. 119-50, all dated October 3, 2012, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact AgustaWestland, Product Support Engineering, Via del Gregge, 100, 21015 Lonate Pozzolo (VA) Italy, ATTN: Maurizio D'Angelo; telephone 39-0331-664757; fax 39-0331-664680; or at <http://www.agustawestland.com/technical-bulletins>. You may review the referenced

service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2012-0208, dated October 5, 2012. You may view the EASA AD on the Internet at <http://www.regulations.gov> in Docket No. FAA-2013-0643.

**(h) Subject**

Joint Aircraft Service Component (JASC) Code: 6200, Main Rotor System.

Issued in Fort Worth, Texas, on February 20, 2014.

**Lance T. Gant,**

*Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.*  
 [FR Doc. 2014-04310 Filed 2-28-14; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2013-0770; Directorate Identifier 2011-SW-057-AD; Amendment 39-17771; AD 2014-04-12]**

**RIN 2120-AA64**

**Airworthiness Directives; Airbus Helicopters (Type Certificate Previously Held by Eurocopter France) (Airbus Helicopters)**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Airbus Helicopters Model EC225LP helicopters. This AD adds a new operating limitation that requires increasing the minimum density altitude flight limitation for helicopters without certain Eurocopter modifications installed. This AD is prompted by a report that flights below a certain density altitude create oscillations in the main rotor which can transfer dynamic loads to the structure, the main gearbox (MGB), and the main servo-control inputs, which could result in subsequent loss of control of the helicopter.

**DATES:** This AD is effective April 7, 2014.

**ADDRESSES:** For service information identified in this AD, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review the referenced service

information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (EASA) AD, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations Office, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Gary Roach, Aviation Safety Engineer, Regulations and Policy Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email [gary.b.roach@faa.gov](mailto:gary.b.roach@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Discussion**

On September 6, 2013, at 78 FR 54792, the **Federal Register** published our notice of proposed rulemaking (NPRM), which proposed to amend 14 CFR part 39 by adding an AD that would apply to Eurocopter France (now Airbus Helicopters) Model EC225LP helicopters, except those with certain modifications (MODs) installed. The NPRM proposed to require, within 50 hours time-in-service (TIS), amending the Rotorcraft Flight Manual (RFM) to limit minimum flight altitude to -2,000 feet density altitude. The proposed requirements were intended to prevent oscillations in the main rotor that can transfer dynamic loads to the structure, the MGB, and the main servo-control inputs, which could result in subsequent loss of control of the helicopter.

The NPRM was prompted by AD No. 2008-0007R3, dated May 12, 2010, issued by EASA, which is the Technical Agent for the Member States of the European Union. EASA issued AD No. 2008-0007R3 to correct an unsafe condition for Model EC 225 LP helicopters that are "not equipped of all three modifications MOD 0726582, MOD 0726477, and MOD 0726583, or, if not equipped of MOD 0726592, or, if equipped with all three modifications MOD 0726606, MOD 0726610, MOD 0726611 and missing accomplishment

of MOD 0726632.” EASA advises that the main rotor control linkage has a coupling between the MGB motion and the main servo-control inputs. According to EASA, in certain flight conditions with increased air density, this design generates “spurious” 14 Hertz control inputs in the main rotor, which, in return, transfer dynamic loads to the structure. These return dynamic loads give feedback to the MGB motion, inducing a continuous vibration phenomenon. EASA states that flight tests have demonstrated that below certain density altitudes, the occurrence of the vibration phenomenon is significantly increased or even diverges, which could lead to the loss of control of the helicopter. EASA advises that Eurocopter has continued to develop MODs for correcting the vibrations below certain density altitudes, and therefore, helicopters with certain MODs installed are exempt from the applicability of EASA AD No. 2008-0007R3.

To correct this unsafe condition, EASA issued AD No. 2008-0007R3, which requires revising the RFM to prohibit operation below – 2,000 feet density altitude for helicopters without certain modifications installed.

Since we issued the NPRM, Eurocopter France has changed its name to Airbus Helicopters. This AD reflects that change and updates the contact information to obtain service information.

## Comments

We gave the public the opportunity to participate in developing this AD, but we did not receive any comments on the NPRM (78 FR 54792, September 6, 2013).

## FAA’s Determination

These helicopters have been approved by the aviation authority of France and are approved for operation in the United States. Pursuant to our bilateral agreement with France, EASA, its technical representative, has notified us of the unsafe condition described in the EASA AD. We are issuing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed, except for the name change from Eurocopter France to Airbus Helicopters. This change is consistent with the intent of the proposals in the NPRM (78 FR 54792, September 6, 2013) and will not increase the

economic burden on any operator nor increase the scope of the AD.

## Differences Between This AD and the EASA AD

The EASA AD specifies a compliance time of 30 days, while this AD requires compliance within 50 hours TIS.

## Related Service Information

Eurocopter has issued Emergency Alert Service Bulletin No. 04A001, Revision 3, dated May 6, 2010, which specifies inserting RFM revision “Normal Revision RN11 (10-04) or later, associated with conditional revision RCe (10-04) or later” into the RFM for helicopters equipped with screen air intakes and inserting “Normal Revision RN21 (10-05) or later, associated with conditional revision RCe (10-04) or later” into the RFM for helicopters equipped with multi-purpose air intakes. Both RFM revisions limit the minimum altitude for flight to – 2,000 feet density altitude.

## Costs of Compliance

We estimate that this AD will affect three helicopters of U.S. Registry and that the costs to comply with this AD by revising the RFM are negligible.

## Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on helicopters identified in this rulemaking action.

## Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a “significant regulatory action” under Executive Order 12866; (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);

(3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

#### 2014-04-12 Airbus Helicopters (Type Certificate Previously Held by

**Eurocopter France:** Amendment 39-17771; Docket No. FAA-2013-0770; Directorate Identifier 2011-SW-057-AD.

##### (a) Applicability

This AD applies to Model EC225LP helicopters, certificated in any category, except helicopters with the following modifications (MOD) installed:

- (1) MOD 0726582, MOD 0726477, and MOD 0726583;
- (2) MOD 0726592; or
- (3) MOD 0726632.

##### (b) Unsafe Condition

This AD defines the unsafe condition as oscillations in the main rotor which can transfer dynamic loads to the structure, the main gearbox (MGB), and the main servo-control inputs, which could result in subsequent loss of control of the helicopter.

##### (c) Effective Date

This AD becomes effective April 7, 2014.

##### (d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

**(e) Required Action**

Within 50 hours time-in-service, revise the Operating Limitations section of the Eurocopter EC225LP Rotorcraft Flight Manual (RFM) by inserting a copy of this AD into Section 2.3 of the RFM, or by making pen and ink changes as follows. Under paragraph 1, Altitude Limits, add the phrase:

The minimum altitude is limited to –2,000 feet density altitude.

**(f) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Gary Roach, Aviation Safety Engineer, Regulations and Policy Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137; telephone (817) 222-5110; email [gary.b.roach@faa.gov](mailto:gary.b.roach@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

**(g) Additional Information**

(1) Eurocopter Emergency Alert Service Bulletin No. 04A001, Revision 3, dated May 4, 2010, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas 76137.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2008-0007R3, dated May 12, 2010. You may view the EASA AD in the AD docket on the Internet at <http://www.regulations.gov>.

**(h) Subject**

Joint Aircraft Service Component (JASC) Code: 2200: Auto Flight System.

Issued in Fort Worth, Texas, on February 19, 2014.

**Lance T. Gant,**

*Acting Directorate Manager, Rotorcraft Directorate, Aircraft Certification Service.*

[FR Doc. 2014-04314 Filed 2-28-14; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 97**

**[Docket No. 30941; Amdt. No. 3575]**

**Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This rule establishes, amends, suspends, or revokes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective March 3, 2014. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the **Federal Register** as of March 3, 2014.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

*For Examination—*

1. FAA Rules Docket, FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591;

2. The FAA Regional Office of the region in which the affected airport is located;

3. The National Flight Procedures Office, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: [http://www.archives.gov/federal\\_register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal_register/code_of_federal_regulations/ibr_locations.html).

**Availability**—All SIAPs and Takeoff Minimums and ODPs are available

online free of charge. Visit <http://www.nfdc.faa.gov> to register.

Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from:

1. FAA Public Inquiry Center (APA-200), FAA Headquarters Building, 800 Independence Avenue SW., Washington, DC 20591; or

2. The FAA Regional Office of the region in which the affected airport is located.

**FOR FURTHER INFORMATION CONTACT:**

Richard A. Dunham III, Flight Procedure Standards Branch (AFS-420), Flight Technologies and Programs Divisions, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125) Telephone: (405) 954-4164.

**SUPPLEMENTARY INFORMATION:** This rule amends Title 14 of the Code of Federal Regulations, Part 97 (14 CFR part 97), by establishing, amending, suspending, or revoking SIAPs, Takeoff Minimums and/or ODPs. The complete regulators description of each SIAP and its associated Takeoff Minimums or ODP for an identified airport is listed on FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR part 97.20. The applicable FAA Forms are FAA Forms 8260-3, 8260-4, 8260-5, 8260-15A, and 8260-15B when required by an entry on 8260-15A.

The large number of SIAPs, Takeoff Minimums and ODPs, in addition to their complex nature and the need for a special format make publication in the **Federal Register** expensive and impractical. Furthermore, airmen do not use the regulatory text of the SIAPs, Takeoff Minimums or ODPs, but instead refer to their depiction on charts printed by publishers of aeronautical materials. The advantages of incorporation by reference are realized and publication of the complete description of each SIAP, Takeoff Minimums and ODP listed on FAA forms is unnecessary. This amendment provides the affected CFR sections and specifies the types of SIAPs and the effective dates of the associated Takeoff Minimums and ODPs. This amendment also identifies the airport and its location, the procedure, and the amendment number.

**The Rule**

This amendment to 14 CFR part 97 is effective upon publication of each separate SIAP, Takeoff Minimums and ODP as contained in the transmittal. Some SIAP and Takeoff Minimums and