

TABLE 1 TO PARAGRAPH (h) OF THIS AD—LOW-PRESSURE OXYGEN HOSES (P/N)—Continued

Boeing specification No.	Hydroflow	B/E Aerospace	RE Darling (aka REDAR)
10-60174-35 .....	37001-35 37001-36	173470-35 ....., 173470-36 ZH833-35 ZH833-36	40830-505-018

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for The Boeing Company Model 707 airplanes, Model 720 and 720B series airplanes, Model 727 airplanes, and Model 737-100, -200, and -200C series airplanes, covered by this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j)(1) or (j)(2) of this AD, as applicable. Information may be emailed to: [ANM-LAACO-AMOC-REQUESTS@faa.gov](mailto:ANM-LAACO-AMOC-REQUESTS@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(j) Related Information**

For more information about this AD, contact the applicable person identified in paragraph (j)(1) or (j)(2) of this AD.

(1) For Model 707 airplanes, Model 720 and 720B series airplanes, and Model 727 airplanes, contact Patrick Farina, Aerospace Engineer, Cabin Safety, Mechanical and Environmental Systems Branch, ANM-150L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5344; fax: 562-627-5210; email: [Patrick.Farina@faa.gov](mailto:Patrick.Farina@faa.gov).

(2) For Model 737-100, -200, and -200C series airplanes, contact Tracy Ton, Aerospace Engineer, Cabin Safety, Mechanical and Environmental Systems Branch, ANM-150L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5352; fax: 562-627-5210; email: [Tracy.Ton@faa.gov](mailto:Tracy.Ton@faa.gov).

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing 707 Alert Service Bulletin A3538, dated October 2, 2013.

(ii) Boeing Alert Service Bulletin 727-35A0031, dated July 18, 2013.

(iii) Boeing Alert Service Bulletin 737-35A1140, dated August 28, 2013.

(3) For service information identified in this AD, contact Boeing Commercial

Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 30, 2014.

**Jeffrey E. Duven,**

*Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2014-18860 Filed 8-18-14; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2014-0120; Directorate Identifier 2013-NM-056-AD; Amendment 39-17932; AD 2014-16-08]**

**RIN 2120-AA64**

**Airworthiness Directives; Bombardier, Inc. Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc. Model CL-215-6B11 (CL-215T Variant), and CL-215-6B11 (CL-415 Variant) airplanes. This AD was prompted by several reports indicating that shorter nacelle strut bushings were inadvertently installed on certain airplanes. This AD requires a general visual inspection of the left and right nacelle upper strut bushings; installation of the bolts and preload indicating (PLI) washers, if necessary; and replacement of the bushing or repair of the bushing installation, if

necessary. We are issuing this AD to detect and correct inadequate nacelle strut bushings, which provide insufficient engagement in the strut fork end, and could deform under the bearing load and lead to the failure of the joint.

**DATES:** This AD becomes effective September 23, 2014.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of September 23, 2014.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov/#/docketDetail;D=FAA-2014-0120>; or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

**FOR FURTHER INFORMATION CONTACT:** Ricardo Garcia, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone 516-228-7331; fax 516-794-5531.

**SUPPLEMENTARY INFORMATION:**

**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc. Model CL-215-6B11 (CL-215T Variant), and CL-215-6B11 (CL-415 Variant) airplanes. The NPRM published in the **Federal Register** on February 27, 2014 (79 FR 11022).

Transport Canada Civil Aviation, which is the aviation authority for

Canada, has issued Canadian Airworthiness Directive CF-2013-06, dated February 27, 2013 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition certain Bombardier, Inc. Model CL-215-6B11 (CL-215T Variant), and CL-215-6B11 (CL-415 Variant) airplanes. The MCAI states:

It was discovered in several cases that nacelle strut bushings with part number (P/N), 85410265-105, have been inadvertently installed in lieu of P/N 85410265-103. Bushing P/N 85410265-105 is shorter than bushing P/N 85410265-103 and provides for less engagement in the strut fork end, P/N 215T16534-12/-13, which may deform under the bearing load leading to the failure of the joint.

The actions for this AD include a general visual inspection of the left and right nacelle upper strut bushings; installation of the bolts and PLI washers, if necessary; and replacement of the bushing or repair of the bushing installation, if necessary. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2014-0120-0002>.

#### Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (79 FR 11022, February 27, 2014) or on the determination of the cost to the public.

#### “Contacting the Manufacturer” Paragraph in This AD

Since late 2006, we have included a standard paragraph titled “Airworthy Product” in all MCAI ADs in which the FAA develops an AD based on a foreign authority’s AD.

The MCAI or referenced service information in an FAA AD often directs the owner/operator to contact the manufacturer for corrective actions, such as a repair. Briefly, the Airworthy Product paragraph allowed owners/operators to use corrective actions provided by the manufacturer if those actions were FAA-approved. In addition, the paragraph stated that any actions approved by the State of Design Authority (or its delegated agent) are considered to be FAA-approved.

In the NPRM (79 FR 11022, February 27, 2014), we proposed to prevent the use of repairs that were not specifically developed to correct the unsafe condition, by requiring that the repair approval provided by the State of Design Authority or its delegated agent specifically refer to this FAA AD. This change was intended to clarify the

method of compliance and to provide operators with better visibility of repairs that are specifically developed and approved to correct the unsafe condition. In addition, we proposed to change the phrase “its delegated agent” to include a design approval holder (DAH) with State of Design Authority design organization approval (DOA), as applicable, to refer to a DAH authorized to approve required repairs for the proposed AD.

No comments were provided to the NPRM (79 FR 11022, February 27, 2014) about these proposed changes. However, a comment was provided for another NPRM having Directorate Identifier 2012-NM-101-AD (78 FR 78285, December 26, 2013). The commenter stated the following: “The proposed wording, being specific to repairs, eliminates the interpretation that Airbus messages are acceptable for approving minor deviations (corrective actions) needed during accomplishment of an AD mandated Airbus service bulletin.”

This comment has made the FAA aware that some operators have misunderstood or misinterpreted the Airworthy Product paragraph to allow the owner/operator to use messages provided by the manufacturer as approval of deviations during the accomplishment of an AD-mandated action. The Airworthy Product paragraph does not approve messages or other information provided by the manufacturer for deviations to the requirements of the AD-mandated actions. The Airworthy Product paragraph only addresses the requirement to contact the manufacturer for corrective actions for the identified unsafe condition and does not cover deviations from other AD requirements. However, deviations to AD-required actions are addressed in 14 CFR 39.17, and anyone may request the approval for an alternative method of compliance to the AD-required actions using the procedures found in 14 CFR 39.19.

To address this misunderstanding and misinterpretation of the Airworthy Product paragraph, we have changed the paragraph and retitled it “Contacting the Manufacturer.” This paragraph now clarifies that for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the FAA, TCCA, or Bombardier’s TCCA Design Approval Organization (DAO).

The Contacting the Manufacturer paragraph also clarifies that, if approved by the DAO, the approval must include the DAO-authorized signature. The DAO signature indicates that the data and information contained in the document

are TCCA-approved, which is also FAA-approved. Messages and other information provided by the manufacturer that do not contain the DAO-authorized signature approval are not TCCA-approved, unless TCCA directly approves the manufacturer’s message or other information.

This clarification does not remove flexibility previously afforded by the Airworthy Product paragraph. Consistent with long-standing FAA policy, such flexibility was never intended for required actions. This is also consistent with the recommendation of the Airworthiness Directive Implementation Aviation Rulemaking Committee to increase flexibility in complying with ADs by identifying those actions in manufacturers’ service instructions that are “Required for Compliance” with ADs. We continue to work with manufacturers to implement this recommendation. But once we determine that an action is required, any deviation from the requirement must be approved as an alternative method of compliance.

Other commenters to the NPRM having Directorate Identifier 2012-NM-101-AD (78 FR 78285, December 26, 2013) pointed out that in many cases the foreign manufacturer’s service bulletin and the foreign authority’s MCAI might have been issued some time before the FAA AD. Therefore, the DOA might have provided U.S. operators with an approved repair, developed with full awareness of the unsafe condition, before the FAA AD is issued. Under these circumstances, to comply with the FAA AD, the operator would be required to go back to the manufacturer’s DOA and obtain a new approval document, adding time and expense to the compliance process with no safety benefit.

Based on these comments, we removed the requirement that the DAH-provided repair specifically refer to this AD. Before adopting such a requirement, the FAA will coordinate with affected DAHs and verify they are prepared to implement means to ensure that their repair approvals consider the unsafe condition addressed in this AD. Any such requirements will be adopted through the normal AD rulemaking process, including notice-and-comment procedures, when appropriate.

We also have decided not to include a generic reference to either the “delegated agent” or “DAH with State of Design Authority design organization approval,” but instead we have provided the specific delegation approval granted by the State of Design

Authority for the DAH in the Contacting the Manufacturer paragraph of this AD.

### Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (79 FR 11022, February 27, 2014) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (79 FR 11022, February 27, 2014).

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

### Costs of Compliance

We estimate that this AD affects 5 airplanes of U.S. registry.

We also estimate that it will take about 4 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Required parts will cost about \$0 per product. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$1,700, or \$340 per product.

In addition, we estimate that any necessary follow-on actions will take about 4 work-hours and require parts costing \$0, for a cost of \$340 per product. We have no way of determining the number of aircraft that might need these actions.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov/#/docketDetail;D=FAA-2014-0120>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the ADDRESSES section.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2014-16-08 Bombardier, Inc.:** Amendment 39-17932. Docket No. FAA-2014-0120; Directorate Identifier 2013-NM-056-AD.

#### (a) Effective Date

This AD becomes effective September 23, 2014.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to the Bombardier, Inc. airplanes, certificated in any category, identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Model CL-215-6B11 (CL-215T Variant) airplanes, serial numbers 1056, 1057, 1061, 1080, 1109, 1113, 1114, 1115, 1116, 1117, 1118, 1119, 1120, 1121, 1122, and 1125.

(2) Model CL-215-6B11 (CL-415 Variant) airplanes, serial numbers 2001 through 2067 inclusive.

#### (d) Subject

Air Transport Association (ATA) of America Code 54, Nacelles/Pylons.

#### (e) Reason

This AD was prompted by several reports indicating that shorter nacelle strut bushings were inadvertently installed on certain airplanes. We are issuing this AD to detect and correct inadequate nacelle strut bushings, which provide insufficient engagement in the strut fork end, and could deform under the bearing load and lead to the failure of the joint.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Inspection of the Bushing

Within 3 months after the effective date of this AD: Do a general visual inspection to determine the part number of the left and right nacelle upper strut bushings, in accordance with the Accomplishment Instructions of Bombardier Alert Service Bulletin 215-A3173, dated April 11, 2012 (for Model CL-215-6B11 (CL-215T Variant) airplanes); or Bombardier Alert Service Bulletin 215-A4453, dated April 10, 2012 (for Model CL-215-6B11 (CL-415 Variant) airplanes).

(1) If any bushing with part number (P/N) 85410265-103 is installed: Before further flight, install the bolts and preload indicating (PLI) washers, in accordance with paragraph 2.G. of the Accomplishment Instructions of Bombardier Alert Service Bulletin 215-A3173, dated April 11, 2012 (for Model CL-215-6B11 (CL-215T Variant) airplanes); or Bombardier Alert Service Bulletin 215-A4453, dated April 10, 2012 (for Model CL-215-6B11 (CL-415 Variant) airplanes).

(2) If any bushing with P/N 85410265-105 is installed in either the left or right nacelle: Do the actions in paragraph (h) of this AD.

#### (h) Replacement or Repair of the Bushing

If any bushing with P/N 85410265-105 is found installed during the inspection required by paragraph (g) of this AD: Before further flight, do the actions specified in paragraph (h)(1) or (h)(2) of this AD.

(1) Replace the bushing in accordance with paragraph 2.E. of the Accomplishment Instructions of Bombardier Alert Service Bulletin 215-A3173, dated April 11, 2012 (for Model CL-215-6B11 (CL-215T Variant) airplanes); or Bombardier Alert Service Bulletin 215-A4453, dated April 10, 2012

(for Model CL-215-6B11 (CL-415 Variant) airplanes); and continue with the installation of the bolt and PLI washer, in accordance with paragraph 2.G. of the Accomplishment Instructions of Bombardier Alert Service Bulletin 215-A3173, dated April 11, 2012 (for Model CL-215-6B11 (CL-215T Variant) airplanes); or Bombardier Alert Service Bulletin 215-A4453, dated April 10, 2012 (for Model CL-215-6B11 (CL-415 Variant) airplanes).

(2) Repair the bushing in accordance with paragraph 2.F. of the Accomplishment Instructions of Bombardier Alert Service Bulletin 215-A3173, dated April 11, 2012 (for Model CL-215-6B11 (CL-215T Variant) airplanes); or Bombardier Alert Service Bulletin 215-A4453, dated April 10, 2012 (for Model CL-215-6B11 (CL-415 Variant) airplanes); and continue with the installation of the bolt and PLI washer, in accordance with paragraph 2.G. of the Accomplishment Instructions of Bombardier Alert Service Bulletin 215-A3173, dated April 11, 2012 (for Model CL-215-6B11 (CL-215T Variant) airplanes); or Bombardier Alert Service Bulletin 215-A4453, dated April 10, 2012 (for Model CL-215-6B11 (CL-415 Variant) airplanes).

#### (i) Replacement of Repaired Bushing

For any bushing that has been repaired as specified in paragraph (h)(2) of this AD: Within 5,000 flight hours after accomplishing the repair or at the next engine removal, whichever occurs first, replace the bushing with P/N 85410265-103, in accordance with paragraph 2.E. of the Accomplishment Instructions of Bombardier Alert Service Bulletin 215-A3173, dated April 11, 2012 (for Model CL-215-6B11 (CL-215T Variant) airplanes); or Bombardier Alert Service Bulletin 215-A4453, dated April 10, 2012 (for Model CL-215-6B11 (CL-415 Variant) airplanes); and continue with the installation of the bolt and PLI washer, in accordance with paragraph 2.G. of the Accomplishment Instructions of Bombardier Alert Service Bulletin 215-A3173, dated April 11, 2012 (for Model CL-215-6B11 (CL-215T Variant) airplanes); or Bombardier Alert Service Bulletin 215-A4453, dated April 10, 2012 (for Model CL-215-6B11 (CL-415 Variant) airplanes).

#### (j) Airplanes for Which No Further Action Is Required

(1) For airplanes on which a general visual inspection specified in paragraph (g) of this AD is done and it is determined that nacelle strut bushings having P/N 85410265-103 are installed in the airplane: No further actions are required by this AD, provided the actions specified in paragraph (g)(1) of this AD have been done.

(2) For airplanes on which nacelle strut bushings having P/N 85410265-103 are installed as specified in paragraph (h)(1) or (i) of this AD: No further actions are required by this AD.

#### (k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA,

has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, Engine and Propeller Directorate, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (l) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2013-06, dated February 27, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#/documentDetail;D=FAA-2014-0120-0002>.

#### (m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Alert Service Bulletin 215-A3173, dated April 11, 2012.

(ii) Bombardier Alert Service Bulletin 215-A4453, dated April 10, 2012.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email [thd.crj@aero.bombardier.com](mailto:thd.crj@aero.bombardier.com); Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on July 30, 2014.

**Jeffrey E. Duven,**

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-18863 Filed 8-18-14; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2012-1158; Directorate Identifier 2011-NM-232-AD; Amendment 39-17501; AD 2013-13-13]**

**RIN 2120-AA64**

#### **Airworthiness Directives; Airbus Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all Airbus Model A310 series airplanes; and Model A300 B4-600, B4-600R, and F4-600R series airplanes, and Model A300 C4-605R Variant F airplanes (collectively called A300-600 series airplanes). This AD was prompted by the revision of certain airworthiness limitation items (ALI) documents, which require more restrictive maintenance requirements and airworthiness limitations. This AD requires revising the maintenance or inspection program to incorporate the limitations section. We are issuing this AD to prevent fatigue cracking, damage, or corrosion in principal structural elements, which could result in reduced structural integrity of the airplane.

**DATES:** This AD becomes effective September 23, 2014.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of September 23, 2014.

**ADDRESSES:** You may examine the AD docket on the Internet at <http://www.regulations.gov/#/documentDetail;D=FAA-2012-1158> or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36