

st02140ny); and to airplanes, certificated in any category, modified by FAA STC ST02033NY, issued December 2, 2004 (http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/99FF781E0BD20AD886256FA300558250?OpenDocument&Highlight=02033).

(d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

(e) Reason

This AD was prompted by a report that certain lanyards for the passenger oxygen masks are longer than the specified length, possibly leading to inactive oxygen masks in an emergency. We are issuing this AD to detect and correct lanyards of incorrect length, which might not activate the flow of oxygen in an emergency, resulting in injury to passengers.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within 750 flight hours or 15 months after the effective date of this AD, whichever occurs first: Replace lanyards having part numbers (P/N) B431564-503 and -505 for all passenger oxygen dispensing units, with lanyards having P/N B431564-507, in accordance with the Accomplishment Instructions of Bombardier Service Bulletin 700-1A11-35-009, Revision 02, dated May 28, 2013.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE-170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE-170, Engine and Propeller Directorate, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2012-31R1, dated September 17, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!documentDetail;D=FAA-2013-0548-0004>.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 700-1A11-35-009, Revision 02, dated May 28, 2013.

(ii) Reserved.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; Internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 13, 2014.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-25101 Filed 10-27-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0140; Directorate Identifier 2013-NM-176-AD; Amendment 39-18004; AD 2014-21-10]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Airbus Model A330-200 and -300 series

airplanes, and Model A340-200 and -300 series airplanes. This AD was prompted by a report of contact between certain electrical harnesses and the hatrack rod that could cause chafing between the harnesses and surrounding structure. This AD requires modifying the routing of certain electrical harnesses. We are issuing this AD to prevent chafing and possible short circuit of two oxygen chemical generator containers in different wiring routes, which could result in malfunction of the electrical opening of all the containers connected to these routes. Such conditions, during a sudden depressurization event, could result in lack of oxygen and consequent injuries to airplane occupants.

DATES: This AD becomes effective December 2, 2014.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of December 2, 2014.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2014-0140>; or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this AD, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus Model A330-200 and -300 series airplanes, and Model A340-200 and -300 series airplanes. The NPRM published in the **Federal Register** on March 12, 2014 (79 FR 13929). The NPRM was prompted by

a report of contact between certain electrical harnesses and the hatrack rod that could cause chafing between the harnesses and surrounding structure. The NPRM proposed to require modifying the routing of certain electrical harnesses. We are issuing this AD to prevent chafing and possible short circuit of two oxygen chemical generator containers in different wiring routes, which could result in malfunction of the electrical opening of all the containers connected to these routes. Such conditions, during a sudden depressurization event, could result in lack of oxygen and consequent injuries to airplane occupants.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA Airworthiness Directive 2013–0196, dated August 28, 2013 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

On the production line, electrical harnesses 1523VB and 1524VB have been found in contact with hatrack rod at Frame (FR) 53.7 between stringers (STR) 14 and 15. It was concluded that there is a risk of chafing between these harnesses and the surrounding structure, which could lead to a short circuit on two oxygen chemical generator containers in different wiring routes. Consequently, the electrical opening of all the containers connected to these routes would not be possible, resulting in a malfunction of up to two thirds of the affected containers.

This condition, if not corrected, could lead, in case of a sudden depressurization event, to lack of oxygen supply, possibly resulting in injuries to aeroplane occupants.

To address this potential unsafe condition, Airbus developed two modifications of the routing of the affected harnesses.

For the reasons described above, this [EASA] AD requires modification of the routing of harnesses 1523VB and 1524VB.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2014-0140-0002>.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (79 FR 13929, March 12, 2014) or on the determination of the cost to the public.

“Contacting the Manufacturer” Paragraph in This AD

Since late 2006, we have included a standard paragraph titled “Airworthy Product” in all MCAI ADs in which the FAA develops an AD based on a foreign authority’s AD.

The MCAI or referenced service information in an FAA AD often directs the owner/operator to contact the manufacturer for corrective actions, such as a repair. Briefly, the Airworthy Product paragraph allowed owners/operators to use corrective actions provided by the manufacturer if those actions were FAA-approved. In addition, the paragraph stated that any actions approved by the State of Design Authority (or its delegated agent) are considered to be FAA-approved.

In the NPRM (79 FR 11016, February 27, 2014), we proposed to prevent the use of repairs that were not specifically developed to correct the unsafe condition, by requiring that the repair approval provided by the State of Design Authority or its delegated agent specifically refer to this FAA AD. This change was intended to clarify the method of compliance and to provide operators with better visibility of repairs that are specifically developed and approved to correct the unsafe condition. In addition, for certain new requirements, we proposed to change the phrase “its delegated agent” to include a design approval holder (DAH) with State of Design Authority design organization approval (DOA), as applicable, to refer to a DAH authorized to approve required repairs for the proposed AD.

No comments were provided to the NPRM (79 FR 11016, February 27, 2014) about these proposed changes. However, a comment was provided for an NPRM having Directorate Identifier 2012–NM–101–AD (78 FR 78285, December 26, 2013). The commenter stated the following: “The proposed wording, being specific to repairs, eliminates the interpretation that Airbus messages are acceptable for approving minor deviations (corrective actions) needed during accomplishment of an AD mandated Airbus service bulletin.”

This comment has made the FAA aware that some operators have misunderstood or misinterpreted the Airworthy Product paragraph to allow the owner/operator to use messages provided by the manufacturer as approval of deviations during the accomplishment of an AD-mandated action. The Airworthy Product paragraph does not approve messages or other information provided by the manufacturer for deviations to the requirements of the AD-mandated actions. The Airworthy Product paragraph only addresses the requirement to contact the manufacturer for corrective actions for the identified unsafe condition and does not cover deviations from other AD requirements. However, deviations to AD-required

actions are addressed in 14 CFR 39.17, and anyone may request the approval for an alternative method of compliance to the AD-required actions using the procedures found in 14 CFR 39.19.

To address this misunderstanding and misinterpretation of the Airworthy Product paragraph, we have changed the paragraph and retitled it “Contacting the Manufacturer.” This paragraph now clarifies that for any requirement in this AD to obtain corrective actions from a manufacturer, the actions must be accomplished using a method approved by the FAA, the European Aviation Safety Agency (EASA), or Airbus’s EASA Design Organization Approval (DOA).

The Contacting the Manufacturer paragraph also clarifies that, if approved by the DOA, the approval must include the DOA-authorized signature. The DOA signature indicates that the data and information contained in the document are EASA-approved, which is also FAA-approved. Messages and other information provided by the manufacturer that do not contain the DOA-authorized signature approval are not EASA-approved, unless EASA directly approves the manufacturer’s message or other information.

This clarification does not remove flexibility previously afforded by the Airworthy Product paragraph. Consistent with long-standing FAA policy, such flexibility was never intended for required actions. This is also consistent with the recommendation of the Airworthiness Directive Implementation Aviation Rulemaking Committee to increase flexibility in complying with ADs by identifying those actions in manufacturers’ service instructions that are “Required for Compliance” with ADs. We continue to work with manufacturers to implement this recommendation. But once we determine that an action is required, any deviation from the requirement must be approved as an alternative method of compliance.

Other commenters to the NPRM having Directorate Identifier 2012–NM–101–AD (78 FR 78285, December 26, 2013) pointed out that in many cases the foreign manufacturer’s service bulletin and the foreign authority’s MCAI might have been issued some time before the FAA AD. Therefore, the DOA might have provided U.S. operators with an approved repair, developed with full awareness of the unsafe condition, before the FAA AD is issued. Under these circumstances, to comply with the FAA AD, the operator would be required to go back to the manufacturer’s DOA and obtain a new

approval document, adding time and expense to the compliance process with no safety benefit.

Based on these comments, we removed the requirement that the DAH-provided repair specifically refer to this AD. Before adopting such a requirement, the FAA will coordinate with affected DAHs and verify they are prepared to implement means to ensure that their repair approvals consider the unsafe condition addressed in this AD. Any such requirements will be adopted through the normal AD rulemaking process, including notice-and-comment procedures, when appropriate.

We also have decided not to include a generic reference to either the “delegated agent” or “DAH with State of Design Authority design organization approval,” but instead we have provided the specific delegation approval granted by EASA for the DAH.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (79 FR

13929, March 12, 2014) for correcting the unsafe condition; and

- Do not add any additional burden upon the public than was already proposed in the NPRM (79 FR 13929, March 12, 2014).

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

Costs of Compliance

We estimate that this AD affects 51 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modification	6 work-hours × \$85 per hour = \$510	Up to \$1,057	Up to \$1,567	Up to \$79,917.

According to the manufacturer, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and

responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov/#/docketDetail;D=FAA-2014-0140>; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the ADDRESSES section.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014-21-10 Airbus: Amendment 39-18004. Docket No. FAA-2014-0140; Directorate Identifier 2013-NM-176-AD.

(a) Effective Date

This AD becomes effective December 2, 2014.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category.

(1) Model A330-201, -202, -203, -223, -243, -301, -302, -303, -321, -322, -323, -341, -342, and -343 airplanes, all manufacturer serial numbers, on which Airbus Modification 48825 has been embodied in production; except for airplanes on which Airbus Modification 52485, 40161, or 201669 has been embodied.

(2) Model A340-211, -212, -213, -311, -312, and -313 airplanes, all manufacturer serial numbers, on which Airbus Modification 48825D42865 has been embodied in production; except for airplanes on which Airbus Modification 55606 or 40161 has been embodied.

(d) Subject

Air Transport Association (ATA) of America Code 92, Wiring Elements.

(e) Reason

This AD was prompted by a report of contact between certain electrical harnesses and the hatrack rod that could cause chafing between the harnesses and surrounding structure. We are issuing this AD to prevent chafing and possible short circuit of two oxygen chemical generator containers in different wiring routes, which could result in malfunction of the electrical opening of all the containers connected to these routes. Such conditions, during a sudden depressurization event, could result in lack of oxygen and consequent injuries to airplane occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

Within 24 months after the effective date of this AD: Modify the routing of electrical harnesses 1523VB on the left-hand side and 1524VB on the right-hand side, at the level of the door 3 area between frames 53.6 and 53.8, and between stringers 14 and 15, in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330-92-3098 or A340-92-4084, both dated January 11, 2013, as applicable.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Vladimir Ulyanov, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1138; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(i) Related Information

Refer to Mandatory Continuing Airworthiness Information (MCAI) 2013-

0196, dated August 28, 2013, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov/#!docketDetail;D=FAA-2014-0140-0002>.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A330-92-3098, dated January 11, 2013.

(ii) Airbus Service Bulletin A340-92-4084, dated January 11, 2013.

(3) For service information identified in this AD, contact Airbus SAS—Airworthiness Office—EAL, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; Internet <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on October 15, 2014.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-25413 Filed 10-27-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF COMMERCE**National Oceanic and Atmospheric Administration****15 CFR Part 902****50 CFR Parts 300, 600, and 665**

[Docket No. 130708597-4380-01]

RIN 0648-BD46

Western Pacific Pelagic Fisheries; U.S. Territorial Catch and Fishing Effort Limits

AGENCY: National Marine Fisheries Service (NMFS), National Oceanic and Atmospheric Administration (NOAA), Commerce.

ACTION: Final rule; final specifications; effectiveness of collection-of-information requirements.

SUMMARY: This final rule implements a management framework for specifying catch and effort limits and accountability measures for pelagic fisheries in the U.S. Pacific territories of American Samoa, Guam, and the Commonwealth of the Northern Mariana Islands (CNMI). Using the established framework, NMFS is also specifying a catch limit of 2,000 metric tons (mt) of longline-caught bigeye tuna for each territory for 2014. A territory may allocate up to 1,000 mt of that limit to eligible U.S. longline fishing vessels. This final rule also makes several technical administrative changes to the regulations and announces the effectiveness of collection-of-information requirements. This action is consistent with international objectives of ending overfishing of bigeye tuna, while allowing for the limited transfer of available catch limits between U.S. participating territories and eligible U.S. fisheries, consistent with the conservation requirements of the bigeye tuna stock.

DATES: This final rule and final specifications are effective October 24, 2014.

The deadline to submit a specified fishing agreement for review pursuant to § 665.819(b)(3) is November 28, 2014.

ADDRESSES: You may review the background and details of this action in Amendment 7 to the Fishery Ecosystem Plan for Pelagic Fisheries of the Western Pacific. You may obtain a copy of Amendment 7 and supporting documents, identified by NOAA-NMFS-2012-0178, from the Federal e-Rulemaking Portal, www.regulations.gov/#!docketDetail;D=NOAA-NMFS-2012-0178, or from the Western Pacific Fishery Management Council (Council), 1164 Bishop St., Suite 1400, Honolulu, HI 96813, tel 808-522-8220, fax 808-522-8226, www.wpcouncil.org.

You may submit written comments regarding the burden-hour estimates or other aspects of the collection-of-information requirements contained in this final rule to Michael D. Tosatto, Regional Administrator, NMFS Pacific Islands Region (PIR), 1845 Wasp Blvd. Bldg. 176, Honolulu, HI 96818, and by email to OIRA_Submission@omb.eop.gov or fax to 202-395-7285.

FOR FURTHER INFORMATION CONTACT: Jarad Makaiau, NMFS PIR Sustainable Fisheries Division, 808-725-5176.

SUPPLEMENTARY INFORMATION: NMFS and the Council manage the pelagic fisheries of American Samoa, Guam, the CNMI, and Hawaii under the Fishery Ecosystem Plan for Pelagic Fisheries of the Western Pacific (FEP). The Council