

lower lobe skin detailed inspection for cracks and do all applicable related investigative and corrective actions. Do all applicable related investigative and corrective actions before further flight.

(ii) Do all applicable repetitive inspections of the fuselage skin thereafter at the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 747-53A2861, dated April 1, 2014.

(i) Exceptions to Service Information Specifications

(1) Where Boeing Alert Service Bulletin 747-53A2861, dated April 1, 2014, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Although Boeing Alert Service Bulletin 747-53A2861, dated April 1, 2014, specifies to contact Boeing for repair data, and specifies that action as "RC" (Required for Compliance), this AD requires repair before further flight using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) Except as required by paragraph (i) of this AD: If the service information contains steps that are labeled as RC (Required for Compliance), those steps must be done to comply with this AD; any steps that are not labeled as RC are recommended. Those steps that are not labeled as RC may be deviated from, done as part of other actions, or done using accepted methods different from those identified in the specified service information without obtaining approval of an AMOC, provided the steps labeled as RC can be done and the airplane can be put back in a serviceable condition. Any substitutions or changes to steps labeled as RC require approval of an AMOC.

(4) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

(1) For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Branch, ANM-120S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6432; fax: 425-917-6590; email: bill.ashforth@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on November 19, 2014.

Suzanne Masterson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-28124 Filed 11-26-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2014-0777; Directorate Identifier 2014-NM-088-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 787-8 airplanes. This proposed AD was prompted by numerous reports of failures of the proximity sensor within the slat skew detection mechanism assembly (DMA) leading to slats up landing events. This proposed AD would require replacing the slat skew DMAs with new slat skew DMAs, and marking the existing identification plates on the slat with the new part number. We are proposing this AD to prevent failure of the proximity sensor, which could result in the slats being shut down and a slats up high speed landing. This condition, in combination with abnormal landing conditions such as a short runway or adverse weather conditions, could result in a runway excursion.

DATES: We must receive comments on this proposed AD by January 12, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2014-0777; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Douglas Tsuji, Senior Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-917-6546; fax: 425-917-6590; email: douglas.tsuji@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2014-0777; Directorate Identifier 2014-NM-088-AD" at the beginning of your comments. We specifically invite

comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received numerous reports of failures of the proximity sensor within the slat skew detection mechanism assembly (DMA) leading to slats up landing events. It was determined that the failed sensors had broken magnet

wires due to stresses induced by thermal expansion and contraction of an epoxy applied around them. This condition, if not corrected, could result in failure of the proximity sensor, which could result in the slats being shut down and a slats up high speed landing. This condition in combination with abnormal landing conditions such as a short runway or adverse weather conditions, could result in a runway excursion.

Relevant Service Information

We reviewed Boeing Alert Service Bulletin B787-81205-SB270021-00, Issue 001, dated March 20, 2014. For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for

and locating Docket No. FAA-2014-0777.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously.

Costs of Compliance

We estimate that this proposed AD affects 15 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Replacement	11 work-hours × \$85 per hour = \$935	\$0	\$935	\$14,025

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This proposed regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2014-0777; Directorate Identifier 2014-NM-088-AD.

(a) Comments Due Date

We must receive comments by January 12, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 787-8 airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin B787-81205-SB270021-00, Issue 001, dated March 20, 2014.

(d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

(e) Unsafe Condition

This AD was prompted by numerous reports of failures of the proximity sensor within the slat skew detection mechanism assembly (DMA) leading to slats up landing events. We are issuing this AD to prevent failure of the proximity sensor, which could result in the slats being shut down and a slats up high speed landing. This condition, in combination with abnormal landing conditions such as a short runway or adverse weather conditions, could result in a runway excursion.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Replacement

Within 24 months after the effective date of this AD: Replace the slat skew DMA in slat number 5 and slat number 8 with new slat skew DMA, and mark the existing identification plates on the slat with the new

part number, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB270021-00, Issue 001, dated March 20, 2014.

(h) Parts Installation Prohibitions

(1) As of the effective date of this AD, no person may install a slat skew DMA, part number P683A0001-03, on any airplane.

(2) As of the effective date of this AD, no person may install, on any airplane, a slat skew DMA in slat number 5, having part number 145Z0201-11-8, 145Z0201-21-4, 145Z0201-21-3, 145Z0201-21-5, 145Z0201-21-8, 145Z0201-21-9, 145Z0201-31-1, or 145Z0201-33-1.

(3) As of the effective date of this AD, no person may install, on any airplane, a slat skew DMA in slat number 8, having part number 145Z0201-12-8, 145Z0201-22-4, 145Z0201-22-3, 145Z0201-22-5, 145Z0201-22-8, 145Z0201-22-9, 145Z0201-32-1, or 145Z0201-34-1.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(j) Related Information

(1) For more information about this AD, contact Douglas Tsuji, Senior Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-917-6546; fax: 425-917-6590; email: douglas.tsuji@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on November 13, 2014.

Jeffrey E. Duven,

Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-28130 Filed 11-26-14; 8:45 am]

BILLING CODE 4910-13-P

FEDERAL TRADE COMMISSION

16 CFR Part 455

Used Motor Vehicle Trade Regulation Rule

AGENCY: Federal Trade Commission (“FTC” or “Commission”).

ACTION: Supplemental notice of proposed rulemaking (“SNPRM”); request for comment.

SUMMARY: The FTC is proposing further amendments to the Used Motor Vehicle Trade Regulation Rule (“Rule” or “Used Car Rule”) that would require dealers to indicate on the Buyers Guide whether they obtained a vehicle history report, and, if so, to provide a copy of the report to consumers who request it; revise the Buyers Guide statement describing the meaning of an “As Is” sale in which a dealer offers a vehicle for sale without a warranty; and move boxes to the front of the Buyers Guide for dealers to indicate whether non-dealer warranties apply to a vehicle. Based on the FTC’s review of the public comments, the Commission proposes these amendments to promote consumer access to vehicle history information, to clarify the meaning of “As Is” in the sale of used vehicles without warranties, and to make disclosures concerning non-dealer warranties more prominent. The FTC is not adopting any final amendments to the Used Car Rule at this time. It continues to consider comments submitted in response to its Notice of Proposed Rulemaking (“NPRM”) published in December 2012 and seeks additional comments in this SNPRM.

DATES: Comments must be received on or before January 30, 2015.

ADDRESSES: Interested parties may file a comment at <https://ftcpublish.commentworks.com/ftc/usedcarrulesnprm> online or on paper, by following the instructions in the Request for Comment part of the **SUPPLEMENTARY INFORMATION** section below. Write “Used Car Rule Regulatory Review, 16 CFR part 455, Project No. P087604,” on your comment, and file your comment online at <https://ftcpublish.commentworks.com/ftc/usedcarrulesnprm> by following the instructions on the web-based form. If you prefer to file your comment on paper, write “Used Car Rule Regulatory Review, 16 CFR part 455, Project No. P087604,” on your comment, and on the envelope, and mail your comment to the following address: Federal Trade Commission, Office of the Secretary, 600 Pennsylvania Avenue NW., Suite CC-5610 (Annex A), Washington, DC

20580, or deliver your comment to the following address: Federal Trade Commission, Office of the Secretary, Constitution Center, 400 7th Street SW., 5th Floor, Suite 5610 (Annex A), Washington, DC 20024. This document, and public records related to the FTC’s regulatory review, are also available at that address and at www.ftc.gov.

FOR FURTHER INFORMATION CONTACT: John C. Hallerud, (312) 960-5634, Attorney, Midwest Region, Federal Trade Commission, 55 West Monroe Street, Suite 1825, Chicago, IL 60603.

SUPPLEMENTARY INFORMATION:

I. Background

In December 2012, the FTC issued an NPRM setting forth proposed changes to the FTC’s Used Car Rule.¹ The Used Car Rule requires dealers to display on used cars offered for sale a window sticker called a “Buyers Guide” containing warranty and other information. Among other things, in the NPRM, the Commission proposed adding a statement to the Buyers Guide advising consumers about the availability of vehicle history reports and directing consumers to an FTC Web site for more information about those reports. The Commission also proposed changing the statement on the Buyers Guide that describes the meaning of “As Is” when a dealer offers to sell a used vehicle without a warranty. In response to the NPRM, the Commission received nearly 150 comments from members of the public including automobile dealers, consumer attorneys, consumer advocacy organizations, automobile dealer associations, providers of vehicle history reports, legal aid agencies, consumer protection agencies, and state attorneys general.² After reviewing the comments, the Commission now proposes additional modifications to the proposal made in the NPRM to address concerns raised by commenters. The Commission also seeks comments on alternative proposals and issues that commenters have submitted or identified.

The Commission now proposes to amend the Used Car Rule to require that dealers who have obtained a vehicle history report on an individual vehicle indicate on the Buyers Guide that they have obtained such a report, and will provide a copy of the report to

¹ 77 FR 74746 (Dec. 17, 2012).

² The comments are available at: <http://www.ftc.gov/os/comments/usedcarrulesnprm/index.shtml>. The comments are numbered, and the Commission has assigned each a number that follows the name of the commenter. Comments cited in this notice are identified by the name of the commenter (organization or individual) followed by the comment number (e.g., Brown (1)).