

along with the \$5,000 contribution from the surplus program, should be adequate to cover expenses for the 2014–15 crop year.

This rule continues in effect the action that decreased the assessment obligation imposed on handlers. Assessments are applied uniformly on all handlers, and some of the costs may be passed on to producers. However, decreasing the assessment rate reduces the burden on handlers, and may reduce the burden on producers.

In addition, the committee's meeting was widely publicized throughout the California date industry, and all interested persons were invited to attend the meetings and encouraged to participate in committee deliberations on all issues. Like all committee meetings, the June 25, 2014, meeting was a public meeting and all entities, both large and small, were able to express views on this issue.

In accordance with the Paperwork Reduction Act of 1995, (44 U.S.C. Chapter 35), the order's information collection requirements have been previously approved by the Office of Management and Budget (OMB) and assigned OMB No. 0581–0178, "Vegetable and Specialty Crops." No changes in those requirements as a result of this action are necessary. Should any changes become necessary, they would be submitted to OMB for approval.

This action imposes no additional reporting or recordkeeping requirements on either small or large Riverside County, California, date handlers. As with all Federal marketing order programs, reports and forms are periodically reviewed to reduce information requirements and duplication by industry and public sector agencies.

USDA has not identified any relevant Federal rules that duplicate, overlap, or conflict with this rule.

Comments on the interim rule were required to be received on or before October 27, 2014. No comments were received. Therefore, for reasons given in the interim rule, we are adopting the interim rule as a final rule, without change.

To view the interim rule, go to: <http://www.regulations.gov/#!documentDetail;D=AMS-FV-14-0057-0001>.

This action also affirms information contained in the interim rule concerning Executive Orders 12866, 12988, 13175, and 13563; the Paperwork Reduction Act (44 U.S.C. Chapter 35); and the E-Gov Act (44 U.S.C. 101).

After consideration of all relevant material presented, it is found that

finalizing the interim rule, without change, as published in the **Federal Register** (79 FR 51067, August 27, 2014) will tend to effectuate the declared policy of the Act.

List of Subjects in 7 CFR Part 987

Dates, Marketing agreements, Reporting and recordkeeping requirements.

PART 987—DATES PRODUCED OR PACKED IN RIVERSIDE COUNTY, CALIFORNIA

■ Accordingly, the interim rule amending 7 CFR part 987, which was published at 79 FR 51067 on August 27, 2014, is adopted as a final rule, without change.

Dated: December 4, 2014.

Rex A. Barnes,

Associate Administrator, Agricultural Marketing Service.

[FR Doc. 2014–28834 Filed 12–8–14; 8:45 am]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2014–0450; Directorate Identifier 2013–NM–250–AD; Amendment 39–18037; AD 2014–24–04]

RIN 2120–AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all The Boeing Company Model MD–90–30 airplanes. This AD was prompted by reports of cracks emanating from the aft-most barrel nut holes of the left and right upper rear spar caps of the horizontal stabilizer. This AD requires repetitive high frequency eddy current (ETHF) inspections for cracks in the areas around the two aft-most barrel nut holes of any repaired or replaced upper rear spar cap, and corrective actions if necessary. We are issuing this AD to detect and correct such cracks, which could propagate until the upper rear spar cap severs, and result in failure of the horizontal stabilizer upper center or aft skin panel

and adversely affect the structural integrity of the airplane.

DATES: This AD is effective January 13, 2015.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 13, 2015.

ADDRESSES: For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800–0019, Long Beach, CA 90846–0001; telephone 206–544–5000, extension 2; fax 206–766–5683; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425 227–1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2014–0450; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800–647–5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: George Garrido, Aerospace Engineer, Airframe Branch, ANM–120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5357; fax: 562–627–5210; email: george.garrido@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all The Boeing Company Model MD–90–30 airplanes. The NPRM published in the **Federal Register** on July 18, 2014 (79 FR 41943). The NPRM was prompted by reports of cracks emanating from the aft-most barrel nut holes of the left and right upper rear spar caps of the horizontal stabilizer. The NPRM proposed to require repetitive high frequency eddy current (ETHF) inspections for cracks in the

areas around the two aft-most barrel nut holes of the upper rear spar caps, and corrective action if necessary; and repetitive EHF inspections for cracks in the areas around the two aft-most barrel nut holes of any repaired or replaced upper rear spar cap, and corrective actions if necessary. We are issuing this AD to detect and correct such cracks, which could propagate until the upper rear spar cap severs, and result in failure of the horizontal stabilizer upper center or aft skin panel and adversely affect the structural integrity of the airplane.

Comments

We gave the public the opportunity to participate in developing this AD. We have considered the comment received. Boeing supported the NPRM (79 FR 41943, July 18, 2014).

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM (79 FR 41943, July 18, 2014) for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM (79 FR 41943, July 18, 2014).

Costs of Compliance

We estimate that this AD affects 52 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	9 work-hours × \$85 per hour = \$765 per inspection cycle	\$1,410	\$2,175 per inspection cycle.	Up to \$113,100 per inspection cycle.

We estimate the following costs to do any necessary repairs and replacements that would be required based on the

results of the inspection. We have no way of determining the number of

aircraft that might need these repairs and replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Repair (per side)	368 work-hours × \$85 per hour = \$31,280	Up to \$90,129	Up to \$121,409.
Replacement	368 work-hours × \$85 per hour = \$31,280	\$81,764	\$113,044.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2014–24–04 The Boeing Company:
Amendment 39–18037; Docket No. FAA–2014–0450; Directorate Identifier 2013–NM–250–AD.

(a) Effective Date

This AD is effective January 13, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model MD–90–30 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code Stabilizers, 55.

(e) Unsafe Condition

This AD was prompted by reports of cracks emanating from the aft-most barrel nut holes of the left and right upper rear spar caps of

the horizontal stabilizer. We are issuing this AD to detect and correct such cracks, which could propagate until the upper rear spar cap severs, and result in failure of the horizontal stabilizer upper center or aft skin panel and adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

At the applicable compliance time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013, except as provided by paragraph (j) of this AD: Do a high frequency eddy current inspection (ETHF) for cracks in the areas around the two aft-most barrel nut holes of the upper rear spar cap; and do all applicable corrective actions; in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013. Thereafter, repeat the ETHF inspection at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013. Do all corrective actions before further flight.

(h) Post-Repair/Replacement Actions

For airplanes on which a splice repair or replacement was done as specified in Boeing Alert Service Bulletin MD90-55A017: At the applicable compliance time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013, do an ETHF inspection for cracks at the two aft-most barrel nut holes of any repaired or replaced upper rear spar cap, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013. Thereafter, repeat the ETHF inspection at the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013. If any cracking is found, before further flight, do the repair or replacement, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013.

(i) Post-Repair Inspections

The post-repair inspections of the upper rear spar cap of the aft flange that has been splice-repaired specified in Table 1 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013, are not required by this AD.

Note 1 to paragraph (i) of this AD: The damage tolerance inspections (post-repair inspections of the upper rear spar cap aft flange) specified in Table 1 of paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013, may be used in support of compliance with Section 121.1109(c)(2) or 129.109(b)(2) of the Federal Aviation Regulations (14 CFR 121.1109(c)(2) or 14 CFR 129.109(b)(2)). The corresponding actions specified in the Accomplishment Instructions of Boeing Alert

Service Bulletin MD90-55A017, dated September 27, 2013, are not required by this AD.

(j) Exception to the Service Information

Where Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-REQUESTS@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and 14 CFR 25.571, Amendment 45, and the approval must specifically refer to this AD.

(l) Related Information

For more information about this AD, contact George Garrido, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5357; fax: 562-627-5210; email: george.garrido@faa.gov.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin MD90-55A017, dated September 27, 2013.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at FAA, Transport Airplane Directorate, 1601

Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425 227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on November 19, 2014.

Suzanne Masterson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2014-28145 Filed 12-8-14; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Parts 117 and 121

[Docket No. FAA-2009-1093]

RIN 2120-AJ58

Flightcrew Member Duty and Rest Requirements

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notification of availability.

SUMMARY: The FAA is issuing a Final Supplemental Regulatory Impact Analysis (Final SRIA) of its final rule that amended its existing flight, duty and rest regulations applicable to certain certificate holders and their flightcrew members. A copy of the Final SRIA may be found in the docket for the rulemaking. The Final SRIA responds to comments that were made in response to the Initial Supplemental Regulatory Impact Analysis, and, where appropriate, incorporates new information provided by the commenters. In addition, the Final SRIA makes adjustments to the methodology used to estimate the costs and benefits of applying the final flight, duty, and rest rule to cargo-only operations, and includes additional sensitivity analyses. The results of the Final SRIA concludes that the base-case benefits of applying the flight, duty, and rest rule to cargo-only operations would be about \$3 million, and the high-case benefits of doing so would be about \$10 million. Conversely, the costs of applying the flight, duty, and rest rule to cargo-only operations would be about \$452 million. Because the results of the analysis continue to indicate that the costs of mandating all-cargo operation compliance with the new flight, duty, and rest rule significantly outweigh the