

(b) Affected ADs

This AD replaces AD 2012–24–10, Amendment 39–17280 (77 FR 73908, December 12, 2012).

(c) Applicability

This AD applies to The Boeing Company Model 747–400 and –400F series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 747–21A2523, Revision 2, dated June 7, 2013.

(d) Subject

Air Transport Association (ATA) of America Code 21, Air Conditioning; 31, Instruments.

(e) Unsafe Condition

This AD was prompted by reports of intermittent or blank displays of a certain integrated display unit (IDU) in the flight deck. We are issuing this AD to prevent IDU malfunctions, which could affect the ability of the flightcrew to read primary displays for airplane attitude, altitude, or airspeed, and consequently reduce the ability of the flightcrew to maintain control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Retained Software Update

This paragraph restates the requirements of paragraph (g) of AD 2012–24–10, Amendment 39–17280 (77 FR 73908, December 12, 2012), with revised service information. Within 12 months after January 16, 2013 (the effective date of AD 2012–24–10), except as provided by paragraph (j) of this AD: Install integrated display system software, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747–21A2523, Revision 1, dated October 3, 2011; or Boeing Alert Service Bulletin 747–21A2523, Revision 2, dated June 7, 2013. As of the effective date of this AD, only Boeing Alert Service Bulletin 747–21A2523, Revision 2, dated June 7, 2013, may be used to accomplish the actions required by this paragraph.

Note 1 to paragraph (g) and (j) of this AD: Boeing Alert Service Bulletin 747–21A2523, Revision 1, dated October 3, 2011; and Boeing Alert Service Bulletin 747–21A2523, Revision 2, dated June 7, 2013; refer to Boeing Service Bulletin 747–31–2426, dated July 29, 2010 (for airplanes with Rolls-Royce engines); Boeing Service Bulletin 747–31–2427, dated July 29, 2010 (for airplanes with General Electric engines); and Boeing Service Bulletin 747–31–2428, dated July 29, 2010 (for airplanes with Pratt & Whitney engines); as additional sources of guidance for the software installation specified by paragraph (g) of this AD. Boeing Service Bulletin 747–31–2426, dated July 29, 2010; Boeing Service Bulletin 747–31–2427, dated July 29, 2010; and Boeing Service Bulletin 747–31–2428, dated July 29, 2010; are not incorporated by reference in this AD.

(h) Retained Duct Assembly Replacement and Wiring Changes

This paragraph restates the requirements of paragraph (h) of AD 2012–24–10,

Amendment 39–17280 (77 FR 73908, December 12, 2012), with revised service information. Within 60 months after January 16, 2013 (the effective date of AD 2012–24–10), except as provided by paragraph (j) of this AD: Replace the duct assembly with a new duct assembly, do wiring changes, and route certain wire bundles, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747–21A2523, Revision 1, dated October 3, 2011; or Boeing Alert Service Bulletin 747–21A2523, Revision 2, dated June 7, 2013. As of the effective date of this AD, only Boeing Alert Service Bulletin 747–21A2523, Revision 2, dated June 7, 2013, may be used to accomplish the actions required by this paragraph.

(i) New Installation of Pressure Switch Bracket and Altitude Pressure Switch

Within 60 months after the effective date of this AD: Install a new or serviceable pressure switch bracket and a new or serviceable altitude pressure switch on the forward side of the station 400 bulkhead, do wiring changes, route certain wire bundles, install a new hose assembly, and perform a leak check and a functional logic test, in accordance with the Accomplishment Instructions of the service information specified in paragraph (i)(1) or (i)(2) of this AD, as applicable.

(1) For Model 747–400F series airplanes: Boeing Alert Service Bulletin 747–21–2532, dated February 13, 2014.

(2) For Model 747–400BCF series airplanes: Boeing Alert Service Bulletin 747–21–2533, dated February 13, 2014.

(j) Actions for Group 21 Airplanes

For Group 21 airplanes, as identified in Boeing Alert Service Bulletin 747–21A2523, Revision 2, dated June 7, 2013, do the actions specified in paragraphs (j)(1) and (j)(2) of this AD, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 747–21A2523, Revision 2, dated June 7, 2013.

(1) Within 12 months after the effective date of this AD, install integrated display system software.

(2) Within 60 months after the effective date of this AD, replace the duct assembly with a new duct assembly, do wiring changes, and route certain wire bundles.

(k) Credit for Previous Actions

This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 747–21A2523, Revision 1, dated October 3, 2011.

(l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in

paragraph (m)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2012–24–10, Amendment 39–17280 (77 FR 73908, December 12, 2012), are approved as AMOCs for the corresponding provisions of paragraphs (g) and (h) of this AD.

(m) Related Information

(1) For more information about this AD, contact Ana Martinez Hueto, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM–150S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6592; fax: 425–917–6591; email: ana.m.hueto@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, Washington. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on February 2, 2015.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015–02925 Filed 2–17–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2015–0243; Directorate Identifier 2014–NM–114–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all

Airbus Model A300 series airplanes; Model A300 B4-600, B4-600R, and F4-600R series airplanes, and A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model A310 series airplanes. This proposed AD was prompted by reports of cracked aluminum support struts of the trimmable horizontal stabilizer (THS) caused by stress corrosion. This proposed AD would require inspections to identify the part number of each support strut, repetitive inspections for cracking of the THS support strut ends, installation of reinforcing clamps on strut ends, and replacement of support struts, if necessary. We are proposing this AD to detect and correct cracked THS support struts, which could lead to the rupture of all four support struts making the remaining structure unable to carry limit loads, which could result in loss of the THS and reduced control of the airplane.

DATES: We must receive comments on this proposed AD by April 6, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0243; or in person at the Docket

Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-2125; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2015-0243; Directorate Identifier 2014-NM-114-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2014-0164, dated July 11, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A300 series airplanes; Model A300 B4-600, B4-600R, and F4-600R series airplanes, and A300 C4-605R Variant F airplanes (collectively called Model A300-600 series airplanes); and Model A310 series airplanes. The MCAI states:

During scheduled maintenance, several Trimmable Horizontal Stabilizer (THS) support struts were found cracked at the strut ends. The THS is supported and articulated at frame (FR) 91 in the tail cone. Lateral movement is prevented by four diagonal support struts.

Investigations revealed that the cracks were caused by stress corrosion and propagated from the inside to the outside of the strut.

This condition, if not detected and corrected, could lead to the rupture of all four THS support struts at FR91, which would make the remaining structure unable to carry limit loads, potentially resulting in loss of the Horizontal Tail Plane.

To address this unsafe condition, EASA issued [EASA] AD 2014-0121 [<http://ad.easa.europa.eu/ad/2014-0121>] to require repetitive High Frequency Eddy Current (HFEC) inspections of the THS support strut ends, installation of reinforcing clamps on strut ends and, depending on findings, replacement of damaged support struts. Installation of reinforcing clamps on strut ends is considered a temporary solution pending introduction of a re-designed support strut.

Since that [EASA] AD was issued, it was discovered that the [EASA] AD appeared to also require HFEC inspections of steel struts, which are not prone to cracking. The unsafe condition exists only on support struts made of aluminum, which were introduced through Airbus modification (mod) 06101, but may also have been installed in service as replacement parts on aeroplanes in pre-mod 06101 configuration.

For the reason described above, this [EASA] AD retains the requirements of EASA AD 2014-0121, which is superseded, and clarifies the need for an initial identification of the support struts installed on aeroplanes in pre-mod 06101 configuration. The related Airbus Service Bulletins (SB) remain unchanged.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0243.

Relevant Service Information Under 1 CFR Part 51

Airbus has issued the following service information. The actions described in this service information are intended to correct the unsafe condition identified in the MCAI.

- Airbus Service Bulletin A300-53-0394, dated February 14, 2014. This service information describes procedures for reinforcing the support struts of the THS at frame 91 in the fuselage tail section of Airbus Model A300 series airplanes.
- Airbus Service Bulletin A300-53-0395, dated February 14, 2014. This service information describes procedures for inspecting for cracking of the support struts of the THS at frame 91 in the fuselage tail section of Airbus Model A300 series airplanes.
- Airbus Service Bulletin A300-53-6172, dated February 14, 2014. This service information describes procedures for reinforcing the support struts of the THS at frame 91 in the fuselage tail section of Airbus Model A300-600 series airplanes.

- Airbus Service Bulletin A300–53–6174, dated February 14, 2014. This service information describes procedures for inspecting for cracking of the support struts of the THS at frame 91 in the fuselage tail section of Airbus Model A300–600 series airplanes.

- Airbus Service Bulletin A310–53–2136, dated February 14, 2014. This service information describes procedures for reinforcing the support struts of the THS at frame 91 in the fuselage tail section of Airbus Model A310 series airplanes.

- Airbus Service Bulletin A310–53–2137, dated February 14, 2014. This service information describes procedures for inspecting for cracking of the support struts of the THS at frame 91 in the fuselage tail section of Airbus Model A310 series airplanes. This service information is reasonably available; see **ADDRESSES** for ways to access this service information.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

Differences Between This Proposed AD and the MCAI or Service Information

Unlike the procedures described in Airbus Service Bulletin A300–53–0395; Airbus Service Bulletin A300–53–6174; and Airbus Service Bulletin A310–53–2137; each dated February 14, 2014; this proposed AD would not permit further flight if cracks are detected in the aluminum support strut ends of the trimmable horizontal stabilizer at frame 91. We have determined that, because of the safety implications and consequences associated with that cracking, any cracked aluminum support strut ends of the trimmable horizontal stabilizer must be repaired or modified before further flight. This difference has been coordinated with EASA and Airbus.

Costs of Compliance

We estimate that this proposed AD affects 174 airplanes of U.S. registry.

We also estimate that it would take about 5 work-hours per product to comply with the basic requirements of

this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$2,100 per product. Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$439,350, or \$2,525 per product.

In addition, we estimate that any necessary follow-on actions would take about 15 work-hours and require parts costing \$10,000, for a cost of \$11,275 per product. We have no way of determining the number of aircraft that might need these actions.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this proposed AD is 2120–0056. The paperwork cost associated with this proposed AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this proposed AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES–200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus: Docket No. FAA–2015–0243; Directorate Identifier 2014–NM–114–AD.

(a) Comments Due Date

We must receive comments by April 6, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Airbus airplanes specified in paragraphs (c)(1) through (c)(6) of this AD, certificated in any category, all manufacturer serial numbers.

- (1) Airbus Model A300 B2–1A, B2–1C, B2K–3C, B2–203, B4–2C, B4–103, and B4–203 airplanes.
- (2) Airbus Model A300 B4–601, B4–603, B4–620, and B4–622 airplanes.
- (3) Airbus Model A300 B4–605R and B4–622R airplanes.
- (4) Airbus Model A300 F4–605R and F4–622R airplanes.

(5) Airbus Model A300 C4–605R Variant F airplanes.

(6) Airbus Model A310–203, –204, –221, –222, –304, –322, –324, and –325 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of cracked aluminum support struts of the trimmable horizontal stabilizer (THS) caused by stress corrosion. We are issuing this AD to detect and correct cracked THS support struts, which could lead to the rupture of all four support struts making the remaining structure unable to carry limit loads, which could result in loss of the THS and reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection for Part Number

For airplanes in pre-modification 06101 configuration: Within 12 months after the effective date of this AD, do an inspection to identify the part number (P/N) of each support strut installed on the trimmable horizontal stabilizer (THS) at frame (FR) 91, in accordance with the Accomplishment Instructions of the applicable service bulletin identified in paragraphs (g)(1) through (g)(3) of this AD. A review of airplane maintenance records is acceptable in lieu of this inspection, provided those records can be relied upon for that purpose and the part number can be positively identified from that review. If no aluminum strut(s) having P/N R21449, R21449D, R21449G, or R21449H is found during any inspection required by this paragraph no further action is required by this AD for that horizontal stabilizer, except for paragraph (l) of this AD.

(1) For Airbus Model A300 series airplanes: Airbus Service Bulletin A300–53–0395, dated February 14, 2014.

(2) For Airbus Model A300 B4–600, B4–600R, and F4–600R series airplanes, and A300 C4–605R Variant F airplanes (collectively called Model A300–600 series airplanes): Airbus Service Bulletin A300–53–6174, dated February 14, 2014.

(3) For Airbus Model A310 series airplanes: Airbus Service Bulletin A310–53–2137, dated February 14, 2014.

(h) Repetitive High Frequency Eddy Current (HFEC) Inspections

For airplanes in post-modification 06101 configuration; and for airplanes in pre-modification 06101 configuration on which one or more aluminum support strut(s) having P/N R21449, P/N R21449D, P/N R21449G, or P/N R21449H was found during the inspection by paragraph (g) of this AD: Within the applicable compliance times specified in paragraphs (h)(1), (h)(2), or (h)(3) of this AD, do an HFEC inspection for cracking of the aluminum THS support strut ends at FR 91, in accordance with the Accomplishment Instructions of the applicable service bulletin identified in paragraphs (g)(1) through (g)(3) of this AD.

Reinforcing clamps already installed on strut ends must be removed before accomplishing the HFEC inspection and re-installed after the inspection, in accordance with the Accomplishment Instructions of the applicable service bulletin specified in paragraphs (g)(1) through (g)(3) of this AD. Repeat the inspection thereafter at intervals not to exceed 24 months.

(1) For airplanes having manufacturer serial number (MSN) 0499 through MSN 0747 inclusive (post-mod 06101): Within 12 months after the effective date of this AD.

(2) For airplanes having MSN 0748 through MSN 0878 inclusive (post-mod 06101): Within 18 months after the effective date of this AD.

(3) For airplanes having MSN 0001 through MSN 0498 inclusive (pre-mod 06101) having one or more aluminum struts: Within 24 months after the effective date of this AD.

(i) Installation of Reinforcing Clamps

Concurrently with the initial HFEC inspection required by paragraph (h) of this AD, identify struts having P/N R21449, P/N R21449D, P/N R21449G, or P/N R21449H with no reinforcing clamps previously installed, and before next flight, install reinforcing clamps on each strut end, in accordance with the Accomplishment Instructions of the applicable service bulletin specified in paragraphs (i)(1) through (i)(3) of this AD.

(1) For Airbus Model A300 series airplanes: Airbus Service Bulletin A300–53–0394, dated February 14, 2014.

(2) For Airbus Model A300 B4–600, B4–600R, and F4–600R series airplanes, and A300 C4–605R Variant F airplanes (collectively called Model A300–600 series airplanes): Airbus Service Bulletin A300–53–6172, dated February 14, 2014.

(3) For Airbus Model A310 series airplanes: Airbus Service Bulletin A310–53–2136, dated February 14, 2014.

(j) Corrective Actions

If, during any inspection required by paragraph (h) of this AD, any cracking is found, before further flight, replace the affected THS support strut(s) with serviceable struts and install clamps on each strut end, in accordance with the Accomplishment Instructions of the applicable service bulletin identified in paragraphs (g)(1) through (g)(3) of this AD.

(k) Clarification

Installation of reinforcing clamps as required by paragraph (i) of this AD, and the replacement of support struts and/or the installation of clamps as required by paragraph (j) of this AD, do not constitute terminating action for the repetitive inspections required by paragraph (h) of this AD.

(l) Reporting

At the applicable time specified in paragraphs (l)(1) and (l)(2) of this AD: After accomplishment of any inspection required by paragraphs (g) and (h) of this AD, report all inspection results to Airbus, including no findings, in accordance with the Accomplishment Instructions of the applicable service bulletins specified in

paragraphs (g)(1) through (g)(3) of this AD, and paragraphs (i)(1) through (i)(3) of this AD.

(1) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(2) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(m) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Dan Rodina, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–2125; fax 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(n) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) European

Aviation Safety Agency Airworthiness Directive 2014–0164, dated July 11, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–0243.

(2) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on February 2, 2015.

Dionne Palermo,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015–02922 Filed 2–17–15; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2015–0086; Directorate Identifier 2014–NM–191–AD]

RIN 2120–AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Model A310–203 airplanes. This proposed AD is intended to complete certain mandated programs intended to support the airplane reaching its limit of validity (LOV) of the engineering data that support the established structural maintenance program. This proposed AD was prompted by reports that side link clevis bolts of the front engine mount do not meet the Design Service Goal (DSG) requirements on airplanes equipped with General Electric Company CF6–80A3 engines. This proposed AD would require repetitive replacement of all side link clevis engine mount bolts. We are proposing this AD to prevent failure of the front engine mount, and consequent possible departure of the engine.

DATES: We must receive comments on this proposed AD by April 6, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR

11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- Fax: 202–493–2251.
- Mail: U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- Hand Delivery: U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Airbus SAS, Airworthiness Office—EAW, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email account.airworth-eas@airbus.com; Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–0086; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Dan Rodina, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, Washington 98057–3356; telephone 425–227–2125; fax 425–227–1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2015–0086; Directorate Identifier 2014–NM–191–AD” at the beginning of your comments. We specifically invite

comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

As described in FAA Advisory Circular 120 104 (http://www.faa.gov/documentLibrary/media/Advisory_Circular/120-104.pdf), several programs have been developed to support initiatives that will ensure the continued airworthiness of aging airplane structure. The last element of those initiatives is the requirement to establish a LOV of the engineering data that support the structural maintenance program under 14 CFR 26.21. This proposed AD is the result of an assessment of the previously established programs by Airbus during the process of establishing the LOV for Airbus Model A310–203 airplanes. The actions specified in this proposed AD are necessary to complete certain programs to ensure the continued airworthiness of aging airplane structure and to support an airplane reaching its LOV.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2014–0191, dated August 29, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A310–203 airplanes. The MCAI states:

During fatigue analysis performed in the scope of the Extended Service Goal, taking into account the certification loads and the new lift-off loads, Airbus determined that side link clevis engine mount bolts do not meet the Design Service Goal (DSG) requirements on aeroplanes equipped with CF6–80A3 engines.

This condition, if not corrected, could lead to failure of the front engine mount, possibly resulting in-flight separation of the engine from the aeroplane.

To address this potential unsafe condition, Airbus issued Service Bulletin (SB) A310–71–2038 to introduce a life limit on the side link clevis engine mount bolts.

For the reason described above, this [EASA] AD requires implementation of the new life limit and replacement of all side link clevis engine mount bolts that have exceeded the new limit.