

(2) The report has been prepared in accordance with all applicable statutory or regulatory requirements, and

(3) The information is true, accurate, and complete to the best of signatories' knowledge and belief.

(c) *Distribution.* The Corporation must distribute the signed report of condition to all its shareholders within 90 days of its fiscal year-end. The Corporation must provide us one paper and one electronic copy of every signed report within 5 days of signing. If the report is the same as that filed with the SEC, the Corporation may instead provide the signed reports to us only in electronic form and simultaneous with filing the report with the SEC.

(1) The Corporation must publish a copy of each report of condition on its Web site within 3 business days of filing the report with us. The report must remain on the Web site until the next report is posted. When the reports are the same as those filed with the SEC, electronic links to the SEC filings Web site, EDGAR, may be used in satisfaction of this requirement.

(2) Upon receiving a request for an annual report of condition from a stockholder, investor, or the public, the Corporation must promptly provide the requester the most recent signed annual report issued in compliance with this section.

#### **§ 655.15 Interim reports, notices, and proxy statements.**

(a) The Corporation must provide to us one paper and one electronic copy of every interim report, notice, and proxy statement filed with the SEC within 1 business day of filing the item with the SEC, including all papers and documents that are a part of the report, notice, or statement.

(b) The Corporation must publish a copy of each interim report, notice, and proxy statement on its Web site within 5 business days of filing the document(s) with the SEC. The interim report, notice, or proxy statement must remain on the Web site for 6 months or until the next annual report of condition is posted, whichever is later. Electronic links to the SEC filings Web site, EDGAR, may be used in satisfaction of this requirement.

#### **Subpart C—Reports Relating to Securities Activities of the Federal Agricultural Mortgage Corporation**

##### **§ 655.20 Securities not registered under the Securities Act.**

The Corporation must make special filings with OSMO for securities either issued or guaranteed by the Corporation that are not registered under the

Securities Act. These filings include, but are not limited to:

(a) One paper and one electronic copy of any offering circular, private placement memorandum, or information statement prepared in connection with the securities offering at or before the time of the securities offering.

(b) For securities backed by qualified loans as defined in section 8.0(9)(A) of the Act, one paper and one electronic copy of the following within 1 business day of the finalization of the transaction:

(1) The private placement memoranda for securities sold to investors; and

(2) The pooling and servicing agreement when the security is purchased by the Corporation as authorized by section 8.6(g) of the Act.

(c) For securities backed by qualified loans as defined in section 8.0(9)(B) of the Act, the Corporation must provide summary information on such securities issued during each calendar quarter in the form prescribed by us. Such summary information must be provided with each report of condition and performance filed pursuant to § 621.12, and at such other times as OSMO may require.

##### **§ 655.21 Filings and communications with the U.S. Treasury, the SEC, and NYSE.**

(a) The Corporation must send us one paper and one electronic copy of every filing made with U.S. Treasury, the SEC, or NYSE, including financial statements and related schedules, exhibits, and other documents that are a part of the filing. Such copies must be filed with us no later than 1 business day after any U.S. Treasury, SEC, or NYSE filing. If the filing is one addressed in subpart B of this part, no action under this paragraph is required.

(b) The Corporation must send us, within 3 business days and according to instructions provided by us, copies of all substantive correspondence between the Corporation and the U.S. Treasury, the SEC, or NYSE.

(c) The Corporation must notify us within 1 business day if it becomes exempt or claims exemption from any filing requirements of the Securities Act.

Dated: March 19, 2015.

**Dale L. Aultman,**

*Secretary, Farm Credit Administration Board.*

[FR Doc. 2015-06755 Filed 3-25-15; 8:45 am]

**BILLING CODE 6705-01-P**

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

[Docket No. FAA-2015-0249; Directorate Identifier 2014-NM-174-AD]

RIN 2120-AA64

#### **Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to supersede Airworthiness Directive (AD) 2012-18-05, which applies to The Boeing Company Model DC-9-10, DC-9-20, DC-9-30, DC-9-40, and DC-9-50 series airplanes; and Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), MD-88, and MD-90-30 airplanes; equipped with a center wing fuel tank and Boeing original equipment manufacturer-installed auxiliary fuel tanks. AD 2012-18-05 currently requires adding design features to detect electrical faults and to detect a pump running in an empty fuel tank. Since we issued AD 2012-18-05, we have determined that it is necessary to clarify the actions for airplanes on which the auxiliary fuel tanks are removed. This proposed AD would allow certain actions as optional methods of compliance. We are proposing this AD to reduce the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

**DATES:** We must receive comments on this proposed AD by May 11, 2015.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855

Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0249.

### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0249; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Sérj Harutunian, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5254; fax: 562-627-5210; email: [serj.harutunian@faa.gov](mailto:serj.harutunian@faa.gov).

### SUPPLEMENTARY INFORMATION:

#### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-0249; Directorate Identifier 2014-NM-174-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

### Discussion

On August 6, 2012, we issued AD 2012-18-05, Amendment 39-17181 (77 FR 54793, September 6, 2012), for The Boeing Company Model DC-9-10, DC-9-20, DC-9-30, DC-9-40, and DC-9-50 series airplanes; and Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), MD-88, and MD-90-30 airplanes; equipped with a center wing fuel tank and Boeing original equipment manufacturer-installed auxiliary fuel tanks. AD 2012-18-05 requires adding design features to detect electrical faults and to detect a pump running in an empty fuel tank. AD 2012-18-05 resulted from fuel system reviews conducted by the manufacturer. We issued AD 2012-18-05 to reduce the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

### Actions Since AD 2012-18-05, Amendment 39-17181 (77 FR 54793, September 6, 2012) Was Issued

Since we issued AD 2012-18-05, Amendment 39-17181 (77 FR 54793, September 6, 2012), we have determined that it is necessary to clarify the actions for airplanes on which the auxiliary fuel tanks are removed. In addition, The Boeing Company has issued new service information for Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and Model MD-88 airplanes; and Model MD-90-30 airplanes, which provides a method of compliance for the actions required by AD 2012-18-05. Boeing has not yet issued corresponding service information for Boeing Model DC-9-10, DC-9-20, DC-9-30, DC-9-40, and DC-9-50 series airplanes. The applicability of AD 2012-18-05 has not changed in this proposed AD.

### Related Service Information Under 1 CFR Part 51

We reviewed Boeing Service Bulletin MD80-28-228, dated September 27, 2013; and Boeing Service Bulletin MD90-28-013, dated September 27, 2013. The service information describes procedures for installing GFI relays that change fuel pump system wiring, installing a low fuel pressure indication system, and revising the inspection or maintenance program to include new limitations.

We have also reviewed Appendixes B, C, and D of Boeing Special Compliance Item Report MDC-92K9145, Revision M, dated February 5, 2013, which includes Critical Design Configuration Control

Limitations (CDCCLs), Airworthiness Limitations Instructions (ALIs), and short-term extensions.

Boeing Service Bulletin MD80-28-228, dated September 27, 2013, specifies prior or concurrent accomplishment of the following concurrent service information.

- Boeing MD-80 Service Bulletin 28-53, Revision 1, dated April 16, 1992, which describes procedures for installing a low fuel pressure indication system.
- Boeing MD-80 Service Bulletin 28-63, Revision 2, dated April 8, 1992, which describes procedures for installing a low fuel pressure indication inhibit system.

This service information is reasonably available; see **ADDRESSES** for ways to access this service information.

### Clarification of the Requirements for the Design Features

In paragraph (c) of this proposed AD, we have added the text "for airplanes on which auxiliary fuel tanks are removed, the AD action specified for the auxiliary fuel tanks are not required" to clarify that the actions specified in this AD for the auxiliary fuel tanks are not required when the auxiliary fuel tanks are removed, but the AD actions for the center fuel tanks still apply.

### Revised Compliance Time

We have determined that it is appropriate to allow additional time to accomplish the design features and requirements specified in this proposed AD. Therefore, we have added a compliance time of "within 42 months after the effective date of this AD" to paragraph (g) of this proposed AD. We have determined that this extension of the compliance time will provide an acceptable level of safety.

### FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

### Proposed AD Requirements

This proposed AD would retain all requirements of AD 2012-18-05, Amendment 39-17181 (77 FR 54793, September 6, 2012). This proposed AD would clarify the actions for airplanes on which the auxiliary fuel tanks are removed, that the actions specified for the auxiliary fuel tanks are not required. This proposed AD would also provide certain methods of compliance for the actions restated from AD 2012-18-05 (one option is accomplishing the actions

specified in the service information described previously, including revising the inspection or maintenance program, as applicable, to include new limitations; the other option is installing a supplemental type certificate (STC).

This proposed AD specifies to revise certain operator maintenance documents to include new actions (e.g., inspections) and CDCCLs. Compliance with these actions and CDCCLs is

required by 14 CFR 91.403(c). For airplanes that have been previously modified, altered, or repaired in the areas addressed by this proposed AD, the operator may not be able to accomplish the actions described in the revisions. In this situation, to comply with 14 CFR 91.403(c), the operator must request approval for an alternative method of compliance according to paragraph (l) of this proposed AD. The

request should include a description of changes to the required actions and CDCCLs that will ensure the continued operational safety of the airplane.

**Costs of Compliance**

We estimate that this proposed AD affects 809 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Installing design features for airplanes with center wing and auxiliary tanks (263 airplanes), using a method approved by the FAA [retained actions from AD 2012-18-05, Amendment 39-17181 (77 FR 54793, September 6, 2012)].	50 work-hours × \$85 per hour = \$4,250.	\$35,000	\$39,250	\$10,322,750
Installing design features for airplanes with center wing tank (546 airplanes), using a method approved by the FAA [retained actions from AD 2012-18-05, Amendment 39-17181 (77 FR 54793, September 6, 2012)].	35 work-hours × \$85 per hour = \$2,975.	17,000	19,975	10,906,350

**ESTIMATED COSTS: NEW OPTIONAL ACTIONS FOR INSTALLING DESIGN FEATURES**

Action	Labor cost	Parts cost	Cost per product
For airplanes with center wing and auxiliary tanks, using service information specified in paragraph (h) of this proposed AD (including revising the maintenance/inspection program).	250 work-hours × \$85 per hour = \$21,250.	\$69,000	\$90,250
For airplanes with center wing tank, using service information specified in paragraph (h) of this proposed AD (including revising the maintenance/inspection program).	110 work-hours × \$85 = 9,350 .....	30,000	39,350
Installing STC specified in paragraph (i) of this proposed AD .....	35 work-hours × \$85 per hour = \$2,975.	17,000	19,975

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We have determined that this proposed AD would not have federalism

implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that the proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2012-18-05, Amendment 39-17181 (77 FR 54793, September 6, 2012), and adding the following new AD:

**The Boeing Company:** Docket No. FAA-2015-0249; Directorate Identifier 2014 NM-174-AD.

**(a) Comments Due Date**

The FAA must receive comments on this AD action by May 11, 2015.

**(b) Affected ADs**

This AD replaces AD 2012-18-05, Amendment 39-17181 (77 FR 54793, September 6, 2012).

**(c) Applicability**

This AD applies to The Boeing Company airplanes identified in paragraphs (c)(1) through (c)(8) of this AD, certificated in any category, and equipped with center wing fuel tanks and Boeing original equipment manufacturer-installed auxiliary fuel tanks. For airplanes on which the auxiliary fuel tanks have been removed, the actions specified for the auxiliary fuel tanks are not required.

(1) Model DC-9-11, DC-9-12, DC-9-13, DC-9-14, DC-9-15, and DC-9-15F airplanes.

(2) Model DC-9-21 airplanes.

(3) Model DC-9-31, DC-9-32, DC-9-32 (VC-9C), DC-9-32F, DC-9-33F, DC-9-34, DC-9-34F, and DC-9-32F (C-9A, C 9B) airplanes.

(4) Model DC-9-41 airplanes.

(5) Model DC-9-51 airplanes.

(6) Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), and DC-9-87 (MD-87) airplanes.

(7) Model MD-88 airplanes.

(8) Model MD-90-30 airplanes.

**(d) Subject**

Air Transport Association (ATA) of America Code 28, Fuel.

**(e) Unsafe Condition**

This AD was prompted by fuel system reviews conducted by the manufacturer. We are issuing this AD to reduce the potential of ignition sources inside fuel tanks, which, in combination with flammable fuel vapors, could result in fuel tank explosions and consequent loss of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Retained Criteria for Operation**

This paragraph restates the actions required by paragraph (g) of AD 2012-18-05, Amendment 39-17181 (77 FR 54793, September 6, 2012), with a new compliance time. Except as provided by paragraphs (h) and (i) of this AD: As of 42 months after the effective date of this AD, no person may operate any airplane affected by this AD unless an amended type certificate or supplemental type certificate that incorporates the design features and requirements described in paragraphs (g)(1) and (g)(2) of this AD has been approved by the Manager, Los Angeles Aircraft Certification Office (ACO), FAA, and those design features are installed on the airplane.

(1) Each electrically powered fuel pump installed in the center wing tank or auxiliary fuel tank must have a protective device installed to detect electrical faults that can cause arcing and burn through the fuel pump housing. The same device must shut off the pump by automatically removing electrical power from the pump when such faults are detected. When a fuel pump is shut off as the result of detection of an electrical fault, the

device must stay latched off until the fault is cleared through maintenance action and verified that the pump and the electrical power feed are safe for operation.

(2) Additional design features must be installed to detect when any center wing tank or auxiliary fuel tank pump is running in an empty fuel tank. The prospective pump shutoff system must shut off each pump no later than 60 seconds after the fuel tank is emptied. The pump shutoff system design must preclude undetected running of a fuel pump in an empty tank, after the pump was commanded off manually or automatically.

**(h) New: Optional Methods of Compliance**

For Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and Model MD-88 airplanes; and Model MD-90-30 airplanes: In lieu of doing the requirements of paragraph (g) of this AD, do the applicable actions specified in paragraphs (h)(1), (h)(2), and (h)(3) of this AD.

(1) For Model DC-9-81 (MD-81), DC-9-82 (MD-82), DC-9-83 (MD-83), DC-9-87 (MD-87), and Model MD-88 airplanes: Do the applicable actions specified in paragraphs (h)(1)(i), (h)(1)(ii), and (h)(1)(iii) of this AD.

(i) For all airplanes identified in paragraph (h)(1) of this AD: Within the compliance time specified in paragraph (g) of this AD, install ground fault interrupter (GFI) relays, in accordance with the Accomplishment Instructions of Boeing Service Bulletin MD80-28-228, dated September 27, 2013.

(ii) For airplanes identified in Boeing MD-80 Service Bulletin 28-53, Revision 1, dated April 16, 1992: Prior to or concurrently with accomplishing the action specified in paragraph (h)(1)(i) of this AD, install a low fuel pressure indication system, in accordance with the Accomplishment Instructions of Boeing MD-80 Service Bulletin 28-53, Revision 1, dated April 16, 1992.

(iii) For airplanes identified in Boeing MD-80 Service Bulletin 28-63, Revision 2, dated April 8, 1992: Prior to or concurrently with accomplishing the action specified in paragraph (h)(1)(i) of this AD, install a low fuel pressure indication inhibition system, in accordance with the Accomplishment Instructions of Boeing MD-80 Service Bulletin 28-63, Revision 2, dated April 8, 1992.

(2) For Model MD-90-30 airplanes: Within the compliance time specified in paragraph (g) of this AD, install brackets and mod block rails, and install GFI relays, in accordance with the Accomplishment Instructions of Boeing Service Bulletin MD90-28-013, dated September 27, 2013.

(3) For all airplanes: Within 30 days after accomplishing the actions required by paragraph (h)(1) or (h)(2) of this AD or within 30 days after the effective date of this AD, whichever occurs later, revise the maintenance or inspection program, as applicable, to incorporate the Critical Design Configuration Control Limitations (CDCCLs), Airworthiness Limitations Instructions (ALIs), and short-term extensions specified in Appendices B, C, and D of Boeing Special Compliance Item Report MDC-92K9145, Revision M, dated February 5, 2013. The

initial compliance time for accomplishing the actions specified in the ALIs is at the later of the times in paragraphs (h)(3)(i) and (h)(3)(ii) of this AD. Doing the revision of the maintenance or inspection program, as applicable, required by this paragraph terminates the requirements in paragraphs (g) and (h) of AD 2008-11-15, Amendment 39-15538 (73 FR 30746, May 29, 2008).

(i) At the applicable time specified in in Appendix C of Boeing Special Compliance Item Report MDC-92K9145, Revision M, dated February 5, 2013, except as provided by Appendix D, of Boeing Special Compliance Item Report MDC-92K9145, Revision M, dated February 5, 2013.

(ii) Within 30 days after accomplishing the actions required by paragraph (h)(1) or (h)(2) of this AD, or within 30 days after the effective date of this AD, whichever occurs later.

**(j) New: Optional Universal Fault Interrupter (UFI) Installation**

In lieu of doing the requirements of paragraph (g) of this AD, within the compliance time specified in paragraph (g) of this AD install a TDG Aerospace Inc. UFI using a method approved in accordance with the procedures specified in paragraph (l) of this AD.

**Note 1 to paragraph (i) of this AD:** TDG Aerospace STC ST02502LA ([http://rgl.faa.gov/Regulatory\\_and\\_Guidance\\_Library/rkstc.nsf/0/4d132827a425d7de86257cd3004dfc02/\\$FILE/ST02502LA.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rkstc.nsf/0/4d132827a425d7de86257cd3004dfc02/$FILE/ST02502LA.pdf)) provides additional guidance for installing the TDG UFI.

**(j) No Alternative Actions, Intervals, and CDCCLs**

After the maintenance or inspection program, as applicable, has been revised as required by paragraph (h)(3) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, or CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (l) of this AD.

**(k) Credit for Previous Actions**

This paragraph provides credit for the actions specified in paragraphs (h)(1)(ii) and (h)(1)(iii) of this AD, if those actions were performed before the effective date of this AD using any of the service information specified in paragraph (k)(1), (k)(2), or (k)(3) of this AD.

(1) Boeing MD-80 Service Bulletin 28-53, dated April 8, 1991.

(2) Boeing MD-80 Service Bulletin 28-63, dated June 14, 1991.

(3) Boeing MD-80 Service Bulletin 28-63, Revision 1, dated July 19, 1991.

**(l) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the

attention of the person identified in paragraph (m)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved for AD 2012-18-05, Amendment 39-17181 (77 FR 54793, September 6, 2012), are approved as AMOCs for the corresponding provisions of this AD.

#### (m) Related Information

(1) For more information about this AD, contact Sérj Harutunian, Aerospace Engineer, Propulsion Branch, ANM-140L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5254; fax: 562-627-5210; email: serj.harutunian@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, 3855 Lakewood Boulevard, MC D800-0019, Long Beach, CA 90846-0001; telephone 206-544-5000, extension 2; fax 206-766-5683; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on February 11, 2015.

**Jeffrey E. Duven,**

Manager, Transport Airplane Directorate,  
Aircraft Certification Service.

[FR Doc. 2015-06745 Filed 3-25-15; 8:45 am]

**BILLING CODE 4910-13-P**

---

## DEPARTMENT OF JUSTICE

### 28 CFR Part 16

[CPCLO Order No. 004-2014]

#### Privacy Act of 1974; Implementation

**AGENCY:** Department of Justice.

**ACTION:** Notice of proposed rulemaking.

**SUMMARY:** As described in the notice section of this issue of the **Federal Register**, the Department of Justice (Department or DOJ) has published a notice of a new Department-wide Privacy Act system of records, "Department of Justice, Giglio Information Files," JUSTICE/DOJ-017. This system has been established to

enable DOJ investigative agencies to collect and maintain records of potential impeachment information and to disclose such information to DOJ prosecuting offices in order to ensure that prosecutors receive sufficient information to meet their obligations under *Giglio v. United States*, 405 U.S. 150 (1972), as well as to enable DOJ prosecuting offices to maintain records of potential impeachment information obtained from DOJ investigative agencies, other federal agencies, and state and local agencies and to disclose such information in accordance with the *Giglio* decision. For the reasons provided below, the Department proposes to amend its Privacy Act regulations by establishing an exemption for records in this system from certain provisions of the Privacy Act pursuant to 5 U.S.C. 552a(j) and (k).

**DATES:** Comments must be received by April 27, 2015.

**ADDRESSES:** Address all comments to the Privacy Analyst, Office of Privacy and Civil Liberties, National Place Building, 1331 Pennsylvania Avenue NW., Suite 1000, Washington, DC 20530, or by facsimile to (202) 307-0693. To ensure proper handling, please reference the CPCLO Order Number on your correspondence. You may review an electronic version of the proposed rule at <http://www.regulations.gov>, and you may also comment by using that Web site's comment form for this regulation. Please include the CPCLO Order Number in the subject box.

Please note that the Department is requesting that electronic comments be submitted before midnight Eastern Time on the day the comment period closes because this is when <http://www.regulations.gov> terminates the public's ability to submit comments. Commenters in time zones other than Eastern Time may want to consider this so that their electronic comments are received. All comments sent via regular or express mail will be considered timely if postmarked on or before the day the comment period closes.

**Posting of Public Comments:** Please note that all comments received are considered part of the public record and made available for public inspection online at <http://www.regulations.gov> and in the Department's public docket. Such information includes personally identifying information (such as your name, address, etc.) voluntarily submitted by the commenter.

If you want to submit personally identifying information (such as your name, address, etc.) as part of your comment, but do not want it to be posted online or made available in the

public docket, you must include the phrase "PERSONALLY IDENTIFYING INFORMATION" in the first paragraph of your comment. You must also place all the personally identifying information you do not want posted online or made available in the public docket in the first paragraph of your comment and identify what information you want redacted.

If you want to submit confidential business information as part of your comment, but do not want it to be posted online or made available in the public docket, you must include the phrase "CONFIDENTIAL BUSINESS INFORMATION" in the first paragraph of your comment. You must also prominently identify confidential business information to be redacted within the comment. If a comment has so much confidential business information that it cannot be effectively redacted, all or part of that comment may not be posted online or made available in the public docket.

Personally identifying information and confidential business information identified and located as set forth above will be redacted and the comment, in redacted form, will be posted online and placed in the Department's public docket file. Please note that the Freedom of Information Act applies to all comments received. If you wish to inspect the agency's public docket file in person by appointment, please see the **FOR FURTHER INFORMATION CONTACT** paragraph.

**FOR FURTHER INFORMATION CONTACT:** Tricia Francis, Executive Office for United States Attorneys, FOIA/Privacy Act Staff, 600 E Street NW., Suite 7300, Washington, DC 20530, or by facsimile at (202) 252-6047.

**SUPPLEMENTARY INFORMATION:** In the notices section of this issue of the **Federal Register**, the Department of Justice has published a system of records notice for the system entitled, "Department of Justice Giglio Information Files," JUSTICE/DOJ-017. This Department-wide system notice replaces the notice for the system entitled, "United States Attorney's Office, Giglio Information Files," JUSTICE/USA-018, 65 FR 75308 (Dec. 1, 2000). That system of records was exempt from certain provisions of the Privacy Act pursuant to 5 U.S.C. 552a(j) and (k). Those exemptions are codified in the Code of Federal Regulations (CFR) section for Exemption of United States Attorneys Systems (28 CFR 16.81(g) and (h)). The Department is now proposing to establish a new CFR section for exemptions of the JUSTICE/DOJ-017 system (28 CFR 16.136) and to