

Proposed Rules

Federal Register

Vol. 80, No. 98

Thursday, May 21, 2015

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-0900; Directorate Identifier 2015-NE-12-AD]

RIN 2120-AA64

Airworthiness Directives; Turbomeca S.A. Turboshift Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Turbomeca S.A. Arrius 2F turboshaft engines with a certain part number oil pump installed. This proposed AD was prompted by cases of deterioration of the gas generator front bearing due to a link loss between the pump driver and the oil pump shaft. This proposed AD would require inspection, and if necessary, replacement before further flight of the oil pump driver assembly and/or the oil pump shaft, or the oil pump itself. We are proposing this AD to prevent link loss between the pump driver and the oil pump shaft, which could lead to an engine in-flight shutdown, forced landing, and damage to the helicopter.

DATES: We must receive comments on this proposed AD by July 20, 2015.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Mail:* Docket Management Facility, U.S. Department of Transportation, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.
- *Fax:* 202-493-2251.

For service information identified in this proposed AD, contact Turbomeca S.A., 40220 Tarnos, France; phone: 33 (0)5 59 74 40 00; telex: 570 042; fax: 33 (0)5 59 74 45 15. You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0900; or in person at the Docket Operations office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Philip Haberlen, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7770; fax: 781-238-7199; email: philip.haberlen@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-0900; Directorate Identifier 2015-NE-12-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact with FAA personnel concerning this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2015-0049, dated March 17, 2015 (Corrected May 7, 2015) (referred to hereinafter as "the MCAI"), to correct an unsafe condition for the specified products. The MCAI states:

A risk of an in-flight shutdown (IFSD) has been identified on an ARRIUS 2F engine, due to deterioration of gas generator front bearing. This could be the result of lack of lubrication, due to a link loss between pump driver and oil pump shaft.

This condition, if not detected and corrected, could lead to cases of IFSD, possibly resulting in forced landing with consequent damage to the helicopter and injury to occupants.

You may obtain further information by examining the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0900.

Related Service Information Under 14 CFR Part 51

Turbomeca S.A. has issued Mandatory Service Bulletin (MSB) No. 319 79 4834, Version B, dated October 21, 2014. The MSB describes procedures for inspecting the oil pump driver assembly on the oil pump shaft, the pump driver splines, and the oil pump splines. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of France, and is approved for operation in the United States. Pursuant to our bilateral agreement with the European Community, EASA has notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design. This proposed AD would require inspection, and if necessary, replacement before further flight, of the oil pump driver

assembly and/or the oil pump shaft, or the oil pump itself.

Costs of Compliance

We estimate that this proposed AD affects about 96 engines installed on helicopters of U.S. registry. We also estimate that it would take about two hours per product to comply with this proposed AD. The average labor rate is \$85 per hour. Required parts would cost about \$17,312 per engine. Based on these figures, we estimate the cost of this proposed AD on U.S. operators to be \$1,678,272.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Turbomeca S.A.: Docket No. FAA-2015-0900; Directorate Identifier 2015-NE-12-AD.

(a) Comments Due Date

We must receive comments by July 20, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all Turbomeca S.A. Arrius 2F turboshaft engines with oil pump, part number (P/N) 0319155050, installed, except for:

- (1) Engines, equipped with an oil pump, P/N 0319155050, that were overhauled in a Turbomeca repair center after January 1, 2013, and
- (2) Engines with a serial number of 34776 or higher, provided that the oil pump was not replaced on that engine since the first flight of that engine on a helicopter.

(d) Reason

This AD was prompted by cases of deterioration of the gas generator front bearing due to a link loss between the pump driver and the oil pump shaft. We are issuing this AD to prevent link loss between the pump driver and the oil pump shaft, which could lead to an engine in-flight shutdown, forced landing, and damage to the helicopter.

(e) Actions and Compliance

Comply with this AD within the compliance times specified, unless already done.

- (1) Inspect the pump driver assembly on the oil pump shaft, the pump driver splines, and the oil pump splines, using paragraph 2.4.2, Operating Instructions, of Turbomeca S.A. Mandatory Service Bulletin (MSB) No. 319 79 4834, Version B, dated October 21, 2014, as follows:

(i) After the effective date of this AD, for engines with less than 250 engine hours (EH), since new, since last overhaul, or since last installation of an affected oil pump, whichever occurred later, inspect before exceeding 300 EH since new, since last

overhaul, or since last installation of an affected oil pump, as applicable.

(ii) After the effective date of this AD, for engines with 250 EH or more, but less than 300 EH, accumulated since new, since last overhaul, or since last installation of an affected oil pump, whichever occurred later, inspect within 50 EH.

(iii) After the effective date of this AD, for engines with 300 EH or more, but less than 800 EH, accumulated since new, since last overhaul, or since last installation of an affected oil pump, whichever occurred later, inspect within 100 EH.

(iv) After the effective date of this AD, for engines with 800 EH or more, accumulated since new, since last overhaul, or since last installation of an affected oil pump, whichever occurred later, inspect during the next scheduled 500 EH inspection.

(2) If any oil pump drive assembly and/or oil pump shaft, or the oil pump itself, fails the inspection required by this AD, then before further flight, replace the failed part(s) with part(s) eligible for installation.

(3) The instruction to report inspection results and the instruction to return a compliance certificate to Turbomeca S.A. as stated in paragraph 2.4.2, Operating Instructions, of Turbomeca S.A. MSB No. 319 79 4834, Version B, dated October 21, 2014, are not required by this AD.

(f) Credit for Previous Action

If you inspected the oil pump driver assembly on the oil pump shaft, the pump driver splines, and the oil pump splines, and replaced any part(s) with part(s) eligible for installation before the effective date of this AD in accordance with Turbomeca S.A. MSB No. 319 79 4834, Version A, dated November 25, 2013, you met the requirements of this AD.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(h) Related Information

(1) For more information about this AD, contact Philip Habermen, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA 01803; phone: 781-238-7770; fax: 781-238-7199; email: philip.habermen@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2015-0049, dated March 17, 2015 (Corrected May 7, 2015), for more information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating it in Docket No. FAA-2015-0900.

(3) Turbomeca S.A. MSB No. 319 79 4834, Version B, dated October 21, 2014, can be obtained from Turbomeca S.A., using the contact information in paragraph (h)(4) of this proposed AD.

(4) For service information identified in this proposed AD, contact Turbomeca, S.A., 40220 Tarnos, France; phone: 33 (0)5 59 74 40 00; telex: 570 042; fax: 33 (0)5 59 74 45 15.

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 12 New England Executive Park, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Issued in Burlington, Massachusetts, on May 11, 2015.

Colleen M. D'Alessandro,

Assistant Directorate Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2015-12039 Filed 5-20-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Docket No. FAA-2015-1394; Airspace Docket No. 15-ACE-4]

Proposed Amendment of Class E Airspace; Tekamah, Nebraska

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: This action proposes to amend Class E airspace at Tekamah Municipal Airport, Tekamah, NE. A Class E extension is no longer required due to the decommissioning of the Tekamah VHF Omni-directional radio range (VOR) facility and its associated standard instrument approach procedures (SIAPs). This would enhance the safety and management of instrument flight rules (IFR) operations at the airport.

DATES: 0901 UTC. Comments must be received on or before July 6, 2015.

ADDRESSES: Send comments on this proposal to the U.S. Department of Transportation, Docket Operations, 1200 New Jersey Avenue SE., West Building Ground Floor, Room W12-140, Washington, DC 20590-0001. You must identify the docket number FAA-2015-1394/Airspace Docket No. 15-ACE-4, at the beginning of your comments. You may also submit comments through the Internet at <http://www.regulations.gov>. You may review the public docket containing the proposal, any comments received, and any final disposition in person in the Dockets Office between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. The Docket Office (telephone 1-800-647-5527), is on the ground floor of the building at the above address.

FAA Order 7400.9Y, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/

publications/. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of this proposed incorporation by reference material at NARA, call 202-741-6030, or go to http://www.archives.gov/federal-register/code_of_federal-regulations/ibr_locations.html.

FAA Order 7400.9, Airspace Designations and Reporting Points, is published yearly and effective on September 15. For further information, you can contact the Airspace Policy and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW., Washington, DC 20591; telephone: 202-267-8783.

FOR FURTHER INFORMATION CONTACT:

Roger Waite, Central Service Center, Operations Support Group, Federal Aviation Administration, Southwest Region, 2601 Meacham Blvd., Fort Worth, TX 76137; telephone: (817) 321-7652.

SUPPLEMENTARY INFORMATION:

Comments Invited

Interested parties are invited to participate in this proposed rulemaking by submitting such written data, views, or arguments, as they may desire. Comments that provide the factual basis supporting the views and suggestions presented are particularly helpful in developing reasoned regulatory decisions on the proposal. Comments are specifically invited on the overall regulatory, aeronautical, economic, environmental, and energy-related aspects of the proposal. Communications should identify both docket numbers and be submitted in triplicate to the address listed above. Commenters wishing the FAA to acknowledge receipt of their comments on this notice must submit with those comments a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket No. FAA-2015-1394/Airspace Docket No. 15-ACE-4." The postcard will be date/time stamped and returned to the commenter.

Availability of NPRMs

An electronic copy of this document may be downloaded through the Internet at <http://www.regulations.gov>. Recently published rulemaking documents can also be accessed through the FAA's Web page at http://www.faa.gov/airports_airtraffic/air_traffic/publications/airspace_amendments/.

You may review the public docket containing the proposal, any comments

received and any final disposition in person in the Dockets Office (see **ADDRESSES** section for address and phone number) between 9:00 a.m. and 5:00 p.m., Monday through Friday, except Federal holidays. An informal docket may also be examined during normal business hours at the office of the Central Service Center, 2601 Meacham Blvd., Fort Worth, TX 76137.

Persons interested in being placed on a mailing list for future NPRMs should contact the FAA's Office of Rulemaking (202) 267-9677, to request a copy of Advisory Circular No. 11-2A, Notice of Proposed Rulemaking Distribution System, which describes the application procedure.

Availability and Summary of Documents Proposed for Incorporation by Reference

This document proposes to amend FAA Order 7400.9Y, Airspace Designations and Reporting Points, dated August 6, 2014, and effective September 15, 2014. FAA Order 7400.9Y is publicly available as listed in the **ADDRESSES** section of this proposed rule. FAA Order 7400.9Y lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

The Proposal

This action proposes to amend Title 14, Code of Federal Regulations (14 CFR), Part 71 by modifying Class E airspace extending upward from 700 feet above the surface to within a 6.4-mile radius of Tekamah Municipal Airport, Tekamah, NE., reconfiguring the airspace for standard instrument approach procedures at the airport. The Tekamah VOR facility has been decommissioned and its associated SIAPs have been canceled. Controlled airspace is necessary for the safety and management of IFR operations for other SIAPs at the airport.

Class E airspace areas are published in Paragraph 6005 of FAA Order 7400.9Y, dated August 6, 2014 and effective September 15, 2014, which is incorporated by reference in 14 CFR 71.1. The Class E airspace designation listed in this document will be published subsequently in the Order.

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current. It, therefore, (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant