

Justice Reform. Under this rule: (1) All State and local laws and regulations that are inconsistent with this rule will be preempted; (2) no retroactive effect will be given to this rule; and (3) no administrative proceedings will be required before parties may file suit in court challenging this rule.

Executive Order 13175

This proposed rule has been reviewed in accordance with the requirements of Executive Order 13175, Consultation and Coordination with Indian Tribal Governments. The review reveals that this proposed regulation will not have substantial and direct effects on Tribal governments and will not have significant Tribal implications.

USDA Non-Discrimination Statement

No agency, officer, or employee of the USDA shall, on the grounds of race, color, national origin, religion, sex, gender identity, sexual orientation, disability, age, marital status, family/parental status, income derived from a public assistance program, or political beliefs, exclude from participation in, deny the benefits of, or subject to discrimination any person in the United States under any program or activity conducted by the USDA.

How To File a Complaint of Discrimination

To file a complaint of discrimination, complete the USDA Program Discrimination Complaint Form, which may be accessed online at http://www.ocio.usda.gov/sites/default/files/docs/2012/Complain_combined_6_8_12.pdf, or write a letter signed by you or your authorized representative.

Send your completed complaint form or letter to USDA by mail, fax, or email:

Mail: U.S. Department of Agriculture, Director, Office of Adjudication, 1400 Independence Avenue SW., Washington, DC 20250-9410, Fax: (202) 690-7442, Email: program.intake@usda.gov.

Persons with disabilities who require alternative means for communication (Braille, large print, audiotape, etc.), should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD).

Additional Public Notification

Public awareness of all segments of rulemaking and policy development is important. Consequently, FSIS will announce this **Federal Register** publication on-line through the FSIS Web page located at: <http://www.fsis.usda.gov/federal-register>.

FSIS also will make copies of this publication available through the FSIS Constituent Update, which is used to

provide information regarding FSIS policies, procedures, regulations, **Federal Register** notices, FSIS public meetings, and other types of information that could affect or would be of interest to our constituents and stakeholders. The Update is available on the FSIS Web page. Through the Web page, FSIS is able to provide information to a much broader, more diverse audience. In addition, FSIS offers an email subscription service which provides automatic and customized access to selected food safety news and information. This service is available at: <http://www.fsis.usda.gov/subscribe>. Options range from recalls to export information, regulations, directives, and notices. Customers can add or delete subscriptions themselves, and have the option to password protect their accounts.

List of Subjects in 9 CFR Part 381

Food grades and standards, Poultry and poultry products.

For the reasons set forth in the preamble, FSIS proposes to amend 9 CFR part 381, as follows:

PART 381—POULTRY PRODUCTS INSPECTION REGULATIONS

- 1. The authority citation for part 381 continues to read as follows:

Authority: 7 U.S.C. 138f; 7 U.S.C. 450; 21 U.S.C. 451-470; 7 CFR 2.18, 2.53.

- 2. Section 381.170 is amended by revising paragraph (a)(1)(iii) to read as follows:

§ 381.170 Standards for kinds and classes, and for cuts of raw poultry.

(a) * * *

(1) * * *

(iii) *Roaster or roasting chicken.* A "roaster" or "roasting chicken" is a young chicken (less than 12 weeks of age) of either sex, with a ready-to-cook carcass weight of 5.5 pounds or more, that is tender-meated with soft, pliable, smooth-textured skin and breastbone cartilage that is somewhat less flexible than that of a broiler or fryer.

* * * * *

Done at Washington, DC, on August 12, 2015.

Alfred V. Almanza,

Acting Administrator.

[FR Doc. 2015-20433 Filed 8-18-15; 8:45 am]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-3141; Directorate Identifier 2014-NM-242-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model 757 airplanes. This proposed AD was prompted by a report of cracking in the fuselage frame at a certain location. This proposed AD would require inspections for cracking in the fuselage frame, left and right sides, and repair if necessary. We are proposing this AD to detect and correct fuselage frame fatigue cracking that could result in loss of structural integrity and the inability to sustain loading conditions.

DATES: We must receive comments on this proposed AD by October 5, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3141.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3141; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Roger Durbin, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5233; fax: 562-627-5210; email: roger.durbin@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-3141; Directorate Identifier 2014-NM-242-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received reports of cracking in the fuselage frame at Station (STA) 1440, stringer S-24L. The airplane had 36,890 total flight cycles and 78,922 total flight hours. The cracking was discovered during unrelated local repairs. An investigation has

determined the cracking may have been caused by fatigue. The cracking initiated in the fuselage frame at the corner radius of the fuselage frame opening for the stringer. It continued to the fastener hole common to the fuselage frame, splice plate, and fail safe chord. The cracking was not visible because it was completely hidden by the splice plate on one side and the fail safe chord on the other side.

Fuselage frame fatigue cracking could result in loss of structural integrity and the inability to sustain loading conditions.

Related Service Information Under 1 CFR part 51

We reviewed Boeing Alert Service Bulletin 757-53A0099, dated September 18, 2014. The service information describes procedures for detailed and high frequency eddy current (HFEC) inspections for cracking in the fuselage frame at stringer 24 and stringer 25, left and right sides. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under "Difference Between this Proposed AD and the Service Information." Refer to his service information for details on the procedures and compliance times.

Difference Between this Proposed AD and the Service Information

Boeing Alert Service Bulletin 757-53A0099, dated September 18, 2014, specifies to contact the manufacturer for instructions on how to repair certain conditions, but this proposed AD would require repairing those conditions in one of the following ways:

- In accordance with a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) whom we have authorized to make those findings.

Explanation of "RC" Steps in Service Information

The FAA worked in conjunction with industry, under the Airworthiness Directive Implementation Aviation Rulemaking Committee (ARC), to enhance the AD system. One enhancement was a new process for annotating which steps in the service information are required for compliance with an AD. Differentiating these steps from other tasks in the service information is expected to improve an owner's/operator's understanding of crucial AD requirements and help provide consistent judgment in AD compliance. The steps identified as Required for Compliance (RC) in any service information identified previously have a direct effect on detecting, preventing, resolving, or eliminating an identified unsafe condition.

For service information that contains steps that are labeled as RC, the following provisions apply: (1) the steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD, and an AMOC is required for any deviations to RC steps, including substeps and identified figures; and (2) steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

Costs of Compliance

We estimate that this proposed AD affects 652 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	68 to 83 work-hours × \$85 per hour = Up to \$7,055 per inspection cycle.	\$0	Up to \$7,055 per inspection cycle	Up to \$4,599,860 per inspection cycle.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2015–3141; Directorate Identifier 2014–NM–242–AD.

(a) Comments Due Date

We must receive comments by October 5, 2015.

(b) Affected ADs

None.

(c) Applicability

This AD applies to all The Boeing Company Model 757–200, –200CB, –200PF, and –300 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by a report of cracking in the fuselage frame at Station (STA) 1440, stringer S–24L. We are issuing this AD to detect and correct fuselage frame fatigue cracking that could result in loss of structural integrity and the inability to sustain loading conditions.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection

At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757–53A0099, dated September 18, 2014, except as required by paragraph (h) of this AD, do detailed and high frequency eddy current (HFEC) inspections for cracking in the fuselage frames at stringers S–24 and S–25, left and right sides, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757–53A0099, dated September 18, 2014.

(1) If cracking is not found, repeat the inspections at intervals not to exceed 12,000 flight cycles.

(2) If any cracking is found, before further flight, repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD. Repeat the inspections at intervals not to exceed 12,000 flight cycles in unrepaired areas.

(h) Exception to Service Information Specifications

Where Boeing Alert Service Bulletin 757–53A0099, dated September 18, 2014, specifies a compliance time "after the Original Issue date of this Service Bulletin,"

this AD requires compliance within the specified compliance time after the effective date of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles Aircraft Certification Office (ACO), to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (h) of this AD: For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

(1) For more information about this AD, contact Roger Durbin, Aerospace Engineer, Airframe Branch, ANM–120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5233; fax: 562–627–5210; email: roger.durbin@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington on August 10, 2015.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2015-20265 Filed 8-18-15; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-3142; Directorate Identifier 2015-NM-003-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 787-8 airplanes. This proposed AD was prompted by reports of hydraulic contamination of the power control unit (PCU) electro-hydraulic servo valves (EHSVs) used in the flight control system; this contamination caused a restriction in the EHSVs resulting in the display of status messages from the engine indication and crew alerting system (EICAS). This proposed AD would require installing markers to limit the hydraulic system fluid used to a specific brand, doing hydraulic fluid tests of the hydraulic systems, replacing hydraulic system fluid if necessary, and doing all applicable related investigative and corrective actions. We are proposing this AD to prevent the failure of flight control hydraulic PCUs, which could lead to reduced controllability of the airplane.

DATES: We must receive comments on this proposed AD by October 5, 2015.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3142.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-3142; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Fnu Winarto, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6659; fax: 425-917-6590; email: fnu.winarto@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2015-3142; Directorate Identifier 2015-NM-003-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We received reports of the display of status messages from the engine indication and crew alerting system (EICAS). Boeing and the actuation system supplier determined these messages are displayed when electro-hydraulic servo valves (EHSVs) of the power control units (PCUs) of the primary flight control system are restricted due to the accumulation of particle deposits. Failures have only occurred on airplanes operated with Skydrol LD-4 hydraulic fluid. Changing the hydraulic fluid to HyJet V would reduce the rate of particle deposit accumulation. This condition, if not corrected, could result in the eventual failure of flight control hydraulic PCUs, which could lead to reduced controllability of the airplane.

Related Service Information Under 14 CFR Part 51

We reviewed Boeing Alert Service Bulletin B787-81205-SB270026-00, Issue 001, dated November 25, 2014. This service information describes procedures for installing markers to limit the hydraulic system fluid used to a specific brand, doing hydraulic fluid tests of the hydraulic systems, replacing the hydraulic system fluid if necessary, and related investigative and corrective actions. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this NPRM.

FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously. Refer to this service information for details on the procedures and compliance times.

The phrase "related investigative actions" is used in this proposed AD. "Related investigative actions" are follow-on actions that (1) are related to the primary actions, and (2) further investigate the nature of any condition found. Related investigative actions in an AD could include, for example, inspections.

The phrase "corrective actions" is used in this proposed AD. "Corrective actions" are actions that correct or address any condition found. Corrective