

petition does not relieve vehicle distributors and dealers of the prohibitions on the sale, offer for sale, or introduction or delivery for introduction into interstate commerce of the noncompliant vehicles under their control after GM notified them that the subject noncompliance existed.

**Authority:** (49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.95 and 501.8).

**Jeffrey M. Giuseppe,**  
Director, Office of Vehicle Safety Compliance.  
[FR Doc. 2016-00449 Filed 1-12-16; 8:45 am]

**BILLING CODE 4910-59-P**

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA-2014-0034; Notice 2]

#### Maserati S.p.A and Maserati North America, Inc., Grant of Petition for Decision of Inconsequential Noncompliance

**AGENCY:** National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT).

**ACTION:** Grant of petition.

**SUMMARY:** Maserati S.p.A and Maserati North America, Inc. (collectively “MNA”) have determined that certain model year (MY) 2011–2014 MNA passenger cars do not fully comply with paragraph S4.4(c)(2), of Federal Motor Vehicle Safety Standard (FMVSS) No. 138, *Tire Pressure Monitoring Systems*. MNA has filed a report dated March 3, 2014, pursuant to 49 CFR part 573, *Defect and Noncompliance Responsibility and Reports*. MNA then petitioned NHTSA under 49 CFR part 556 requesting a decision that the subject noncompliance is inconsequential to motor vehicle safety.

**ADDRESSES:** For further information on this decision contact Kerrin Bressant, Office of Vehicles Safety Compliance, the National Highway Traffic Safety Administration (NHTSA), telephone (202) 366-1110, facsimile (202) 366-3081.

#### SUPPLEMENTARY INFORMATION:

I. *MNA’s Petition:* Pursuant to 49 U.S.C. 30118(d) and 30120(h) and the rule implementing those provisions at 49 CFR part 556, MNA submitted a petition for an exemption from the notification and remedy requirements of 49 U.S.C. Chapter 301 on the basis that this noncompliance is inconsequential to motor vehicle safety.

Notice of receipt of the petition was published, with a 30-day public

comment period, on September 8, 2015 in the **Federal Register** (80 FR 53912). No comments were received. To view the petition and all supporting documents log onto the Federal Docket Management System (FDMS) Web site at: <http://www.regulations.gov/>. Then follow the online search instructions to locate docket number “NHTSA-2014-0034.”

II. *Vehicles Involved:* Affected are approximately 8,789 MY 2011–2013 Maserati Quattroporte and MY 2011–2014 Maserati Granturismo and Granturismo Convertible passenger vehicles.

III. *Noncompliance:* MNA explains that after the car’s ignition is switched to the ON position, the Tire Pressure Monitoring System (TPMS) immediately seeks to confirm if all wheel sensors are present. When the TPMS first detects a sensor is missing, it illuminates the malfunction indicator as required by FMVSS No. 138. Upon subsequent ignition cycles, if the sensor detected as missing during the previous ignition cycle is still missing, the TPMS malfunction indicator will again illuminate as required and stay illuminated until the vehicle begins to move, at which time the indicator will extinguish. The extinguishment of the malfunction indicator while the malfunction still exists is in violation to paragraph S4.4(c)(2) of FMVSS No. 138. The malfunction indicator must illuminate when a malfunction is identified and remain illuminated as long as the condition exists.

IV. *Rule Text:* Paragraph S4.4(c)(2) of FMVSS No. 138 requires in pertinent part:

S4.4 TPMS Malfunction.

\* \* \* \* \*

(c) *Combination low tire pressure/TPMS malfunction telltale.* The vehicle meets the requirements of S4.4(a) when equipped with a combined Low Tire Pressure/TPMS malfunction telltale that:

(2) Flashes for a period of at least 60 seconds but no longer than 90 seconds upon detection of any condition specified in S4.4(a) after the ignition locking system is activated to the “On” (“Run”) position. After each period of prescribed flashing, the telltale must remain continuously illuminated as long as a malfunction exists and the ignition locking system is in the “On” (“Run”) position. This flashing and illumination sequence must be repeated each time the ignition locking system is placed in the “On” (“Run”) position until the situation causing the malfunction has been corrected.

· · ·

V. *Summary of MNA’s Analyses:* MNA stated its belief that the subject noncompliance is inconsequential to motor vehicle safety for the following reasons:

(A) MNA states that after the car’s ignition is switched to the ON position, the TPMS immediately seeks to confirm if all wheel sensors are present. If the TPMS detects a sensor is not present, an internal timer is started. If the sensor detected as missing was also detected as missing during the previous ignition cycle, the TPMS malfunction indicator will illuminate as required to indicate a hardware fault is still present. If the engine is subsequently started again and left in its steady state (engine not cold) idle, the warning lamp will continue to remain illuminated as required. However, if the car is then driven, the warning lamp will extinguish. Once the vehicle has been moving above 22 mph for a period of 15 seconds, the TPMS will seek to confirm that all wheel sensors are fitted to the vehicle. If the internal timer reaches 160 seconds, and the vehicle has been moving above 22 mph for 15 seconds, the TPMS malfunction indicator will illuminate correctly. Once the malfunction indicator is illuminated, it remains so throughout that ignition cycle, regardless of the vehicle’s speed.

(B) MNA explained that if the TPMS fails to detect the wheel sensors, the TPMS will display no value on the TPMS pressures screen for the tire pressure, indicating that the status of the wheel sensor is unconfirmed.

(C) MNA said that the noncompliance is confined to one particular aspect of the functionality of the otherwise compliant TPMS malfunction indicator. All other aspects of the low-pressure monitoring system functionality are fully compliant with the requirements of FMVSS No. 138. Also MNA stated that NHTSA had previously published a rule (April 8, 2005) that said a malfunction, in and of itself, does not represent a safety risk to vehicle occupants and that the chances of having a TPMS malfunction and a significantly under-inflated tire at the same time are unlikely.

(D) MNA said that NHTSA has previously granted petitions for inconsequential noncompliances related to the TPMS malfunction indicator not illuminating in the manner required by FMVSS No. 138 due to a software malfunction. MNA mentioned a grant to a petition submitted by Volkswagen Group of America, Inc. for Audi vehicles.<sup>1</sup> MNA explained that in the Volkswagen case, the TPMS would initially display the required warning, but the telltale light would not stay illuminated in the manner required by FMVSS No. 138 in that the warning light would be extinguished on

<sup>1</sup> 76 FR 30239 (May 24, 2011).

subsequent drive cycles if the vehicle speed was maintained below 12.5 mph. (E) MNA stated that it is not aware of any customer complaints, field communications, incidents or injuries related to this condition.

(F) MNA explained that it provides additional warnings through tire inflation and usage fitment information provided in the subject vehicles owner's manuals. In addition, customer calls into the Roadside Assistance and Customer Care department can also help provide specific wheel and tire fitment information to MNA customers. The Maserati Authorized Dealer network can also address this issue with Maserati customers.

In summation, MNA believes that the described noncompliance of the subject vehicles is inconsequential to motor vehicle safety, and that its petition, to exempt MNA from providing recall notification of noncompliance as required by 49 U.S.C. 30118 and remedying the recall noncompliance as required by 49 U.S.C. 30120 should be granted.

#### NHTSA'S Decision

*NHTSA's Analysis:* MNA explained that although the malfunction indicator extinguishes once the car starts moving, it will illuminate shortly thereafter—within 160 seconds of ignition start and after the vehicle speed exceeds 22 mph for 15 seconds.

NHTSA agrees with MNA that the malfunction indicator will not illuminate as required only during very short periods of time when the vehicle is traveling at low speeds and thus poses little risk to vehicle safety. Under normal driving conditions, a driver will begin a trip by accelerating moderately beyond 22 mph, and as explained by MNA, once the vehicle accelerates above 22 mph (combined with the Ignition-On internal clock reaching 160 seconds), the malfunction indicator re-illuminates and then it will remain illuminated for the entire ignition cycle, regardless of vehicle speed. The telltale fails to re-illuminate only in the very rare case when the driver begins a trip and never exceeds the 22 mph threshold, the speed required to re-activate the malfunction indicator. No real safety risk exists because at such low speeds there is little risk of vehicle loss of control due to underinflated tires. Furthermore, the possibility that the vehicle will experience both a low inflation pressure condition and a malfunction simultaneously is highly unlikely.

MNA stated that if the TPMS fails to detect the wheel sensors, the TPMS will display no value on the vehicle's central

digital cluster for the associated tire pressure, indicating that the status of the wheel sensor is unconfirmed for a given wheel.

The agency evaluated the displays MNA uses in the noncompliant vehicles. In addition to the combination low inflation pressure and malfunction telltale indicator lamp, the subject vehicles are equipped with a "plan view" icon which displays the pressures for all four wheels individually. If any wheel has a malfunctioning pressure sensor the indicator for that wheel displays several dashes "—" indicating there is a problem with that respective wheel. The additional information is not required by the safety standard, but can be used as an aid to the driver to determine the status of a vehicle's tires.

MNA discussed that the noncompliance only involves one specific aspect of the malfunction functionality and that the primary function of the TPMS, identification of other malfunctions and identification of low inflation pressure scenarios, is not affected.

The agency agrees with MNA's reasoning that the primary function of the TPMS is to identify low inflation pressure conditions which MNA's system does as required by FMVSS No. 138.

There are also a variety of other malfunctions that can occur in addition to the delayed re-illumination malfunction identified in this petition. NHTSA understands from MNA that its TPMS will perform as required during all other type system malfunctions.

MNA additionally mentioned that NHTSA had previously granted petitions for inconsequential noncompliances pertaining to FMVSS No. 138 and specifically mentioned Volkswagen's (VW) Audi petition.<sup>2</sup> In the case of that petition, the Audi vehicle's TPMS would initially display the required warning, but the telltale would not stay illuminated in the manner required by FMVSS No. 138. The telltale light would extinguish on subsequent drive cycles if the vehicle speed was maintained below 12.5 mph. The MNA condition is similar to the VW condition because the malfunction telltales in both cases illuminate upon subsequent ignition cycles, but then extinguish at low speeds after the vehicles begin to move. Both conditions happen at relatively low speeds and for short durations of time. The VW petition was granted due to the fact that the noncompliance took place at

relatively low speeds and for a short duration of time.

MNA added that it also provides several warnings via the owner's manual text with regards to the TPMS and its proper usage. Specifically, tire inflation and usage fitment information is provided. A Roadside Assistance and a Customer Care department are additionally mentioned as resources for an owner with issues or concerns about proper tire inflation and/or tire usage fitment. The additional information provided inside the owner's manual, and via telephone for Roadside Assistance and the Customer Care Department offers the MNA owner ample opportunity to ensure their vehicle operates as designed.

MNA also stated that they have not received or are aware of any consumer complaints, field communications, incidences or injuries related to this noncompliance.

In addition to the analysis done by MNA that looked at customer complaints, field communications, incidents or injuries related to this condition, NHTSA also conducted checks of NHTSA's Office of Defects Investigations consumer complaint database and found no related complaints.

*NHTSA's Decision:* In consideration of the foregoing analysis, NHTSA has decided that MNA has met its burden of demonstrating that the FMVSS No. 138 noncompliance is inconsequential to motor vehicle safety. Accordingly, MNA's petition is hereby granted and MNA is exempted from the obligation of providing notification of, and a free remedy for, the subject noncompliance under 49 U.S.C. 30118 and 30120.

NHTSA notes that the statutory provisions (49 U.S.C. 30118(d) and 30120(h)) that permit manufacturers to file petitions for a determination of inconsequentiality allow NHTSA to exempt manufacturers only from the duties found in sections 30118 and 30120, respectively, to notify owners, purchasers, and dealers of a defect or noncompliance and to remedy the defect or noncompliance. Therefore, any decision on this petition only applies to the subject vehicles that MNA no longer controlled at the time it determined that the noncompliance existed. However, any decision on this petition does not relieve vehicle distributors and dealers of the prohibitions on the sale, offer for sale, or introduction or delivery for introduction into interstate commerce of the noncompliant vehicles under their control after MNA notified them that the subject noncompliance existed.

<sup>2</sup> 76 FR 30239 (May 24, 2011).

**Authority:** (49 U.S.C. 30118, 30120; delegations of authority at 49 CFR 1.95 and 501.8)

**Jeffrey M. Giuseppe,**  
*Director, Office of Vehicle Safety Compliance.*  
 [FR Doc. 2016-00448 Filed 1-12-16; 8:45 am]  
**BILLING CODE 4910-59-P**

## DEPARTMENT OF TRANSPORTATION

### National Highway Traffic Safety Administration

[Docket No. NHTSA-2015-0016, Notice 2]

#### Decision That Nonconforming Model Year 2009 Ford F-150 Trucks Are Eligible for Importation

**AGENCY:** National Highway Traffic Safety Administration (NHTSA), Department of Transportation (DOT).

**ACTION:** Grant of petition.

**SUMMARY:** This document announces a decision by the National Highway Traffic Safety Administration that certain model year (MY) 2009 Ford F-150 trucks that were not originally manufactured to comply with all applicable Federal Motor Vehicle Safety Standards (FMVSS), are eligible for importation into the United States because they are substantially similar to vehicles originally manufactured for sale in the United States and that were certified by their manufacturer as complying with the safety standards (the U.S. certified version of the MY 2009 Ford F-150 trucks) and they are capable of being readily altered to conform to the standards.

**DATES:** This decision became effective on January 7, 2016.

**ADDRESSES:** For further information contact George Stevens, Office of Vehicle Safety Compliance, NHTSA (202-366-5308).

#### SUPPLEMENTARY INFORMATION:

##### Background

Under 49 U.S.C. 30141(a)(1)(A), a motor vehicle that was not originally manufactured to conform to all applicable FMVSS shall be refused admission into the United States unless NHTSA has decided that the motor vehicle is substantially similar to a motor vehicle originally manufactured for importation into and sale in the United States, certified as required under 49 U.S.C. 30115, of the same model year as the model of the motor vehicle to be compared, and is capable of being readily altered to conform to all applicable FMVSS.

Petitions for eligibility decisions may be submitted by either manufacturers or

importers who have registered with NHTSA pursuant to 49 CFR part 592. As specified in 49 CFR 593.7, NHTSA publishes notice in the **Federal Register** of each petition that it receives, and affords interested persons an opportunity to comment on the petition. At the close of the comment period, NHTSA decides, on the basis of the petition and any comments that it has received, whether the vehicle is eligible for importation. The agency then publishes this decision in the **Federal Register**.

Wallace Environmental Testing Laboratories (WETL), Inc., of Houston, Texas (Registered Importer R-90-005) petitioned NHTSA to decide whether certain model year (MY) 2009 Ford F-150 trucks are eligible for importation into the United States. NHTSA published a notice of the petition on November 5, 2015 (80 FR 68603) to afford an opportunity for public comment. No comments were received in response to the notice of petition. The reader is referred to that notice for a thorough description of the petition.

To view the petition, and all supporting documents log onto the Federal Docket Management System (FDMS) Web site at: <http://www.regulations.gov/>. Then follow the online search instructions to locate docket number "NHTSA-2015-0016."

#### Conclusions and Conditions

NHTSA has reviewed the petition and has concluded that the vehicles covered by the petition are capable of being readily altered to comply with all applicable FMVSS. However, NHTSA has also decided that an RI who imports or modifies one of these vehicles must include in each statement of conformity and associated documents (referred to as a "conformity package") it submits to NHTSA under 49 CFR 592.6(d) specific proof to confirm that the vehicle was manufactured to conform to, or was successfully altered to conform to, each of the following standards:

**Standard No. 101 Controls and Displays:** The petition stated that the vehicles could be conformed to the standard through replacement of the speedometer with the U.S.-model part, which includes the BRAKE telltale, and reprogramming of the speedometer software.

NHTSA has decided that a description of how the programming changes were completed, and how compliance with the standard was verified after reprogramming, must be included in each conformity package. Photographs, printouts, and/or images of the installation computer's monitor ("screenshots"), as practicable, must be

submitted as part of the proof that the reprogramming was carried out successfully.

**Standard No. 138 Tire Pressure Monitoring Systems:** The petition stated that the vehicles meet the requirements of the standard and are equipped with hardware and software that is identical to that installed in the U.S.-model vehicles.

NHTSA has decided that a description of how compliance was verified must accompany each conformity package. Photographs, printouts, and/or screenshots, as practicable, must be submitted as proof that compliance verification (including substantiation that hardware and software installed in the vehicle is identical to that installed in the U.S.-model vehicles) was carried out successfully.

**Standard No. 208 Occupant Crash Protection:** The petition stated that a U.S.-version of the owner's manual must be provided with the vehicle to meet the information requirements of the standard.

NHTSA has decided that each conformity package must include a detailed description of the occupant protection system, including photographs of all required labeling, and a description of how compliance was verified. Photographs, printouts, and/or screenshots, as practicable, must be submitted as proof that compliance verification (including substantiation that hardware and software installed in the vehicle is identical to that installed in the U.S.-model vehicles) was carried out successfully.

NHTSA has also determined that each conformity package must include evidence showing how the RI verified that the changes it made in loading or reprogramming vehicle software to achieve conformity with each separate FMVSS, did not also cause the vehicle to fall out of compliance with any other applicable FMVSS.

#### Decision

Accordingly, on the basis of the foregoing, NHTSA hereby decides that MY 2009 Ford F-150 trucks that were not originally manufactured to comply with all applicable FMVSS, are substantially similar to MY 2009 Ford F-150 trucks manufactured for sale in the United States, and certified under 49 U.S.C. 30115, and are capable of being readily altered to conform to all applicable FMVSS.

#### Vehicle Eligibility Number for Subject Vehicles

The importer of a vehicle admissible under any final decision must indicate