

(v)	Opportunity to contribute to achieving organizational mission I know how my work relates to the agency's goals.
-----------	--

§ 250.303 Availability of results.

(a) Each agency will make the results of its annual survey available to the public and post the results on its Web site unless the agency head determines that doing so would jeopardize or negatively impact national security. The posted survey results will include the following:

(1) The agency's evaluation of its survey results;

(2) How the survey was conducted;

(3) Description of the employee sample, unless all employees are surveyed;

(4) The survey questions and response choices with the prescribed questions identified;

(5) The number of employees surveyed and number of employees who completed the survey; and

(6) The number of respondents for each survey question and each response choice.

(b) Data must be collected by December 31 of each calendar year. Each agency must post the beginning and ending dates of its employee survey and either the survey results described in paragraph (a) of this section, or a statement noting the decision not to post, no later than 120 days after the agency completes survey administration. OPM may extend this date under unusual circumstances.

[FR Doc. 2016-02112 Filed 2-5-16; 8:45 am]

BILLING CODE 6325-39-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-0462; Directorate Identifier 2015-NM-144-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes. This proposed AD was prompted by a report of wire chafing damage, which caused an electrical arc to an adjacent hydraulic tube located on

the forward bulkhead of the main landing gear (MLG) wheel well, resulting in a hole in a hydraulic tube and consequent total loss of system B hydraulic fluid. This proposed AD would require an inspection for chafing damage of wire bundles and a hydraulic tube in the right side of the MLG wheel well, and corrective action if necessary; and installation of clamps between the wire bundles and hydraulic tube. We are proposing this AD to prevent chafing damage, which could result in electrical arcing that can cause a hole in the hydraulic tube and consequent loss of hydraulic fluid, possibly resulting in a fire in the MLG wheel well.

DATES: We must receive comments on this proposed AD by March 24, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-0462.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-0462; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the

regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Sean J. Schauer, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6479; fax: 425-917-6590; email: sean.schauer@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-0462; Directorate Identifier 2015-NM-144-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

We have received a report of damage to wire W6128-0506-10. The wire had chafed and arced to an adjacent hydraulic tube located on the forward bulkhead of the MLG wheel well. The chafing and electrical arc created a small hole in a system B hydraulic tube and caused damage to the wire bundle, which resulted in a ground fault detection on the system A electrical motor-driven pump (EMDP). The small hole led to a total loss of system B hydraulic fluid and the ground fault resulted in removal of power from the system A EMDP and illumination of the system A EMDP low power light. An investigation found that there was not sufficient separation between the wire bundles W6128, W8122, and the adjacent hydraulic tube at that location. This condition, if not corrected, could result in electrical arcing that can cause

a hole in the hydraulic tube and consequent loss of hydraulic fluid, possibly resulting in a fire in the MLG wheel well.

Related Service Information Under 14 CFR Part 51

We reviewed Boeing Alert Service Bulletin 737-29A1119, dated August 4, 2015. The service information describes procedures for doing an inspection for chafing damage of the wire bundles and hydraulic tube in the right side of the MLG wheel well, corrective actions, and installation of clamps and an optional spacer between the wire bundles and hydraulic tube. This service information is reasonably available because the

interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously. For information on the

procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-0462.

The phrase “corrective actions” is used in this proposed AD. “Corrective actions” are actions that correct or address any condition found. Corrective actions in an AD could include, for example, repairs.

Costs of Compliance

We estimate that this proposed AD affects 1,270 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection and Installation	2 work-hours × \$85 per hour = \$170	\$9	\$179	\$227,330

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:
Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA-2016-0462; Directorate Identifier 2015-NM-144-AD.

(a) Comments Due Date

We must receive comments by March 24, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin 737-29A1119, dated August 4, 2015.

(d) Subject

Air Transport Association (ATA) of America Code 29, Hydraulic power.

(e) Unsafe Condition

This AD was prompted by a report of wire chafing damage, which caused an electrical arc to an adjacent hydraulic tube located on the forward bulkhead of the main landing gear (MLG) wheel well, resulting in a hole in a hydraulic tube and consequent total loss of system B hydraulic fluid. We are issuing this AD to prevent chafing damage, which could result in electrical arcing that can cause a hole in the hydraulic tube and consequent loss of hydraulic fluid, possibly resulting in a fire in the MLG wheel well.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection and Corrective Action and Clamp Installation

Within 24 months after the effective date of this AD: Do the actions specified in paragraphs (g)(1) and (g)(2) of this AD:

- (1) Do a detailed inspection for chafing damage of the wire bundles and hydraulic tube in the right side of the MLG wheel well, and do all applicable corrective actions, in

accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737–29A1119, dated August 4, 2015. Do all applicable corrective actions before further flight.

(2) Install new clamps and an optional spacer between the wire bundles and hydraulic tube in the right side of the MLG wheel well, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737–29A1119, dated August 4, 2015.

(h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(i) Related Information

(1) For more information about this AD, contact Sean J. Schauer, Aerospace Engineer, Systems and Equipment Branch, ANM–130S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6479; fax: 425–917–6590; email: sean.schauer@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on January 27, 2016.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–02193 Filed 2–5–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF THE INTERIOR

Office of Surface Mining Reclamation and Enforcement

30 CFR Part 936

[SATS No. OK–037–FOR; Docket ID: OSM–2015–0006; S1D1S SS08011000 SX064A000 167S180110; S2D2S SS08011000 SX064A000 16XS501520]

Oklahoma Regulatory Program

AGENCY: Office of Surface Mining Reclamation and Enforcement, Interior.

ACTION: Proposed rule; public comment period and opportunity for public hearing on proposed amendment.

SUMMARY: We, the Office of Surface Mining Reclamation and Enforcement (OSMRE), are announcing receipt of a proposed amendment to the Oklahoma regulatory program (Oklahoma program) under the Surface Mining Control and Reclamation Act of 1977 (SMCRA or the Act). Oklahoma proposes revisions to its regulations regarding: Permit eligibility for permits with violations on lands eligible for re-mining; permit suspension or rescission posting locations and appeal procedures; requiring GPS coordinates for aspects of permit maps; topsoil removal distances; blasting records requirements; annual reporting requirements; temporary cessation of operations requirements; casing and sealing temporary underground openings; right of entry requirements; surface drainage associated with auger mining; correcting reference errors; updating addresses; and correcting spelling and grammatical errors. Oklahoma intends to revise its program to be no less effective than the Federal regulations and to improve operational efficiency.

This document gives the times and locations that the Oklahoma program and this proposed amendment to that program are available for your inspection, the comment period during which you may submit written comments on the amendment, and the procedures that we will follow for the public hearing, if one is requested.

DATES: We will accept written comments on this amendment until 4:00 p.m., central time, March 9, 2016. If requested, we will hold a public hearing on the amendment on March 4, 2016. We will accept requests to speak at a hearing until 4:00 p.m., central time on February 23, 2016.

ADDRESSES: You may submit comments, identified by SATS No. OK–037–FOR, by any of the following methods:

- *Mail/Hand Delivery:* Director, Tulsa Field Office, Office of Surface Mining

Reclamation and Enforcement, 1645 South 101st East Avenue, Suite 145, Tulsa, Oklahoma 74128–4629.

- *Fax:* (918) 581–6419.
- *Federal eRulemaking Portal:* The amendment has been assigned Docket ID OSM–2015–0006. If you would like to submit comments go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

Instructions: All submissions received must include the agency name and docket number for this rulemaking. For detailed instructions on submitting comments and additional information on the rulemaking process, see the “Public Comment Procedures” heading of the **SUPPLEMENTARY INFORMATION** section of this document.

Docket: For access to the docket to review copies of the Oklahoma program, this amendment, a listing of any scheduled public hearings, and all written comments received in response to this document, you must go to the address listed below during normal business hours, Monday through Friday, excluding holidays. You may receive one free copy of the amendment by contacting OSMRE’s Tulsa Field Office or the full text of the program amendment is available for you to read at www.regulations.gov.

Elaine Ramsey, Director, Tulsa Field Office, Office of Surface Mining Reclamation and Enforcement, 1645 South 101st East Avenue, Suite 145, Tulsa, Oklahoma 74128–4629.

Telephone: (918) 581–6430.

Email: eramsey@osmre.gov.

In addition, you may review a copy of the amendment during regular business hours at the following location: Oklahoma Department of Mines, 2915 N. Classen Blvd., Suite 213, Oklahoma City, Oklahoma 73106–5406. Telephone: (405) 427–3859.

FOR FURTHER INFORMATION CONTACT: Elaine Ramsey, Director, Tulsa Field Office. Telephone: (918) 581–6430.

SUPPLEMENTARY INFORMATION:

- Background on the Oklahoma Program
- Description of the Proposed Amendment
- Public Comment Procedures
- Procedural Determinations

I. Background on the Oklahoma Program

Section 503(a) of the Act permits a State to assume primacy for the regulation of surface coal mining and reclamation operations on non-Federal and non-Indian lands within its borders by demonstrating that its program includes, among other things, “. . . State law which provides for the regulation of surface coal mining and reclamation operations in accordance with the requirements of this Act . . . ;