

indefinitely until amended, suspended, or terminated. The Committee's crop year begins on October 1, and ends on September 30.

In an interim rule published in the **Federal Register** on October 28, 2015, and effective on October 29, 2015 (80 FR 65886, Doc. No. AMS-FV-15-0034, FV15-987-1 IR), § 987.339 was amended by decreasing the assessment rate established for California dates for the 2015-16 and subsequent crop years from \$0.20 to \$0.10 per hundredweight of dates. The decrease in the per hundredweight assessment rate allows the Committee to reduce its financial reserve while still providing adequate funding to meet program expenses.

Final Regulatory Flexibility Analysis

Pursuant to requirements set forth in the Regulatory Flexibility Act (RFA) (5 U.S.C. 601-612), the Agricultural Marketing Service (AMS) has considered the economic impact of this rule on small entities. Accordingly, AMS has prepared this final regulatory flexibility analysis.

The purpose of the RFA is to fit regulatory actions to the scale of businesses subject to such actions in order that small businesses will not be unduly or disproportionately burdened. Marketing orders issued pursuant to the Act, and the rules issued thereunder, are unique in that they are brought about through group action of essentially small entities acting on their own behalf.

There are approximately 70 producers of dates in the production area and 11 handlers subject to regulation under the marketing order. The Small Business Administration defines small agricultural producers as those having annual receipts of less than \$750,000, and small agricultural service firms as those whose annual receipts are less than \$7,500,000. (13 CFR 121.201)

According to the National Agricultural Statistics Service (NASS), data for the most-recently completed crop year (2014) shows that about 3.54 tons, or 7,080 pounds, of dates were produced per acre. The 2014 producer price published by NASS was \$1,190 per ton. Thus, the value of date production per acre in 2014-15 averaged about \$4,213 (3.54 tons times \$1,190 per ton). At that average price, a producer would have to farm over 178 acres to receive an annual income from dates of \$750,000 (\$750,000 divided by \$4,213 per acre equals 178.02 acres). According to committee staff, the majority of California date producers farm less than 178 acres. Thus, it can be concluded that the majority of date producers could be considered small

entities. In addition, according to data from the committee staff, the majority of handlers of California dates have receipts of less than \$7,500,000 and may also be considered small entities.

This rule continues in effect the action that decreased the assessment rate established for the committee and collected from handlers for the 2015-16 and subsequent crop years from \$0.20 to \$0.10 per hundredweight of dates. The committee unanimously recommended 2015-16 expenditures of \$59,250 and an assessment rate of \$0.10 per hundredweight of dates, which is \$0.10 lower than the rate previously in effect. Applying the \$0.10 per hundredweight assessment rate to the estimated crop at 29,000,000 pounds (290,000 hundredweight) should provide \$29,000 in assessment income. Thus, income derived from handler's assessments, along with other income and funds from the committee's authorized reserve, should be adequate funding to meet program expenses.

This rule continues in effect the action that decreased the assessment obligation imposed on handlers. Assessments are applied uniformly on all handlers; however, decreasing the assessment rate reduces the burden on handlers.

In addition, the committee's meeting was widely publicized throughout the California date industry, and all interested persons were invited to attend the meetings and encouraged to participate in committee deliberations on all issues. Like all committee meetings, the June 25, 2015, meeting was a public meeting and all entities, both large and small, were able to express views on this issue.

In accordance with the Paperwork Reduction Act of 1995 (44 U.S.C. Chapter 35), the order's information collection requirements have been previously approved by Office of Management and Budget (OMB) and assigned OMB No. 0581-0178, "Vegetable and Specialty Crop Marketing Orders." No changes in those requirements as a result of this action are necessary. Should any changes become necessary, they would be submitted to OMB for approval.

This action imposes no additional reporting or recordkeeping requirements on either small or large Riverside County, California, date handlers. As with all Federal marketing order programs, reports and forms are periodically reviewed to reduce information requirements and duplication by industry and public sector agencies.

USDA has not identified any relevant Federal rules that duplicate, overlap, or conflict with this rule.

Comments on the interim rule were required to be received on or before December 28, 2015. No comments were received. Therefore, for reasons given in the interim rule, we are adopting the interim rule as a final rule, without change.

To view the interim rule, go to: <http://www.regulations.gov/#!documentDetail;D=AMS-FV-15-0034-0001>.

This action also affirms information contained in the interim rule concerning Executive Orders 12866, 12988, 13175, and 13563; the Paperwork Reduction Act (44 U.S.C. Chapter 35); and the E-Gov Act (44 U.S.C. 101).

After consideration of all relevant material presented, it is found that finalizing the interim rule, without change, as published in the **Federal Register** (80 FR 65886, October 28, 2015) will tend to effectuate the declared policy of the Act.

List of Subjects in 7 CFR Part 987

Dates, Marketing agreements, Reporting and recordkeeping requirements.

PART 987—DATES PRODUCED OR PACKED IN RIVERSIDE COUNTY, CALIFORNIA [AMENDED]

■ Accordingly, the interim rule amending 7 CFR part 987, which was published at 80 FR 65886 on October 28, 2015, is adopted as a final rule, without change.

Dated: February 22, 2016.

Elanor Starmer,

Acting Administrator, Agricultural Marketing Service.

[FR Doc. 2016-04044 Filed 2-25-16; 8:45 am]

BILLING CODE P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-4070; Directorate Identifier 2015-NE-31-AD; Amendment 39-18408; AD 2016-04-14]

RIN 2120-AA64

Airworthiness Directives; Turbomeca S.A. Turboshaft Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain

Turbomeca S.A. Arriel 1E2 turboshaft engines. This AD requires removing the tachometer box on affected engines. This AD was prompted by reports of uncommanded in-flight shutdowns (IFSDs). We are issuing this AD to prevent failure of the tachometer box, which could lead to failure of the engine, IFSD, and loss of control of the helicopter.

DATES: This AD becomes effective April 1, 2016.

ADDRESSES: For service information identified in this AD, contact Turbomeca S.A., 40220 Tarnos, France; phone: 33 (0)5 59 74 40 00; fax: 33 (0)5 59 74 45 15. You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-4070.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-4070; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the mandatory continuing airworthiness information (MCAI), the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Document Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Philip Haberlen, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7770; fax: 781-238-7199; email: philip.haberlen@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to the specified products. The NPRM was published in the **Federal Register** on November 24, 2015 (80 FR 73147). The NPRM proposed to correct an unsafe condition for the specified products. The MCAI states:

There have been reports of Arriel 1E2 engines having experienced an uncommanded in-flight shut-down (IFSD) due to an untimely activation of the tachometer box shut-off system which was activated by the power turbine monitoring function of the tachometer box.

This condition, if not corrected, could potentially lead to further cases of IFSD, possibly resulting in a forced landing.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM (80 FR 73147, November 24, 2015).

Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting this AD as proposed.

Related Service Information

Turbomeca S.A. has issued Mandatory Service Bulletin No. 292 77 0844, Version B, dated July 6, 2015. The service information describes procedures for removing pre-TU 369 tachometer boxes.

Costs of Compliance

We estimate that this AD affects 200 engines installed on helicopters of U.S. registry. We also estimate that it will take about 3 hours per engine to comply with this AD. The average labor rate is \$85 per hour. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$51,000.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will

not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2016-04-14 Turbomeca S.A.: Amendment 39-18408; Docket No. FAA-2015-4070; Directorate Identifier 2015-NE-31-AD.

(a) Effective Date

This AD becomes effective April 1, 2016.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to Turbomeca S.A. Arriel 1E2 turboshaft engines with tachometer boxes with the following part number (P/N) and serial number (S/N) combinations:

- (i) P/N 9580116170—all S/Ns
- (ii) P/N 9580116260—all S/Ns
- (iii) P/N 9580116900—all S/Ns
- (iv) P/N 9580117110—all S/Ns
- (v) P/N 9580117550—all S/Ns 1499 and below with or without suffix letters and all S/Ns 1500 and above that do not contain the suffix letters EL.

(2) This AD applies only to Turbomeca S.A. Arriel 1E2 turboshaft engines with

tachometer boxes identified in paragraph (c)(1) of this AD that also have installed electrical connectors labeled as P10106, P10098, and P10108; or P11F, P13F, and P15F.

(d) Reason

This AD was prompted by reports of uncommanded in-flight shutdowns (IFSDs). We are issuing this AD to prevent failure of the tachometer box, which could lead to failure of the engine, IFSD, and loss of control of the helicopter.

(e) Actions and Compliance

Comply with this AD within the compliance times specified, unless already done.

(1) Within 1,600 flight hours after the effective date of this AD, remove the affected tachometer box from the engine.

(2) Reserved.

(f) Credit for Previous Action

You may take credit for the action required by paragraph (e) of this AD if you performed the action before the effective date of this AD in accordance with Turbomeca S.A. Mandatory Service Bulletin 292 77 0844, Version A, dated March 4, 2015.

(g) Alternative Methods of Compliance (AMOCs)

The Manager, Engine Certification Office, FAA, may approve AMOCs for this AD. Use the procedures found in 14 CFR 39.19 to make your request. You may email your request to: ANE-AD-AMOC@faa.gov.

(h) Related Information

(1) For more information about this AD, contact Philip Haberen, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7770; fax: 781-238-7199; email: philip.haberen@faa.gov.

(2) Refer to MCAI European Aviation Safety Agency AD 2015-0175, dated August 24, 2015, which includes Mandatory Service Bulletin No. 292 77 0844, Version B, dated July 6, 2015, for related information. You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-4070.

(3) Turbomeca S.A. Mandatory Service Bulletin No. 292 77 0844, Version B, dated July 6, 2015, which is not incorporated by reference in this AD, can be obtained from Turbomeca S.A., using the contact information in paragraph (h)(4) of this AD.

(4) For service information identified in this AD, contact Turbomeca S.A., 40220 Tarnos, France; phone: 33 (0)5 59 74 40 00; fax: 33 (0)5 59 74 45 15.

(5) You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

(i) Material Incorporated by Reference

None.

Issued in Burlington, Massachusetts, on February 16, 2016.

Ann C. Mollica,

Acting Manager, Engine & Propeller Directorate, Aircraft Certification Service.

[FR Doc. 2016-04028 Filed 2-25-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2015-1280; Directorate Identifier 2014-NM-064-AD; Amendment 39-18404; AD 2016-04-10]

RIN 2120-AA64

Airworthiness Directives; ATR—GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain ATR—GIE Avions de Transport Régional Model ATR42-500 airplanes, and Model ATR72-102, -202, -212, and -212A airplanes. This AD was prompted by a report of chafed wires between electrical harnesses. This AD requires inspections for wire discrepancies, and corrective actions if necessary. We are issuing this AD to detect and correct damaged wiring and incorrect installation of the wiring harness and adjacent air ducts that could lead to wire harness chafing and arcing, possibly resulting in an on-board fire.

DATES: This AD becomes effective April 1, 2016.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 1, 2016.

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov/> #!docketDetail;D=FAA-2015-1280 or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC.

For service information identified in this final rule, contact ATR—GIE Avions de Transport Régional, 1, Allée Pierre Nadot, 31712 Blagnac Cedex, France; telephone +33 (0) 5 62 21 62 21; fax +33 (0) 5 62 21 67 18; email continued.airworthiness@atr.fr; Internet

<http://www.aerochain.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-1280.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1137; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain ATR—GIE Avions de Transport Régional Model ATR42-500 airplanes, and Model ATR72-102, -202, -212, and -212A airplanes. The NPRM published in the **Federal Register** on May 12, 2015 (80 FR 27114) (“the NPRM”). The NPRM was prompted by a report of chafed wires between electrical harnesses. The NPRM proposed to require inspections for wire discrepancies, and corrective actions if necessary. We are issuing this AD to detect and correct damaged wiring and incorrect installation of the wiring harness and adjacent air ducts, which could lead to wire harness chafing and arcing, possibly resulting in an on-board fire.

Since the NPRM was issued, the European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2015-0171, dated August 20, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain ATR—GIE Avions de Transport Régional Model ATR42-500 airplanes, and Model ATR72-102, -202, -212, and -212A airplanes. The MCAI states:

An erroneous cockpit indication has been reported on an in-service aeroplane. Subsequent investigation identified chafed wiring between harnesses (2M-2S-6M) and the metallic structure of the cargo lining panel above the electronic rack 90VU shelf. The chafing was most likely the result of incorrect harness installation. In some cases, the bracket, which supports the harnesses, could be incorrectly positioned. Consequently, the wiring harnesses, and in certain configurations, the adjacent air duct, could be incorrectly routed.