

effective date of this AD using the service information identified in paragraph (i)(1)(i) through (i)(1)(xxvi) of this AD. This service information is not incorporated by reference in this AD.

- (i) Airbus Service Bulletin A320-34-1170, Revision 04, dated May 24, 2000.
- (ii) Airbus Service Bulletin A320-34-1170, Revision 05, dated September 11, 2000.
- (iii) Airbus Service Bulletin A320-34-1170, Revision 06, dated October 18, 2001.
- (iv) Airbus Service Bulletin A320-34-1170, Revision 07, dated December 4, 2001.
- (v) Airbus Service Bulletin A320-34-1170, Revision 08, dated January 15, 2003.
- (vi) Airbus Service Bulletin A320-34-1170, Revision 09, dated February 17, 2003.
- (vii) Airbus Service Bulletin A320-34-1170, Revision 10, dated November 21, 2003.
- (viii) Airbus Service Bulletin A320-34-1170, Revision 11, dated August 18, 2004.
- (ix) Airbus Service Bulletin A320-34-1170, Revision 12, dated December 2, 2004.
- (x) Airbus Service Bulletin A320-34-1170, Revision 13, dated January 18, 2005.
- (xi) Airbus Service Bulletin A320-34-1170, Revision 14, dated April 21, 2005.
- (xii) Airbus Service Bulletin A320-34-1170, Revision 15, dated July 19, 2005.
- (xiii) Airbus Service Bulletin A320-34-1170, Revision 16, dated November 23, 2006.
- (xiv) Airbus Service Bulletin A320-34-1170, Revision 17, dated February 14, 2007.
- (xv) Airbus Service Bulletin A320-34-1170, Revision 18, dated October 9, 2009.
- (xvi) Airbus Service Bulletin A320-34-1170, Revision 19, dated November 9, 2009.
- (xvii) Airbus Service Bulletin A320-34-1170, Revision 20, dated December 1, 2010.
- (xviii) Airbus Service Bulletin A320-34-1170, Revision 21, dated March 24, 2011.
- (xix) Airbus Service Bulletin A320-34-1170, Revision 22, dated July 19, 2011.
- (xx) Airbus Service Bulletin A320-34-1170, Revision 23, dated February 3, 2012.
- (xxi) Airbus Service Bulletin A320-34-1170, Revision 24, dated April 12, 2012.
- (xxii) Airbus Service Bulletin A320-34-1170, Revision 25, dated September 4, 2012.
- (xxiii) Airbus Service Bulletin A320-34-1170, Revision 26, dated September 16, 2013.
- (xxiv) Airbus Service Bulletin A320-34-1170, Revision 27, dated March 18, 2014.
- (xxv) Airbus Service Bulletin A320-34-1170, Revision 28, dated September 1, 2014.
- (xxvi) Airbus Service Bulletin A320-34-1170, Revision 29, dated February 16, 2015.

(2) This paragraph provides credit for the replacement of pitot probes on the captain and standby sides specified in paragraph (h)(1) of this AD, if the replacement was performed before the effective date of this AD using Airbus Service Bulletin A320-34-1456, dated December 2, 2009, which is not incorporated by reference in this AD.

(3) This paragraph provides credit for the replacement of pitot probes on the first officer side as specified in paragraph (h)(1) of this AD, if those actions were performed before the effective date of this AD using Airbus Service Bulletin A320-34-1463, dated March 9, 2010, which is not incorporated by reference in this AD.

(j) Parts Installation Limitations

(1) At the applicable time specified in paragraph (j)(1)(i) or (j)(1)(ii) of this AD: No

person may install on any airplane a Thales pitot probe having P/N C16195AA or P/N C16195BA.

(i) For airplanes with a Thales pitot probe having P/N C16195AA or P/N C16195BA installed: After accomplishing the replacement required by paragraph (g) of this AD.

(ii) For airplanes without a Thales pitot probe having P/N C16195AA or P/N C16195BA installed: As of the effective date of this AD.

(2) As of the effective date of this AD, no person may install on any airplane a Thales pitot probe having part number P/N 50620-10.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Sanjay Ralhan, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1405; fax: 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA

Airworthiness Directive 2015-0205, dated October 9, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-0250.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (m)(3) and (m)(4) of this AD.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Service Bulletin A320-34-1170, Revision 30, dated June 18, 2015.

(ii) Airbus Service Bulletin A320-34-1456, Revision 01, dated May 15, 2012.

(iii) Airbus Service Bulletin A320-34-1463, Revision 01, dated May 15, 2012.

(3) For service information identified in this AD, contact Airbus, Airworthiness Office—ELAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; Internet: <http://www.airbus.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 20, 2016.

John P. Piccola, Jr.,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-10215 Filed 5-5-16; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-6149; Directorate Identifier 2016-NM-047-AD; Amendment 39-18510; AD 2016-09-12]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 787-8 and 787-9 airplanes. This AD requires repetitive inspections of the bilge barriers located in the forward and aft cargo compartments for disengaged decompression panels, and reinstalling any disengaged panels. This AD was prompted by several reports of disengaged decompression panels found on in-service airplanes. We are issuing this AD to detect and correct disengaged decompression panels from the bilge barriers located in the forward and aft cargo compartments. In the event of a cargo compartment fire, this condition would provide a path for smoke and Halon to enter the flight compartment and passenger cabin, which could result in the inability to contain and extinguish a fire.

DATES: This AD is effective May 23, 2016.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 23, 2016.

We must receive comments on this AD by June 20, 2016.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6149.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6149; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Caspar Wang, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM-150S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6414; fax: 425-917-6590; email: caspar.wang@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We have received several reports of disengaged decompression panels found on in-service airplanes. It appears these decompression panels disengaged prior to delivery, during test flights. Tests done by the airplane manufacturer revealed some decompression panels disengage at a pressure differential below the design/intended value. This condition, if not corrected, would provide a path for smoke and Halon to enter the flight compartment and passenger cabin in the event of a cargo compartment fire, which could result in the inability to contain and extinguish a fire.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 001, dated November 16, 2015. The service information describes procedures for repetitive inspections of the bilge barriers located in the forward and aft cargo compartments for disengaged decompression panels, and reinstalling any disengaged panels. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination

We are issuing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or

develop in other products of the same type design.

AD Requirements

This AD requires accomplishing the actions specified in the service information described previously.

For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6149.

Interim Action

We consider this AD interim action. The airplane manufacturer is currently developing a modification that will address the unsafe condition identified in this AD. Once this modification is developed, approved, and available, we might consider additional rulemaking.

FAA's Justification and Determination of the Effective Date

An unsafe condition exists that requires the immediate adoption of this AD. The FAA has found that the risk to the flying public justifies waiving notice and comment prior to adoption of this rule because if any decompression panel is disengaged from the bilge barriers located in the forward and aft cargo compartments and a cargo compartment fire were to occur, the fire could not be contained or extinguished. Therefore, we find that notice and opportunity for prior public comment are impracticable and that good cause exists for making this amendment effective in less than 30 days.

Comments Invited

This AD is a final rule that involves requirements affecting flight safety and was not preceded by notice and an opportunity for public comment. However, we invite you to send any written data, views, or arguments about this AD. Send your comments to an address listed under the **ADDRESSES** section. Include the docket number FAA-2016-6149 and Directorate Identifier 2016-NM-047-AD at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this AD. We will consider all comments received by the closing date and may amend this AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this AD.

Costs of Compliance

We estimate that this AD affects 42 airplanes of U.S. registry. We estimate

the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	3 work-hours × \$85 per hour = \$255 per inspection cycle.	\$0	\$255 per inspection cycle	\$10,710 per inspection cycle.

We estimate the following costs to do any necessary reinstallation that would

be required based on the results of the inspection. We have no way of

determining the number of aircraft that might need this action:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Reinstallation	1 work-hour × \$85 per hour = \$85	\$0	\$85

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative,

on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2016-09-12 The Boeing Company:
Amendment 39-18510; Docket No. FAA-2016-6149; Directorate Identifier 2016-NM-047-AD.

(a) Effective Date

This AD is effective May 23, 2016.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 787-8 and 787-9 airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 001, dated November 16, 2015.

(d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

(e) Unsafe Condition

This AD was prompted by several reports of disengaged decompression panels found on in-service airplanes. We are issuing this AD to detect and correct disengaged decompression panels from the bilge barriers located in the forward and aft cargo compartments. In the event of a cargo compartment fire, this condition would provide a path for smoke and Halon to enter the flight compartment and passenger cabin, which could result in the inability to contain and extinguish a fire.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspections

At the applicable time specified in paragraph (g)(1) or (g)(2) of this AD: Do a general visual inspection of the bilge barriers located in the forward and aft cargo compartments for disengaged decompression panels, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 001, dated November 16, 2015. Repeat the inspection thereafter at the applicable times specified in paragraph 5., “Compliance,” of Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 001, dated November 16, 2015.

(1) For Group 1 airplanes identified in Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 001, dated November 16, 2015: Inspect within 30 days after the effective date of this AD.

(2) For Group 2 airplanes identified in Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 001, dated November 16, 2015: Inspect within 180 flight cycles or within 90 days after the effective date of this AD, whichever occurs later.

(h) Reinstallation of Decompression Panels

If any disengaged decompression panel is found during any inspection required by paragraph (g) of this AD: Before further flight, reinstall the panel, in accordance with the

Accomplishment Instructions of Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 001, dated November 16, 2015.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Caspar Wang, Aerospace Engineer, Cabin Safety and Environmental Systems Branch, ANM–150S, FAA, Seattle Aircraft Certification Office (ACO), 1601 Lind Avenue SW., Renton, WA 98057–3356; phone: 425–917–6414; fax: 425–917–6590; email: caspar.wang@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 001, dated November 16, 2015.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H–65, Seattle, WA 98124–2207; telephone 206–544–5000, extension 1; fax 206–766–5680; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on April 25, 2016.

Ross Landes,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–10404 Filed 5–5–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2015–3741; Directorate Identifier 2014–SW–040–AD; Amendment 39–18507; AD 2016–09–09]

RIN 2120–AA64

Airworthiness Directives; Airbus Helicopters (Type Certificate Previously Held by Eurocopter France)

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are superseding airworthiness directive (AD) 2013–08–17 for Airbus Helicopters Model SA–365N, SA–365N1, AS–365N2, AS 365 N3, and SA–366G1 helicopters. AD 2013–08–17 required initial and recurring inspections of the 9-degree fuselage frame for a crack and repairing the frame if a crack exists. This new AD modifies the compliance times and expands the inspection area of the 9-inch frame. The actions of this AD are intended to detect a crack in the 9-degree frame to prevent loss of structural integrity and subsequent loss of control of the helicopter.

DATES: This AD is effective June 10, 2016.

The Director of the Federal Register approved the incorporation by reference

of certain documents listed in this AD as of June 10, 2016.

ADDRESSES: For service information identified in this final rule, contact Airbus Helicopters, Inc., 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641–0000 or (800) 232–0323; fax (972) 641–3775; or at <http://www.airbushelicopters.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–3741.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–3741; or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (EASA) AD, any incorporated-by-reference service information, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (phone: 800–647–5527) is U.S. Department of Transportation, Docket Operations Office, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Robert Grant, Aviation Safety Engineer, Safety Management Group, FAA, 10101 Hillwood Pkwy., Fort Worth, Texas 76177; telephone (817) 222–5110; email robert.grant@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to remove AD 2013–08–17, Amendment 39–17434 (78 FR 25380, May 1, 2013) and add a new AD. AD 2013–08–17 applied to Airbus Helicopters Model SA–365N, SA–365N1, AS–365N2, AS 365 N3, and SA–366G1 helicopters and required initial and recurring inspections of the inner angles and flanges of the 9-degree fuselage frame on the right-hand (RH) and left-hand (LH) sides for a crack. If a crack was found, AD 2013–08–17 required repairing the frame. AD 2013–08–17 was prompted by EASA Emergency AD No. 2010–0064–E, dated April 1, 2010, to correct an unsafe condition for the specified model