

Instructions of Boeing Alert Service Bulletin B787-81205-SB270032-00, Issue 001, dated November 3, 2015. If any discrepant rotary actuator is found, within 60 months after the effective date of this AD, do the actions specified in paragraph (g)(1) or (g)(2) of this AD, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787-81205-SB270032-00, Issue 001, dated November 3, 2015.

(1) Replace the discrepant rotary actuator.

(2) Check the maintenance records to determine the flight cycles of each discrepant rotary actuator and, within 60 months after the effective date of this AD, do all applicable related investigative and corrective actions.

#### (h) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (i)(1) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO to make those findings. For a repair method to be approved, the repair must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (h)(4)(i) and (h)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

#### (i) Related Information

(1) For more information about this AD, contact Fnu Winarto, Aerospace Engineer, Systems and Equipment Branch, ANM-130S, FAA, Seattle ACO, 1601 Lind Avenue SW., Renton, WA 98057-3356; phone: 425-917-6659; fax: 425-917-6590; email: [fnu.winarto@faa.gov](mailto:fnu.winarto@faa.gov).

(2) For service information identified in this AD, contact Boeing Commercial

Airplanes, Attention: Data & Services Management, P.O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone 206-544-5000, extension 1; fax 206-766-5680; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on June 28, 2016.

**John P. Piccola, Jr.,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2016-16323 Filed 7-11-16; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2015-6544; Directorate Identifier 2014-NM-198-AD]

RIN 2120-AA64

#### **Airworthiness Directives; Saab AB, Saab Aeronautics (Formerly Known as Saab AB, Saab Aerosystems) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Supplemental notice of proposed rulemaking (NPRM); reopening of comment period.

**SUMMARY:** We are revising an earlier proposed airworthiness directive (AD) for certain Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) and SAAB 340B airplanes. The NPRM proposed to supersede AD 2012-24-06. AD 2012-24-06 currently requires replacing the stall warning computer (SWC) with a new SWC that provides an artificial stall warning in icing conditions, and modifying the airplane for the replacement of the SWC. The NPRM was prompted by a determination that airplanes with certain modifications were excluded from the applicability in AD 2012-24-06, and are affected by the identified unsafe condition; and the SWC required by AD 2012-24-06 contained erroneous logic. This action revises the NPRM by reducing the compliance time for replacing the SWCs. We are proposing this supplemental NPRM (SNPRM) to prevent natural stall events during operation in icing conditions, which could result in loss of control of the airplane. Since this compliance time reduction imposes an additional burden to operators, we are reopening the comment period to allow the public the

chance to comment on these proposed changes.

**DATES:** We must receive comments on this SNPRM by August 26, 2016.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this SNPRM, contact Saab AB, Saab Aeronautics, SE-581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email [saab340.techsupport@saabgroup.com](mailto:saab340.techsupport@saabgroup.com); Internet <http://www.saabgroup.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-6544; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1112; fax 425-227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments

to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2015–6544; Directorate Identifier 2014–NM–198–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) and SAAB 340B airplanes. The NPRM published in the **Federal Register** on December 17, 2015 (80 FR 78699) (“the NPRM”). The NPRM proposed to supersede AD 2012–24–06, Amendment 39–17276 (77 FR 73279, December 10, 2012) (“AD 2012–24–06”). AD 2012–24–06 currently requires replacing the SWC with a new SWC that provides an artificial stall warning in icing conditions, and modifying the airplane for the replacement of the SWC. The NPRM was prompted by a determination that airplanes with certain modifications were excluded from the applicability in AD 2012–24–06, and are affected by the identified unsafe condition; and the SWC required by AD 2012–24–06 contained erroneous logic. The NPRM proposed to add airplanes to the applicability, and would add requirements to replace the existing SWCs with new, improved SWCs and modify the airplane for the new replacement of the SWC.

### Actions Since Previous NPRM Was Issued

Since we issued the NPRM, we have determined that the compliance time for replacing the SWCs must be reduced to ensure the unsafe condition is addressed prior to the beginning of icing season after publication of the AD. We have determined that parts are available to support the reduced compliance time.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2014–0218, dated September 29, 2014 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct

an unsafe condition on certain Saab AB, Saab Aeronautics Model 340A (SAAB/SF340A) and SAAB 340B airplanes. The MCAI states:

A few natural stall events, specifically when operating in icing conditions, have been experienced on SAAB 340 series aeroplanes, without receiving a prior stall warning.

This condition, if not corrected, could result in loss of control of the aeroplane.

To address this potential unsafe condition, SAAB developed a modified stall warning system, incorporating improved stall warning logic, and issued Service Bulletin (SB) 340–27–098 and SB 340–27–099, providing instructions to replace the Stall Warning Computer (SWC) with a new SWC, and instructions to activate the new SWC. The new system included stall warning curves optimized for operation in icing conditions, which are activated by selection of Engine Anti-Ice.

Consequently, EASA issued AD 2011–0219 [<http://ad.easa.europa.eu/ad/2011-0219>], which corresponds to FAA AD 2012–24–06] to require installation of the improved SWC.

After that [EASA] AD was issued, in-service experience with the improved stall warning system revealed cases of premature stall warning activation during the take-off phase. In numerous recorded cases, the onset of stall warning occurred without the 6 minute delay after weight off wheels.

This condition, if not corrected, could lead to premature stick shaker activation and consequent increase in pilot workload during the take-off phase, possibly resulting in reduced control of the aeroplane.

To correct this unsafe condition, EASA issued AD 2013–0254 [<http://ad.easa.europa.eu/ad/2013-0254>] retaining the requirements of EASA AD 2011–0219, which was superseded, to require deactivation of the ice speed curves in the improved SWC on SAAB 340 aeroplanes, in accordance with SAAB SB 340–27–116.

Since EASA AD 2013–0254 was issued, SAAB developed a technical solution to eliminate the premature activation of the stall warning ice curves and issued SB 340–27–120 (modification of the existing Stall Warning System installation), SB 340–27–121 (activation of improved SWC for aeroplanes with a basic wing tip) and SB 340–27–122 (activation of improved SWC for aeroplanes with an extended wing tip). SAAB SB 340–27–120 provides modification and installation instructions valid for pre- and post-SB 340–27–097, 340–27–098, SB 340–27–099 and SB 340–27–116 aeroplanes. For aeroplanes modified in accordance with SAAB AB mod. No. 2650 and/or mod. No. 2859 which are no longer registered in Canada, SAAB AB issued SAAB AB SB 340–27–109 to provide modification and installation instructions to remove the ice speed curve function.

For the reasons described above, this [EASA] AD retains the requirements of EASA AD 2013–0254, which is superseded, and requires modification of the Stall Warning and Identification System and replacement of the SWC with an improved unit.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2015–6544.

### Related Service Information Under 1 CFR Part 51

Saab AB, Saab Aeronautics has issued the following service information:

- Saab Service Bulletin 340–27–109, dated April 14, 2014.
- Saab Service Bulletin 340–27–116, dated October 18, 2013.
- Saab Service Bulletin 340–27–120, dated July 11, 2014.
- Saab Service Bulletin 340–27–121, dated July 11, 2014.
- Saab Service Bulletin 340–27–122, dated July 11, 2014.

The service information describes procedures for deactivating the stall warning speed curves in the SWCs for certain airplanes; replacing the existing SWCs with new, improved SWCs; and modifying the airplane for the new replacement of the SWC. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

### Comments

We gave the public the opportunity to participate in developing this proposed AD. We considered the comments received.

### Request To Reduce Compliance Time

Saab asked that the compliance time in paragraph (h) of the proposed AD (in the NPRM) for replacement of the SWC be reduced from 12 to 3 months. Saab stated that a global alternative method of compliance (AMOC) was issued by the FAA on September 4, 2014, with a compliance time of 18 months; therefore, operators should have scheduled replacement of the SWCs after the AMOC was issued. Saab also stated that the MCAI required compliance within 18 months after September 29, 2014, and that time has expired. Saab added that reducing the compliance time to 3 months is more in line with the MCAI. In addition, Saab noted that all operators have ordered replacement SWCs, and Saab has those parts in stock and ready for delivery.

We agree with the commenter’s request to reduce the compliance time, for the reasons provided. We also note that reducing the compliance time will ensure that new SWCs are installed before the icing season begins. We have changed the compliance time in paragraph (h) of this proposed AD from 12 to 3 months accordingly.

### Request To Correct Email Address

Saab asked that the Saab email address in the proposed AD (in the NPRM) be corrected to specify the following: *saab340.techsupport@saabgroup.com*.

We agree with the commenter's request. The email address for Model SAAB 2000 airplanes was inadvertently cited in the NPRM. We have corrected the address in the **ADDRESSES** section and in paragraph (l)(2) of this proposed AD.

### Request To Use Later Revisions of Service Information

Silver Airways asked if we could include subsequent revisions of the referenced service information for AD 2012–24–06.

We do not agree with the commenter's request because this proposed AD does not require the service information referenced in AD 2012–24–06. This proposed AD does refer to the latest available service information for the proposed actions. Referring to a specific service bulletin in an AD and using the phrase "or later FAA-approved revisions" violates Office of the Federal Register regulations for approving materials that are incorporated by reference. However, operators may request approval to use a later revision of the referenced service information as an AMOC under the provisions of paragraph (k)(1) of this proposed AD. We have not changed this final rule regarding this issue.

### FAA's Determination and Requirements of This SNPRM

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

Certain changes described above expand the scope of the NPRM. As a result, we have determined that it is necessary to reopen the comment period to provide additional opportunity for the public to comment on this SNPRM.

### Costs of Compliance

We estimate that this SNPRM affects 105 airplanes of U.S. registry.

The actions that are required by AD 2012–24–06, and retained in this SNPRM, take about 78 work-hours per

product, at an average labor rate of \$85 per work-hour. Required parts cost about \$33,000 per product. Based on these figures, the estimated cost of the actions that are required by AD 2012–24–06 is \$39,630 per product.

The new requirement of this SNPRM adds no additional economic burden.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2012–24–06, Amendment 39–17276 (77 FR 73279, December 10, 2012), and adding the following new AD:

**Saab AB, Saab Aeronautics:** Docket No. FAA–2015–6544; Directorate Identifier 2014–NM–198–AD.

#### (a) Comments Due Date

We must receive comments by August 26, 2016.

#### (b) Affected ADs

This AD replaces AD 2012–24–06, Amendment 39–17276 (77 FR 73279, December 10, 2012) ("AD 2012–24–06").

#### (c) Applicability

This AD applies to Saab AB, Saab Aeronautics (formerly known as Saab AB, Saab Aerosystems) Model 340A (SAAB/SF340A) and SAAB 340B airplanes, certificated in any category, as identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Model 340A (SAAB/SF340A) airplanes, serial numbers 004 through 159 inclusive.

(2) Model SAAB 340B airplanes, serial numbers 160 through 459 inclusive, except serial numbers 170, 342, 362, 363, 367, 372, 379, 385, 395, 405, 409, 431, 441, and 455.

#### (d) Subject

Air Transport Association (ATA) of America Code 27, Flight Controls.

#### (e) Reason

This AD was prompted by a determination that airplanes with certain modifications were excluded from the applicability in AD 2012–24–06, and are affected by the identified unsafe condition; and the stall warning computer (SWC) required by AD 2012–24–06 contained erroneous logic. We are issuing this AD to prevent natural stall events during operation in icing conditions, which could result in loss of control of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Deactivation of Stall Speed Curves

For airplanes identified in paragraphs (g)(1) and (g)(2) of this AD: Within 30 days after the effective date of this AD, do the deactivation specified in paragraph (g)(1) or (g)(2) of this AD, as applicable to airplane configuration, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340–27–116, dated October 18, 2013.

(1) For airplanes with a basic wing tip that has been modified using Saab Service Bulletin 340–27–098: Deactivate the stall speed curves in the SWC having part number (P/N) 0020AK6.

(2) For airplanes with an extended wing tip that has been modified using Saab Service Bulletin 340-27-099: Deactivate the stall speed curves in the SWC having P/N 0020AK7.

#### (h) Replacement of SWCs

Within 3 months after the effective date of this AD: Do the replacement specified in paragraph (h)(1) or (h)(2) of this AD, as applicable.

(1) For airplanes with basic wing tips: Replace all SWCs with new, improved SWCs having P/N 0020AK6-1, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340-27-121, dated July 11, 2014.

(2) For airplanes with extended wing tips: Replace all SWCs with new, improved SWCs having P/N 0020AK7-1, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340-27-122, dated July 11, 2014.

#### (i) Concurrent Modification

Before or concurrently with the accomplishment of the applicable requirements of paragraph (h) of this AD, do the actions specified in paragraph (i)(1) or (i)(2) of this AD, as applicable to airplane configuration.

(1) For airplanes on which either Saab AB Mod No. 2650 or Mod No. 2859 is not installed: Modify the stall warning and identification system, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340-27-120, dated July 11, 2014.

(2) For airplanes on which either Saab AB Mod No. 2650 or Mod No. 2859 is installed, or on which both mods are installed: Modify the stall warning and identification system, in accordance with the Accomplishment Instructions of Saab Service Bulletin 340-27-109, dated April 14, 2014.

#### (j) Parts Installation Prohibitions

After the replacement required by paragraph (h) of this AD, no person may install any SWC having P/N 0020AK, 0020AK1, 0020AK2, 0020AK4, 0020AK6, 0020AK7, or 0020AK3 MOD 1, on any airplane.

#### (k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1112; fax 425-227-1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight

standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM-116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Saab AB, Saab Aeronautics' EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (l) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2014-0218, dated September 29, 2014, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2015-6544.

(2) For service information identified in this AD, contact Saab AB, Saab Aeronautics, SE-581 88, Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email [saab340.techsupport@saabgroup.com](mailto:saab340.techsupport@saabgroup.com); Internet <http://www.saabgroup.com>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on June 23, 2016.

#### Dorr M. Anderson,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-15927 Filed 7-11-16; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2016-7426; Directorate Identifier 2015-NM-199-AD]

RIN 2120-AA64

#### Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737-100, -200, and -200C series airplanes. This proposed AD is intended to complete certain mandated programs intended to support the airplane reaching its limit of validity (LOV) of the engineering data that support the established structural maintenance program. This proposed AD would require repetitive detailed,

high frequency eddy current (HFEC), and ultrasonic inspections of the center section rear spar upper clevis lugs and horizontal stabilizer rear spar upper lugs, as applicable, for any cracking, and related investigative and corrective actions if necessary. For certain airplanes, this proposed AD would require replacement of the center section rear spar upper chord with a new part and a serviceable center section assembly. This proposed AD would also require repetitive HFEC and fluorescent dye penetrant inspections of the center section for cracking of the front and rear spar upper clevis lugs or horizontal stabilizer front and rear spar upper lugs, and related investigative and corrective actions if necessary. We are proposing this AD to detect and correct cracking in the rear spar upper clevis lugs of the center section, and in the rear spar upper lugs of the horizontal stabilizer which could result in the loss of structural integrity and controllability of the airplane.

**DATES:** We must receive comments on this proposed AD by August 26, 2016.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Data & Services Management, P. O. Box 3707, MC 2H-65, Seattle, WA 98124-2207; telephone: 206-544-5000, extension 1; fax: 206-766-5680; Internet: <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7426.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for