

household of three by 12 months and rounding the value to the nearest \$5000.

(s) Disqualification for certain convicted felons. An individual shall not be eligible for SNAP benefits if:

(1) The individual is convicted as an adult of:

(i) Aggravated sexual abuse under Section 2241 of Title 18, United States Code;

(ii) Murder under Section 1111 of Title 18, United States Code;

(iii) An offense under Chapter 110 of Title 18, United States Code;

(iv) A Federal or State offense involving sexual assault, as defined in 40002(a) of the Violence Against Women Act of 1994 (42 U.S.C. 13925(a)); or

(v) An offense under State law determined by the Attorney General to be substantially similar to an offense described in clause (i), (ii), or (iii) and

(2) The individual is not in compliance with the terms of the sentence of the individual or the restrictions under § 273.11(n).

(3) The disqualification contained in this subsection shall not apply to a conviction if the conviction is for conduct occurring on or before February 7, 2014.

■ 12. In § 273.12:

■ a. Add paragraph (a)(1)(viii)

■ b. Revise paragraph (a)(4)(iv)

■ c. Revise paragraph (a)(5)(iii)(E); and

■ d. Revise paragraph (a)(5)(vi)(B).

The revisions to read as follows:

§ 273.12 Requirements for Change Reporting Households.

(a) * * *

(1) * * *

(viii) whenever a member of the household wins substantial lottery or gambling winnings in accord with § 273.11(r).

(4) * * *

(iv) *Content of the quarterly report form.* The State agency may include all of the items subject to reporting under paragraph (a)(1) of this section in the quarterly report, except changes reportable under paragraphs (a)(1)(vii) of this section, or may limit the report to specific items while requiring that households report other items through the use of the change report form.

(5) * * *

(iii) * * *

(E) The periodic report form shall be the sole reporting requirement for any information that is required to be reported on the form, except that a household required to report less frequently than quarterly shall report:

(1) when the household monthly gross income exceeds the monthly gross income limit for its household size in

accordance with paragraph (a)(5)(v) of this section;

(2) whenever able-bodied adults subject to the time limit of § 273.24 have their work hours fall below 20 hours per week, averaged monthly, and;

(3) whenever a member of the household wins substantial lottery or gambling winnings in accord with § 273.11(r).

* * * * *

(vi) * * *

(B) * * *

(1) The household has voluntarily requested that its case be closed in accordance with § 273.13(b)(12);

(2) The State agency has information about the household's circumstances considered verified upon receipt;

(3) A household member has been identified as a fleeing felon or probation or parole violator in accord with § 273.11(n);

(4) There has been a change in the household's PA grant, or GA grant in project areas where GA and food stamp cases are jointly processed in accord with § 273.2(j)(2); or

(5) The State agency has verified information (including information considered verified upon receipt) that a member of a SNAP household has won substantial lottery or gambling winnings in accordance with § 273.11(r).

* * * * *

Dated: November 17, 2016.

Audrey Rowe,

Administrator, Food and Nutrition Service.

[FR Doc. 2016-28520 Filed 11-30-16; 8:45 am]

BILLING CODE 3410-30-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-9430; Directorate Identifier 2016-NM-051-AD]

RIN 2120-AA64

Airworthiness Directives; ATR-GIE Avions de Transport Régional Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain ATR-GIE Avions de Transport Régional Model ATR42-500 and Model ATR72-102, -202, -212, and -212A airplanes. This proposed AD was prompted by reports of failure of emergency power

supply units (EPSUs) in production and in service. This proposed AD would require an inspection to determine the part number and serial number of each EPSU, and replacement if necessary. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by January 17, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For ATR service information identified in this NPRM, contact ATR—GIE Avions de Transport Régional, 1, Allée Pierre Nadot, 31712 Blagnac Cedex, France; telephone +33 (0) 5 62 21 62 21; fax +33 (0) 5 62 21 67 18; email continued.airworthiness@atr.fr; Internet <http://www.aerochain.com>.

For COBHAM service information identified in this NPRM, contact COBHAM 174-178 Quai de Jemmapes, 75010, Paris, France; telephone +33 (0) 1 53 38 98 98; fax +33 (0) 1 42 00 67 83.

You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9430; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate,

FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1112; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the

ADDRESSES section. Include “Docket No. FAA-2016-9430; Directorate Identifier 2016-NM-051-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2016-0070, dated April 11, 2016; corrected April 12, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”); to correct an unsafe condition for certain ATR-GIE Avions de Transport Régional

Model ATR42-500 and Model ATR72-102, -202, -212, and -212A airplanes. The MCAI states:

Some failure cases have been reported of emergency power supply units (EPSU), Part Number (P/N) 301-3100 Amdt [Amendment] A, both on the production line and in service. The results of the technical investigations revealed that these failures could have been caused by a defective internal electronic component, which could affect the EPSU internal battery charge.

To address this potential unsafe condition, ATR issued Service Bulletin (SB) ATR42-33-0050 and SB ATR72-33-1043 to provide instructions to inspect EPSUs.

For the reason described above, this [EASA] AD requires identification and replacement of the affected EPSUs with serviceable units.

This [EASA] AD was republished to correct two typographical errors in paragraph (3) of the [EASA] AD and to specify the correct Revision (3) of the Cobham SB 301-3100-33-002.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9430.

Related Service Information Under 1 CFR Part 51

ATR has issued Service Bulletin ATR42-33-0050, Revision 01, dated January 26, 2016; and ATR Service Bulletin ATR72-33-1043, Revision 01, dated January 26, 2016. This service information describes procedures for inspecting an EPSU to determine the

part number, serial number, and amendment level, and replacing the EPSU. These documents are distinct since they apply to different airplane models.

Cobham has issued COBHAM Service Bulletin 301-3100-33-002, Revision 3, dated July 30, 2015, which describes procedures for modifying an EPSU by replacing the printed circuit board.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

Costs of Compliance

We estimate that this proposed AD affects 11 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection	1 work-hour × \$85 per hour = \$85 per EPSU.	\$0	\$85 per EPSU (4 EPSUs per airplane)	\$3,740

We estimate the following costs to do any necessary replacements that would

be required based on the results of the proposed inspection. We have no way of

determining the number of airplanes that might need these replacements:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replacement	1 work-hour × \$85 per hour = \$85 per EPSU	Not available	\$85

According to the manufacturer, some of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for

safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

ATR—GIE Avions de Transport Régional:

Docket No. FAA–2016–9430; Directorate Identifier 2016–NM–051–AD.

(a) Comments Due Date

We must receive comments by January 17, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the ATR—GIE Avions de Transport Régional airplanes, certificated in any category, identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) Model ATR42–500 airplanes, all manufacturer serial numbers (MSNs), except those on which ATR Modification 6780 has been embodied in production.

(2) Model ATR72–102, –202, –212, and –212A airplanes, all MSNs on which ATR Model 3715 has been embodied in production, except those on which ATR Modification 6780 has been embodied in production.

(d) Subject

Air Transport Association (ATA) of America Code 33, Lights.

(e) Reason

This AD was prompted by reports of failure of emergency power supply units (EPSUs) in production and in service. We are issuing this AD to detect and correct defective internal electronic components, which could adversely affect the EPSU internal battery. This condition could result in a partial or total loss of emergency lighting, possibly affecting passenger evacuation during an emergency situation.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection of EPSU and Corrective Action

Within 12 months after the effective date of this AD, inspect each EPSU on the airplane to determine the part number and serial number. For any EPSU having part number (P/N) 301–3100 Amendment (Amdt) A and a serial number identified in figure 1 to paragraph (g) of this AD, and that does not have a control sticker marked with “SIL 301–3100–33–001”: Except as provided by paragraph (i) of this AD, before further flight, replace the EPSU with a serviceable unit, as specified in paragraph (h) of this AD, in accordance with the Accomplishment Instructions of ATR Service Bulletin ATR42–33–0050, Revision 01, dated January 26, 2016; or Service Bulletin ATR72–33–1043, Revision 01, dated January 26, 2016; as applicable. A review of airplane maintenance records may be done in lieu of inspection of the EPSUs on the airplane if the part number and serial number of each EPSU can be positively determined from that review.

FIGURE 1 TO PARAGRAPH (g) OF THIS AD—AFFECTED SERIAL NUMBERS OF EPSU P/N 301–3100 AMDT A

Affected Serial Numbers of EPSU P/N 301–3100 Amdt A

2905	4929	4960	4994	5025	5077	5113	5156
2906	4930	4961	4995	5026	5079	5114	5157
3401	4931	4962	4996	5027	5080	5115	5158
3697	4932	4963	4997	5028	5081	5116	5159
3825	4933	4964	4998	5029	5082	5117	5160
4343	4934	4965	4999	5031	5083	5118	5161
4420	4935	4966	5000	5032	5084	5119	5162
4634	4936	4967	5001	5033	5085	5120	5163
4706	4937	4968	5002	5034	5086	5121	5164
4707	4938	4969	5003	5038	5087	5122	5166
4708	4939	4970	5004	5041	5088	5123	5171
4709	4940	4971	5005	5042	5089	5124	5172
4710	4941	4972	5006	5046	5090	5125	5173
4711	4942	4973	5007	5047	5091	5126	5174
4712	4943	4976	5008	5050	5092	5127	5175
4713	4944	4977	5009	5052	5096	5128	5176
4714	4945	4978	5010	5054	5097	5129	5177
4715	4946	4979	5011	5055	5098	5130	5178
4716	4947	4980	5012	5056	5099	5131	5179
4717	4948	4981	5013	5058	5100	5132	5180
4718	4949	4982	5014	5059	5101	5133	5181
4719	4950	4983	5015	5065	5103	5134	5182
4720	4951	4984	5016	5067	5104	5135	5183
4721	4952	4985	5017	5068	5105	5136	5184
4722	4953	4986	5018	5069	5106	5138	5185
4723	4954	4987	5019	5070	5107	5139	5186
4724	4955	4988	5020	5071	5108	5140	5187

FIGURE 1 TO PARAGRAPH (g) OF THIS AD—AFFECTED SERIAL NUMBERS OF EPSU P/N 301–3100 AMDT A—Continued

4745	4956	4989	5021	5072	5109	5147	None
4926	4957	4990	5022	5073	5110	5153	None
4927	4958	4991	5023	5075	5111	5154	None
4928	4959	4993	5024	5076	5112	5155	None

(h) Definition of Serviceable EPSU

For the purpose of this AD, a serviceable EPSU is one that meets the criteria in paragraph (h)(1), (h)(2), or (h)(3) of this AD.

(1) Has P/N 301–3100 Amtd A and a serial number that is not included figure 1 to paragraph (g) of this AD.

(2) Has P/N 301–3100 Amtd A, a serial number that is included in figure 1 to paragraph (g) of this AD, but has a control sticker marked with “SIL 301–3100–33–001.”

(3) Has P/N 301–3100 Amtd B, or later amendment.

(i) Alternative Modification of Affected EPSU

In lieu of the replacement required by paragraph (g) of this AD, modification of an affected EPSU may be done in accordance with the Accomplishment Instructions of COBHAM Service Bulletin 301–3100–33–002, Revision 3, dated July 30, 2015.

(j) Parts Installation Prohibition

As of the effective date of this AD, no person may install on any airplane any EPSU having P/N 301–3100 Amtd A and a serial number identified in figure 1 to paragraph (g) of this AD, unless it has a control sticker marked with “SIL 301–3100–33–001”.

(k) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using the service information identified in paragraph (k)(1) or (k)(2) of this AD, provided it can be determined that no EPSU having a serial number listed in figure 1 to paragraph (g) of this AD has been installed on that airplane since the actions in the applicable service bulletin were completed.

(1) ATR Service Bulletin ATR42–33–0050, dated December 11, 2015.

(2) ATR Service Bulletin ATR72–33–1043, dated December 11, 2015.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1112; fax 425–227–1149. Information may be emailed to: 9-ANM-116-

AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or ATR—GIE Avions de Transport Régional’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2016–0070, dated April 11, 2016; corrected April 12, 2016; for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9430.

(2) For ATR service information identified in this AD, contact ATR—GIE Avions de Transport Régional, 1, Allée Pierre Nadot, 31712 Blagnac Cedex, France; telephone +33 (0) 5 62 21 62 21; fax +33 (0) 5 62 21 67 18; email continued.airworthiness@atr.fr; Internet <http://www.aerochain.com>. For Cobham service information identified in this AD, contact COBHAM 174–178 Quai de Jemmapes, 75010, Paris, France; telephone +33 (0) 1 53 38 98 98; fax +33 (0) 1 42 00 67 83. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on November 17, 2016.

Phil Forde,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016–28618 Filed 11–30–16; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA–2014–0363; Directorate Identifier 2014–NE–08–AD]

RIN 2120–AA64

Airworthiness Directives; Rolls-Royce plc Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to supersede airworthiness directive (AD) 2015–17–19 that applies to all Rolls-Royce plc (RR) RB211 Trent 768–60, 772–60, and 772B–60 turbofan engines. AD 2015–17–19 requires inspection of the fan case low-pressure (LP) fuel tubes and associated clips and the fuel oil heat exchanger (FÔHE) mounts and associated hardware. Since we issued AD 2015–17–19, fractures on the LP fuel return tube at mid-span locations were found with resulting fuel leaks. This proposed AD would require a modification, which terminates the repetitive inspections. We are proposing this AD to prevent failure of the fan case LP fuel tubes, which could lead to an in-flight shutdown, loss of thrust control, and damage to the airplane.

DATES: We must receive comments on this proposed AD by January 30, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Rolls-Royce plc, Corporate Communications, P.O. Box 31, Derby, England, DE248BJ; phone: