

(e) *Delay fee.* If, in the judgment of SBA, the time required to complete your examination is delayed due to your lack of cooperation or the condition of your records, SBA may assess an additional fee of \$700 per day. Beginning on October 1, 2021, SBA will annually adjust this fee using the Inflation Adjustment and will publish a Notice prior to such adjustment in the **Federal Register** identifying the amount of the fee.

Dated: November 17, 2016.

**Maria Contreras-Sweet,**  
Administrator.

[FR Doc. 2016-30104 Filed 12-15-16; 8:45 am]

BILLING CODE 8025-01-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2016-9438; Directorate Identifier 2016-NM-109-AD]

RIN 2120-AA64

#### Airworthiness Directives; Bombardier, Inc. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Bombardier, Inc. Model DHC-8-400 series airplanes. This proposed AD was prompted by reports of interruptions in the airstair door operation. This proposed AD would require repetitive inspections and modification of the handrail hardware. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by January 30, 2017.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., Q-

Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416-375-4000; fax 416-375-4539; email [thd.qseries@aero.bombardier.com](mailto:thd.qseries@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9438; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Cesar A. Gomez, Aerospace Engineer, Airframe and Mechanical Systems Branch, ANE-171, FAA, New York Aircraft Certification Office (ACO), 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7318; fax 516-794-5531.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2016-9438; Directorate Identifier 2016-NM-109-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF-2015-02, dated January 27, 2015 (referred to after

this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Bombardier, Inc. Model DHC-8-400, -401, and -402 airplanes. The MCAI states:

A number of airstair door operation interruptions have been reported. In one case, the airstair door could not be opened. It was found that the airstair door handrail holder bracket was deformed and became lodged into the adjacent wardrobe bulkhead, which prevented the door from opening.

On airstair doors with Jetway Compatible option, a deformed handrail holder bracket or a failure of the pin retainer bracket can interfere with the operation of the airstair door and prevent it from opening.

The airstair door is classified as an emergency exit. The inability to open an emergency exit could impede evacuation in the event of an emergency.

This [Canadian] AD mandates the repetitive inspection of airstair door handrail hardware, and the modification of the handrail stowage hardware.

Required actions include applicable corrective actions (replacing or removing brackets, installing lanyards, adjusting pins, and adjusting affected parts of the assembly). You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9438.

#### Related Service Information Under 14 CFR Part 51

We reviewed Bombardier Service Bulletin 84-52-79, Revision C, dated February 2, 2016. This service information describes procedures for a general visual inspection to detect deformities and cracks of the forward and aft handle holder brackets on the airstair handrail; a detailed visual inspection of the forward and aft pin retainer brackets for the condition of the lanyards and the pins; a check for unobstructed movement of the pin retainer brackets; and rework of the airstair door handrail to prevent damage to the bulkhead and to prevent the door from jamming once the handrails are stowed. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified

of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe

condition exists and is likely to exist or develop on other products of the same type design.

**Costs of Compliance**

We estimate that this proposed AD affects 82 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Repetitive Inspections ...	1 work-hour × \$85 per hour = \$85 per inspection cycle.	\$0	\$85 per inspection cycle.	\$6,970 per inspection cycle.
Modification .....	3 work-hours × \$85 per hour = \$255 .....	1,556	\$1,811 .....	\$148,502.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities

under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Bombardier, Inc.:** Docket No. FAA–2016–9438; Directorate Identifier 2016–NM–109–AD.

**(a) Comments Due Date**

We must receive comments by January 30, 2017.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to Bombardier, Inc. Model DHC–8–400, –401, and –402 airplanes, certificated in any category, serial numbers 4001 through 4473 inclusive, equipped with Jetway Compatible Passenger Airstair Door Modsum 4–422100 or Modsum 4–458687.

**(d) Subject**

Air Transport Association (ATA) of America Code 52, Doors.

**(e) Reason**

This AD was prompted by reports of interruptions in the airstair door operation, including one case where the door would not open. The airstair door is classified as an emergency exit. We are issuing this AD to ensure the ability to evacuate passengers through the airstair door in the event of an emergency.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Repetitive Inspections of the Forward and Aft Handle Holder Brackets and Forward and Aft Pin Retainer Brackets, Repetitive Checks, and Corrective Actions**

Within 600 flight hours after the effective date of this AD, perform a general visual inspection of the forward and aft handle holder brackets for damage, such as visible cracks and deformation; a detailed visual inspection of the forward and aft pin retainer brackets to make sure that both lanyards are installed and to make sure that the head of each pin is installed correctly; a check of the pin retainer brackets for unobstructed movement; an operational check of the forward passenger door; and all applicable corrective actions; in accordance with PART A1 and PART A2 of the Accomplishment Instructions of Bombardier Service Bulletin 84–52–79, Revision C, dated February 2, 2016, except as required by paragraphs (g)(1), (g)(2), and (g)(3) of this AD. Do all applicable corrective actions before further flight. Repeat the inspections and checks thereafter at intervals not to exceed 600 flight hours until the terminating action required by paragraph (h) of this AD is accomplished.

(1) If one or both lanyards are missing, before further flight, install lanyards as specified in, and in accordance with PART A1 of the Accomplishment Instructions of Bombardier Service Bulletin 84–52–79, Revision C, dated February 2, 2016.

(2) If a pin is not installed correctly, as specified in PART A1 of the Accomplishment Instructions of Bombardier Service Bulletin 84–52–79, Revision C, dated February 2, 2016, before further flight, adjust the affected pin until it is installed correctly as specified in, and in accordance with PART A1 of the Accomplishment Instructions of Bombardier Service Bulletin 84–52–79, Revision C, dated February 2, 2016.

(3) If a pin retainer bracket does not rotate freely, before further flight, adjust affected parts of the assembly until the pin retainer bracket rotates freely as specified in, and in accordance with PART A1 of the Accomplishment Instructions of Bombardier Service Bulletin 84–52–79, Revision C, dated February 2, 2016.

**(h) Terminating Action**

Within 6,000 flight hours or 36 months, whichever occurs first, after the effective date

of this AD: Incorporate ModSum 4–903234 to modify installed Jetway Compatible Handrail Stowage Bracket, in accordance with PART A3 of the Accomplishment Instructions of Bombardier Service Bulletin 84–52–79, Revision C, dated February 2, 2016. Incorporating ModSum 4–903234 terminates the actions required by paragraph (g) of this AD.

#### (i) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using the service information identified in paragraph (i)(1), (i)(2), or (i)(3) of this AD.

(1) Bombardier Service Bulletin 84–52–79, dated May 1, 2014.

(2) Bombardier Service Bulletin 84–52–79, Revision A, dated November 18, 2014.

(3) Bombardier Service Bulletin 84–52–79, Revision B, dated April 8, 2015.

#### (j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York Aircraft Certification Office (ACO), ANE–170, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7300; fax 516–794–5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO, ANE–170, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

#### (k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF–2015–02, dated January 27, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9438.

(2) For service information identified in this NPRM, contact Bombardier, Inc., Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; telephone 416–375–4000; fax 416–375–4539; email [thd.qseries@aero.bombardier.com](mailto:thd.qseries@aero.bombardier.com); Internet <http://www.bombardier.com>. You may view this referenced service information at the FAA,

Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on December 2, 2016.

**Michael Kaszycki**,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2016–29671 Filed 12–15–16; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA–2016–9498; Directorate Identifier 2016–NM–105–AD]**

**RIN 2120–AA64**

#### Airworthiness Directives; Airbus Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all Airbus Model A321 series airplanes. This proposed AD was prompted by a determination from fatigue testing on the Model A321 airframe that cracks could develop in the cabin floor beam junction at certain fuselage frame locations. This proposed AD would require repetitive inspections for cracking in the cabin floor beam junction at certain fuselage frame locations, and repair if necessary. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by January 30, 2017.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac

Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); Internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9498; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Sanjay Ralhan, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone 425–227–1405; fax 425–227–1149.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2016–9498; Directorate Identifier 2016–NM–105–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2016–0105, dated June 6, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe