

installed, where “XX” is any two alphanumeric characters, certificated in any category.

(b) Unsafe Condition

This AD defines the unsafe condition as detachment of the angle section of an IGB and subsequent interference between an IGB fairing and tail rotor inclined drive shaft. This condition could result in failure of a tail rotor drive shaft, loss of the tail rotor drive, and subsequent loss of control of the helicopter.

(c) Comments Due Date

We must receive comments by March 6, 2017.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

(1) Within 15 hours time-in-service (TIS) and thereafter at intervals not to exceed 15 hours TIS, visually inspect the IGB fairing and the left- and right-hand attachment supports for a crack as shown in Figure 2 of Airbus Helicopters Emergency Alert Service Bulletin (EASB) No. 53.01.47, Revision 5, dated March 5, 2015 (EASB No. 53.01.47) or EASB No. 53A001, Revision 5, dated March 5, 2015 (EASB No. 53A001), as appropriate for your model helicopter.

(i) If there is a crack in an attachment support, replace the attachment support.

(ii) If there is a crack in the fairing, replace the IGB fairing with IGB fairing P/N 332A24-0322-00 in accordance with the Accomplishment Instructions, paragraph 3.B.2, of Airbus Helicopters Service Bulletin No. AS332-53.01.78, Revision 0, dated March 9, 2015 (SB No. AS332-53.01.78) or Service Bulletin No. EC225-53-041, Revision 0, dated March 9, 2015 (SB No. EC225-53-041), as appropriate for your model helicopter.

(2) For helicopters with IGB fairing P/N 332A24-0303-05XX or P/N 332A24-0303-06XX, within 15 hours TIS and thereafter at intervals not to exceed 15 hours TIS, visually inspect for a crack in the fairing gutter as shown in Figure 1 of EASB No. 53.01.47 or EASB No. 53A001. If there is a crack in the fairing gutter:

(i) Inspect for interference and separation of the fairing gutter. If there is any interference between the gutter and the tail rotor inclined drive shaft tube, replace the tail rotor inclined drive shaft tube. If there is any interference between the gutter and a hydraulic pipe, repair or replace the hydraulic pipe. If there is any interference between the gutter and the flight controls, repair the flight controls in accordance with FAA-approved procedures. If there is any separation of the gutter, remove the gutter.

(ii) Replace the IGB fairing with IGB fairing P/N 332A24-0322-00 in accordance with the Accomplishment Instructions, paragraph 3.B.2, of SB No. AS332-53.01.78 or SB No. EC225-53-041.

(3) Within 150 hours TIS, replace the IGB fairing P/N 332A24-0303-05XX, 332A24-0303-06XX, 332A08-1391-00, or 332A08-

1391-01 with IGB fairing P/N 332A24-0322-00 in accordance with the Accomplishment Instructions, paragraph 3.B.2, of SB No. AS332-53.01.78 or SB No. EC225-53-041.

(4) Replacing the IGB fairing with IGB fairing P/N 332A24-0322-00 is terminating action for the repetitive inspections required by this AD.

(5) Do not install an IGB fairing P/N 332A24-0303-05XX, P/N 332A24-0303-06XX, P/N 332A08-1391-00, or P/N 332A08-1391-01 on any helicopter.

(f) Credit for Actions Previously Completed

Compliance with Airbus Helicopters Emergency Alert Service Bulletin No. 53.01.47, Revision 4, dated September 27, 2011, before the effective date of this AD is considered acceptable for compliance with the initial inspections specified in paragraphs (e)(1) and (e)(2) of this AD, but does not constitute terminating action for the repetitive inspections required by this AD.

(g) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: David Hatfield, Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5116; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(h) Additional Information

The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2015-0092, dated May 26, 2015. You may view the EASA AD on the Internet at <http://www.regulations.gov> in the AD Docket.

(i) Subject

Joint Aircraft Service Component (JASC) Code: 5350 Aerodynamic Fairings.

Issued in Fort Worth, Texas, on December 21, 2016.

Lance T. Gant,

Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 2016-31866 Filed 1-4-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-9566; Directorate Identifier 2016-NM-191-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model 757-200, -200PF, and -200CB series airplanes. This proposed AD was prompted by an evaluation by the design approval holder (DAH) indicating that certain fuselage circumferential splice plates are subject to widespread fatigue damage (WFD). This proposed AD would require repetitive low frequency eddy current (LFEC) inspections for cracks of certain circumferential splice plates, and repairs if necessary. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by February 21, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the internet at <http://www.regulations.gov> by searching for

and locating Docket No. FAA–2016–9566.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9566; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Eric Schrieber, Aerospace Engineer, Airframe Branch, ANM–120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5348; fax: 562–627–5210; email: eric.schrieber@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2016–9566; Directorate Identifier 2016–NM–191–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

Fatigue damage can occur locally, in small areas or structural design details, or globally, in widespread areas. Multiple-site damage is widespread damage that occurs in a large structural element such as a single rivet line of a lap splice joining two large skin panels. Widespread damage can also occur in multiple elements such as adjacent frames or stringers. Multiple-site damage and multiple-element damage cracks are typically too small initially to be reliably detected with normal inspection methods. Without

intervention, these cracks will grow, and eventually compromise the structural integrity of the airplane. This condition is known as widespread fatigue damage. It is associated with general degradation of large areas of structure with similar structural details and stress levels. As an airplane ages, WFD will likely occur, and will certainly occur if the airplane is operated long enough without any intervention.

The FAA’s WFD final rule (75 FR 69746, November 15, 2010) became effective on January 14, 2011. The WFD rule requires certain actions to prevent structural failure due to WFD throughout the operational life of certain existing transport category airplanes and all of these airplanes that will be certificated in the future. For existing and future airplanes subject to the WFD rule, the rule requires that DAHs establish a limit of validity (LOV) of the engineering data that support the structural maintenance program. Operators affected by the WFD rule may not fly an airplane beyond its LOV, unless an extended LOV is approved.

The WFD rule (75 FR 69746, November 15, 2010) does not require identifying and developing maintenance actions if the DAHs can show that such actions are not necessary to prevent WFD before the airplane reaches the LOV. Many LOVs, however, do depend on accomplishment of future maintenance actions. As stated in the WFD rule, any maintenance actions necessary to reach the LOV will be mandated by airworthiness directives through separate rulemaking actions.

In the context of WFD, this action is necessary to enable DAHs to propose LOVs that allow operators the longest operational lives for their airplanes, and still ensure that WFD will not occur. This approach allows for an implementation strategy that provides flexibility to DAHs in determining the timing of service information development (with FAA approval), while providing operators with certainty regarding the LOV applicable to their airplanes.

We have received a report indicating that the fuselage circumferential splice plates along the center fastener rows, forward and aft of station 900 and station 1180 splice centerlines, are susceptible to WFD. There have been no reports of cracking on airplanes in service. Inspections will mitigate a safety issue, allowing continued operation to the limit of validity. This condition, if not corrected, could result in failure of a principle structural element, which could adversely impact the structural integrity of the airplane.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Alert Service Bulletin 757–53A0105, dated June 10, 2016. The service information describes procedures for repetitive LFEC inspections and repairs of the circumferential splice plates at station 900 and station 1180, from stringer S–6L to stringer S–6R, for any cracks. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under “Differences Between this Proposed AD and the Service Information.” For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9566.

The phrase “corrective actions” is used in this proposed AD. Corrective actions correct or address any condition found. Corrective actions in an AD could include, for example, repairs.

Differences Between This Proposed AD and the Service Information

Boeing Alert Service Bulletin 757–53A0105, dated June 10, 2016, specifies to contact the manufacturer for certain instructions, but this proposed AD would require using repair methods, modification deviations, and alteration deviations in one of the following ways:

- In accordance with a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) whom we have authorized to make those findings.

Costs of Compliance

We estimate that this proposed AD affects 634 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
LFEC inspection	6 work-hours × \$85 per hour = \$510 per inspection cycle.	\$0	\$510 per inspection cycle	\$323,340 per inspection cycle.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

The Boeing Company: Docket No. FAA–2016–9566; Directorate Identifier 2016–NM–191–AD.

(a) Comments Due Date

We must receive comments by February 21, 2017.

(b) Affected ADs

This AD affects AD 2006–11–11, Amendment 39–14615 (71 FR 30278, May 26, 2006) ("AD 2006–11–11").

(c) Applicability

This AD applies to all The Boeing Company Model 757–200, –200PF, and –200CB series airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Unsafe Condition

This AD was prompted by an evaluation by the design approval holder (DAH) indicating that the fuselage circumferential splice plates along the center fastener rows, forward and aft of station 900 and station 1180 splice centerlines, are subject to widespread fatigue damage (WFD). We are issuing this AD to detect and correct any such cracks, which could lead to the failure of a principal structural element and consequently adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Low Frequency Eddy Current (LFEC) Inspections and Corrective Actions

At the applicable time specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757–53A0105, dated June 10, 2016, except as required by

paragraph (h)(1) of this AD: Do an LFEC inspection for cracking of the circumferential splice plates at station 900 and station 1180, from stringer S–6L to stringer S–6R, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 757–53A0105, dated June 10, 2016, except as required by paragraph (h)(2) of this AD. Do all applicable corrective actions before further flight. Repeat the inspections thereafter at the applicable times specified in paragraph 1.E., "Compliance," of Boeing Alert Service Bulletin 757–53A0105, dated June 10, 2016. Accomplishing these inspections terminates the requirements of paragraph (h) of AD 2006–11–11 for the inspections of structurally significant item (SSI) 53–40–05, circumferential skin splice body station BS900 stringer S–6L to stringer S–6R and circumferential skin splice body station BS1180 stringer S–6L to stringer S–6R, as specified in Section 9 of Boeing Maintenance Planning Data (MPD) Document D622N001–9, May 2003 or June 2005 revisions. All other provisions of AD 2006–11–11 remain fully applicable and must be complied with.

(h) Service Information Exceptions

(1) Where Boeing Alert Service Bulletin 757–53A0105, dated June 10, 2016, specifies a compliance time "after the original issue date of this service bulletin," this AD requires compliance within the specified compliance time after the effective date of this AD.

(2) Where Boeing Alert Service Bulletin 757–53A0105, dated June 10, 2016, specifies to contact Boeing for repair instructions, and specifies that action as Required for Compliance (RC), this AD requires repair using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (h) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

(1) For more information about this AD, contact Eric Schrieber, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5348; fax: 562-627-5210; email: eric.schrieber@faa.gov.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Issued in Renton, Washington, on December 22, 2016.

Robert D. Breneman,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2016-31619 Filed 1-4-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-9405; Directorate Identifier 2016-NE-22-AD]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney Division Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Pratt & Whitney Division (PW) PW2037, PW2037M, and PW2040 turbofan engines. This proposed AD was prompted by an unrecoverable engine in-flight shutdown (IFSD) after an ice crystal icing event. This proposed AD would require installing a software standard eligible for installation and preclude the use of electronic engine control (EEC) software standards earlier than SCN 5B/I. We are proposing this AD to correct the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by February 21, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

• *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Pratt & Whitney Division, 400 Main St., East Hartford, CT 06118; phone: 800-565-0140; fax: 860-565-5442. You may view this service information at the FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA. For information on the availability of this material at the FAA, call 781-238-7125.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9405; or in person at the Docket

Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Kevin Clark, Aerospace Engineer, Engine Certification Office, FAA, Engine & Propeller Directorate, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7088; fax: 781-238-7199; email: kevin.m.clark@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this NPRM. Send your comments to an address listed under the section. Include "Docket No. FAA-2016-9405; Directorate Identifier 2016-NE-22-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

We propose to adopt an AD for certain PW PW2037, PW2037M, and PW2040 turbofan engines with EEC, model number EEC104-40 or EEC104-60, installed with an EEC software standard earlier than SCN 5B/I. This proposed AD was prompted by a report of an unrecoverable engine IFSD after an ice crystal icing event. The root cause of the event is ice crystal icing causing the engine to flameout. An attempt to restart the engine was made while the active clearance control was on, which caused damage to the HPT and rotor seizure. This condition, if not corrected, could result in failure of the HPT, rotor seizure, failure of one or more engines, loss of thrust control, and loss of the airplane.

Related Service Information Under 1 CFR Part 51

We reviewed PW Alert Service Bulletin (ASB) PW2000 A73-170, dated July 14, 2016. The ASB describes