

in ADAMS under Accession No. ML16355A092.

The NRC changed the title of this rulemaking activity from “Role of Third Parties in Access Authorization and Fitness-for-Duty Determinations” to “Access Authorization and Fitness-for-Duty Determinations.”

II. Public Meeting

The public meeting will be on February 13, 2017, from 1:00 p.m. to 4:00 p.m. (EST) in the Commission Hearing Room, 11555 Rockville Pike, Rockville, Maryland 20852. Interested stakeholders may attend in person or via teleconference and Webinar. The purpose of the meeting is to provide background information on this rulemaking activity and obtain stakeholder input in order to enhance the NRC’s understanding of the associated issues. The NRC staff will use this input to inform its determination of what action, if any, the agency should take to address the issue of third party participation in licensee access authorization and fitness-for-duty determinations. The NRC staff will discuss the various opportunities for the public to participate in the rulemaking process. The NRC will not provide formal written responses to the oral comments made at this meeting. In addition, the NRC is not providing an opportunity to submit written public comments in connection with this meeting.

Information for the teleconference and Webinar is available in the meeting notice, which can be accessed through the NRC’s public Web site at: <http://meetings.nrc.gov/pmns/mtg>. Participants must register at the Internet link in the meeting notice to participate in the Webinar.

Additional details regarding the meeting will be posted at least 10 days prior to the public meeting on the NRC’s public meeting Web site at: <http://meetings.nrc.gov/pmns/mtg>.

Dated at Rockville, Maryland, this 31st day of January 2017.

For the Nuclear Regulatory Commission.

Louise Lund,

*Director, Division of Policy and Rulemaking,
Office of Nuclear Reactor Regulation.*

[FR Doc. 2017-02515 Filed 2-6-17; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0051; Directorate Identifier 2016-CE-043-AD]

RIN 2120-AA64

Airworthiness Directives; DG Flugzeugbau GmbH

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for DG Flugzeugbau GmbH Model DG-500MB gliders that are equipped with a Solo 2625 02 engine modified with a fuel injection system following the instructions of Solo Kleinmotoren GmbH Service Bulletin (SB)/Technische Mitteilung (TM) 4600-3 “Fuel Injection System”) and identified as Solo 2625 02i. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as the potential of an in-flight shut-down and engine fire due to failure of the connecting stud for the two fuel injector mounts of the engine redundancy system on gliders equipped with a Solo 2625 02i engine. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by March 24, 2017.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Solo Kleinmotoren GmbH, Postfach 600152, 71050 Sindelfingen, Germany;

telephone: +49 703 1301-0; fax: +49 703 1301-136; email: aircraft@solo-germany.com; Internet: <http://aircraft.solo-online.com>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0051; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aerospace Engineer, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2017-0051; Directorate Identifier 2016-CE-043-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD No.: 2014-0269, dated December 11, 2014 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

An occurrence was reported involving a failure of the connecting stud for the two fuel injector mounts of the engine redundancy system.

This condition, if not corrected, could lead to an uncommanded in-flight engine shut-down and engine fire, possibly resulting in loss of control of the aeroplane.

To address this unsafe condition, Solo Kleinmotoren GmbH issued SB/TM 4600–5 to provide instructions for reinforcement and securing of the injector mounts.

For the reason described above, this AD requires modification of the engine redundancy system.

Solo Kleinmotoren GmbH SB/TM 4600–3 (currently at issue 2, dated 03 December 2012) will be revised to incorporate the modification required by SB/TM 4600–5 for future Solo 2625 02i engines.

You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0051.

Related Service Information Under 1 CFR Part 51

Solo Kleinmotoren GmbH has issued Technische Mitteilung (English translation: Service Bulletin), Nr. 4600–5, Ausgabe 2 (English translation: Issue 2), dated December 12, 2014. The service information describes procedures for changing the fuel injector mounts of the engine redundancy system and securing the connection of the lower to the upper mount. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section of this NPRM.

FAA's Determination and Requirements of the Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with this State of Design Authority, they have notified us of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all information and determined the unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD will affect 3 products of U.S. registry. We also estimate that it would take about 1 work-hour per product to comply with the basic requirements of this proposed AD. The average labor rate is \$85 per work-hour. Required parts would cost about \$67 per product.

Based on these figures, we estimate the cost of the proposed AD on U.S. operators to be \$456, or \$152 per product.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new AD:

DG Flugzeugbau GmbH: Docket No. FAA–2017–0051; Directorate Identifier 2016–CE–043–AD.

(a) Comments Due Date

We must receive comments by March 24, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to DG Flugzeugbau GmbH DG–500MB gliders, all serial numbers, that are:

- (1) Equipped with a Solo 2625 02 engine modified with a fuel injection system following the instructions of Solo Kleinmotoren GmbH Service Bulletin (SB)/ Technische Mitteilung (TM) 4600–3 "Fuel Injection System"; and
- (2) certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 72: Engine.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as failure of the connecting stud for the two fuel injector mounts of the engine redundancy system on gliders equipped with a Solo 2625 02i engine. We are issuing this AD to prevent such failure that could lead to the potential of an in-flight shut-down and engine fire and result in loss of control.

(f) Actions and Compliance

Unless already done, within the next 60 days after the effective date of this AD, modify the engine redundancy system following the actions in Solo Kleinmotoren GmbH Technische Mitteilung (English translation: Service Bulletin), Nr. 4600–5, Ausgabe 2 (English translation: Issue 2), dated December 12, 2014.

Note 1 to paragraph (f) of this AD: This service information contains German to English translation. The EASA used the English translation in referencing the document. For enforceability purposes, we will refer to the Solo Kleinmotoren service information as it appears on the document.

(g) Credit for Actions Accomplished in Accordance With Previous Service Information

This AD allows credit for modification of the engine redundancy system as required in

paragraph (f) of this AD if done before the effective date of this AD following Solo Kleinmotoren GmbH Technische Mitteilung (English translation: Service Bulletin), Nr. 4600-5, Ausgabe 1 (English translation: Issue 1), dated November 24, 2014.

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Jim Rutherford, Aerospace Engineer, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Airworthy Product*: For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(i) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2014-0269, dated December 11, 2014 for related information. You may examine the MCAI on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0051. For service information related to this AD, contact Solo Kleinmotoren GmbH, Postfach 600152, 71050 Sindelfingen, Germany; telephone: +49 703 1301-0; fax: +49 703 1301-136; email: aircraft@solo-germany.com; Internet: <http://aircraft.solo-online.com>. You may review this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on January 18, 2017.

Melvin Johnson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-01779 Filed 2-6-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0048; Directorate Identifier 2016-CE-035-AD]

RIN 2120-AA64

Airworthiness Directives; Slingsby Aviation Ltd. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Slingsby Aviation Ltd. Models T67M260 and T67M260-T3A airplanes that would supersede AD 2015-11-01. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as failure of a brake master cylinder pivot pin, which could cause the rudder pedal mechanism to detach from the brake cylinder. We are issuing this proposed AD to require actions to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by March 24, 2017.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Marshall Aerospace and Defence Group, The Airport, Newmarket Road, Cambridge, CB5 8RX, UK; telephone: +44 (0) 1223 399856; fax: +44 (0) 7825365617; email: mark.bright@marshalladg.com; Internet: www.marshalladg.com. You may review copies of the referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the

availability of this material at the FAA, call (816) 329-4148.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0048; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Jim Rutherford, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2017-0048; Directorate Identifier 2016-CE-035-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

On May 18, 2015, we issued AD 2015-11-01, Amendment 39-18164 (80 FR 30136; May 27, 2015). That AD required actions intended to address an unsafe condition on Slingsby Aviation Ltd. Models T67M260 and T67M260-T3A airplanes and was based on mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country.

Since we issued AD 2015-11-01, new service information was issued to revise the inspection instructions and to add a new initial inspection period after