

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2016-7415; Directorate Identifier 2015-SW-076-AD; Amendment 39-18786; AD 2017-02-07]

RIN 2120-AA64

**Airworthiness Directives; Airbus Helicopters Deutschland GmbH Helicopters**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for Airbus Helicopters Deutschland GmbH (Airbus Helicopters) Model MBB-BK 117 C-2 and MBB-BK 117 D-2 helicopters. This AD requires inspections and a torque of certain attachment points. This AD was prompted by a design reassessment. These actions are intended to prevent an unsafe condition on these products.

**DATES:** This AD is effective March 17, 2017.

The Director of the Federal Register approved the incorporation by reference of certain documents listed in this AD as of March 17, 2017.

**ADDRESSES:** For service information identified in this final rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7415.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-7415; or in person at the Docket Operations Office between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the European Aviation Safety Agency (EASA) ADs, any incorporated-by-reference service information, the economic evaluation, any comments received, and other information. The street address for the Docket Operations Office (phone: 800-647-5527) is U.S. Department of

Transportation, Docket Operations Office, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate, FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email [matthew.fuller@faa.gov](mailto:matthew.fuller@faa.gov).

**SUPPLEMENTARY INFORMATION:**

**Discussion**

On June 21, 2016, at 81 FR 40203, the **Federal Register** published our notice of proposed rulemaking (NPRM), which proposed to amend 14 CFR part 39 by adding an AD that would apply to Airbus Helicopters Model MBB-BK 117 C-2 and MBB-BK 117 D-2 helicopters with a hydraulic module plate assembly part number B291M0003103 with a single locking attachment point (attachment point) installed. The NPRM proposed to require performing repetitive visual inspections of each attachment point of the hydraulic module plate assembly for a crack and proper installation and a one-time torque of the nuts of each attachment point. The proposed requirements were intended to prevent failure of an attachment point, which could result in loss of the hydraulic module plate and subsequent loss of control of the helicopter.

The NPRM was prompted by AD No. 2015-0210R1, Revision 1, dated October 28, 2015, issued by EASA, which is the Technical Agent for the Member States of the European Union, to correct an unsafe condition for the Airbus Helicopters Model MBB-BK117 C-2, MBB-BK117 C-2e, MBB-BK117 D-2, and MBB-BK117 D-2m helicopters. EASA advises that the hydraulic plate assembly on certain MBB-BK117 models has four attachment points on the fuselage secured by a single locking mechanism. According to EASA, a design reassessment revealed stiffness of the hydraulic plate may be insufficient to withstand the in-service loads in the event one of the four single locking attachment points fails. EASA states that if this condition is not detected and corrected, it may lead to loss of the hydraulic module plate and possible loss of control of the helicopter. Therefore, the EASA AD requires a repetitive inspection and one-time torque tightening of the attachment points in accordance with Airbus Helicopters' service information. EASA considers its AD an interim action and states further AD action may follow.

After we issued the NPRM, EASA revised its AD and issued EASA AD No. 2015-0210R2, Revision 2, dated December 2, 2016. AD 2015-0210R2 reduces the applicability by serial number to exclude helicopters with an improved hydraulic module plate installation that is not subject to the unsafe condition.

**Comments**

After our NPRM was published, we received comments from one commenter.

**Request**

Airbus Helicopters requested revising the statements regarding what prompted this AD action and the intended effects of this AD action to more accurately describe the unsafe condition. Specifically, the commenter requested we state the design assessment showed that in case of a failure of a single attachment point, the stiffness of the hydraulic plate installation may be insufficient to withstand the in-service loads.

We agree. We have revised this statement in the Discussion paragraph of this Final Rule.

The commenter also requested that in our statement of what the proposed actions are intended to prevent, we change "subsequent loss of control of the helicopter" to "possible loss of control of the helicopter."

We disagree. This AD states the unsafe condition "could result" in loss of the hydraulic module plate and subsequent loss of control of the helicopter. This language indicates that loss of control of the helicopter is a possibility. Thus, the requested change is unnecessary.

**FAA's Determination**

These helicopters have been approved by the aviation authority of Germany and are approved for operation in the United States. Pursuant to our bilateral agreement with Germany, EASA, its technical representative, has notified us of the unsafe condition described in the EASA AD. We are issuing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed except for the change to the Applicability section previously described. This change is consistent with the intent of the proposals in the NPRM and will not increase the economic burden on any operator nor increase the scope of this AD.

### Differences Between This AD and the EASA AD

The EASA AD requires contacting Airbus Helicopters customer support when replacing affected parts, and this AD does not.

### Related Service Information Under 1 CFR Part 51

We reviewed Airbus Helicopters Alert Service Bulletin (ASB) No. ASB MBB-BK117 C-2-29A-003 for Model MBB-BK 117 C-2 helicopters and Airbus Helicopters ASB No. ASB MBB-BK117 D-2-29A-001 for Model MBB-BK 117 D-2 helicopters, both Revision 0, and both dated October 12, 2015. This service information specifies a repetitive visual inspection for condition and correct installation of the attachment points, and if there is a crack, replacing the affected parts and contacting Airbus Helicopters customer support. This service information also specifies a tightening torque check after the initial inspection and, if torque cannot be applied, replacing the affected parts and contacting Airbus Helicopters customer support.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

### Other Related Service Information

We also reviewed Airbus Helicopters ASB No. ASB MBB-BK117 C-2-29A-003 for Model MBB-BK 117 C-2 helicopters and Airbus Helicopters ASB No. ASB MBB-BK117 D-2-29A-001 for Model MBB-BK 117 D-2 helicopters, both Revision 1 and both dated October 14, 2016. This service information specifies the same repetitive visual inspection for condition and correct installation of the attachment points except it reduces the applicability by serial number due to the introduction of a new locking design.

### Costs of Compliance

We estimate that this AD affects 134 helicopters of U.S. Registry. We estimate that operators may incur the following costs in order to comply with this AD. We estimate the cost of labor at \$85 per work-hour. Visually inspecting the four attachment points will take about 0.75 work-hour for an estimated cost of \$64 per helicopter and \$8,576 for the U.S. fleet per inspection cycle. Inspecting the torque of the four attachment points will take about 0.25 work-hour for an estimated cost of \$21 per helicopter and \$2,814 for the U.S. fleet. Replacing any of the attachment point parts will take a minimal amount of time and parts will cost about \$48 per attachment point.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on helicopters identified in this rulemaking action.

### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866;
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
- (3) Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this AD and placed it in the AD docket.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

#### 2017-02-07 Airbus Helicopters

**Deutschland GmbH:** Amendment 39-18786; Docket No. FAA-2016-7415; Directorate Identifier 2015-SW-076-AD.

#### (a) Applicability

This AD applies to Model MBB-BK 117 C-2 helicopters, serial numbers up to and including 9750, and Model MBB-BK 117 D-2 helicopters, serial numbers up to and including 20110, with a hydraulic module plate assembly part number B291M0003103 with a single locking attachment point installed, certificated in any category.

#### (b) Unsafe Condition

This AD defines the unsafe condition as failure of a hydraulic module plate assembly attachment point (attachment point). This condition could result in loss of the hydraulic module plate and subsequent loss of control of the helicopter.

#### (c) Effective Date

This AD becomes effective March 17, 2017.

#### (d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

#### (e) Required Actions

- (1) Within 100 hours time-in-service (TIS):
  - (i) Visually inspect the split pins, castellated nuts, plugs, nuts, and hexagon bolts of each attachment point for a crack and for proper installation by following the Accomplishment Instructions, paragraphs 3.B.1.2.a. through 3.B.1.2.e., of Airbus Helicopters Alert Service Bulletin (ASB) No. ASB MBB-BK117 C-2-29A-003, Revision 0, dated October 12, 2015 (ASB MBB-BK117 C-2-29A-003), or Airbus Helicopters ASB No. ASB MBB-BK117 D-2-29A-001, Revision 0, dated October 12, 2015 (ASB MBB-BK117 D-2-29A-001), as applicable to your model helicopter. Replace any part that has a crack before further flight. If the split pins, castellated nuts, or hexagon bolts are not as depicted in Figure 2 of ASB MBB-BK117 C-2-29A-003 or ASB MBB-BK117 D-2-29A-001, before further flight, properly install them.
  - (ii) Apply a torque of 9 to 10 Nm to the left-hand and right-hand nuts of each attachment point. If a torque of 9 to 10 Nm cannot be applied, replace the affected nut before further flight.
- (2) Thereafter, at intervals not to exceed 400 hours TIS, perform the inspection in paragraph (e)(1)(i) of this AD.

#### (f) Alternative Methods of Compliance (AMOCs)

- (1) The Manager, Safety Management Group, FAA, may approve AMOCs for this AD. Send your proposal to: Matt Fuller, Senior Aviation Safety Engineer, Safety Management Group, Rotorcraft Directorate,

FAA, 10101 Hillwood Pkwy, Fort Worth, TX 76177; telephone (817) 222-5110; email [9-ASW-FTW-AMOC-Requests@faa.gov](mailto:9-ASW-FTW-AMOC-Requests@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office, before operating any aircraft complying with this AD through an AMOC.

#### (g) Additional Information

(1) Airbus Helicopters Alert Service Bulletin (ASB) No. ASB MBB-BK117 C-2-29A-003 and Airbus Helicopters ASB No. ASB MBB-BK117 D-2-29A-001, both Revision 1, and both dated October 14, 2016, which are not incorporated by reference, contain additional information about the subject of this final rule. For service information identified in this final rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>. You may review a copy of the service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2015-0210R1, Revision 1, dated October 28, 2015, and EASA AD No. 2015-0210R2, Revision 2, dated December 2, 2016. You may view the EASA ADs on the Internet at <http://www.regulations.gov> in Docket No. FAA-2016-7415.

#### (h) Subject

Joint Aircraft Service Component (JASC) Code: 2900, Hydraulic Power System.

#### (i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Airbus Helicopters Alert Service Bulletin No. ASB MBB-BK117 C-2-29A-003, Revision 0, dated October 12, 2015.

(ii) Airbus Helicopters Alert Service Bulletin No. ASB MBB-BK117 D-2-29A-001, Revision 0, dated October 12, 2015.

(3) For Airbus Helicopters service information identified in this AD, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at <http://www.airbushelicopters.com/techpub>.

(4) You may view this service information at FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177. For information on the availability of this material at the FAA, call (817) 222-5110.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on

the availability of this material at NARA, call (202) 741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Fort Worth, Texas, on January 18, 2017.

**Lance T. Gant,**

*Manager, Rotorcraft Directorate, Aircraft Certification Service.*

[FR Doc. 2017-01772 Filed 2-9-17; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 97

[Docket No. 31118; Amdt. No. 3733]

#### Standard Instrument Approach Procedures, and Takeoff Minimums and Obstacle Departure Procedures; Miscellaneous Amendments

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This rule establishes, amends, suspends, or removes Standard Instrument Approach Procedures (SIAPs) and associated Takeoff Minimums and Obstacle Departure Procedures (ODPs) for operations at certain airports. These regulatory actions are needed because of the adoption of new or revised criteria, or because of changes occurring in the National Airspace System, such as the commissioning of new navigational facilities, adding new obstacles, or changing air traffic requirements. These changes are designed to provide safe and efficient use of the navigable airspace and to promote safe flight operations under instrument flight rules at the affected airports.

**DATES:** This rule is effective February 10, 2017. The compliance date for each SIAP, associated Takeoff Minimums, and ODP is specified in the amendatory provisions.

The incorporation by reference of certain publications listed in the regulations is approved by the Director of the Federal Register as of February 10, 2017.

**ADDRESSES:** Availability of matters incorporated by reference in the amendment is as follows:

#### For Examination

1. U.S. Department of Transportation, Docket Ops-M30, 1200 New Jersey Avenue SE., West Bldg., Ground Floor, Washington, DC 20590-0001.

2. The FAA Air Traffic Organization Service Area in which the affected airport is located;

3. The office of Aeronautical Navigation Products, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 or,

4. The National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: [http://www.archives.gov/federal-register/code\\_of\\_federal\\_regulations/ibr\\_locations.html](http://www.archives.gov/federal-register/code_of_federal_regulations/ibr_locations.html).

#### Availability

All SIAPs and Takeoff Minimums and ODPs are available online free of charge. Visit the National Flight Data Center at [nfdc.faa.gov](http://nfdc.faa.gov) to register. Additionally, individual SIAP and Takeoff Minimums and ODP copies may be obtained from the FAA Air Traffic Organization Service Area in which the affected airport is located.

#### FOR FURTHER INFORMATION CONTACT:

Thomas J. Nichols, Flight Procedure Standards Branch (AFS-420), Flight Technologies and Programs Divisions, Flight Standards Service, Federal Aviation Administration, Mike Monroney Aeronautical Center, 6500 South MacArthur Blvd., Oklahoma City, OK 73169 (Mail Address: P.O. Box 25082, Oklahoma City, OK 73125) Telephone: (405) 954-4164.

**SUPPLEMENTARY INFORMATION:** This rule amends Title 14 of the Code of Federal Regulations, Part 97 (14 CFR part 97), by establishing, amending, suspending, or removes SIAPs, Takeoff Minimums and/or ODPS. The complete regulatory description of each SIAP and its associated Takeoff Minimums or ODP for an identified airport is listed on FAA form documents which are incorporated by reference in this amendment under 5 U.S.C. 552(a), 1 CFR part 51, and 14 CFR part § 97.20. The applicable FAA forms are FAA Forms 8260-3, 8260-4, 8260-5, 8260-15A, and 8260-15B when required by an entry on 8260-15A.

The large number of SIAPs, Takeoff Minimums and ODPs, their complex nature, and the need for a special format make publication in the **Federal Register** expensive and impractical. Further, airmen do not use the regulatory text of the SIAPs, Takeoff Minimums or ODPs, but instead refer to their graphic depiction on charts printed by publishers of aeronautical materials. Thus, the advantages of incorporation by reference are realized and publication of the complete description of each SIAP, Takeoff Minimums and ODP listed on FAA form documents is unnecessary. This