

**(i) Special Flight Permit**

Special flight permits, as described in Section 21.197 and Section 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199), are not allowed.

**(j) Paperwork Reduction Act Burden Statement**

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

**(k) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Wichita Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (l) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(l) Related Information**

For more information about this AD, contact Craig Henrichsen, Aerospace Engineer, Electrical Systems and Avionics, ACE-119W, FAA, Wichita ACO, 1801 Airport Road, Room 100, Dwight D. Eisenhower Airport, Wichita, KS 67209; phone: 316-946-4110; fax: 316-946-4107; email: [Wichita-COS@faa.gov](mailto:Wichita-COS@faa.gov).

**(m) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Textron Aviation Service Letter SL560XL-24-07, including Attachment, dated January 13, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Textron Aviation Inc., P.O. Box 7706, Wichita, KS 67277; telephone 316-

517-6215; fax 316-517-5802; email [citationpubs@txtav.com](mailto:citationpubs@txtav.com); Internet <https://support.cessna.com/custsupt/csuptsupport/newlogin.jsp>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 9, 2017.

**Michael Kaszycki,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2017-03363 Filed 2-21-17; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2016-9186; Directorate Identifier 2015-NM-160-AD; Amendment 39-18799; AD 2017-04-04]**

**RIN 2120-AA64**

**Airworthiness Directives; BAE Systems (Operations) Limited**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are superseding Airworthiness Directive (AD) 2012-16-08 for certain BAE Systems (Operations) Limited Model BAe 146 and Avro 146-RJ series airplanes. AD 2012-16-08 required repetitive inspections for bulging, surface anomalies, and cracking of the fuselage skin adjacent to the discharge valves, and repair and application of additional sealant in the affected area if necessary. This new AD retains the requirements of AD 2012-16-08, expands the applicability, and requires an additional one-time inspection for the presence of water traps/air driers to determine which airplanes must be inspected. This AD was prompted by reports of cracking and surface anomalies of the fuselage skin at the water trap/air drier unit of the forward discharge valve due to corrosion, and the determination that airplanes on which a certain auto-pressurization modification was incorporated during production were excluded from the applicability of AD

2012-16-08, but are also affected by this condition. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective March 29, 2017.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of March 29, 2017.

The Director of the Federal Register approved the incorporation by reference of certain other publications listed in this AD as of September 18, 2012 (77 FR 48420, August 14, 2012).

**ADDRESSES:** For service information identified in this final rule, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email [RAPublications@baesystems.com](mailto:RAPublications@baesystems.com); Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9186.

**Examining the AD Docket**

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9186; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Theodore Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1175; fax 425-227-1149.

**SUPPLEMENTARY INFORMATION:****Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR

part 39 to supersede AD 2012–16–08, Amendment 39–17155 (77 FR 48420, August 14, 2012) (“AD 2012–16–08”). AD 2012–16–08 applied to certain BAE Systems (Operations) Limited Model BAe 146 and Avro 146–RJ series airplanes. The NPRM published in the **Federal Register** on October 20, 2016 (81 FR 72557). The NPRM was prompted by reports of cracking and surface anomalies of the fuselage skin at the water trap/air drier unit of the forward discharge valve due to corrosion, and the determination that airplanes on which auto-pressurization modification No. HCM50259A was incorporated during production were excluded from the applicability of AD 2012–16–08, but are also affected by this condition. The NPRM proposed to continue to require repetitive detailed inspections for bulging, surface anomalies, and cracking of the fuselage skin adjacent to the discharge valves, and repair and application of additional sealant in the affected area if necessary. The NPRM also proposed to expand the applicability, and require an additional one-time inspection for the presence of water traps/air driers to determine which airplanes must be inspected. We are issuing this AD to detect and correct bulging, surface anomalies, and cracking that could propagate towards the forward discharge valve outlet and result in the failure of the fuselage skin, leading to a possible sudden loss of cabin pressure and injury to occupants.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2015–0180, dated August 28, 2015 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all BAE Systems (Operations) Limited Model BAe 146 series airplanes and Model Avro 146–RJ series airplanes. The MCAI states:

An operator reported finding cracking and surface anomalies (bulges and/or dents) of the fuselage skin at the water trap/air drier unit of the forward discharge valve, located between fuselage frame (FR) 22 and FR23 and between stringers 22 and 23. Further investigation established that these surface anomalies were due to corrosion beneath the water trap/air drier unit that has resulted in cracking of the fuselage skin

This condition, if not detected and corrected, could lead to failure of the fuselage skin, possibly resulting in loss of cabin pressure and injury to occupants.

To address this potential unsafe condition, EASA issued AD 2011–0099 [which corresponds to FAA AD 2012–16–08] to require repetitive detailed visual inspections (DVI) of the fuselage skin adjacent to the front and rear discharge valves to check for

bulging, surface anomalies and cracking, and depending on findings, accomplishment of applicable corrective action(s), and the application of additional sealant in the affected area.

Since that [EASA] AD was issued, it was found that aeroplanes that have incorporated auto-pressurisation modification No. HCM50259A during production, which were excluded from the Applicability, were also affected by this condition.

In addition, and in order to simplify instructions for applicability, BAE Systems (Operations) Limited issued Revision 4 of Inspection Service Bulletin (ISB) No. 21–162, introducing a one-time inspection to identify if water trap/air driers are installed.

For the reasons described above, this [EASA] AD retains the requirements of EASA AD 2011–0099, which is superseded, expands the Applicability and requires the additional one-time inspection as specified in the latest ISB revision.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9186.

#### Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

#### Conclusion

We reviewed the available data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

#### Related Service Information Under 1 CFR Part 51

BAE Systems (Operations) Limited has issued BAE Systems (Operations) Limited Inspection Service Bulletin ISB.21–162, Revision 4, dated January 28, 2015. The service information describes procedures for a visual inspection of the internal fuselage at the location of the water trap/air driers to determine if water trap/air driers are installed; an external detailed visual inspection for bulging, surface anomalies, and cracking of the fuselage skin adjacent to the forward and rear discharge valve outlets; repair; and sealant application.

BAE Systems (Operations) Limited has also issued the following service information, which describes procedures for structural repairs. These

documents are distinct since they apply to different airplane models.

- Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146–RJ Series Structural Repair Manual for Series 100–200, Revision 68, dated October 15, 2014.

- Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146–RJ Series Structural Repair Manual for Series 300, Revision 46, dated October 15, 2014.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### Costs of Compliance

We estimate that this AD affects 4 airplanes of U.S. registry.

The actions required by AD 2012–16–08 and retained in this AD take about 8 work-hours per product, at an average labor rate of \$85 per work-hour. Based on these figures, the estimated cost of the actions that are required by AD 2012–16–08 is \$680 per product.

We also estimate that it will take about 8 work-hours per product to comply with the basic requirements of this AD. The average labor rate is \$85 per work-hour. Based on these figures, we estimate the cost of this AD on U.S. operators to be \$2,720, or \$680 per product.

We have received no definitive data that will enable us to provide cost estimates for the on-condition actions specified in this AD.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, Section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

## Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

## List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

## Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2012–16–08, Amendment 39–17155 (77 FR 48420, August 14, 2012), and adding the following new AD:

#### 2017–04–04 BAE Systems (Operations)

**Limited:** Amendment 39–18799; Docket No. FAA–2016–9186; Directorate Identifier 2015–NM–160–AD.

#### (a) Effective Date

This AD is effective March 29, 2017.

#### (b) Affected ADs

This AD replaces AD 2012–16–08, Amendment 39–17155 (77 FR 48420, August 14, 2012) (“AD 2012–16–08”).

#### (c) Applicability

This AD applies to the airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category, all serial numbers.

(1) BAE Systems (Operations) Limited Model BAe 146–100A, –200A, and –300A airplanes.

(2) BAE Systems (Operations) Limited Model Avro 146–RJ70A, 146–RJ85A, and 146–RJ100A airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 21, Air Conditioning.

#### (e) Reason

This AD was prompted by reports of cracking and surface anomalies of the fuselage skin at the water trap/air drier unit of the forward discharge valve due to corrosion, and the determination that airplanes on which auto-pressurization modification No. HCM50259A was incorporated during production were excluded from the applicability of AD 2012–16–08, but are also affected by this condition. We are issuing this AD to detect and correct bulging, surface anomalies, and cracking that could propagate towards the forward discharge valve outlet and result in the failure of the fuselage skin, leading to a possible sudden loss of cabin pressure and injury to occupants.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Retained Detailed Inspection of External Fuselage Skin, With Specific Delegation Approval Language

This paragraph restates the requirements of paragraph (g) of AD 2012–16–08, with specific delegation approval language. For all airplanes except airplanes that have incorporated auto-pressurization modification HCM50259A during production: Within 12 months after September 18, 2012 (the effective date of AD 2012–16–08), do a detailed inspection to check for bulging, surface anomalies, and cracking of the fuselage skin adjacent to the discharge valve outlets (one frame fore and aft, one stringer above and below), in accordance with the Accomplishment Instructions of BAE Systems (Operations) Limited Inspection Service Bulletin ISB.21–162, Revision 1, dated September 16, 2010. Repeat the inspection thereafter at intervals not to exceed 24 months.

(1) If any bulging, surface anomalies, or cracking of the fuselage skin is found to be within the criteria defined in Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146–RJ Series Structural Repair Manual for Series 100–200, Revision 66, dated October 15, 2011 (for Model 146–100A and –200A, and Avro 146–RJ70A and 146–RJ85A airplanes); or Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146–RJ Series Structural Repair Manual for Series 300, Revision 44, dated October 15, 2011 (for Model 146–300A and Avro 146–RJ100A airplanes): Before further flight, repair the damage, in accordance with the Accomplishment Instructions specified in BAE Systems (Operations) Limited Inspection Service Bulletin ISB.21–162, Revision 1, dated September 16, 2010.

(2) If any bulging, surface anomalies, or cracking of the fuselage skin is found exceeding the criteria as specified by Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146–RJ Series Structural Repair Manual for Series 100–200, Revision 66, dated October 15, 2011 (for Model 146–100A and –200A, and Avro 146–RJ70A and 146–RJ85A airplanes); or Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146/AVRO 146–RJ Series Structural Repair Manual for Series 300, Revision 44, dated October 15, 2011 (for Model 146–300A and Avro 146–RJ100A airplanes): Before further flight, repair the condition according to a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or BAE Systems (Operations) Limited’s EASA Design Organization Approval (DOA).

#### (h) Retained Application of Sealant, With No Changes

This paragraph restates the requirements of paragraph (h) of AD 2012–16–08, with no changes. For all airplanes except airplanes on which auto-pressurization modification HCM50259A was incorporated during production: Within 24 months after September 18, 2012 (the effective date of AD 2012–16–08), unless a repair has already been accomplished in accordance with paragraph (g) of this AD, apply additional PR1422A–2 or PR1764B–2 edge sealant between the water trap/air drier and the fuselage skin, in accordance with the Accomplishment Instructions of BAE Systems (Operations) Limited Inspection Service Bulletin ISB.21–162, Revision 1, dated September 16, 2010. Application of additional sealant does not constitute terminating action for the repetitive detailed inspections required by paragraph (g) of this AD. Accomplishment of a repair as required by paragraph (g) of this AD terminates the repetitive inspection requirements of paragraph (g) of this AD.

#### (i) New Requirement of This AD: Inspection for Water Traps/Air Driers

Within 12 months after the effective date of this AD, inspect the airplane to determine whether water traps/air driers are installed, in accordance with paragraph 2.C of BAE Systems (Operations) Limited Inspection Service Bulletin ISB.21–162, Revision 4, dated January 28, 2015 (“ISB.21–162 R4”). If there are no water traps/air driers installed on an airplane, then no further inspections are required by this AD, except as required by paragraph (n) of this AD.

#### (j) New Requirement of This AD: Repetitive Inspections

For airplanes that have water traps/air driers installed, determined as required by paragraph (i) of this AD: Within 12 months after the effective date of this AD, accomplish a detailed visual inspection for bulging, surface anomalies, and cracking of the external fuselage skin adjacent to the discharge valve outlets (one frame bay fore and aft, one stringer above and below), in

accordance with the Accomplishment Instructions of paragraph 2.C. of ISB.21–162 R4. Repeat the inspection of the external fuselage skin adjacent to the discharge valve outlets thereafter at intervals not to exceed 24 months. Accomplishing an inspection required by this paragraph terminates the inspections required by paragraph (g) of this AD.

**(k) New Requirement of This AD: Corrective Actions**

If, during any detailed visual inspection required by paragraph (j) of this AD, any bulging, surface anomalies, or cracking is found, before further flight, accomplish the applicable corrective action as specified in paragraphs (k)(1) and (k)(2) this AD.

(1) If any bulging, surface anomalies, or cracking is found to be within the criteria as specified in the applicable service information specified in paragraph (k)(1)(i) or (k)(1)(ii) of this AD, before further flight, repair in accordance with the Accomplishment Instructions of paragraph 2.G. of ISB.21–162 R4.

(i) For Model BAe 146–100A and –200A airplanes, and Model Avro 146–RJ70A and 146–RJ85A airplanes: Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146–RJ Series Structural Repair Manual for Series 100–200, Revision 68, dated October 15, 2014.

(ii) For Model BAe 146–300A airplanes and Model Avro 146–RJ100A airplanes: Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146–RJ Series Structural Repair Manual for Series 300, Revision 46, dated October 15, 2014.

(2) If any bulging, surface anomalies, or cracking is found exceeding the criteria as specified in the applicable service information specified in paragraph (k)(1)(i) or (k)(1)(ii) of this AD, before further flight, repair using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or EASA; or BAE Systems (Operations) Limited’s EASA DOA.

**(l) New Requirement of This AD: Application of Sealant**

Within 24 months after the effective date of this AD, unless a repair has already been accomplished as required by paragraph (k) of this AD, apply additional sealant, in accordance with the Accomplishment Instructions of paragraph 2.C.(3) of ISB.21–162 R4. Application of additional sealant on an airplane does not constitute terminating action for the repetitive inspections required by paragraph (j) of this AD for that airplane.

**(m) New Terminating Action for Inspections Required by Paragraph (i) of This AD**

Accomplishment of a repair on the forward (FWD) or aft (AFT) position as required by paragraph (k) of this AD constitutes terminating action for the repetitive inspections required by paragraph (j) of this AD for that FWD or AFT position.

**(n) New Requirement of This AD: Actions for Airplanes on Which Water Trap/Air Driers Are Installed After the Effective Date**

For airplanes that do not have water traps/air driers installed, determined as required by paragraph (i) of this AD: If water traps/air driers are installed in service after the effective date of this AD, accomplish the actions required by paragraphs (j), (k), and (l) of this AD on that airplane within the applicable compliance times specified in paragraphs (j), (k), and (l) of this AD; except where paragraphs (j) and (l) of this AD refer to “the effective date of this AD,” this AD requires compliance within the specified compliance time after the installation of water traps/air driers.

**(o) Credit for Previous Actions**

(1) This paragraph provides credit for inspections and sealant applications required by paragraphs (g) and (h) of this AD, if those actions were performed before September 18, 2012 (the effective date of AD 2012–16–08), using BAE SYSTEMS (OPERATIONS) LIMITED Inspection Service Bulletin ISB.21–162, dated June 7, 2010.

(2) This paragraph provides credit for using criteria defined in the following subject of the applicable structural repair manual, as required by paragraphs (g)(1) and (g)(2) of this AD, if those criteria were used before September 18, 2012 (the effective date of AD 2012–16–08), using Subject 53–00–00, “Fuselage, General—Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146–RJ Series Structural Repair Manual for Series 100–200, Revision 65, dated September 15, 2010 (for Model 146–100A and –200A, and Avro 146–RJ70A and 146–RJ85A airplanes); or Subject 53–00–00, “Fuselage, General—Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146–RJ Series Structural Repair Manual for Series 300, Revision 43, dated September 15, 2010 (for Model 146–300A and Avro 146–RJ100A airplanes).

(3) This paragraph provides credit for actions required by paragraphs (i), (j), and (l) of this AD, if those actions were performed before the effective date of this AD using any of the service information specified in paragraphs (o)(3)(i) through (o)(3)(iv) of this AD.

(i) BAE Systems (Operations) Limited Inspection Service Bulletin ISB.21–162, dated June 7, 2010.

(ii) BAE Systems (Operations) Limited Inspection Service Bulletin ISB.21–162, Revision 1, dated September 16, 2010, which was incorporated by reference in AD 2012–16–08.

(iii) BAE Systems (Operations) Limited Inspection Service Bulletin ISB.21–162, Revision 2, dated December 12, 2012.

(iv) BAE Systems (Operations) Limited Inspection Service Bulletin ISB.21–162, Revision 3, dated January 15, 2013.

**(p) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane

Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Theodore Thompson, Aerospace Engineer, telephone 425–227–1175; fax 425–227–1149. Information may be emailed to: 9–ANM–116–AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: As of the effective date of this AD, for any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or EASA; or BAE Systems (Operations) Limited’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

**(q) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2015–0180, dated August 28, 2015, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9186.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (r)(5) and (r)(6) of this AD.

**(r) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on March 29, 2017.

(i) BAE Systems (Operations) Limited Inspection Service Bulletin ISB.21–162, Revision 4, dated January 28, 2015.

(ii) Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146 RJ Series Structural Repair Manual for Series 100–200, Revision 68, dated October 15, 2014.

(iii) Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of the BAE SYSTEMS BAe 146 Series/AVRO 146–RJ Series Structural Repair Manual for Series 300, Revision 46, dated October 15, 2014.

(4) The following service information was approved for IBR on September 18, 2012.

(i) BAE SYSTEMS (OPERATIONS) LIMITED Inspection Service Bulletin ISB.21–162, Revision 1, dated September 16, 2010.

(ii) Subject 53–00–00, “Fuselage, General Description,” of Chapter 53, “Fuselage,” of

the BAE SYSTEMS BAe 146 Series/AVRO 146-RJ Series Structural Repair Manual for Series 100-200, Revision 66, dated October 15, 2011. The revision level of this document is specified only in the Letter of Transmittal.

(iii) Subject 53-00-00, "Fuselage, General Description," of Chapter 53, "Fuselage," of the BAE SYSTEMS BAe 146 Series/AVRO 146-RJ Series Structural Repair Manual for Series 300, Revision 44, dated October 15, 2011. The revision level of this document is specified only in the Letter of Transmittal.

(5) For service information identified in this AD, contact BAE Systems (Operations) Limited, Customer Information Department, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland, United Kingdom; telephone +44 1292 675207; fax +44 1292 675704; email [RAPublications@baesystems.com](mailto:RAPublications@baesystems.com); Internet <http://www.baesystems.com/Businesses/RegionalAircraft/index.htm>.

(6) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on January 23, 2017.

**Dionne Palermo,**

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 2017-03022 Filed 2-21-17; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2016-9049; Directorate Identifier 2016-NM-039-AD; Amendment 39-18807; AD 2017-04-12]

RIN 2120-AA64

#### Airworthiness Directives; Empresa Brasileira de Aeronautica S.A. (Embraer) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Empresa Brasileira de Aeronautica S.A. (Embraer) Model EMB-135BJ, EMB-135ER, EMB-135KE, EMB-135KL, EMB-135LR, EMB-145, EMB-145EP, EMB-145ER, EMB-145LR, EMB-145MP, EMB-145MR, and EMB-145XR airplanes. This AD was prompted by

reports of main airspeed indication discrepancies during flight; these discrepancies resulted from ice blockages in certain pitot total pressure lines. This AD requires an inspection for tube misalignment of the pitot number 1 and pitot number 2 tube assembly lines, and corrective actions if necessary; installation or replacement (as applicable) of a tube ribbon heater on the pitot number 1 and pitot number 2 tube assembly lines; and revision of the airplane flight manual (AFM) to provide certain procedures and airspeed tables for the flightcrew. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective March 29, 2017.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of March 29, 2017.

**ADDRESSES:** For service information identified in this final rule, contact Empresa Brasileira de Aeronautica S.A. (Embraer), Technical Publications Section (PC 060), Av. Brigadeiro Faria Lima, 2170-Putim-12227-901 São Jose dos Campos-SP-Brasil; telephone +55 12 3927-5852 or +55 12 3309-0732; fax +55 12 3927-7546; email [distrib@embraer.com.br](mailto:distrib@embraer.com.br); Internet <http://www.flyembraer.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9049.

#### Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-9049; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Todd Thompson, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA,

1601 Lind Avenue SW., Renton, WA 98057-3356; telephone 425-227-1175; fax 425-227-1149.

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Empresa Brasileira de Aeronautica S.A. (Embraer) Model EMB-135BJ, -135ER, -135KE, -135KL, and -135LR airplanes; and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. The NPRM published in the **Federal Register** on August 30, 2016 (81 FR 59528) ("the NPRM"). The NPRM was prompted by reports of main airspeed indication discrepancies during flight; these discrepancies resulted from ice blockages in certain pitot total pressure lines. The NPRM proposed to require an inspection for tube misalignment of the pitot number 1 and pitot number 2 tube assembly lines, and corrective actions if necessary; installation or replacement (as applicable) of a tube ribbon heater on the pitot number 1 and pitot number 2 tube assembly lines; and revision of the AFM to provide certain procedures and airspeed tables for the flightcrew. We are issuing this AD to detect and correct water accumulating and freezing in the pitot number 1 and pitot number 2 total pressure lines, which could result in erroneous main airspeed indications and consequent reduced ability of the flightcrew to maintain safe flight and landing of the airplane.

Agência Nacional de Aviação Civil (ANAC), which is the aviation authority for Brazil, has issued Brazilian Airworthiness Directive 2016-03-01, effective March 11, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Empresa Brasileira de Aeronautica S.A. (Embraer) Model EMB-135 airplanes, and Model EMB-145, -145ER, -145MR, -145LR, -145XR, -145MP, and -145EP airplanes. The MCAI states:

This [Brazilian] AD results from reports of main airspeed indication discrepancies during flight. The investigation has revealed that Pitot #1 and #2 total pressure line blockage may occur due to water accumulation and freezing during heavy rain conditions. We are issuing this [Brazilian] AD to prevent water accumulation and freezing in the Pitot #1 and Pitot #2 total pressure lines, which could result in erroneous main airspeed indications and reduce the ability of the flight crew to maintain the safe flight and landing of the airplane.

Since this condition may occur in other airplanes of the same type and affects flight