

Issued in Renton, Washington, on February 15, 2017.

Thomas Groves,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-03712 Filed 2-27-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0123; Directorate Identifier 2016-NM-033-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Defense and Space S.A. (Formerly Known as Construcciones Aeronauticas, S.A.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Defense and Space S.A. Model CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes. This proposed AD was prompted by a reported inability to extend the external handle of the emergency door from its recess due to a jammed spring mechanism. This proposed AD would require a one-time functional check of each emergency door handle, and corrective actions if necessary. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by April 14, 2017.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact EADS-CASA, Military Transport Aircraft Division (MTAD), Integrated Customer Services (ICS), Technical Services, Avenida de Aragón 404, 28022 Madrid, Spain;

telephone: +34 91 585 55 84; fax: +34 91 585 55 05; email:

MTA.TechnicalService@casa.eads.net;

Internet: <http://www.eads.net>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0123; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM-116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057-3356; telephone: 425-227-1112; fax: 425-227-1149.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2017-0123; Directorate Identifier 2016-NM-033-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. We will consider all comments received by the closing date and may amend this proposed AD based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2016-0051, dated March 11, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition

for all Airbus Defense and Space S.A. Model CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes. The MCAI states:

Failure to extend the external handle of emergency door from its recess was reported. As a consequence, it was impossible to open the rear emergency door from outside. Subsequent investigation determined that jamming of the door spring mechanism led to failure pushing out the emergency door external handle from its position normally aligned with the door skin.

This condition, if not detected and corrected, could lead to failure to open the emergency door from outside in an emergency.

To address this potential unsafe condition, Airbus Defence&Space (D&S) issued Alert Operators Transmission (AOT) AOT-CN235-52-0001 and AOT-C295-52-0001 to provide inspection instructions [and corrective actions if necessary].

For the reasons described above, this [EASA] AD requires a one-time functional check of [each of] the affected emergency door external handle[s] and, depending on findings, [detailed visual inspection for damage or unexpected material and] corrective action [repair]. This [EASA] AD also requires reporting the check result.

You may examine the MCAI in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0123.

Related Service Information Under 14 CFR Part 51

We reviewed the following Airbus Defense and Space service information.

- Airbus Defense and Space Alert Operators Transmission (AOT) AOT-CN235-52-0001, dated September 4, 2014.
- Airbus Defense and Space AOT-C295-52-0001, dated September 4, 2014.

The service information describes procedures for a one-time functional check of each emergency door handle and corrective actions if necessary. These documents are distinct since they apply to different airplane models. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA's Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this

AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of these same type designs.

Costs of Compliance

We estimate that this proposed AD affects 27 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Functional Check	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$2,295
Reporting	1 work-hour × \$85 per hour = \$85	0	85	2,295

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this proposed AD is 2120-0056. The paperwork cost associated with this proposed AD has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this proposed AD is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW., Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES-200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition

that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Airbus Defense and Space S.A. (formerly known as Construcciones Aeronauticas,

S.A.): Docket No. FAA-2017-0123; Directorate Identifier 2016-NM-033-AD.

(a) Comments Due Date

We must receive comments by April 14, 2017.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Airbus Defense and Space S.A. (formerly known as Construcciones Aeronauticas, S.A.) Model CN-235, CN-235-100, CN-235-200, CN-235-300, and C-295 airplanes, certificated in any category, all manufacturer serial numbers.

(d) Subject

Air Transport Association (ATA) of America Code 52, Doors.

(e) Reason

This AD was prompted by a reported inability to extend the external handle of the emergency door from its recess due to a jammed spring mechanism. We are issuing this AD to detect and correct jamming of the door spring mechanism, which could lead to the inability to push out the emergency door external handle from its position normally aligned with the door skin. This condition could result in the inability to open the emergency door from outside during an emergency.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) One Time Functional Check

Within 30 days after the effective date of this AD, do a one-time functional check of each emergency door handle in accordance with Airbus Defense and Space Alert Operators Transmission (AOT) AOT-CN235-52-0001, dated September 4, 2014; or Airbus Defense and Space AOT-C295-52-0001, dated September 4, 2014; as applicable.

(h) Additional Actions for Discrepancies

If any discrepancy (non-working emergency door handle) is found during the functional check required by paragraph (g) of this AD, before further flight, do the actions required by paragraphs (h)(1) and (h)(2) of this AD.

- (1) Accomplish a detailed visual inspection for damage and unexpected material in

accordance with Airbus Defense and Space AOT–CN235–52–0001, dated September 4, 2014; or Airbus Defense and Space AOT–C295–52–0001, dated September 4, 2014; as applicable.

(2) Before further flight, repair using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or the European Aviation Safety Agency (EASA); or Airbus Defense and Space S.A.’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(i) Reporting

Submit a report of the findings (both positive and negative) from the functional test required by paragraph (g) of this AD and the inspection required by paragraph (h)(1) of this AD to Airbus Defense and Space in accordance with the instructions of Airbus Defense and Space AOT–CN235–52–0001, dated September 4, 2014; or Airbus Defense and Space AOT–C295–52–0001, dated September 4, 2014; as applicable; at the applicable time specified in paragraph (i)(1) or (i)(2) of this AD.

(1) If the functional test or inspection was done on or after the effective date of this AD: Submit the report within 30 days after the functional test or inspection.

(2) If the functional test or inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Branch, send it to ATTN: Shahram Daneshmandi, Aerospace Engineer, International Branch, ANM–116, Transport Airplane Directorate, FAA, 1601 Lind Avenue SW., Renton, WA 98057–3356; telephone: 425–227–1112; fax: 425–227–1149. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office. The AMOC approval letter must specifically reference this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Branch, ANM–116, Transport Airplane Directorate, FAA; or EASA; or Airbus Defense and Space S.A.’s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements*: A federal agency may not conduct or sponsor, and a

person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120–0056. Public reporting for this collection of information is estimated to be approximately 5 minutes per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW., Washington, DC 20591, Attn: Information Collection Clearance Officer, AES–200.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2016–0051, dated March 11, 2016, for related information. This MCAI may be found in the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0123.

(2) For service information identified in this AD, contact EADS–CASA, Military Transport Aircraft Division (MTAD), Integrated Customer Services (ICS), Technical Services, Avenida de Aragón 404, 28022 Madrid, Spain; telephone: +34 91 585 55 84; fax: +34 91 585 55 05; email: MTA.TechnicalService@casa.eads.net; Internet: <http://www.eads.net>. You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425–227–1221.

Issued in Renton, Washington, on February 15, 2017.

Thomas Groves,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017–03718 Filed 2–27–17; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF HOMELAND SECURITY

Coast Guard

33 CFR Part 165

[Docket Number USCG–2017–0092]

RIN 1625–AA00

Safety Zone; City of Valdez July 4th Fireworks, Port Valdez; Valdez, AK

AGENCY: Coast Guard, DHS.

ACTION: Notice of proposed rulemaking.

SUMMARY: The Coast Guard proposes to establish a permanent safety zone on the navigable waters of Port Valdez, Valdez, Alaska, in the vicinity of the Valdez

Spit. The proposed safety zone is necessary to protect persons and vessels from the hazards associated with the annual City of Valdez July 4th Fireworks Display event. This rule is intended to restrict vessels from a portion of the navigable waters of Port Valdez, in the immediate vicinity of the fireworks launch platforms, before, during, and immediately after the fireworks event. We invite your comments on this proposed rulemaking.

DATES: Comments and related material must be received by the Coast Guard on or before March 30, 2017.

ADDRESSES: You may submit comments identified by docket number USCG–2017–0092 using the Federal eRulemaking Portal at <http://www.regulations.gov>.

See the “Public Participation and Request for Comments” portion of the **SUPPLEMENTARY INFORMATION** section for further instructions on submitting comments.

FOR FURTHER INFORMATION CONTACT: If you have questions about this proposed rulemaking, call or email Lieutenant Commander Walner W. Alvarez, Chief of Waterways Management Division, U.S. Coast Guard Marine Safety Unit Valdez; telephone (907) 835–7223, email Walner.W.Alvarez@uscg.mil.

SUPPLEMENTARY INFORMATION:

I. Table of Abbreviations

CFR Code of Federal Regulations
COTP Captain of the Port
DHS Department of Homeland Security
FR Federal Register
NPRM Notice of proposed rulemaking
§ Section
U.S.C. United States Code

II. Background, Purpose, and Legal Basis

The Coast Guard began issuing temporary final rules in 2011 to establish a safety zone during the Valdez July 4th Fireworks Display. The Coast Guard received no comments or concerns from the public when the temporary safety zones were in place. This Notice of Proposed Rulemaking proposes to permanently establish a safety zone of the exact same size and position as that which were established under the temporary final rules since 2014. The legal basis for the rule is the Coast Guard’s authority to establish limited access areas: 33 U.S.C 1231; 50 U.S.C. 191; 33 CFR 1.05–1, 6.04–1, 6.04–6, 160.5; Department of Homeland Security Delegation No. 0170.1.

The purpose of this rule is to enhance the safety for spectators and mariners attending a community event that involves a relatively large fireworks