

by paragraph (h)(3) of this AD. Do all applicable related investigative and corrective actions before further flight.

(k) Post-Repair Inspections

Table 6 of paragraph 1.E., "Compliance," of SASB 737-53-1168, Revision 4, specifies post-repair airworthiness limitation inspections in compliance with 14 CFR 25.571(a)(3) at the repaired locations, which support compliance with 14 CFR 121.1109(c)(2) or 129.109(b)(2). As airworthiness limitations, these inspections are required by maintenance and operational rules. It is therefore unnecessary to mandate them in this AD. Deviations from these inspections require FAA approval, but do not require an AMOC.

(l) Skin Panel Replacement

At the later of the times specified in paragraphs (l)(1), (l)(2), and (l)(3) of this AD: Replace the applicable skin panels, and do all applicable related investigative and corrective actions, in accordance with the Accomplishment Instructions of SASB 737-53-1168, Revision 4. Do all applicable related investigative and corrective actions before further flight. Doing the skin panel replacement required by this paragraph terminates the inspection requirements of paragraphs (g), (i), and (j) of this AD for that skin panel only, provided the skin panel replacement was done with a production skin panel after 53,000 total flight cycles.

(1) Before 60,000 total flight cycles, but not before 53,000 total flight cycles.

(2) Within 6,000 flight cycles after the effective date of this AD, but not before 53,000 total flight cycles.

(3) If the skin panel is replaced with a production skin panel, not before 53,000 total flight cycles. If the skin panel is replaced with a kit skin panel as specified in SASB 737-53-1168, Revision 4, the 53,000 total flight cycle limit does not apply.

(m) Credit for Previous Actions

(1) This paragraph provides credit for the actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Service Bulletin 737-53-1168, Revision 3, dated November 28, 2006, except as required by paragraph (h)(4) of this AD. Boeing Service Bulletin 737-53-1168, Revision 3, dated November 28, 2006, was incorporated by reference in AD 2009-21-01.

(2) This paragraph provides credit for the actions required by paragraph (l) of this AD, if those actions were performed before the effective date of this AD using Boeing Service Bulletin 737-53-1168, Revision 3, dated November 28, 2006, except as required by paragraph (h)(4) of this AD. Boeing Service Bulletin 737-53-1168, Revision 3, dated November 28, 2006, was incorporated by reference in AD 2009-21-01.

(3) This paragraph provides credit for the actions required by paragraph (l) of this AD, if those actions were performed before November 17, 2009 (the effective date of AD 2009-21-01), using any service information specified in paragraphs (m)(3)(i), (m)(3)(ii), and (m)(3)(iii) of this AD, provided the replacement is made with a kit skin panel, except as required by paragraph (h)(4) of this

AD. The service information specified in paragraphs (m)(3)(i), (m)(3)(ii), and (m)(3)(iii) of this AD was incorporated by reference in AD 2009-21-01.

(i) Part 3 of the Accomplishment Instructions of Boeing Service Bulletin 737-53-1168, dated March 16, 1995.

(ii) Part 3 of the Accomplishment Instructions of Boeing Service Bulletin 737-53-1168, Revision 1, dated August 17, 1995.

(iii) Part 3 of the Accomplishment Instructions of Boeing Service Bulletin 737-53-1168, Revision 2, dated November 27, 1996.

(n) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles Aircraft Certification Office (ACO), FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (o)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane and the approval must specifically refer to this AD.

(4) AMOCs approved previously for repairs required by AD 2009-21-01 are approved as AMOCs for the corresponding provisions of paragraph (g) of this AD.

(5) AMOCs approved previously for modifications done as optional terminating action for AD 2009-21-01 are approved as AMOCs for the skin panel replacement required by paragraph (l) of this AD.

(o) Related Information

(1) For more information about this AD, contact Jennifer Tsakoumakis, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles ACO, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5264; fax: 562-627-5210; email: jennifer.tsakoumakis@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (p)(3) and (p)(4) of this AD.

(p) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Special Attention Service Bulletin 737-53-1168, Revision 4, dated June 3, 2015.

(ii) Reserved.

(3) For Boeing service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; Internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on May 2, 2017.

Michael Kaszycki,

Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-10288 Filed 5-26-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0156; Directorate Identifier 2017-CE-003-AD; Amendment 39-18877; AD 2017-10-03]

RIN 2120-AA64

Airworthiness Directives; ZLIN AIRCRAFT a.s. Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are superseding Airworthiness Directive (AD) 2003-11-12 for ZLIN AIRCRAFT a.s. Model Z-242L airplanes (type certificate previously held by MORAVAN a.s.). This AD results from mandatory continuing airworthiness information (MCAI) issued by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a need to incorporate new revisions into the Limitations section, Chapter 9, of the FAA-approved maintenance program (e.g., maintenance manual) to impose

new or more restrictive life limits on critical components. We are issuing this AD to require actions to address the unsafe condition on these products.

DATES: This AD is effective July 5, 2017.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of July 5, 2017.

The Director of the Federal Register approved the incorporation by reference of a certain other publication as of June 5, 2003 (68 FR 32629, June 2, 2003).

ADDRESSES: You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0156; or in person at the Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

For service information identified in this AD, contact ZLIN AIRCRAFT a.s., Letiště 1887, 765 02 Otrokovice, Czech Republic, telephone: +420 725 266 711; fax: +420 226 013 830; email: info@zlinaircraft.eu, Internet: <http://www.zlinaircraft.eu>. You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the Internet at <http://www.regulations.gov> by searching for Docket No. FAA-2017-0156.

FOR FURTHER INFORMATION CONTACT: Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to ZLIN AIRCRAFT a.s. Model Z-242L airplanes (type certificate previously held by MORAVAN a.s.). That NPRM was published in the **Federal Register** on March 2, 2017 (82 FR 12305), and proposed to supersede AD 2003-11-12, Amendment 39-13171 (68 FR 32629, June 2, 2003) (“AD 2003-11-12”).

Since we issued AD 2003-11-12, a revision to the airworthiness limitations chapter of the aircraft maintenance manual has been issued, and the State of Design airworthiness authority took AD action, as identified below.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No.: 2017-0005, dated January 10, 2017 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

The airworthiness limitations for the Zlin Aircraft a.s. Z 242 L aeroplanes, which are approved by EASA, are defined and published in Chapter 9 of Zlin Aircraft a.s. Z 242 L Maintenance Manual (MM)—Volume I Document 003.021.1 (in Czech language) or in Chapter 9 of Z 242 L MM—Volume I Document 003.22.1 (in English language). These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition.

Zlin Aircraft a.s. recently published Revision 22 to Chapter 9, Volume I, of the Z 242 L MM, introducing new and/or more restrictive limitations.

For the reason described above, this [EASA] AD requires accomplishment of the actions specified in the Zlin Aircraft a.s. Z 242 L MM Chapter 9, Volume I, at Revision 22.

The MCAI can be found in the AD docket on the Internet at <https://www.regulations.gov/document?D=FAA-2017-0156-0002>.

Comments

We gave the public the opportunity to participate in developing this AD. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR 51

We reviewed Chapter 9, Airworthiness Limitations, Revision No. 22, dated March 15, 2016, of ZLIN AIRCRAFT a.s. Z 242 L DOC. No. 003.22.1 Maintenance Manual-Vol. I., and Moravan-Aeroplanes a.s. Mandatory Service Bulletin Z 142C/17a, Z 242L/37a—Rev. 1, dated October 31, 2000. The revision to the Limitations sections introduces new and/or more restrictive safe life limits for the Model Z 242 airplane. The mandatory service bulletin describes procedures for

annotating acrobatic and utility category operational time in the logbook. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section of this AD.

Costs of Compliance

We estimate that this AD will affect 30 products of U.S. registry. We also estimate that it will take about 1 work-hour per product to comply with the requirement to incorporate the new revision into the Limitations section of the FAA-approved maintenance program (e.g., maintenance manual). The average labor rate is \$85 per work-hour.

Based on these figures, we estimate the cost of this portion of this AD on U.S. operators to be \$2,550, or \$85 per product.

The above costs only account for the time to incorporate the document into the Limitations section of the FAA-approved maintenance program. These limitations will impose more restrictive life limits on some parts and provide new life limits for others. While the cost of these replacements could be expensive, they will only be required to operate the airplane past the established times. Ultimately, the estimated cost of replacing all life-limited parts could come close to the cost of the airplane. These life limits are necessary to continue to operate the airplane in an airworthy manner.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. “Subtitle VII: Aviation Programs,” describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in “Subtitle VII, Part A, Subpart III, section 44701: General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this AD will not have federalism implications under

Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0156; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains the NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone (800) 647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Amendment 39–13171 (68 FR 32629, June 2, 2003), and adding the following new AD:

2017–10–03 ZLIN AIRCRAFT a.s. (type certificate previously held by MORAVAN a.s.): Amendment 39–18877; Docket No. FAA–2017–0156; Directorate Identifier 2017–CE–003–AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective July 5, 2017.

(b) Affected ADs

This AD replaces AD 2003–11–12, Amendment 39–13171 (68 FR 32629, June 2, 2003) (“AD 2003–11–12”).

(c) Applicability

This AD applies to ZLIN AIRCRAFT a.s. Model Z–242L airplanes, all serial numbers, certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 5: Time Limits.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as a need to incorporate new revisions into the Limitations section, Chapter 9, of the FAA-approved maintenance program (*e.g.*, maintenance manual). We are issuing this AD to prevent structural failure of the wing due to fatigue cracking. Such failure could result in a wing separating from the airplane with consequent loss of control.

(f) Actions and Compliance

Unless already done, do the following actions:

(1) *For all affected airplanes:* As of March 21, 2003 (the effective date of AD 2003–03–13 (68 FR 4905, January 21, 2003) (“AD 2003–03–13”)), annotate Acrobatic and Utility category operational time in the logbook. If the airplane is utilized in either of these categories at any time during a flight, annotate the total time for that flight in the Utility or Acrobatic category, as appropriate. Do the logbook annotation following the procedures in Moravan-Aeroplanes a.s. Mandatory Service Bulletin Z 142C/17a, Z 242L/37a—Rev. 1, dated October 31, 2000; and Moravan Mandatory Service Bulletin Z 242L/38a—Rev. 1, April 15, 2003. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 may do this action.

(2) *For airplane serial numbers 0001 through 0656 that do not have strengthened wings installed (both left and right side) in accordance with Moravan Mandatory Service Bulletin Z 242L/27a—Rev. 1, dated October 31, 2000, or Rev. 2, dated April 15, 2003:*

(i) On or before 10 days after June 5, 2003 (the effective date of AD 2003–11–12), incorporate aerobatic frequency information into the Limitations section of the airplane flight manual (AFM) as specified in Moravan Mandatory Service Bulletin Z 242L/38a—Rev. 1, April 15, 2003. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 may do this action. Make an entry into the aircraft records showing compliance with these portions of this AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(ii) On or before reaching 190 hours time-in-service in the Acrobatic category and/or

Utility category or on or before 90 days after March 21, 2003 (the effective date of AD 2003–03–13), whichever occurs later, insert the following information into the Limitations section of the airplane flight manual (AFM): “Do not operate in the Acrobatic or Utility category. Operate in the Normal category only.” The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may accomplish this AFM insertion of this AD. Make an entry into the aircraft records showing compliance with these portions of this AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9). This operational restriction is referenced in Moravan-Aeroplanes a.s. Mandatory Service Bulletin Z 142C/17a, Z 242L/37a—Rev. 1, dated October 31, 2000.

(3) *For airplane serial numbers 0657 or higher or one in the range of 0001 through 0656 that has strengthened wings (both left and right side) installed in accordance with Moravan Mandatory Service Bulletin Z 242L/27a—Rev. 1, dated October 31, 2000, or Rev. 2, dated April 15, 2003:* On or before 10 days after June 5, 2003 (the effective date of AD 2003–11–12), incorporate aerobatic frequency information into the Limitations section of the airplane flight manual (AFM) as specified in Moravan Mandatory Service Bulletin Z 242L/38a—Rev. 1, April 15, 2003. The owner/operator holding at least a private pilot certificate as authorized by section 43.7 may do this action. Make an entry into the aircraft records showing compliance with these portions of this AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(4) *For all affected airplanes:* Within 10 days after July 5, 2017 (the effective date of this AD), insert Chapter 9, Airworthiness Limitations, Revision No. 22, dated March 15, 2016, of ZLIN AIRCRAFT a.s. Z 242 L, DOC. No. 003.22.1 Maintenance Manual-Vol. I into the Limitations section of the FAA-approved maintenance program (*e.g.*, maintenance manual). The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may accomplish this maintenance manual insertion requirement of this AD. Make an entry into the aircraft records showing compliance with these portions of this AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9). If a discrepancy is found during the accomplishment of any of the actions required by the document listed in this paragraph, before further flight after finding such discrepancy, contact ZLIN AIRCRAFT a.s. at the address specified in paragraph (h) of this AD for an FAA-approved repair scheme and incorporate that repair scheme.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Standards Office, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Doug Rudolph, Aerospace Engineer,

FAA, Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: doug.rudolph@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) **Airworthy Product:** For any requirement in this AD to obtain corrective actions from a manufacturer or other source, use these actions if they are FAA-approved. Corrective actions are considered FAA-approved if they are approved by the State of Design Authority (or their delegated agent). You are required to assure the product is airworthy before it is returned to service.

(h) Related Information

Refer to MCAI European Aviation Safety Agency (EASA) AD No.: 2017-0005, dated January 10, 2017, for related information. The MCAI can be found in the AD docket on the Internet at <https://www.regulations.gov/document?D=FAA-2017-0156-0002>.

(i) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on July 5, 2017 (the effective date of this AD).

(i) Chapter 9, Airworthiness Limitations, Revision No. 22, dated March 15, 2016, of ZLIN AIRCRAFT a.s. Z 242 L DOC. No. 003.22.1 Maintenance Manual—Vol. I.

(ii) Moravan-Aeroplanes a.s. Mandatory Service Bulletin Z 142C/17a, Z 242L/37a—Rev. 1, dated October 31, 2000.

(4) The following service information was approved for IBR on June 5, 2003 (68 FR 32629, June 2, 2003).

(i) Moravan Mandatory Service Bulletin Z 242L/38a—Rev.1, April 15, 2003.

(ii) Reserved.

(5) For service information identified in this AD, contact ZLIN AIRCRAFT a.s., Letiště 1887, 765 02 Otrokovice, Czech Republic, telephone: +420 725 266 711; fax: +420 226 013 830; email: info@zlinaircraft.eu, Internet: <http://www.zlinaircraft.eu>.

(6) You may view this service information at FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call 816-329-4148. In addition, you can access this service information on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0156.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on May 15, 2017.

Melvin Johnson,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 2017-10406 Filed 5-26-17; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2016-6666; Directorate Identifier 2015-NM-124-AD; Amendment 39-18881; AD 2017-10-07]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 737-400 series airplanes. This AD was prompted by an evaluation by the design approval holder (DAH), which indicates that the aft fuselage skin is subject to widespread fatigue damage (WFD), and reports of aft fuselage skin cracking. This AD requires repetitive inspections to detect cracking of the aft fuselage skin, inspections to detect missing or loose fasteners and any disbonding or cracking of bonded doublers, permanent repairs of time-limited repairs, related investigative and corrective actions if necessary, and skin panel replacement. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 5, 2017.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 5, 2017.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone: 562-797-1717; Internet: <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Airplane Directorate, 1601 Lind Avenue SW., Renton, WA. For information on the availability of this material at the FAA, call 425-227-1221. It is also available on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6666.

Examining the AD Docket

You may examine the AD docket on the Internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2016-6666; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE., Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Jennifer Tsakoumakis, Aerospace Engineer, Airframe Branch, ANM-120L, FAA, Los Angeles Aircraft Certification Office (ACO), 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5264; fax: 562-627-5210; email: jennifer.tsakoumakis@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Boeing Model 737-400 series airplanes. The NPRM published in the **Federal Register** on May 13, 2016 (81 FR 29809) (“the NPRM”). The NPRM was prompted by an evaluation by the DAH, which indicates that the aft fuselage skin is subject to WFD, and reports of aft fuselage skin cracking. The NPRM proposed to require repetitive inspections to detect cracking of the aft fuselage skin, inspections to detect missing or loose fasteners and any disbonding or cracking of bonded doublers, permanent repairs of time-limited repairs, related investigative and corrective actions if necessary, and skin panel replacement. We are issuing this AD to prevent cracking in the aft fuselage skin along the longitudinal edges of the bonded skin doubler, which could result in possible rapid decompression and reduced structural integrity of the airplane.

Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA’s response to each comment.

Request To Specify Repair Procedures

Boeing requested that we revise the proposed AD to address repairs that are