

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

#### 2018–05–07 The Boeing Company:

Amendment 39–19216; Docket No. FAA–2017–0806; Product Identifier 2017–NM–064–AD.

#### (a) Effective Date

This AD is effective April 11, 2018.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to all The Boeing Company Model 787–8 and 787–9 airplanes, certificated in any category.

#### (d) Subject

Air Transport Association (ATA) of America Code 35, Oxygen.

#### (e) Unsafe Condition

This AD was prompted by a flight test report indicating that the crew oxygen masks in the flight deck did not deploy correctly. We are issuing this AD to prevent the oxygen mask harness from getting caught in the oronasal mask or goggles, which may lead to flight crew hypoxia and the loss of useful consciousness, possibly resulting in loss of control of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Oxygen Mask Inspection and Replacement

For airplanes with an original certificate of airworthiness or original export certificate of airworthiness issued on or before the effective date of this AD: Within 72 months after the effective date of this AD, do an inspection to determine whether any crew oxygen mask having part number (P/N) MLD20–626–1 is installed at the four locations identified in Boeing Service Bulletin B787–81205–SB350007–00, Issue 001, dated May 9, 2017. A review of airplane maintenance records is acceptable in lieu of this inspection if the part number of the crew oxygen mask can be conclusively determined from that review. If any crew oxygen mask having P/N MLD20–626–1 is found installed, within 72 months after the effective date of this AD, do all applicable actions identified as “RC” (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Service Bulletin B787–81205–SB350007–00, Issue 001, dated May 9, 2017.

#### (h) Parts Installation Prohibition

(1) For airplanes with an original certificate of airworthiness or original export certificate

of airworthiness issued on or before the effective date of this AD: As of the effective date of this AD, no person may install a crew oxygen mask having P/N MLD20–626–1 on any airplane, except as provided in this paragraph. Within 72 months after the effective date of this AD, installation of a crew oxygen mask having P/N MLD20–626–1 is acceptable when the action of replacing the mask is done as unscheduled maintenance, and as a replacement only for another crew oxygen mask having P/N MLD20–626–1. For the purposes of this AD, unscheduled maintenance is defined as maintenance that was not planned for or scheduled in advance, such as changing a defective or unserviceable oxygen mask at dispatch.

(2) For airplanes with an original certificate of airworthiness or original export certificate of airworthiness issued after the effective date of this AD: As of the effective date of this AD, no person may install a crew oxygen mask having P/N MLD20–626–1 on any airplane.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as RC, the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can

still be done as specified, and the airplane can be put back in an airworthy condition.

#### (j) Related Information

For more information about this AD, contact Susan L. Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Section, Seattle ACO Branch, FAA, 2200 South 216th St., Des Moines, WA; phone: 206–231–3570; email: [susan.l.monroe@faa.gov](mailto:susan.l.monroe@faa.gov).

#### (k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Service Bulletin B787–81205–SB350007–00, Issue 001, dated May 9, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 22, 2018.

**Jeffrey E. Duven,**

*Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018–04259 Filed 3–6–18; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2017–0527; Product Identifier 2017–NM–015–AD; Amendment 39–19215; AD 2018–05–06]

RIN 2120–AA64

### Airworthiness Directives; The Boeing Company Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** We are superseding Airworthiness Directive (AD) 2016–09–12, which applied to certain The Boeing

Company Model 787-8 and 787-9 airplanes. AD 2016-09-12 required repetitive inspections of the bilge barriers located in the forward and aft cargo compartments for disengaged decompression panels, and reinstalling any disengaged panels. This AD retains the actions required by AD 2016-09-12 and requires replacing the existing decompression panels with new panels and straps, which terminates the repetitive inspections. This AD also removes airplanes from the applicability. This AD was prompted by a terminating modification developed to address the unsafe condition. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective April 11, 2018.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of April 11, 2018.

**ADDRESSES:** For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0527.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0527; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### FOR FURTHER INFORMATION CONTACT:

Susan L. Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th Street, Des Moines, WA 98198-6547; phone: 206-

231-3570; email: [susan.l.monroe@faa.gov](mailto:susan.l.monroe@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 to supersede AD 2016-09-12, Amendment 39-18510 (81 FR 27300, May 6, 2016) (“AD 2016-09-12”). AD 2016-09-12 applied to certain The Boeing Company Model 787-8 and 787-9 airplanes. The NPRM published in the **Federal Register** on June 6, 2017 (82 FR 25983). The NPRM was prompted by a terminating modification developed to address the unsafe condition. The NPRM proposed to continue to require repetitive inspections of the bilge barriers located in the forward and aft cargo compartments for disengaged decompression panels, and reinstallation of any disengaged panels. The NPRM also proposed to require replacing the existing decompression panels with new panels and straps, which would terminate the repetitive inspections. The NPRM also proposed to remove airplanes from the applicability. We are issuing this AD to prevent decompression panels from disengaging from the bilge barriers located in the forward and aft cargo compartments. In the event of a cargo compartment fire, this condition would provide a path for smoke and Halon to enter the flight compartment and passenger cabin, which could result in the inability to contain and extinguish a fire.

##### Comments

We gave the public the opportunity to participate in developing this AD. The following presents the comments received on the NPRM and the FAA’s response to each comment.

##### Supportive Comment

The Air Line Pilots Association, International stated that it agrees with the intent of the NPRM.

##### Request To Extend Compliance Time

Japan Airlines (JAL) asked that we extend the compliance time for the replacement of the decompression panels required by paragraph (i) of the proposed AD from 22 to 48 months. JAL stated that extending this compliance time will not affect the safety level because the repetitive inspections specified by paragraph (g) of the proposed AD would still be required. JAL asked that the replacement be done during a C-check maintenance interval, which is three years. JAL added that it would also like to add a one-year margin for airplanes on which the

decompression panel is not replaced due to inevitable circumstances.

American Airlines (AAL) and United Airlines (UAL) asked that we extend the compliance time from 22 to 36 months, for the same reasons provided by JAL. AAL added that replacing the panels within 22 months would result in an undue maintenance burden on operators.

We agree to extend the compliance time for the replacement of the decompression panels from 22 to 36 months, because the repetitive inspections will maintain an acceptable margin of safety until the redesigned decompression panels are installed. This extension has been coordinated with the manufacturer. Therefore, we have extended the compliance time in paragraph (i) of this AD accordingly.

We do not agree to extend the compliance time to 48 months, which would exceed the acceptable margin of safety. A 36-month compliance time provides an adequate interval of time for replacing the decompression panels without compromising safety.

##### Request To Include the Latest Service Information

Boeing asked that we add Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 003, dated December 7, 2016, to the proposed AD as an alternative to using Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 001, dated November 16, 2015 (referenced in the NPRM as the appropriate source of service information for accomplishing the actions).

We agree that this final rule should refer to the latest service information. Since we issued the NPRM, Boeing has released Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 003, dated December 7, 2016. In the NPRM, we refer to Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 001, dated November 16, 2015, as the appropriate source of service information. No additional work is necessary on airplanes on which the actions were performed before the effective date of this AD using Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 001, dated November 16, 2015. We have therefore revised paragraphs (g) and (h) of this AD to add Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 003, dated December 7, 2016, as the source of service information for accomplishing the actions. We have added paragraph (k) to this AD to specify credit for prior accomplishment of the actions specified in Boeing Alert Service Bulletin B787-81205-SB500009-00, Issue 001, dated

November 16, 2015. We have redesignated subsequent paragraphs accordingly.

**Request To Clarify Description of “Adjustable Straps”**

Boeing asked that we change the term “adjustable straps” to “adjustable straps (zip ties)” throughout the NPRM for clarification.

We agree with the commenter’s request for the reason provided. We have changed the “Related Service Information under 1 CFR part 51” section and paragraph (i) of this AD accordingly.

**Conclusion**

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD with the changes described previously,

and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this AD.

**Related Service Information Under 1 CFR Part 51**

We reviewed Boeing Alert Service Bulletin B787–81205–SB500008–00, Issue 001, dated December 7, 2016. This service information describes procedures for replacing the existing decompression panels with new panels and adjustable straps (zip ties).

We also reviewed Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 003, dated December 7, 2016. This service information describes procedures for repetitive inspections of the bilge barriers located in the forward and aft cargo compartments for disengaged decompression panels, and reinstalling any disengaged panels.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**Costs of Compliance**

We estimate that this AD affects 50 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Retained inspections .....	3 work-hours × \$85 per hour = \$255 per inspection cycle.	\$0	\$255 per inspection cycle.	\$12,750 per inspection cycle.
New modification .....	7 work-hours × \$85 per hour = \$595 .....	11,748	12,343 .....	617,150.

We estimate the following costs to do any necessary reinstallation required

based on the results of the inspection. We have no way of determining the

number of aircraft that might need this action:

**ON-CONDITION COSTS**

Action	Labor cost	Parts cost	Cost per product
Reinstallation .....	1 work-hour × \$85 per hour = \$85 .....	\$0	\$85

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

**Regulatory Findings**

We have determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

## PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2016–09–12, Amendment 39–18510 (81 FR 27300, May 6, 2016), and adding the following new AD:

**2018–05–06 The Boeing Company:**  
Amendment 39–19215; Docket No. FAA–2017–0527; Product Identifier 2017–NM–015–AD.

#### (a) Effective Date

This AD is effective April 11, 2018.

#### (b) Affected ADs

This AD replaces AD 2016–09–12, Amendment 39–18510 (81 FR 27300, May 6, 2016) (“AD 2016–09–12”).

#### (c) Applicability

This AD applies to The Boeing Company Model 787–8 and 787–9 airplanes, certificated in any category, as identified in Boeing Alert Service Bulletin B787–81205–SB500008–00, Issue 001, dated December 7, 2016.

#### (d) Subject

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

#### (e) Unsafe Condition

This AD was prompted by a terminating modification developed to address the unsafe condition. We are issuing this AD to prevent decompression panels from disengaging from the bilge barriers located in the forward and aft cargo compartments. In the event of a cargo compartment fire, this condition would provide a path for smoke and Halon to enter the flight compartment and passenger cabin, which could result in the inability to contain and extinguish a fire.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Retained Repetitive Inspections, With Revised Service Information and Added Reference to Terminating Action

This paragraph restates the requirements of paragraph (g) of AD 2016–09–12, with revised service information and an added reference to terminating action: At the applicable time specified in paragraph (g)(1) or (g)(2) of this AD, do a general visual inspection of the bilge barriers located in the forward and aft cargo compartments for disengaged decompression panels, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 001, dated November 16, 2015; or Issue 003, dated December 7, 2016. Repeat the inspection thereafter at the applicable times specified in paragraph 5. “Compliance,” of Boeing Alert

Service Bulletin B787–81205–SB500009–00, Issue 001, dated November 16, 2015; or Issue 003, dated December 7, 2016; until the terminating modification required by paragraph (i) of this AD is done. As of the effective date of this AD, only Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 003, dated December 7, 2016, may be used.

(1) For Group 1 airplanes identified in Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 001, dated November 16, 2015; or Issue 003, dated December 7, 2016: Inspect within 30 days after May 23, 2016 (the effective date of AD 2016–09–12).

(2) For Group 2 airplanes identified in Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 001, dated November 16, 2015; or Issue 003, dated December 7, 2016: Inspect within 180 flight cycles or within 90 days after May 23, 2016 (the effective date of AD 2016–09–12), whichever occurs later.

#### (h) Retained Reinstallation of Decompression Panels With Revised Service Information

This paragraph restates the requirements of paragraph (h) of AD 2016–09–12, with revised service information: If any disengaged decompression panel is found during any inspection required by paragraph (g) of this AD; before further flight, reinstall the panel, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 001, dated November 16, 2015; or Issue 003, dated December 7, 2016, as applicable. As of the effective date of this AD, only Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 003, dated December 7, 2016, may be used.

#### (i) New Terminating Modification

Within 36 months after the effective date of this AD: Replace the existing decompression panels of the bilge barriers located in the forward and aft cargo compartments with new decompression panels and adjustable straps (zip ties), in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin B787–81205–SB500008–00, Issue 001, dated December 7, 2016; except as provided by paragraph (j) of this AD. Accomplishing this modification terminates the repetitive inspections required by paragraph (g) of this AD.

#### (j) Exceptions to Service Information

(1) Where Step 3 of Task 10 of the Accomplishment Instructions of Boeing Alert Service Bulletin B787–81205–SB500008–00, Issue 001, dated December 7, 2016, identifies part number (P/N) C412705–577, the correct part number is P/N C412705–575.

(2) Where Step 4 of Task 10 of the Accomplishment Instructions of Boeing Alert Service Bulletin B787–81205–SB500008–00, Issue 001, dated December 7, 2016, identifies P/N C412705–575, the correct part number is P/N C412705–577.

#### (k) Credit for Previous Actions

This paragraph provides credit for the actions specified in paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using

Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 001, dated November 16, 2015.

#### (l) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (m)(1) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2016–09–12, are approved as AMOCs for the corresponding provisions of paragraphs (g) and (h) of this AD.

(5) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (l)(5)(i) and (l)(5)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

#### (m) Related Information

(1) For more information about this AD, contact Susan L. Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th Street, Des Moines, WA 98198–6547; phone: 206–231–3570; email: [susan.l.monroe@faa.gov](mailto:susan.l.monroe@faa.gov).

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

**(n) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin B787–81205–SB500008–00, Issue 001, dated December 7, 2016.

(ii) Boeing Alert Service Bulletin B787–81205–SB500009–00, Issue 003, dated December 7, 2016.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740; telephone 562–797–1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th Street, Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on February 21, 2018.

**Michael Kaszycki,**

*Acting Director, System Oversight Division,  
Aircraft Certification Service.*

[FR Doc. 2018–04261 Filed 3–6–18; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA–2016–9074; Product Identifier 2016–NM–097–AD; Amendment 39–19213; AD 2018–05–04]**

**RIN 2120–AA64**

**Airworthiness Directives; Airbus Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for all Airbus Model A318–111 and –112 airplanes; Model A319–111, –112, –113, –114, and –115 airplanes; Model A320–211, –212, and –214 airplanes; and Model A321–111, –112, –211, –212, and –213 airplanes. This AD was prompted by reports of engine fan cowl door (FCD)

losses on airplanes equipped with CFM56 engines due to operator failure to close the FCD during ground operations. This AD requires modification and re-identification, or replacement, of certain FCDs. This AD also requires installation of a placard. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective April 11, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 11, 2018.

**ADDRESSES:** For service information identified in this final rule, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 44 51; email [account.airworth-eas@airbus.com](mailto:account.airworth-eas@airbus.com); internet <http://www.airbus.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9074.

**Examining the AD Docket**

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2016–9074; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800–647–5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3223.

**SUPPLEMENTARY INFORMATION:****Discussion**

We issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Model A318–111 and –112 airplanes; Model A319–111, –112, –113, –114, and –115

airplanes; Model A320–211, –212, and –214 airplanes; and Model A321–111, –112, –211, –212, and –213 airplanes. The SNPRM published in the **Federal Register** on September 27, 2017 (82 FR 44974) (“the SNPRM”). We preceded the SNPRM with a notice of proposed rulemaking (NPRM) that published in the **Federal Register** on September 26, 2016 (81 FR 65980) (“the NPRM”). The NPRM was prompted by reports of engine FCD losses on airplanes equipped with CFM56 engines due to operator failure to close the FCD during ground operations. The NPRM proposed to require modification and re-identification, or replacement, of certain FCDs. The NPRM also proposed to require installation of a placard. The SNPRM proposed to add airplanes to the applicability and expand the list of affected FCD part numbers. We are issuing this AD to prevent in-flight loss of an engine FCD and possible consequent damage to the airplane.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2016–0257, dated December 16, 2016 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A318–111 and –112 airplanes; Model A319–111, –112, –113, –114, and –115 airplanes; Model A320–211, –212, and –214 airplanes; and Model A321–111, –112, –211, –212, and –213 airplanes. The MCAI states:

Fan Cowl Door (FCD) losses were reported on aeroplanes equipped with CFM56 engines. Investigation results confirmed that in all cases the fan cowls were opened prior to the flight and were not correctly re-secured. During the pre-flight inspection, it was then not detected that the FCD[s] were not properly latched.

This condition, if not detected and corrected, could lead to in-flight loss of a FCD, possibly resulting in damage to the aeroplane and/or injury to persons on the ground.

Prompted by these events, new FCD front latch and keeper assembly were developed, having a specific key necessary to unlatch the FCD. This key cannot be removed unless the FCD front latch is safely closed. The key, after removal, must be stowed in the flight deck at a specific location, as instructed in the applicable Aircraft Maintenance Manual. Applicable Flight Crew Operating Manuals have been amended accordingly. After modification, the FCD is identified with a different Part Number (P/N). Airbus issued Service Bulletin (SB) A320–71–1068 to provide the modification instructions. Consequently, EASA issued AD 2016–0069 to require modification and re-identification of [affected] FCD[s] [or replacement of affected FCDs].