

Texas (24)

Concordia University-Texas
Houston Community College
McLennan Community College
Odessa College
Palo Alto College
Saint Edwards's University
San Antonio College
Southwest Texas Junior College
South Plains College
St. Mary's University
Tarrant County College District
Texas State Technical College
Texas A & M International University
Texas A & M University-Corpus Christi
The University of Texas at El Paso
The University of Texas Rio Grande Valley
The University of Texas at San Antonio
The University of Texas at Brownsville
University of Houston
University of Houston-Clear Lake
University of the Incarnate Word
University of St. Thomas
Western Texas College
Wayland Baptist University

Washington (4)

Columbia Basin College
Heritage University
Wenatchee Valley College
Yakima Valley Community College

Done in Washington, DC, this 8th day of March 2018.

Sonny Ramaswamy,

Director, National Institute of Food and Agriculture.

[FR Doc. 2018-05541 Filed 3-16-18; 8:45 am]

BILLING CODE 3410-22-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2017-0903; Product Identifier 2017-NM-074-AD; Amendment 39-19225; AD 2018-06-05]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 737-300 and -500 series airplanes. This AD was prompted by a report indicating that fatigue cracks were found in the lower wing skin of an airplane with winglets installed. This AD requires repetitive inspections for cracking of the lower wing skin, and repair if necessary. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 23, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 23, 2018.

ADDRESSES: For service information identified in this final rule, contact Aviation Partners Boeing, 2811 South 102nd St., Suite 200, Seattle, WA 98168; phone: 1-206-830-7699; fax: 1-206-767-3355; email: leng@aviationpartners.com; internet: <http://www.aviationpartnersboeing.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0903.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0903; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for the Docket Office (phone: 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Lu Lu, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3525; email: lu.lu@faa.gov.

SUPPLEMENTARY INFORMATION:**Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 737-300 and -500 series airplanes. The NPRM published in the **Federal Register** on October 6, 2017 (82 FR 46725). The NPRM was prompted by a report indicating that fatigue cracks were found in the lower wing skin of an airplane with winglets installed. The NPRM proposed to require repetitive inspections for cracking of the lower wing skin, and repair if necessary.

We are issuing this AD to detect and correct fatigue cracking of the lower wing skin common to the runout of stringer L-5. Such cracking could grow

and result in loss of structural integrity of the wing, and consequent reduced, or complete loss of, controllability of the airplane.

Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment. Aviation Partners Boeing concurred with the proposed AD.

Request for Manufacturer To Share Expense

One commenter, Mary Lou Allen, requested that the airplane manufacturer share in the expense with the airplane's purchaser or owner, because of the high costs associated with supplemental type certificates. We infer that the commenter wants manufacturers to be required to help pay for compliance with the proposed AD.

We do not agree to this request. We provide estimates of the cost on U.S. operators for AD compliance, but do not determine who is responsible for payment. We are aware that airplane manufacturers and modifiers often have warranty agreements with owners and operators to cover some or all of the costs of modifications or repairs, but we do not participate in these agreements. We have not changed this AD in this regard.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 14 CFR Part 51

We reviewed Aviation Partners Boeing Service Bulletin AP737C-57-002, dated April 5, 2017. The service information describes procedures for repetitive inspections for cracking of the lower wing skin, and repair if necessary. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 93 airplanes of U.S. registry. We estimate

the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Repetitive inspection	1 work-hour × \$85 per hour = \$85 per inspection cycle.	\$0	\$85 per inspection cycle.	Up to \$7,905 per inspection cycle.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018-06-05 The Boeing Company:
Amendment 39-19225; Docket No. FAA-2017-0903; Product Identifier 2017-NM-074-AD.

(a) Effective Date

This AD is effective April 23, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to The Boeing Company Model 737-300 and -500 series airplanes, certificated in any category, with blended winglet kits installed in accordance with Supplemental Type Certificate (STC) ST01219SE.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by a report indicating that fatigue cracks were found in the lower wing skin at stringer L-5 of a Boeing Model 737-300 airplane with winglets installed. We are issuing this AD to detect and correct fatigue cracking of the lower wing skin common to the runout of stringer L-5. Such cracking could grow and result in loss of structural integrity of the wing, and consequent reduced, or complete loss of, controllability of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Repetitive Inspection

Within 18 months after the effective date of this AD: Do a detailed inspection for cracking of the lower wing skin external surface at the stringer L-5 location on the left and right wings, in accordance with the Accomplishment Instructions of Aviation Partners Boeing Service Bulletin AP737C-57-002, dated April 5, 2017. Repeat the inspection thereafter at intervals not to exceed 6,000 flight cycles or 9,000 flight hours, whichever occurs first.

(h) Repair

If any crack is found during any inspection required by paragraph (g) of this AD, repair before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD. Although Aviation Partners Boeing Service Bulletin AP737C-57-002, dated April 5, 2017, specifies to contact Boeing for repair instructions, and specifies that action as "RC" (Required for Compliance), this AD requires repair as specified in this paragraph.

(i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: 9-ANM-Seattle-ACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager

of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) Except as required by paragraph (h) of this AD: For service information that contains steps that are labeled as RC, the provisions of paragraphs (i)(4)(i) and (i)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

(j) Related Information

For more information about this AD, contact Lu Lu, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3525; email: lu.lu@faa.gov.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Aviation Partners Boeing Service Bulletin AP737C-57-002, dated April 5, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Aviation Partners Boeing, 2811 South 102nd St., Suite 200, Seattle, WA 98168; phone: 1-206-830-7699; fax: 1-206-767-3355; email: leng@aviationpartners.com; internet: <http://www.aviationpartnersboeing.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Renton, Washington, on March 5, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-05016 Filed 3-16-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0210; Product Identifier 2018-CE-004-AD; Amendment 39-19229; AD 2018-06-09]

RIN 2120-AA64

Airworthiness Directives; Pacific Aerospace Limited Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are adopting a new airworthiness directive (AD) for Pacific Aerospace Limited Model 750XL airplanes. This AD results from mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as the possibility for the control column to snag on the cockpit control tee handles on certain airplanes. We are issuing this AD to require actions to address the unsafe condition on these products.

DATES: This AD is effective April 9, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in the AD as of April 9, 2018.

We must receive comments on this AD by May 3, 2018.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* (202) 493-2251.
- *Mail:* U.S. Department of

Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this AD, contact Pacific Aerospace Limited, Airport Road, Hamilton, Private Bag 3027, Hamilton 3240, New Zealand; phone: +64 7843 6144; fax: +64 843 6134; email: pacific@aerospace.co.nz; internet: www.aerospace.co.nz. You may view this referenced service information at the FAA, Policy and Innovation Division, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <http://www.regulations.gov> by searching for locating Docket No. FAA-2018-0210.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0210; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (telephone (800) 647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Mike Kiesov, Aerospace Engineer, FAA, Small Airplane Standards Branch, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4144; fax: (816) 329-4090; email: mike.kiesov@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The Civil Aviation Authority, which is the aviation authority for New Zealand, has issued CAA AD DCA/750XL/22, dated December 19, 2017 (referred to after this as "the MCAI"), to correct an unsafe condition for Pacific Aerospace Limited Model 750XL airplanes. To accompany that MCAI, the CAA issued Notification of Airworthiness Directive issued for New Zealand Aeronautical Products IAW ICAO Annex 8, dated December 21, 2017; the Notification states:

This [CAA] AD is prompted by a ground inspection which found it is possible for the control column to snag on the cockpit control tee handles on certain aircraft. When the tee handle is pulled out to the maximum limit it fouls with the control column in the extreme forward right and left positions. The tee handles are mounted below the switch panels adjacent to the centre console.

This [CAA] AD with effective date 28 December 2017 mandates the inspection and corrective actions per the Accomplishment