

Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new AD:

2018-07-15 XtremeAir GmbH: Amendment 39-19246; Docket No. FAA-2018-0284; Directorate Identifier 2018-CE-014-AD.

(a) Effective Date

This airworthiness directive (AD) becomes effective April 30, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to XtremeAir GmbH Model XA42 airplanes, all serial numbers, that are:

- (1) Equipped with an engine mount part number (P/N) XA42-7120-151; and
- (2) certificated in any category.

(d) Subject

Air Transport Association of America (ATA) Code 71: Power Plant.

(e) Reason

This AD was prompted by mandatory continuing airworthiness information (MCAI) issued by the aviation authority of another country to identify and address an unsafe

condition on an aviation product. The MCAI describes the unsafe condition as cracking of the diagonal strut of the engine mount frame. We are issuing this AD to detect and address cracking of the engine mount frame, which could lead to detachment of the engine in-flight and result in loss of control.

(f) Actions and Compliance

Unless already done, do the following actions in paragraphs (f)(1) through (4) of this AD.

(1) Before the next acrobatic flight after April 30, 2018 (the effective date of this AD) or within 50 hours time-in-service after the installation of P/N XA42-7120-151 engine mount on the airplane, whichever occurs later, and repetitively thereafter at intervals not to exceed 10 acrobatic flight hours, inspect the engine mount following the Accomplishment Instructions in XtremeAir Mandatory Service Bulletin SB-XA42-2018-006, Issue A.00, dated March 2, 2018.

(2) After the initial inspection required in paragraph (f)(1) of this AD, acrobatic flight hours must be recorded in the maintenance records. For the purpose of this AD, we define acrobatic flight as "flight during which a load factor of 6g is exceeded."

(3) If a crack is found during any inspection required in paragraph (f)(1) of this AD, before further flight, replace the engine mount with a serviceable part following the Accomplishment Instructions in XtremeAir Mandatory Service Bulletin SB-XA42-2018-006, Issue A.00, dated March 2, 2018. Replacement of the engine mount does not eliminate the repetitive inspection requirement in paragraph (f)(1) of this AD.

(4) After the effective date of this AD, you may install a new or used P/N XA42-7120-151 engine mount on the airplane. The used P/N XA42-7120-151 engine mount must be inspected as specified in paragraph (f)(1) of this AD and found free of cracks before installation on the airplane. The repetitive inspection requirement in paragraph (f)(1) of this AD still applies.

(g) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, Small Airplane Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. Send information to ATTN: Jim Rutherford, Aerospace Engineer, FAA, Policy and Innovation Division, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4165; fax: (816) 329-4090; email: jim.rutherford@faa.gov. Before using any approved AMOC on any airplane to which the AMOC applies, notify your appropriate principal inspector (PI) in the FAA Flight Standards District Office (FSDO), or lacking a PI, your local FSDO.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, Small Airplane Standards Branch, FAA; or the European Aviation Safety Agency (EASA).

(h) Special Flight Permit

A special flight permit is allowed for this AD per 14 CFR 39.23 with the following limitations: Acrobatic flights are prohibited.

(i) Related Information

Refer to MCAI, EASA AD No. 2018-0050-E, dated March 2, 2018, for related information. You may examine the MCAI on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0284.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) XtremeAir Mandatory Service Bulletin SB-XA42-2018-006, Issue A.00, dated March 2, 2018.

(ii) Reserved.

(3) For XtremeAir service information identified in this AD, contact XtremeAir GmbH, Harzstrasse 2, Am Flughafen Cochstedt, D-39444 Hecklingen, Germany; phone: +49 39267 60999 0; fax: +49 39267 60999 20; email: info@xtremeair.de; internet: <https://www.xtremeair.com>.

(4) You may view this service information at the FAA, Policy and Innovation Division, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148. It is also available on the internet at <http://www.regulations.gov> by searching for locating Docket No. FAA-2018-0284.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Kansas City, Missouri, on March 30, 2018.

Pat Mullen,

Acting Deputy Director, Policy & Innovation Division, Aircraft Certification Service.

[FR Doc. 2018-06949 Filed 4-6-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-0908; Product Identifier 2017-NM-103-AD; Amendment 39-19238; AD 2018-07-07]

RIN 2120-AA64

Airworthiness Directives; Dassault Aviation Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Dassault Aviation Model FAN JET FALCON, FAN JET FALCON SERIES D, E, F, and G airplanes; and certain Model MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes. This AD was prompted by reports of the collapse of the main landing gear (MLG) on touchdown. This AD requires an electrical modification of the landing gear sequence logic. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective May 14, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 14, 2018.

ADDRESSES: For service information identified in this final rule, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201-440-6700; internet <http://www.dassaultfalcon.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0908.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0908; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140,

1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Dassault Aviation Model FAN JET FALCON, FAN JET FALCON SERIES D, E, F, and G airplanes; and certain Model MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes. The NPRM published in the **Federal Register** on October 24, 2017 (82 FR 49151) (“the NPRM”). The NPRM was prompted by reports of the collapse of the main landing gear on touchdown. The NPRM proposed to require an electrical modification of the landing gear sequence logic. We are issuing this AD to prevent MLG collapse, which could result in damage to the airplane and injury to the occupants.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2017-0130, dated July 26, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Dassault Aviation Model FAN JET FALCON, FAN JET FALCON SERIES D, E, F, and G airplanes; and certain Model MYSTERE-FALCON 20-C5, 20-D5, 20-E5, and 20-F5 airplanes. The MCAI states:

An incident occurred in January 2016 on a Falcon 20-5 aeroplane where, upon touchdown, one main landing gear (MLG) collapsed, due to a sequence anomaly.

This condition, if not corrected, could lead to additional events of MLG collapse, possibly resulting in damage to the aeroplane and injury to the occupants.

Prompted by previous similar events, Dassault developed a modification, ensuring that hydraulic pressure of circuit #1 of the landing gear actuators is maintained after the extension sequence is completed. As a result, in the unlikely case of having one of the legs

not properly mechanically locked down, the pressure maintained in the landing gear bracing devices will prevent landing gear from collapsing. Dassault published Service Bulletin (SB) F20-676 in 1981 (later revised in 1998) which contains the necessary instructions to modify in-service aeroplanes.

For the reasons described above, this [EASA] AD requires an electrical modification of the landing gear sequence logic.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-0908.

Comments

We gave the public the opportunity to participate in developing this final rule. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this AD as proposed except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for correcting the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR part 51

Dassault Aviation has issued Service Bulletin F20-676, Revision 1, dated March 4, 1998. This service information describes procedures for an electrical modification of the MLG sequence logic to prevent landing gear collapse on touchdown. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 308 airplanes of U.S. registry.

We estimate the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Modification	21 work-hours × \$85 per hour = \$1,785	\$912	\$2,697	\$830,676

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We determined that this AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

1. Is not a "significant regulatory action" under Executive Order 12866,
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
3. Will not affect intrastate aviation in Alaska, and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018–07–07 Dassault Aviation:

Amendment 39–19238; Docket No. FAA–2017–0908; Product Identifier 2017–NM–103–AD.

(a) Effective Date

This AD is effective May 14, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Dassault Aviation airplanes, certificated in any category, identified in paragraphs (c)(1) and (c)(2) of this AD.

(1) All Model FAN JET FALCON, FAN JET FALCON SERIES D, E, F, and G airplanes.

(2) Model MYSTERE–FALCON 20–C5, 20–D5, 20–E5, and 20–F5 airplanes, except serial numbers (S/Ns) 478 and 485.

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by reports of the collapse of the main landing gear (MLG) on touchdown. We are issuing this AD to prevent MLG collapse, which could result in damage to the airplane and injury to the occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Modification

Within 74 months after the effective date of this AD, accomplish an electrical modification in accordance with the Accomplishment Instructions of Dassault Service Bulletin F20–676, Revision 1, dated March 4, 1998.

(h) No Reporting Requirement

Although the service information identified in paragraph (g) of this AD specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (j)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA Airworthiness Directive 2017–0130, dated July 26, 2017, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0908.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3226.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (k)(3) and (k)(4) of this AD.

(k) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Dassault Service Bulletin F20–676, Revision 1, dated March 4, 1998.

(ii) Reserved.

(3) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; telephone 201–440–6700; internet <http://www.dassaultfalcon.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the

National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on March 20, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-06711 Filed 4-6-18; 8:45 am]

BILLING CODE 4910-13-P

(C&DS), 2600 Westminster Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1176.

entry door, which would terminate the AFM limitation revision. We are issuing this AD to prevent restricted motion of the brake pedals, which can affect stopping performance and directional control of the airplane. This restricted motion can lead to high speed runway excursion or lateral runway excursion.

Comments

We gave the public the opportunity to participate in developing this final rule. We have considered the comment received. Boeing stated its support for the NPRM.

Conclusion

We reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

We reviewed Boeing Alert Requirements Bulletin 747-32A2525 RB, dated September 6, 2017. This service information describes procedures for modifying intercostal webs near main entry door 3 by drilling two drain holes in the station-18 intercostal web at door stop 8 and applying sealant at the fore-aft drain path of the upper main sill web at station 16 near door 3R and door 3L. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

Costs of Compliance

We estimate that this AD affects 2 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-1176; Product Identifier 2017-NM-123-AD; Amendment 39-19237; AD 2018-07-06]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain The Boeing Company Model 747-8 series airplanes. This AD was prompted by a report of restricted movement of the right brake pedals after landing rollout. This AD requires revising the airplane flight manual (AFM) by adding an autobrake system limitation. This AD also requires modifying intercostal webs near a main entry door, which terminates the AFM limitation. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective May 14, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 14, 2018.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1176; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is Docket Operations, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Kelly McGuckin, Aerospace Engineer, Systems and Equipment Section, Seattle ACO Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3546; email: Kelly.McGuckin@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain The Boeing Company Model 747-8 series airplanes. The NPRM published in the **Federal Register** on January 2, 2018 (83 FR 80). The NPRM was prompted by a report of restricted movement of the right brake pedals after landing rollout. The NPRM proposed to require revising the AFM by adding an autobrake system limitation. The NPRM also proposed to require modifying intercostal webs near a main

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
AFM revision	1 work-hour × \$85 per hour = \$85	\$0	\$85	\$170
Modification	10 work-hours × \$85 per hour = \$850	(¹)	850	1,700

¹ We have received no definitive data that enables us to provide parts cost estimates for the modification specified in this AD.