

Proposed Rules

Federal Register

Vol. 83, No. 100

Wednesday, May 23, 2018

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF AGRICULTURE

Agricultural Marketing Service

7 CFR Part 66

[Doc. No. AMS-TM-17-0050]

National Bioengineered Food Disclosure Standard

AGENCY: Agricultural Marketing Service, USDA.

ACTION: Proposed rule; notice of availability of informational webinar.

SUMMARY: The Agricultural Marketing Service (AMS) is announcing the availability of an informational webinar regarding the proposed National Bioengineered Food Disclosure Standard (NBFDS or standard). The proposed standard would require food manufacturers and other entities that label foods for retail sale to disclose information about bioengineered food and bioengineered food ingredients. The pre-recorded webinar will provide an overview of the background, provisions, and potential impacts of the proposed standard. Establishment and implementation of the new standard is required by recent amendment to the Agricultural Marketing Act of 1946.

DATES: The webinar will be made available on the AMS website at <https://www.ams.usda.gov/rules-regulations> beginning June 1, 2018.

FOR FURTHER INFORMATION CONTACT: Email: befooddisclosure@ams.usda.gov; telephone: (202) 690-1300; or Fax: (202) 690-0338. Comments on the proposed rule sent to this email address will not be considered. Comments must be submitted through [regulations.gov](http://www.regulations.gov); by mail to the Docket Clerk, 1400 Independence Ave., AS, Room 4543-S, Washington, DC 20250; or by Fax to (202) 690-0338.

SUPPLEMENTARY INFORMATION: On July 29, 2016, Public Law 114-216 amended the Agricultural Marketing Act of 1946 (7 U.S.C. 1621 *et seq.*), as amended, and directed the Secretary of Agriculture to establish the NBFDS for disclosing any

food that is or may be bioengineered. AMS published a proposed rule regarding the new standard in the **Federal Register** on May 4, 2018 (83 FR 19860). The proposed rule announced that AMS would be providing a webinar regarding the proposed NBFDS. The webinar, which is pre-recorded, will be made available to interested persons on the AMS website at <https://www.ams.usda.gov/rules-regulations> beginning June 1, 2018. The webinar is intended to supply basic information about the proposed rule and several regulatory alternatives on which AMS is seeking public comment.

The rule seeks comments on the proposed scope of the standard, including what foods should bear disclosures and what entities would be responsible for making disclosures. The rule proposes several alternatives for consideration, including methods of disclosure, and outlines procedures for recordkeeping and compliance. The proposed rule also seeks comments on the recordkeeping and information collection burden associated with the new standard. Comments on the proposed rule and on the information collection are being accepted through July 3, 2018, and should be submitted as directed in the May 4, 2018, **Federal Register** document.

In conjunction with the proposed rule, AMS published a Regulatory Impact Analysis, which describes potential impacts of the rule under alternative scenarios. Comments on the regulatory impacts of the proposed NBFDS are also invited. The full text of the proposed rule, as well as the Regulatory Impact Analysis, may be viewed at www.regulations.gov.

Authority: 7 U.S.C. 1621 *et seq.*

Dated: May 18, 2018.

Bruce Summers,
Administrator.

[FR Doc. 2018-11025 Filed 5-22-18; 8:45 am]

BILLING CODE 3410-02-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-1081; Product Identifier 2017-SW-090-AD]

RIN 2120-AA64

Airworthiness Directives; AgustaWestland S.p.A. Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for AgustaWestland S.p.A. (AgustaWestland) Model AW189 helicopters. This proposed AD would require replacing the tail plane lower fitting with an improved tail plane lower fitting. This proposed AD is prompted by reports of cracks on the tail plane fittings of Model AW189 helicopters. The actions of this proposed AD are intended to correct an unsafe condition on these products.

DATES: We must receive comments on this proposed AD by July 23, 2018.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.

- *Fax:* 202-493-2251.

- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590-0001.

- *Hand Delivery:* Deliver to the "Mail" address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1081; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the European Aviation Safety Agency (EASA) AD, the economic evaluation, any comments received, and

other information. The street address for Docket Operations (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact Leonardo S.p.A. Helicopters, Matteo Ragazzi, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-711756; fax +39-0331-229046; or at <http://www.leonardocompany.com/-/bulletins>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

FOR FURTHER INFORMATION CONTACT:

Martin R. Crane, Aviation Safety Engineer, Regulations & Policy Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email martin.r.crane@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

We will file in the docket all comments that we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, we will consider all comments we receive on or before the closing date for comments. We will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. We may change this proposal in light of the comments we receive.

Discussion

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD No. 2016-0161, dated August 8, 2016, to correct an unsafe condition for Leonardo Helicopters (previously Finmeccanica S.p.A, AgustaWestland) Model AW189

helicopters. EASA advises that some cracks have been reported in-service on the tail plane fitting of AW189 helicopters following an onset of abnormal play. According to EASA, this condition, if not detected and corrected, could jeopardize structural integrity of the helicopter. EASA further advises that Leonardo Helicopters developed a tail plane lower fitting with an improved design (part number 8G0000P00511). Accordingly, EASA AD No. 2016-0161 requires repetitive inspections of the tail plane lower fitting assembly until the improved tail plane lower fitting is installed.

Because the FAA is in the process of updating AgustaWestland's name changes to Finmeccanica S.p.A. and then to Leonardo Helicopters on its FAA type certificate, this proposed AD specifies AgustaWestland as the type certificate holder.

FAA's Determination

These helicopters have been approved by the aviation authority of Italy and are approved for operation in the United States. Pursuant to our bilateral agreement with Italy, EASA, its technical representative, has notified us of the unsafe condition described in its AD. We are proposing this AD because we evaluated all known relevant information and determined that an unsafe condition is likely to exist or develop on other products of the same type design.

Related Service Information

We reviewed Leonardo Helicopters Bollettino Tecnico (BT) No. 189-038, Revision B, dated October 13, 2016, which specifies repetitively inspecting the tail plane assembly for a crack.

We also reviewed BT No. 189-070, Revision A, dated October 13, 2016, which provides instructions for replacing the tail plane lower fitting with the improved tail plane lower fitting, retromodification part number (P/N) 8G0000P00511.

Proposed AD Requirements

This proposed AD would require, within 50 hours time-in-service (TIS), replacing the tail plane fitting with tail plane retromodification kit P/N 8G0000P00511.

Differences Between This Proposed AD and the EASA AD

The EASA AD requires inspecting the tail plane lower fitting for play within 50 flight hours and thereafter at intervals not to exceed 25 flight hours. If a crack or other damage exists, the EASA AD requires the improved tail plane lower fitting be installed within

10 flight hours. If no crack exists, the EASA AD requires that the improved tail plane lower fitting be installed within 200 flight hours or 2 months, whichever occurs first. This proposed AD would not require inspections and would require installing the improved tail plane lower fitting within 50 hours TIS.

Costs of Compliance

We estimate that this proposed AD would affect 2 helicopters of U.S. Registry and that labor costs average \$85 a work-hour. Based on these estimates, we expect that replacing the tail plane lower fitting with an improved tail plane lower fitting would require 64 work-hours and parts would cost \$15,424 for a total cost of \$20,864 per helicopter and \$41,728 for the U.S. fleet.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. "Subtitle VII: Aviation Programs," describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska to the extent that it justifies making a regulatory distinction; and

4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

We prepared an economic evaluation of the estimated costs to comply with this proposed AD and placed it in the AD docket.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

AgustaWestland S.p.A.: Docket No. FAA–2017–1081; Product Identifier 2017–SW–090–AD.

(a) Applicability

This AD applies to AgustaWestland S.p.A. Model AW189 helicopters, certificated in any category, with a tail plane lower fitting P/N 8G5350A07051 installed.

(b) Unsafe Condition

This AD defines the unsafe condition as a crack on a tail plane fitting, which could result in failure of the tail plane fitting and loss of helicopter control.

(c) Comments Due Date

We must receive comments by July 23, 2018.

(d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

(e) Required Actions

Within 50 hours time-in-service, install tail plane retromodification kit part number 8G0000P00511.

(f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Section, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Martin R. Crane, Aviation Safety Engineer, Regulations & Policy Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222–5110; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

(g) Additional Information

(1) Leonardo Helicopters Bollettino Tecnico (BT) No. 189–038, Revision B, and BT No. 189–070, Revision A, both dated October 13, 2016, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Leonardo S.p.A. Helicopters, Matteo Ragazzi, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39–0331–711756; fax +39–0331–229046; or at <http://www.leonardocompany.com/-/bulletins>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2016–0161, dated August 8, 2016. You may view the EASA AD on the internet at <http://www.regulations.gov> in the AD Docket.

(h) Subject

Joint Aircraft Service Component (JASC) Code: 5510, Horizontal Stabilizer Structure.

Issued in Fort Worth, Texas, on May 15, 2018.

Scott A. Horn,

Deputy Director for Regulatory Operations, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2018–10918 Filed 5–22–18; 8:45 am]

BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2017–0947; Product Identifier 2017–SW–059–AD]

RIN 2120–AA64

Airworthiness Directives; Robinson Helicopter Company Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for Robinson Helicopter Company (Robinson) Model R44 and R44 II helicopters. This proposed AD would require visually checking each tail rotor blade for a crack. This proposed AD is prompted by a report of cracking in

certain tail rotor blades. The actions of this proposed AD are intended to address an unsafe condition on these products.

DATES: We must receive comments on this proposed AD by July 23, 2018.

ADDRESSES: You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.
- *Fax:* 202–493–2251.
- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590–0001.
- *Hand Delivery:* Deliver to the “Mail” address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2017–0947; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the economic evaluation, any comments received, and other information. The street address for Docket Operations (telephone 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact Robinson Helicopter Company, 2901 Airport Drive, Torrance, CA 90505; telephone (310) 539–0508; fax (310) 539–5198; or at <http://www.robinsonheli.com/servletlib.htm>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N–321, Fort Worth, TX 76177.

FOR FURTHER INFORMATION CONTACT: James Guo, Aerospace Engineer, Los Angeles ACO Branch, Compliance & Airworthiness Division, FAA, 3960 Paramount Blvd., Lakewood, California 90712; telephone (562) 627–5357; email james.guo@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that might result