

Proposed Rules

Federal Register

Vol. 83, No. 102

Friday, May 25, 2018

This section of the FEDERAL REGISTER contains notices to the public of the proposed issuance of rules and regulations. The purpose of these notices is to give interested persons an opportunity to participate in the rule making prior to the adoption of the final rules.

DEPARTMENT OF THE TREASURY

Office of the Comptroller of the Currency

12 CFR Part 6

[Docket ID OCC–2018–0002]

RIN 1557–AE35

FEDERAL RESERVE SYSTEM

12 CFR Parts 208, 217, and 252

[Docket No. R–1604]

RIN 7100 AF–03

Regulatory Capital Rules: Regulatory Capital, Enhanced Supplementary Leverage Ratio Standards for U.S. Global Systemically Important Bank Holding Companies and Certain of Their Subsidiary Insured Depository Institutions; Total Loss-Absorbing Capacity Requirements for U.S. Global Systemically Important Bank Holding Companies

AGENCY: Office of the Comptroller of the Currency, Treasury, and the Board of Governors of the Federal Reserve System.

ACTION: Notice; extension of comment period.

SUMMARY: On April 19, 2018, the Board of Governors of the Federal Reserve System (Board) and the Office of the Comptroller of the Currency (OCC) published in the *Federal Register* a proposal to modify the enhanced supplementary leverage ratio standards for U.S. top-tier bank holding companies identified as global systemically important bank holding companies, or GSIBs, and certain of their insured depository institution subsidiaries. The proposal also included conforming modifications to the Board's total-loss absorbing capacity and long-term debt rules. The Board and the OCC have determined that an extension of the comment period until June 25, 2018, is appropriate.

DATES: Comments must be received by June 25, 2018.

ADDRESSES: You may submit comments by any of the methods identified in the proposal.

FOR FURTHER INFORMATION CONTACT:

OCC: Venus Fan, Risk Expert (202) 649–6514, Capital and Regulatory Policy; or Carl Kaminski, Special Counsel; Allison Hester-Haddad, Counsel, or Christopher Rafferty, Attorney, Legislative and Regulatory Activities Division, (202) 649–5490 or, for persons who are deaf or hearing impaired, TTY, (202) 649–5597, Office of the Comptroller of the Currency, 400 7th Street SW, Washington, DC 20219.

Board: Constance M. Horsley, Deputy Associate Director, (202) 452–5239; Elizabeth MacDonald, Manager, (202) 475–6316, Holly Kirkpatrick, Supervisory Financial Analyst, (202) 452–2796, or Noah Cuttler, Senior Financial Analyst (202) 912–4678, Capital and Regulatory Policy, Division of Banking Supervision and Regulation; or Benjamin W. McDonough, Assistant General Counsel, (202) 452–2036; David Alexander, Counsel, (202) 452–2877, Greg Frischmann, Counsel, (202) 452–2803, Mark Buresh, Senior Attorney, (202) 452–5270, or Mary Watkins, Attorney, (202) 452–3722, Legal Division, Board of Governors of the Federal Reserve System, 20th and C Streets NW, Washington, DC 20551. For the hearing impaired only, Telecommunication Device for the Deaf (TDD), (202) 263–4869.

SUPPLEMENTARY INFORMATION: On April 19, 2018, the Board of Governors of the Federal Reserve System (Board) and the Office of the Comptroller of the Currency (OCC) published in the *Federal Register* a proposal to amend the enhanced supplementary leverage ratio (eSLR) standards of the Board and the OCC.¹ The proposal stated that the comment period would close on May 21, 2018. Commenters have requested that the Board and the OCC extend the comment period. An extension of the comment period will provide additional opportunity for the public to consider the proposal and prepare comments, including to address the questions posed by the Board and the OCC. Therefore, the Board and the OCC are extending the end of the comment

period for the proposal from May 21, 2018 to June 25, 2018.

Dated: May 22, 2018

Joseph M. Otting,

Comptroller of the Currency.

By order of the Board of Governors of the Federal Reserve System, acting through the Secretary of the Board under delegated authority, May 17, 2018.

Ann E. Misback,

Secretary of the Board.

[FR Doc. 2018–11336 Filed 5–24–18; 8:45 am]

BILLING CODE 4810–33–6210–01–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2018–0448; Product Identifier 2017–NM–129–AD]

RIN 2120–AA64

Airworthiness Directives; Fokker Services B.V. Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes. This proposed AD was prompted by a report of cracks, in various directions, in the lower portion of a main landing gear (MLG) piston. This proposed AD would require a detailed visual inspection of the MLG, and replacement if necessary. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by July 9, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5

¹83 FR 17317 (April 19, 2018).

p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone: +31 (0)88-6280-350; fax: +31 (0)88-6280-111; email: technicalservices@fokker.com; internet: <http://www.myfokkerfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0448; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2018-0448; Product Identifier 2017-NM-129-AD” at the beginning of your comments. We specifically invite

comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2017-0163, dated September 4, 2017; corrected September 5, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes. The MCAI states:

An occurrence was reported where, during a walk around check, a number of cracks, in various directions, were discovered in the lower portion of a MLG piston, Part Number (P/N) 41141-5. No technical investigation results are available as yet, but based on a previous event, as a result of which EASA issued AD 2009-0221R1, later superseded by [EASA] AD 2011-0159, stress corrosion is suspected to have caused these cracks.

This condition, if not detected and corrected, could lead to MLG failure during the landing roll-out, possibly resulting in damage to the aeroplane and injury to occupants.

To address this potential unsafe condition, Fokker Services published Service Bulletin (SB) SBF100-32-169 to provide inspection instructions.

For the reasons described above, this [EASA] AD requires a one-time detailed visual inspection (DVI) of the MLG pistons for cracks and, depending on findings, replacement. This [EASA] AD also requires

the reporting of inspection results to Fokker Services.

This [EASA] AD has been republished to correct wrong P/N references in paragraphs (1) and (4).

This [EASA] AD is considered an interim measure and further [EASA] AD action may follow.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0448.

Related Service Information Under 1 CFR Part 51

Fokker Services B.V. has issued Fokker Service Bulletin SBF100-32-169, dated August 23, 2017. The service information describes procedures for a detailed visual inspection of the MLG, and replacement if necessary. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all pertinent information and determined an unsafe condition exists and is likely to exist or develop on other products of the same type design.

Costs of Compliance

We estimate that this proposed AD affects 5 airplanes of U.S. registry.

We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Detailed visual inspection	3 work-hours × \$85 per hour = \$255	\$0	\$255	\$1,275
Reporting	1 work-hour × \$85 per hour = \$85	0	85	425

We estimate the following costs to do any necessary replacement that would

be required based on the results of the proposed inspection. We have no way of

determining the number of aircraft that might need this replacement:

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
MLG Replacement	12 work-hours × \$85 per hour = \$1,020	\$95,000	\$96,020

Paperwork Reduction Act

A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB control number. The control number for the collection of information required by this NPRM is 2120-0056. The paperwork cost associated with this NPRM has been detailed in the Costs of Compliance section of this document and includes time for reviewing instructions, as well as completing and reviewing the collection of information. Therefore, all reporting associated with this NPRM is mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at 800 Independence Ave. SW, Washington, DC 20591, ATTN: Information Collection Clearance Officer, AES-200.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in "Subtitle VII, Part A, Subpart III, Section 44701: General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications

under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a "significant regulatory action" under Executive Order 12866;
2. Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Fokker Services B.V.: Docket No. FAA-2018-0448; Product Identifier 2017-NM-129-AD.

(a) Comments Due Date

We must receive comments by July 9, 2018.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes, certificated in any category, all manufacturer serial numbers, if equipped with Goodrich main landing gear (MLG).

(d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

(e) Reason

This AD was prompted by a report of cracks, in various directions, in the lower portion of a MLG piston. We are issuing this AD to detect and correct cracks in the lower portion of the MLG, which could lead to

MLG failure during the landing roll-out, and possibly result in damage to the airplane and injury to occupants.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) One-Time Detailed Visual Inspection

Within 30 days after the effective date of this AD, do a detailed visual inspection of each MLG piston part number 41141-5, in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-32-169, dated August 23, 2017.

(h) Corrective Actions

If any crack is found, during any inspection required by paragraph (g) of this AD, before further flight, replace the MLG piston with a serviceable piston (*i.e.*, a new piston, a piston that has not accumulated any flight cycles since overhaul, or a piston that has been inspected as required by paragraph (g) of this AD and has no cracks), in accordance with the Accomplishment Instructions of Fokker Service Bulletin SBF100-32-169, dated August 23, 2017.

(i) Reporting

(1) Submit a report of the findings (both positive and negative) of the inspection required by paragraph (g) of this AD to Fokker Services B.V., Technical Services, fax: +31 (0)25-2627-211; email: technicalservices@fokker.com, at the applicable time specified in paragraph (i)(1)(i) or (i)(1)(ii) of this AD. The report must include the information specified in the questionnaire of Fokker Service Bulletin SBF100-32-169, dated August 23, 2017.

(i) If the inspection was done on or after the effective date of this AD: Submit the report within 30 days after the inspection.

(ii) If the inspection was done before the effective date of this AD: Submit the report within 30 days after the effective date of this AD.

(2) Although Fokker Service Bulletin SBF100-32-169, dated August 23, 2017, specifies to submit certain information to Goodrich, this AD does not include that requirement.

(j) Parts Installation Limitations

As of the effective date of this AD, it is allowed to install a piston P/N 41141-5, or a replacement MLG with a piston P/N 41141-5, on any airplane, provided the piston is new, or has not accumulated any flight cycles since overhaul, or has been inspected as required by paragraph (g) of this AD and has no cracks.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information

directly to the International Section, send it to the attention of the person identified in paragraph (1)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Fokker Services B.V.'s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Reporting Requirements:* A federal agency may not conduct or sponsor, and a person is not required to respond to, nor shall a person be subject to a penalty for failure to comply with a collection of information subject to the requirements of the Paperwork Reduction Act unless that collection of information displays a current valid OMB Control Number. The OMB Control Number for this information collection is 2120-0056. Public reporting for this collection of information is estimated to be approximately 1 hour per response, including the time for reviewing instructions, completing and reviewing the collection of information. All responses to this collection of information are mandatory. Comments concerning the accuracy of this burden and suggestions for reducing the burden should be directed to the FAA at: 800 Independence Ave. SW, Washington, DC 20591, Attn: Information Collection Clearance Officer, AES-200.

(I) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2017-0163, dated September 4, 2017; corrected September 5, 2017; for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0448.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3226.

(3) For service information identified in this AD, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; telephone: +31 (0)88-6280-350; fax: +31 (0)88-6280-111; email: technicalservices@fokker.com; internet: <http://www.myfokkerfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on May 15, 2018.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-11135 Filed 5-24-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0416; Product Identifier 2017-NM-164-AD]

RIN 2120-AA64

Airworthiness Directives; Airbus Defense and Space S.A. (Formerly Known as Construcciones Aeronauticas, S.A.) Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Airbus Defense and Space S.A. Model CN-235, CN-235-100, CN-235-200, and CN-235-300 airplanes; and certain Model C-295 airplanes. This proposed AD was prompted by a report that cracks were found on the stabilizer-to-fuselage rear attachment fitting. This proposed AD would require a detailed inspection of the upper and lower lugs of each horizontal stabilizer-to-fuselage rear attachment fitting, repair if necessary, and a report of findings. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by July 9, 2018.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus Defense and Space Services/Engineering Support, Avenida de Aragón 404, 28022 Madrid, Spain; telephone +34 91 585 55 84; fax

+34 91 585 31 27; email MTA.TechnicalService@airbus.com.

You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0416; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for the Docket Operations office (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3220.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2018-0416; Product Identifier 2017-NM-164-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM based on those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2017-0218, dated November 8, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for all Airbus Defense and Space S.A. Model CN-235, CN-235-100, CN-235-200, and CN-235-300 airplanes; and