

**(c) Applicability**

This AD applies to Honda Aircraft Company LLC Model HA-420 airplanes, all serial numbers, that:

- (1) Have power brake valve, part number (P/N) HJ1-13243-101-005 or HJ1-13243-101-007, installed; and
- (2) are certificated in any category.

**(d) Subject**

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 32, Landing Gear.

**(e) Unsafe Condition**

This AD was prompted by reports of unannounced asymmetric braking during ground operations and landing deceleration. We are issuing this AD to detect failure of the power brake valve (PBV). The unsafe condition, if not addressed, could result in degraded braking performance and reduced directional control during ground operations and landing deceleration.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Insert Temporary Revision Into the Airplane Flight Manual (AFM)**

Before further flight after May 29, 2018 (the effective date retained from AD 2018-11-05) insert Honda Aircraft Company Temporary Revision TR 01.1, dated February 16, 2018, into the Honda Aircraft Company (Honda) HA-420 Airplane Flight Manual (AFM) (“the temporary revision”). The procedures listed in the temporary revision are required while operating with PBV P/N HJ1-13243-101-005 or P/N HJ1-13243-101-007 installed. This insertion and the steps therein may be performed by the owner/operator (pilot) holding at least a private pilot certificate and must be entered into the airplane records showing compliance with this AD in accordance with 14 CFR 43.9(a)(1)-(4) and 14 CFR 91.417(a)(2)(v). The record must be maintained as required by 14 CFR 91.417, 121.380, or 135.439.

**(h) No Reporting Requirement**

Although Honda Service Bulletin SB-420-32-001, dated January 8, 2018, and Revision B, dated April 16, 2018, specify submitting certain information to the manufacturer, this AD does not require that action.

**(i) Replace the Power Brake Valve**

As of and at any time after May 29, 2018 (the effective date retained from AD 2018-11-05), if any of the procedures listed in the temporary revision referenced in paragraph (g) of this AD reveal a leaking PBV, before further flight, replace the installed PBV, P/N HJ1-13243-101-005 or P/N HJ1-13243-101-007, with the improved design PBV, P/N HJ1-13243-101-009. The replacement must be done using the Accomplishment Instructions in either Honda Service Bulletin SB-420-32-001, dated January 8, 2018, or Revision B, dated April 16, 2018. Before further flight after installing P/N HJ1-13243-101-009, remove the temporary revision from the Honda HA-420 AFM.

**(j) Optional Terminating Action for Inserting the AFM Temporary Revision/Pilot Checks**

(1) Instead of inserting the temporary revision or at any time after inserting the temporary revision required by paragraph (g) of this AD and before the mandatory replacement required in paragraph (j) of this AD, you may replace the installed PBV, P/N HJ1-13243-101-005 or P/N HJ1-13243-101-007, with the improved design PBV, P/N HJ1-13243-101-009. The replacement must be done using the Accomplishment Instructions in either Honda Service Bulletin SB-420-32-001, dated January 8, 2018, or Revision B, dated April 16, 2018. Before further flight after installing P/N HJ1-13243-101-009, remove the temporary revision from the Honda HA-420 AFM.

(2) The on-condition replacement required by paragraph (h) of this AD is still required before further flight.

**(k) Mandatory Replacement**

Within the next 12 months after the effective date of this AD, replace the installed PBV, P/N HJ1-13243-101-005 or P/N HJ1-13243-101-007, with the improved design PBV, P/N HJ1-13243-101-009. The replacement must be done using the Accomplishment Instructions in either Honda Service Bulletin SB-420-32-001, dated January 8, 2018, or Revision B, dated April 16, 2018. Before further flight after installing P/N HJ1-13243-101-009, remove the temporary revision from the Honda HA-420 AFM.

**(l) Special Flight Permit**

Special flight permits for the AFM Limitations portion of this AD are prohibited. Special flight permits for the PBV replacement required in this AD are permitted with the following limitations: One ferry flight, including fuel stops, to service center with Honda Aircraft Company Temporary Revision TR 01.1, dated February 16, 2018, incorporated into the Honda HA-420 AFM.

**(m) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Atlanta ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (n) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (h) through (j) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

**(n) Related Information**

(1) For more information about this AD, contact Samuel Kovitch, Aerospace Engineer, Atlanta ACO Branch, FAA, 1701 Columbia Avenue, College Park, Georgia 30337; phone: (404) 474-5570; fax: (404) 474-5605; email: [samuel.kovitch@faa.gov](mailto:samuel.kovitch@faa.gov).

(2) For service information identified in this AD, contact Honda Aircraft Company LLC, 6430 Ballinger Road, Greensboro, North Carolina 27410; telephone (336) 662-0246; internet: <http://www.hondajet.com>. FAA, Policy and Innovation Division, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on May 29, 2018.

**Melvin J. Johnson,**

*Aircraft Certification Service, Deputy Director, Policy and Innovation Division, AIR-601.*

[FR Doc. 2018-12127 Filed 6-6-18; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2018-0504; Product Identifier 2018-NM-046-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model 707 series airplanes and Model 720 and 720B series airplanes. This proposed AD was prompted by a report indicating that a fracture of the midspar fitting resulted in the separation of the inboard strut and engine from the airplane, and a determination that existing inspections are not sufficient for timely detection of cracking. This proposed AD would require repetitive inspections of certain nacelle strut spar and overwing fittings, and diagonal braces and associated fittings; replacement of the diagonal brace assembly on certain airplanes; and applicable related investigative and corrective actions. We are proposing

this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by July 23, 2018.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0504.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0504; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Jeffrey Chang, Aerospace Engineer, Propulsion Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5263; fax: 562-627-5210; email: [jeffrey.chang@faa.gov](mailto:jeffrey.chang@faa.gov) or George Garrido, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5232; fax: 562-627-5210; email [george.garrido@faa.gov](mailto:george.garrido@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2018-0504; Product Identifier 2018-NM-046-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

##### Discussion

We have received reports of cracking of the midspar fittings and of the engine and nacelle strut separating from the airplane. We issued AD 2012-16-12, Amendment 39-16159 (77 FR 49708, August 17, 2012) to require inspection of the inboard and outboard strut midspar fittings and AD 2015-11-04, Amendment 39-18167 (80 FR 30605, May 29, 2015) to require replacement of all engine strut midspar fittings and to initiate a life limit program. Since that time, we have determined that inspections of other strut fittings are needed for timely detection of cracking. Cracks have been reported in the diagonal brace end fittings, forward mating fittings, aft mating fittings, overwing support fittings, and the upper surface and the aft lug(s) of the front spar fittings on the nacelle struts, numbers 1, 2, 3 and 4. This cracking is attributed to fatigue in the end fittings and stress corrosion or fatigue in the mating fittings. This condition, if not addressed, could result in cracks that grow beyond a critical length, allowing strut fittings to fail and reducing the structural integrity of the nacelle. This, in combination with damage to adjacent attachment structure, could result in the loss of an engine from the airplane.

##### Related Service Information Under 1 CFR Part 51

We reviewed the following service information.

- Boeing 707 Alert Service Bulletin A3364, Revision 4, dated February 21, 2017. The service information describes procedures for repetitive detailed inspections of the diagonal brace tube for any crack; repetitive detailed

inspections and high frequency eddy current (HFEC) inspections of the nacelle strut diagonal brace end fittings, forward mating fitting, and aft mating fitting for any crack; an alternative dye penetrant inspection of vertical webs on aft mating fitting for any crack; an HFEC inspection of the diagonal brace tube for any crack; and corrective actions.

- Boeing 707 Alert Service Bulletin A3365, Revision 3, dated March 9, 2017. The service information describes procedures for repetitive detailed, HFEC, and ultrasonic inspections of the overwing support fittings for any crack at the bolt hole forward of the wing front spar and at the holes for the four fasteners attaching the fitting to the spar, and related investigative and corrective actions.

- Boeing 707 Alert Service Bulletin A3514, Revision 1, dated November 9, 2016. The service information describes procedures for repetitive detailed and surface HFEC inspections of the front spar fittings at nacelle struts numbers 1, 2, 3, and 4 for cracks, and replacement of cracked front spar fittings.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

##### FAA's Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of these same type designs.

##### Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in the service information described previously, except as discussed under “Differences Between this Proposed AD and the Service Information.” For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0504.

The phrase “related investigative actions” is used in this proposed AD. Related investigative actions are follow-on actions that (1) are related to the primary action, and (2) further investigate the nature of any condition found. Related investigative actions in an AD could include, for example, inspections.

The phrase “corrective actions” is used in this proposed AD. Corrective actions correct or address any condition found. Corrective actions in an AD could include, for example, repairs.

**Differences Between This Proposed AD and the Service Information**

Boeing 707 Alert Service Bulletin A3364, Revision 4, dated February 21, 2017; Boeing 707 Alert Service Bulletin A3365, Revision 3, dated March 9, 2017; and Boeing 707 Alert Service Bulletin A3514, Revision 1, dated November 9, 2016; specify to contact the manufacturer for certain instructions,

but this proposed AD would require using repair methods, modification deviations, replacement deviations, and alteration deviations in one of the following ways:

- In accordance with a method that we approve; or
- Using data that meet the certification basis of the airplane, and that have been approved by the Boeing

Commercial Airplanes Organization Designation Authorization (ODA) whom we have authorized to make those findings.

**Costs of Compliance**

We estimate that this proposed AD affects 65 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Detailed inspections per Service Bulletin A3364, Revision 4.	36 work-hours × \$85 per hour = \$3,060 per inspection cycle.	\$0	\$3,060 per inspection cycle.	\$198,900 per inspection cycle.
HFEC inspections per Service Bulletin A3364, Revision 4.	128 work-hours × \$85 per hour = \$10,880 per inspection cycle.	0	\$10,880 per inspection cycle.	\$707,200 per inspection cycle.
Inspections per Service Bulletin A3365, Revision 3.	20 work-hours × \$85 per hour = \$1,700 per inspection cycle.	0	\$1,700 per inspection cycle.	\$110,500 per inspection cycle.
Detailed inspections per Service Bulletin A3514, Revision 1.	12 work-hours × \$85 per hour = \$1,020 per inspection cycle.	0	\$1,020 per inspection cycle.	\$66,300 per inspection cycle.
HFEC inspections per Service Bulletin A3514, Revision 1.	32 work-hours × \$85 per hour = \$2,720 per inspection cycle.	0	\$2,720 per inspection cycle.	\$176,800 per inspection cycle.

We have received no definitive data that would enable us to provide cost estimates for the on-condition actions specified in this proposed AD.

We estimate that any necessary proposed replacement of affected fittings would take about 96 work-hours for a cost of \$8,160 per fitting. We have received no definitive data on the parts costs of the affected fittings. We have no way of determining the number of aircraft that might need this replacement.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by

FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**The Boeing Company:** Docket No. FAA-2018-0504; Product Identifier 2018-NM-046-AD.

**(a) Comments Due Date**

We must receive comments by July 23, 2018.

**(b) Affected ADs**

This AD affects AD 82-24-03, Amendment 39-4496 (47 FR 51099, November 12, 1982) ("AD 82-24-03") and AD 2005-08-15, Amendment 39-14067 (70 FR 21136, April 25, 2005) ("AD 2005-08-15").

**(c) Applicability**

This AD applies to all The Boeing Company Model 707-100 Long Body, -200, -100B Long Body, and -100B Short Body series airplanes; Model 707-300, -300B, -300C, and -400 series airplanes; and Model 720 and 720B series airplanes; certificated in any category.

**(d) Subject**

Air Transport Association (ATA) of America Code 54, Nacelles/pylons.

**(e) Unsafe Condition**

This AD was prompted by a report indicating that a fracture of the midspar fitting resulted in the separation of the inboard strut and engine from the airplane, and a determination that existing inspections for other nacelle strut fittings are not sufficient for timely detection of cracking. We are issuing this AD to address cracks, which if not detected and corrected, could grow beyond a critical length, allowing the strut fitting to fail and reducing the structural integrity of the nacelle. This, in combination with damage to adjacent attachment structure, could result in the loss of an engine from the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Repetitive Detailed Inspections of the Front Spar Fittings at Nacelle Struts Numbers 1, 2, 3, and 4**

Prior to the accumulation of 3,500 total flight hours; within 700 flight hours after the most recent inspection specified in Boeing 707 Alert Service Bulletin A3514, dated July 29, 2004, was done; or within three months after the effective date of this AD; whichever occurs later: Do a detailed inspection for cracking of the front spar fittings at nacelle struts numbers 1, 2, 3, and 4, in accordance with the Accomplishment Instructions of Boeing 707 Alert Service Bulletin A3514, Revision 1, dated November 9, 2016. If any cracking is found, before further flight, replace the affected fitting, in accordance with the Accomplishment Instructions of Boeing 707 Alert Service Bulletin A3514, Revision 1, dated November 9, 2016. Repeat the inspections thereafter at intervals not to exceed 700 flight hours.

**(h) Repetitive Surface High Frequency Eddy Current (HFEC) Inspections of the Aft Lugs on the Front Spar Fittings at Nacelle Struts Numbers 1, 2, 3, and 4**

Within 1,500 flight cycles or 48 months after the most recent detailed inspection required by paragraph (g) of this AD was done, whichever occurs first, do a surface HFEC inspection for cracking of the aft lugs on the front spar fittings at nacelle struts numbers 1, 2, 3, and 4, and do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing 707 Alert Service Bulletin A3514, Revision 1, dated November 9, 2016, except as required by paragraph (l)(4) of this AD. Do all applicable corrective actions before further flight. Repeat the inspection thereafter at intervals not to exceed 1,500 flight cycles or 48 months, whichever occurs first.

**(i) Repetitive Inspections of the Overwing Support Fitting at Nacelle Struts Numbers 1, 2, 3, and 4**

At the times specified in paragraph 1.E., "Compliance," of Boeing 707 Alert Service Bulletin A3365, Revision 3, dated March 9, 2017, except as required by paragraph (l)(1) of this AD: Do the inspections specified in paragraphs (i)(1) through (i)(3) of this AD and do all applicable related investigative and

corrective actions, in accordance with the Accomplishment Instructions of Boeing 707 Alert Service Bulletin A3365, Revision 3, dated March 9, 2017, except as required by paragraph (l)(3) of this AD. Do all applicable related investigative and corrective actions before further flight. Repeat the inspections thereafter at the applicable time specified in paragraph 1.E., "Compliance," of Boeing 707 Alert Service Bulletin A3365, Revision 3, dated March 9, 2017.

(1) Do a detailed inspection for any crack at all five holes in the overwing support fitting, and at the flange radii.

(2) Do the inspection specified in paragraph (i)(2)(i) or (i)(2)(ii) of this AD.

(i) Do a surface HFEC inspection for any crack in the overwing support fitting around the hole immediately forward of the spar chord, with the bolt in place, and at the flange radii.

(ii) Do an open hole HFEC inspection for any crack in the overwing support fitting at the hole immediately forward of the spar chord.

(3) Do the inspection specified in paragraph (i)(3)(i) or (i)(3)(ii) of this AD.

(i) Do an ultrasonic inspection for any crack in the overwing support fitting around the four holes common to the fitting and the spar chord, with the bolts in place.

(ii) Do a surface HFEC inspection for any crack in the overwing support fitting around the four holes common to the fitting and the spar chord, with the bolts in place.

**(j) Inspections of the Nacelle Strut Diagonal Braces and Associated Fittings**

For airplanes with nacelle strut diagonal braces and associated fittings which have accumulated 7,500 flight cycles or more: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing 707 Alert Service Bulletin A3364, Revision 4, dated February 21, 2017, except as required by paragraph (l)(2) of this AD, do the inspections specified in paragraphs (j)(1) through (j)(3) of this AD. Repeat the inspections thereafter at the applicable intervals specified in tables 1, 2, 3, and 4 of paragraph 1.E., "Compliance," of Boeing 707 Alert Service Bulletin A3364, Revision 4, dated February 21, 2017. If any crack is found during any inspection required by this paragraph, before further flight, do all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing 707 Alert Service Bulletin A3364, Revision 4, dated February 21, 2017, except as required by paragraph (l)(3) of this AD.

(1) Do a detailed inspection of the nacelle strut diagonal brace end fittings, diagonal brace tube, forward mating fitting, and aft mating fitting for any crack.

(2) Do HFEC inspections of the nacelle strut diagonal brace end fittings, forward mating fitting, and aft mating fitting for any crack. As an alternative for the aft mating fitting, do a dye penetrant inspection of vertical webs on aft mating fitting for any crack.

(3) Do an HFEC inspection of the diagonal brace tube for any crack.

**(k) Replacement**

For Group 3, 4, and 6 airplanes as identified in Boeing 707 Alert Service

Bulletin A3364, Revision 4, dated February 21, 2017, on which the outboard diagonal brace end fitting (forward or aft) attach holes have been oversized as specified in Boeing 707 Alert Service Bulletin A3364, Revision 4, dated February 21, 2017: Within 1,000 flight cycles after the effective date of this AD, replace the diagonal brace assembly, in accordance with Figure 3 of Boeing 707 Alert Service Bulletin A3364, Revision 4, dated February 21, 2017.

**(l) Exceptions to Service Information Specifications**

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing 707 Alert Service Bulletin A3365, Revision 3, dated March 9, 2017, uses the phrase "the Revision 3 date of this service bulletin," this AD requires using "the effective date of this AD."

(2) For purposes of determining compliance with the requirements of this AD: Where Boeing 707 Alert Service Bulletin A3364, Revision 4, dated February 21, 2017, uses the phrase "the Revision 4 date of this service bulletin," this AD requires using "the effective date of this AD."

(3) Where Boeing 707 Alert Service Bulletin A3364, Revision 4, dated February 21, 2017; and Boeing 707 Alert Service Bulletin A3365, Revision 3, dated March 9, 2017; specify contacting Boeing: This AD requires repair using a method approved in accordance with the procedures specified in paragraph (o) of this AD.

(4) Where Boeing 707 Alert Service Bulletin A3514, Revision 1, dated November 9, 2016, specifies contacting Boeing: This AD requires replacement using a method approved in accordance with the procedures specified in paragraph (o) of this AD.

**(m) Terminating Action for Other ADs**

(1) Accomplishing the initial inspections required by paragraph (j) of this AD terminates all requirements of AD 82-24-03.

(2) Accomplishing the initial inspections required by paragraph (g) of this AD, terminates all requirements of AD 2005-08-15.

**(n) Parts Installation Prohibition**

As of the effective date of this AD, no person may install, on any airplane, a front spar fitting having a part number other than the part numbers specified in paragraph 2.C.2. of Boeing 707 Alert Service Bulletin A3514, Revision 1, dated November 9, 2016.

**(o) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person(s) identified in paragraph (p)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager

of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, replacement, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, replacement deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

#### (p) Related Information

(1) For more information about this AD, contact Jeffrey Chang, Aerospace Engineer, Propulsion Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5263; fax: 562-627-5210; email: [jeffrey.chang@faa.gov](mailto:jeffrey.chang@faa.gov) or George Garrido, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5232; fax: 562-627-5210; email [george.garrido@faa.gov](mailto:george.garrido@faa.gov).

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on May 24, 2018.

**James Cashdollar,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018-12128 Filed 6-6-18; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0517; Product Identifier 2017-SW-098-AD]

RIN 2120-AA64

#### Airworthiness Directives; Airbus Helicopters Deutschland GmbH Helicopters

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for Airbus Helicopters Deutschland GmbH (Airbus Helicopters) Model MBB-BK 117 C-2

and MBB-BK 117 D-2 helicopters. This proposed AD would require altering and re-identifying the overhead panel shock mount assembly (shock mount). This proposed AD is prompted by the manufacturer's stress recalculations. The actions of this proposed AD are intended to correct an unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by August 6, 2018.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Docket:* Go to <http://www.regulations.gov>. Follow the online instructions for sending your comments electronically.
- *Fax:* 202-493-2251.
- *Mail:* Send comments to the U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590-0001.

- *Hand Delivery:* Deliver to the "Mail" address between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0517; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the European Aviation Safety Agency (EASA) AD, the economic evaluation, any comments received, and other information. The street address for Docket Operations (telephone 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

For service information identified in this proposed rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; telephone (972) 641-0000 or (800) 232-0323; fax (972) 641-3775; or at [http://www.helicopters.airbus.com/website/en/ref/Technical-Support\\_73.html](http://www.helicopters.airbus.com/website/en/ref/Technical-Support_73.html). You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

**FOR FURTHER INFORMATION CONTACT:** Matt Fuller, Senior Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email [matthew.fuller@faa.gov](mailto:matthew.fuller@faa.gov).

**SUPPLEMENTARY INFORMATION:**

#### Comments Invited

We invite you to participate in this rulemaking by submitting written comments, data, or views. We also invite comments relating to the economic, environmental, energy, or federalism impacts that might result from adopting the proposals in this document. The most helpful comments reference a specific portion of the proposal, explain the reason for any recommended change, and include supporting data. To ensure the docket does not contain duplicate comments, commenters should send only one copy of written comments, or if comments are filed electronically, commenters should submit only one time.

We will file in the docket all comments that we receive, as well as a report summarizing each substantive public contact with FAA personnel concerning this proposed rulemaking. Before acting on this proposal, we will consider all comments we receive on or before the closing date for comments. We will consider comments filed after the comment period has closed if it is possible to do so without incurring expense or delay. We may change this proposal in light of the comments we receive.

#### Discussion

EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD No. 2017-0026, dated February 14, 2017, to correct an unsafe condition for Airbus Helicopters Model MBB-BK 117 C-2, MBB-BK117 C-2e, MBB-BK 117 D-2, and MBB-BK117 D-2m helicopters. EASA advises that a recent stress calculation identified that the shock mount may not withstand certification crash loads. EASA states that this condition, if not corrected, could lead to the overhead panel disconnecting during an emergency landing and injuring occupants. Accordingly, the EASA AD requires modifying and re-identifying the shock mounts.

#### FAA's Determination

These helicopters have been approved by the aviation authority of Germany and are approved for operation in the United States. Pursuant to our bilateral agreement with Germany, EASA, its technical representative, has notified us of the unsafe condition described in its AD. We are proposing this AD because we evaluated all known relevant information and determined that an unsafe condition is likely to exist or develop on other products of the same type design.