

(v) Add together the amounts computed in paragraphs (c)(3)(i) through (v) of this section and from that sum deduct any payment made pursuant to paragraph (c)(1) of this section.

(d) *Handler underpayment proration.* If a handler has not received full payment from the market administrator pursuant to § 1051.72 by the payment date specified in paragraph (a), (b), or (c) of this section, the handler may reduce pro rata its payments to producers or to the cooperative association (with respect to receipts described in paragraph (b) of this section, prorating the underpayment to the volume of milk received from the cooperative association in proportion to the total milk received from producers by the handler), but not by more than the amount of the underpayment. The payments shall be completed on the next scheduled payment date after receipt of the balance due from the market administrator.

(e) *Payments to missing or deceased producers.* If a handler claims that a required payment to a producer cannot be made because the producer is deceased or cannot be located, or because the cooperative association or its lawful successor or assignee is no longer in existence, the payment shall be made to the producer-settlement fund, and in the event that the handler subsequently locates and pays the producer or a lawful claimant, or in the event that the handler no longer exists and a lawful claim is later established, the market administrator shall make the required payment from the producer-settlement fund to the handler or to the lawful claimant, as the case may be.

(f) *Producer payment record.* In making payments to producers pursuant to this section, each handler shall furnish each producer, except a producer whose milk was received from a cooperative association handler described in § 1000.9(a) or (c), a supporting statement in a form that may be retained by the recipient which shall show:

(1) The name, address, Grade A identifier assigned by a duly constituted regulatory agency, and payroll number of the producer;

(2) The daily and total pounds, and the month and dates such milk was received from that producer;

(3) The total pounds of butterfat, protein, and other solids contained in the producer's milk;

(4) The minimum rate or rates at which payment to the producer is required pursuant to the order in this part;

(5) The rate used in making payment if the rate is other than the applicable minimum rate;

(6) The amount, or rate per hundredweight, or rate per pound of component, and the nature of each deduction claimed by the handler; and

(7) The net amount of payment to the producer or cooperative association.

§ 1051.74 [Reserved]

§ 1051.75 Plant location adjustments for producer milk and nonpool milk.

For purposes of making payments for producer milk and nonpool milk, a plant location adjustment shall be determined by subtracting the Class I price specified in § 1051.51 from the Class I price at the plant's location. The difference, plus or minus as the case may be, shall be used to adjust the payments required pursuant to §§ 1051.73 and 1000.76.

§ 1051.76 Payments by a handler operating a partially regulated distributing plant.

See § 1000.76.

§ 1051.77 Adjustment of accounts.

See § 1000.77.

§ 1051.78 Charges on overdue accounts.

See § 1000.78.

Administrative Assessment and Marketing Service Deduction

§ 1051.85 Assessment for order administration.

On or before the payment receipt date specified under § 1051.71, each handler shall pay to the market administrator its pro rata share of the expense of administration of the order at a rate specified by the market administrator that is no more than 8 cents per hundredweight with respect to:

(a) Receipts of producer milk (including the handler's own production) other than such receipts by a handler described in § 1000.9(c) that were delivered to pool plants of other handlers;

(b) Receipts from a handler described in § 1000.9(c);

(c) Receipts of concentrated fluid milk products from unregulated supply plants and receipts of nonfluid milk products assigned to Class I use pursuant to § 1000.43(d) and other source milk allocated to Class I pursuant to § 1000.44(a)(3) and (8) and the corresponding steps of § 1000.44(b), except other source milk that is excluded from the computations pursuant to § 1051.60(h) and (i); and

(d) Route disposition in the marketing area from a partially regulated distributing plant that exceeds the skim

milk and butterfat subtracted pursuant to § 1000.76(a)(1)(i) and (ii).

§ 1051.86 Deduction for marketing services.

See § 1000.86.

Subpart D—Miscellaneous Provisions

§ 1051.90 Dates.

See § 1000.90.

Dated: June 4, 2018.

Bruce Summers,
Administrator, Agricultural Marketing Service.

[FR Doc. 2018–12245 Filed 6–7–18; 8:45 am]

BILLING CODE 3410–02–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2018–0074; Product Identifier 2017–NM–148–AD; Amendment 39–19309; AD 2018–12–05]

RIN 2120–AA64

Airworthiness Directives; the Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all The Boeing Company Model 737–100, –200, –200C, –300, –400, and –500 series airplanes. This AD was prompted by reports of cracks found in the rear spar web and lower chord on the left and right wings. This AD requires repetitive detailed inspections for cracking of the rear spar web and lower chord, and applicable on-condition actions. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 13, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 13, 2018.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0074.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0074; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is Docket Operations, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Payman Soltani, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712-4137; phone: 562-627-5313; fax: 562-627-5210; email: payman.soltani@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all The Boeing Company Model 737-100, -200, -200C, -300, -400, and -500 series airplanes. The NPRM published in the **Federal Register** on February 9, 2018 (83 FR 5743). The NPRM was prompted by reports of cracks found in the rear spar web and lower chord on the left and right wings. The NPRM proposed to require repetitive detailed inspections for cracking of the rear spar web and lower chord, and applicable on-condition actions.

We are issuing this AD to address cracks in the rear spar of the left and right wing between wing buttock line (WBL) 91 and WBL 155, which could lead to the inability of a principal structural element to sustain required

flight loads and adversely affect the structural integrity of the airplane.

Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA’s response to each comment.

Support for the NPRM

The Boeing Company stated its support for the NPRM.

Request To Require the Same Grace Period Regardless of Inspection Method

Southwest Airlines (Southwest), requested that we revise paragraph (h) of the proposed AD, which refers to the “Compliance” section of Boeing Alert Requirements Bulletin 737-57A1337 RB, dated September 14, 2017, regarding the different compliance times for the two inspection methods given in Table 1 of the “Compliance” section for Group 2 airplanes. Southwest stated that the planned inspection method should have no bearing on the timing of the inspection, and therefore the compliance times should be the same for both options. They did not specify which of the two compliance times they would favor.

We acknowledge the commenter’s request. While the compliance times for inspections are not normally dependent on the planned inspection method, in this case, the initial compliance times were adjusted to account for differences in the probability of detection using a visual inspection versus an eddy current inspection. Because an eddy current inspection is more capable of detecting smaller cracks than a visual inspection, the initial compliance time was shortened for those airplanes that are inspected using the visual inspection option. We have not changed this AD in this regard.

Effect of Winglets on Accomplishment of the Proposed Actions

Aviation Partners Boeing stated that the installation of winglets using Supplemental Type Certificate (STC) ST01219SE does not affect the actions specified in the NPRM.

We agree with the commenter. We have redesignated paragraph (c) of the proposed AD as paragraph (c)(1) of this AD and added paragraph (c)(2) to this AD to state that installation of STC ST01219SE does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a “change in product” alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

Conclusion

We reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this final rule with the changes described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

Related Service Information Under 14 CFR Part 51

We reviewed Boeing Alert Requirements Bulletin 737-57A1337 RB, dated September 14, 2017. This service information describes procedures for repetitive detailed or surface High Frequency Eddy Current (HFEC) inspections for cracking of the rear spar web and lower chord, and applicable on-condition actions. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 160 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspections	Up to 22 work-hours × \$85 per hour = up to \$1,870 per inspection cycle.	\$0	Up to \$1,870 per inspection cycle.	Up to \$299,200 per inspection cycle.

We have received no definitive data that would enable us to provide cost

estimates for the on-condition actions specified in this AD.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue

rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator,

the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018–12–05 The Boeing Company:

Amendment 39–19309; Docket No. FAA–2018–0074; Product Identifier 2017–NM–148–AD.

(a) Effective Date

This AD is effective July 13, 2018.

(b) Affected ADs

None.

(c) Applicability

(1) This AD applies to all The Boeing Company Model 737–100, –200, –200C, –300, –400, and –500 series airplanes, certificated in any category.

(2) Installation of Supplemental Type Certificate (STC) ST01219SE ([http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/\\$FILE/ST01219SE.pdf](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgstc.nsf/0/ebd1cec7b301293e86257cb30045557a/$FILE/ST01219SE.pdf)) does not affect the ability to accomplish the actions required by this AD. Therefore, for airplanes on which STC ST01219SE is installed, a "change in product" alternative method of compliance (AMOC) approval request is not necessary to comply with the requirements of 14 CFR 39.17.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Unsafe Condition

This AD was prompted by reports of cracks found in the rear spar web and lower chord on the left and right wings. We are issuing this AD to detect and correct cracks in the rear spar of the left and right wing between wing buttock line (WBL) 91 and WBL 155, which could lead to the inability of a principal structural element to sustain required flight loads and adversely affect the structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions for Group 1 Airplanes

For airplanes identified as Group 1 in Boeing Alert Requirements Bulletin 737–57A1337 RB, dated September 14, 2017: Within 120 days after the effective date of this AD, inspect the airplane and do all applicable corrective actions using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(h) Required Actions for Group 2 Airplanes

For airplanes identified as Group 2 in Boeing Alert Requirements Bulletin 737–57A1337 RB, dated September 14, 2017: Except as required by paragraph (i) of this AD, at the applicable times specified in the "Compliance" section of Boeing Alert Requirements Bulletin 737–57A1337 RB, dated September 14, 2017, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 737–57A1337 RB, dated September 14, 2017.

Note 1 to paragraph (h) of this AD:

Guidance for accomplishing the actions required by this AD is included in Boeing Alert Service Bulletin 737–57A1337, dated September 14, 2017, which is referred to in Boeing Alert Requirements Bulletin 737–57A1337 RB, dated September 14, 2017.

(i) Exceptions to Service Information Specifications

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 737–57A1337 RB, dated September 14, 2017, uses the phrase "the original issue date of Requirements Bulletin 737–57A1337 RB," this AD requires using "the effective date of this AD."

(2) Where Boeing Alert Requirements Bulletin 737–57A1337 RB, dated September 14, 2017, specifies contacting Boeing, this AD requires repair using a method approved in accordance with the procedures specified in paragraph (j) of this AD.

(j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k)(1) of this AD. Information may be emailed to: 9-ANM-LAACO-AMOC-Requests@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(k) Related Information

(1) For more information about this AD, contact Payman Soltani, Aerospace Engineer, Airframe Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–

5313; fax: 562-627-5210; email: paysman.soltani@faa.gov.

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (l)(3) and (l)(4) of this AD.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 737-57A1337 RB, dated September 14, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on May 31, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-12279 Filed 6-7-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2017-1020; Product Identifier 2017-NM-114-AD; Amendment 39-19306; AD 2018-12-02]

RIN 2120-AA64

Airworthiness Directives; Airbus Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Airbus Model A318-111 and -112 airplanes; Model A319-111, -112, -113, -114, and -115 airplanes; Model A320-211, -212, -214, and -216 airplanes;

and Model A321-111, -112, -211, -212, and -213 airplanes. This AD was prompted by a review of maintenance instructions for a blend repair of the snout diameter of the main beam assembly of the forward engine mount that would create an excessive gap between the bearing mono-ball and the snout. This AD requires modifying the main beam assembly of the forward engine mount. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 13, 2018.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of July 13, 2018.

ADDRESSES: For Airbus service information identified in this final rule, contact Airbus, Airworthiness Office—EIAS, 1 Rond Point Maurice Bellonte, 31707 Blagnac Cedex, France; telephone: +33 5 61 93 36 96; fax: +33 5 61 93 44 51; email: account.airworth-eas@airbus.com; internet: <http://www.airbus.com>. For Goodrich service information identified in this final rule, contact Goodrich Corporation, Aerostructures, 850 Lagoon Drive, Chula Vista, CA 91910-2098; phone: 619-691-2719; email: jan.lewis@goodrich.com; internet: <http://www.goodrich.com/TechPubs>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1020.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2017-1020; or in person at the Docket Management Facility between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for the Docket Office (telephone 800-647-5527) is Docket Management Facility, U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Sanjay Ralhan, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South

216th St., Des Moines, WA 98198-6547; telephone 425-227-1405; fax 425-227-1149.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus Model A318-111 and -112 airplanes; Model A319-111, -112, -113, -114, and -115 airplanes; Model A320-211, -212, -214, and -216 airplanes; and Model A321-111, -112, -211, -212, and -213 airplanes. The NPRM published in the **Federal Register** on October 24, 2017 (82 FR 49146) (“the NPRM”). The NPRM was prompted by a review of maintenance instructions for a blend repair of the snout diameter of the main beam assembly of the forward engine mount that would create an excessive gap between the bearing mono-ball and the snout. The NPRM proposed to require modifying the main beam assembly of the forward engine mount. We are issuing this AD to prevent in-flight failure of a forward engine mount, and consequent detachment of an engine, which could result in reduced controllability of the airplane.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2017-0132R1, dated November 22, 2017 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus Model A318-111 and -112 airplanes; Model A319-111, -112, -113, -114, and -115 airplanes; Model A320-211, -212, -214, and -216 airplanes; and Model A321-111, -112, -211, -212, and -213 airplanes. The MCAI states:

A review of maintenance instructions revealed that the Goodrich Aerospace CFM56-5B, Forward Engine Mount Component Maintenance Manual (CMM) 71-21-08, revision (rev.) 1 up to 46 (inclusive), repair 10 (Blend Repair-Beam Assembly Snout Diameter), provides instructions to blend the wear on the forward engine mount assembly, Part Number (P/N) 642-2000-9, 642-2000-13, or 642-2000-25, creating an excessive gap between the bearing mono-ball and the snout of the forward engine mount main beam assembly, P/N 642-2006-501, or P/N 642-2006-503.

This condition, if not detected and corrected, could lead to in-flight failure of a forward engine mount and consequent detachment of an engine, possibly resulting in reduced control of the aeroplane and injury to persons on the ground.

To address this potential unsafe condition, Airbus issued Service Bulletin (SB) A320-71-1065 and SB A320-71-1066, and