

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(3) The following service information was approved for IBR on October 22, 2018.

(i) Honeywell International Inc. (Honeywell) Service Bulletin (SB) TPE331-72-2179, Revision 0, dated May 3, 2011.

(ii) Reserved.

(4) The following service information was approved for IBR on February 28, 2018 (83 FR 3263, January 24, 2018).

(i) Honeywell SB TPE331-72-2178, Revision 0, dated May 3, 2011.

(ii) Reserved.

(5) For service information identified in this AD, contact Honeywell International Inc., 111 S 34th Street, Phoenix, AZ 85034-2802; phone: 800-601-3099; website: <https://myaerospace.honeywell.com/wps/portal>.

(6) You may view this service information at FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Burlington, Massachusetts, on September 5, 2018.

**Robert J. Ganley,**

Manager, Engine and Propeller Standards Branch, Aircraft Certification Service.

[FR Doc. 2018-20142 Filed 9-14-18; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0552; Product Identifier 2018-NM-049-AD; Amendment 39-19402; AD 2018-19-02]

RIN 2120-AA64

#### **Airworthiness Directives; Airbus Defense and Space S.A. (Formerly Known as Construcciones Aeronauticas, S.A. (CASA)) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Airbus Defense and Space S.A. Model C-212-CB, C-212-CC, C-212-CD, C-212-CE, and C-212-DF airplanes. This AD was prompted by reports of failures of the rudder pedal control system support. This AD requires repetitive detailed visual inspections of the rudder

pedal control system support box and shaft and applicable corrective actions. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective October 22, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 22, 2018.

**ADDRESSES:** For service information identified in this final rule, contact Airbus Defense and Space, Services/Engineering support, Avenida de Aragón 404, 28022 Madrid, Spain; phone: +34 91 585 55 84; fax: +34 91 585 31 27; email:

[MTA.TechnicalService@military.airbus.com](mailto:MTA.TechnicalService@military.airbus.com). You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0552.

#### **Examining the AD Docket**

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0552; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### **FOR FURTHER INFORMATION CONTACT:**

Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3220.

#### **SUPPLEMENTARY INFORMATION:**

##### **Discussion**

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus Defense and Space S.A. Model C-212-CB, C-212-CC, C-212-CD, C-212-CE, and C-212-DF airplanes. The NPRM published in the **Federal Register** on June 25, 2018 (83 FR 29476). The NPRM was prompted by reports of failures of the rudder pedal control system support. The NPRM proposed to require

repetitive detailed visual inspections of the rudder pedal control system support box and shaft and applicable corrective actions.

We are issuing this AD to address failure of the rudder pedal control system, which could result in reduced controllability of the airplane.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018-0051, dated March 2, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Airbus Defense and Space S.A. Model C-212-CB, C-212-CC, C-212-CD, C-212-CE, and C-212-DF airplanes. The MCAI states:

Failures were reported of the rudder pedal control system support on CASA C-212 aeroplanes. Subsequent investigation revealed that the welding area of the affected support structure had broken.

This condition, if not corrected, could lead to failure of the rudder [pedal] control system, possibly resulting in reduced control of the aeroplane.

To address this potential unsafe condition, EADS-CASA issued the SB [EADS-CASA Service Bulletin SB-212-27-0057, dated May 21, 2014] to provide modification instructions and EASA issued AD 2017-0036 [which corresponds to FAA AD 2017-19-08, Amendment 39-19038 (82 FR 43835, September 20 2017) ("AD 2017-19-08")] to require that modification [of the rudder pedal adjustment system]. During accomplishment of that modification, several operators reported difficulties or impossibility to follow the accomplishment instruction. Consequently, EASA and Airbus D&S [Defense and Space S.A.] reviewed the difficulty reports and decided that the modification instructions have to be improved.

Pending the improvement of the instructions of the SB [EADS-CASA Service Bulletin SB-212-27-0057, dated May 21, 2014] and in order to reduce the risk of failure of the [rudder] pedal adjustment system to an acceptable level, Airbus D&S issued the inspection AOT [Airbus Alert Operators Transmission AOT-C212-27-0002, dated February 28, 2018] to provide instructions to repetitively inspect the affected parts [rudder pedal support box Part Number (P/N) 212-46195.1 and shaft P/N 212-46120-20].

For the reasons described above, this [EASA] AD cancels the requirements of EASA AD 2017-0036, which is superseded, and requires repetitive [detailed visual] inspections of the rudder pedal adjustment system [rudder pedal support box P/N 212-46195.1 and shaft P/N 212-46120-20] and, depending on findings, accomplishment of applicable corrective action(s).

This [EASA] AD is considered to be an interim action and further [EASA] AD action may follow.

Corrective actions include obtaining corrective actions approved by the

Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus Defense and Space S.A.'s EASA Design Organization Approval (DOA); and accomplishing the corrective actions within the compliance time specified therein. You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0552.

**Comments**

We gave the public the opportunity to participate in developing this final rule. We received no comments on the NPRM or on the determination of the cost to the public.

**Conclusion**

We reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

**Related Service Information Under 1 CFR Part 51**

Airbus Defense and Space S.A. has issued Airbus Alert Operators

Transmission AOT-C212-27-0002, dated February 28, 2018. This service information describes procedures for repetitive detailed visual inspections of the rudder pedal control system support box and shaft. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**Costs of Compliance**

We estimate that this AD affects 36 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 8 work-hours × \$85 per hour = Up to \$680 .....	\$0	Up to \$680 .....	Up to \$24,480.

We have received no definitive data that would enable us to provide cost estimates for the on-condition repair specified in this AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to

the Director of the System Oversight Division.

**Regulatory Findings**

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2018-19-02 Airbus Defense and Space S.A. (Formerly Known as Construcciones Aeronauticas, S.A. (CASA)):**  
Amendment 39-19402; Docket No. FAA-2018-0552; Product Identifier 2018-NM-049-AD.

**(a) Effective Date**

This AD is effective October 22, 2018.

**(b) Affected ADs**

This AD affects AD 2017-19-08, Amendment 39-19038 (82 FR 43835, September 20 2017) ("AD 2017-19-08").

**(c) Applicability**

This AD applies to Airbus Defense and Space S.A. Model C-212-CB, C-212-CC, C-212-CD, C-212-CE, and C-212-DF airplanes; manufacturer serial numbers 009, 034, 039, 089, 092, 119, 125, 133, 138, 149, 150, 154, 159, 161, 162, 164, 165, 167 through 169 inclusive, 171, 172, 174, 175, 178, 180, 181, 190, 192, 193, 195, 209 through 212 inclusive, 214 through 216 inclusive, 219 through 222 inclusive, 224 through 227 inclusive, 229, 235, 236, 238, 240, 242, 247 through 257 inclusive, 261 through 263 inclusive, 265, 272 through 282 inclusive, 286, 287, 289 through 292 inclusive, 294, 308, 311, 320, 322 through 324 inclusive, 328, 332, 336, 343, 347 through 349 inclusive, 356, 359, 363, 371, 379, 393, 397,

398, 405, 410, 411, 413, 465, 470, 472, 474, 475, 478, and 480 through 482 inclusive; certified in any category; except airplanes modified in accordance with the Accomplishment Instructions of EADS-CASA Service Bulletin SB-212-27-0057, dated May 21, 2014.

**(d) Subject**

Air Transport Association (ATA) of America Code 27, Flight controls.

**(e) Reason**

This AD was prompted by reports of failures of the rudder pedal control system support. We are issuing this AD to address failure of the rudder pedal control system, which could result in reduced controllability of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Definitions**

(1) For the purposes of this AD, an affected part is defined as a rudder pedal support box having Part Number (P/N) 212-46195.1 and shaft P/N 212-46120-20.

(2) For the purposes of this AD, a discrepancy or defect of the rudder pedal support box P/N 212-46195.1 is defined as any crack or deformation on any welded area.

(3) For the purposes of this AD, a discrepancy or defect of the shaft P/N 212-46120-20 is defined as any crack or deformation.

**(h) Repetitive Detailed Visual Inspections**

Within 3 months or during the next scheduled A-check maintenance, whichever occurs first after the effective date of this AD, and thereafter, at intervals not to exceed 150 flight hours, do a detailed visual inspection of each affected part in accordance with the instructions of Airbus Alert Operators Transmission AOT-C212-27-0002, dated February 28, 2018.

**(i) Corrective Action for Any Discrepancy or Defect**

If any discrepancy or defect is detected during any inspection required by paragraph (h) of this AD: Before further flight, obtain corrective actions approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus Defense and Space S.A.'s EASA Design Organization Approval (DOA); and accomplish the corrective actions within the compliance time specified therein. If approved by the DOA, the approval must include the DOA-authorized signature. Accomplishment of a repair, as required by this paragraph, does not constitute terminating action for the repetitive inspections required by paragraph (h) of this AD.

**(j) Parts Installation Limitation**

As of the effective date of this AD, an affected part may be installed on any airplane provided that it is a new part or that, before installation, the visual inspection required by paragraph (h) of this AD has been accomplished on that part and the part

passed the inspection (no discrepancy or defect detected), as required by paragraph (h) of this AD.

**(k) Terminating Action for AD 2017-19-08**

Accomplishing the actions required by this AD terminates all of the requirements of AD 2017-19-08.

**(l) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (m)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus Defense and Space S.A.'s EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

**(m) Related Information**

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018-0051, dated March 2, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0552.

(2) For more information about this AD, contact Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3220.

**(n) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus Alert Operators Transmission AOT-C212-27-0002, dated February 28, 2018.

(ii) Reserved.

(3) For service information identified in this AD, contact Airbus Defense and Space, Services/Engineering support, Avenida de Aragón 404, 28022 Madrid, Spain; phone: +34 91 585 55 84; fax: +34 91 585 31 27; email: [MTA.TechnicalService@military.airbus.com](mailto:MTA.TechnicalService@military.airbus.com).

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on August 30, 2018.

**Jeffrey E. Duven,**

*Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018-19756 Filed 9-14-18; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2018-0448; Product Identifier 2017-NM-129-AD; Amendment 39-19403; AD 2018-19-03]**

**RIN 2120-AA64**

**Airworthiness Directives; Fokker Services B.V. Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Fokker Services B.V. Model F28 Mark 0070 and 0100 airplanes. This AD was prompted by a report of cracks, in various directions, in the lower portion of a main landing gear (MLG) piston. This AD requires a detailed visual inspection of the MLG, and replacement if necessary. We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective October 22, 2018.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of October 22, 2018.

**ADDRESSES:** For service information identified in this final rule, contact Fokker Services B.V., Technical Services Dept., P.O. Box 1357, 2130 EL Hoofddorp, the Netherlands; phone: +31 (0)88-6280-350; fax: +31 (0)88-6280-111; email: [technicalservices@fokker.com](mailto:technicalservices@fokker.com); internet: <http://www.myfokkerfleet.com>. You may view this service information at the FAA, Transport Standards Branch, 2200