

Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017, except as required by paragraph (m)(1) of this AD. Do all applicable corrective actions before further flight. Thereafter, repeat the inspections at the time specified in table 3 or table 4, as applicable, of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017.

(1) Do an open-hole HFEC inspection for cracking of the buttock line (BL) 45.5 longitudinal floor beam web at each fastener hole common to the stub beam attachment angle.

(2) Do an HFEC surface inspection for cracking of the BL 45.5 longitudinal floor beam web around the fastener head/tail at each fastener location common to the backup strap.

**(j) Repetitive Post-Repair Inspections of Buttock Line 45.5 Longitudinal Floor Beam Web at Body Station 639 and Corrective Actions**

For Group 2 airplanes as identified in Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017, at the applicable time specified in table 5 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017, except as required by paragraph (m)(2) of this AD: Do the inspections required by paragraphs (j)(1) and (j)(2) of this AD and all applicable corrective actions, in accordance with the Accomplishment Instructions of Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017, except as required by paragraph (m)(1) of this AD. Do all applicable corrective actions before further flight. Thereafter, repeat the inspections at the applicable time specified in table 5 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017.

(1) Do an open-hole HFEC inspection for cracking of the BL 45.5 longitudinal floor beam web filler at each fastener hole common to the stub beam attachment angle.

(2) Do an HFEC surface inspection for cracking of the BL 45.5 longitudinal floor beam web filler around the fastener head/tail at each fastener location common to the backup strap.

**(k) Repetitive Inspections for Cracking of BS 616 Machined Stub Beam Upper Chord and Corrective Actions**

For Group 2 and Group 3 airplanes as identified in Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017, at the applicable time specified in table 9 of paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017, except as required by paragraph (m)(2) of this AD; do detailed and medium frequency eddy current subsurface inspections for cracking of the BS 616 machined stub beam upper chord, and all applicable corrective actions, except as required by paragraph (m)(1) of this AD. Do all applicable corrective actions before further flight. Thereafter, repeat the inspections at the applicable time specified in table 9 of paragraph 1.E., “Compliance,”

of Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017.

**(l) Credit for Previous Actions**

(1) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD, using Boeing Alert Service Bulletin 737–53A1254, Revision 1, dated July 9, 2009; or Boeing Alert Service Bulletin 737–53A1254, Revision 2, dated February 22, 2012.

(2) This paragraph provides credit for actions required by paragraph (h) of this AD, if those actions were performed before the effective date of this AD, using Boeing Alert Service Bulletin 737–53A1254, Revision 2, dated February 22, 2012.

**(m) Exceptions to Service Information Specifications**

(1) Where Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017, specifies to contact Boeing for repair instructions: Before further flight, do the repair using a method approved in accordance with the procedures specified in paragraph (n) of this AD.

(2) Where Paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017, specifies a compliance time “after the Revision 3 date of this service bulletin,” this AD requires compliance within the specified compliance time after the effective date of this AD.

**(n) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (o)(1) of this AD. Information may be emailed to: [9-ANM-LAACO-AMOC-Requests@faa.gov](mailto:9-ANM-LAACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) AMOCs approved previously for AD 2010–25–06 are approved as AMOCs for the corresponding provisions of Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017, that are required by paragraphs (g) and (h) of this AD.

**(o) Related Information**

(1) For information about this AD, contact Galib Abumeri, Aerospace Engineer, Airframe Section, Los Angeles ACO Branch, FAA, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5324; fax: 562–627–5210; email: [galib.abumeri@faa.gov](mailto:galib.abumeri@faa.gov).

(2) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (p)(3) and (p)(4) of this AD.

**(p) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 737–53A1254, Revision 3, dated November 13, 2017.

(ii) Reserved.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on September 10, 2018.

**Michael Kaszycki**,  
Acting Director, System Oversight Division,  
Aircraft Certification Service.

[FR Doc. 2018–20358 Filed 9–25–18; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 71**

**[Docket No. FAA–2018–0312; Airspace Docket No. 18–AGL–07]**

**RIN 2120–AA66**

**Establishment of Class E Airspace; Glen Ullin, ND**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action establishes Class E airspace extending upward from 700

feet above the surface at Glen Ullin Regional Airport, Glen Ullin, ND. Controlled airspace is necessary to accommodate new standard instrument approach procedures developed at Glen Ullin Regional Airport, for the safety and management of instrument flight rules (IFR) operations at this airport.

**DATES:** Effective 0901 UTC, November 8, 2018. The Director of the Federal Register approves this incorporation by reference action under Title 1, Code of Federal Regulations, part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11C, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11C at NARA, call (202) 741-6030, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** Rebecca Shelby, Federal Aviation Administration, Operations Support Group, Central Service Center, 10101 Hillwood Parkway, Fort Worth, TX 76177; telephone (817) 222-5857.

**SUPPLEMENTARY INFORMATION:**

**Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it establishes Class E airspace extending upward from 700 feet above the surface at Glen Ullin Regional Airport, Glen Ullin, ND to support IFR operations at the airport.

**History**

On May 21, 2018, the FAA published a notice of proposed rulemaking in the **Federal Register** (83 FR 23381) for Docket No. FAA-2018-0312, to establish Class E airspace extending upward from 700 feet above the surface at Glen Ullin Regional Airport, Glen Ullin, ND. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal to the FAA. No comments were received.

**Availability and Summary of Documents for Incorporation by Reference**

This document amends FAA Order 7400.11C, Airspace Designations and Reporting Points, dated August 13, 2018, and effective September 15, 2018. FAA Order 7400.11C is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11C lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

**The Rule**

This amendment to Title 14, Code of Federal Regulations (14 CFR) part 71 establishes Class E airspace extending upward from 700 feet above the surface within a 6.4-mile radius of Glen Ullin Regional Airport, Glen Ullin, ND, to accommodate new standard instrument approach procedures developed for the airport, for the safety and management of instrument flight rules (IFR) operations. Controlled airspace is necessary.

**Regulatory Notices and Analyses**

The FAA has determined that this regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to keep them operationally current, is non-controversial and unlikely to result in adverse or negative comments. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under DOT Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**Environmental Review**

The FAA has determined that this action qualifies for categorical exclusion under the National Environmental Policy Act in accordance with FAA Order 1050.1F, "Environmental Impacts: Policies and Procedures," paragraph 5-6.5.a. This airspace action is not expected to cause any potentially significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment.

**Lists of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (air).

**Adoption of the Amendment**

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

**PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959-1963 Comp., p. 389.

**§ 71.1 [Amended]**

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11C, Airspace Designations and Reporting Points, dated August 13, 2018, and effective September 15, 2018, is amended as follows:

*Paragraph 6005 Class E Airspace Areas Extending Upward From 700 Feet or More Above the Surface of the Earth.*

\* \* \* \* \*

**AGL ND E5 Glen Ullin, ND [New]**

Glen Ullin Regional Airport, WI  
(Lat. 46°48'52" N, long. 101°51'55" W)

That airspace extending upward from 700 feet above the surface within a 6.4-mile radius of the Glen Ullin Regional Airport.

Issued in Fort Worth, Texas, on September 18, 2018.

**Walter Tweedy,**

*Acting Manager, Operations Support Group, ATO Central Service Center.*

[FR Doc. 2018-20870 Filed 9-25-18; 8:45 am]\*COM007\*

**BILLING CODE 4910-13-P**