(g)(1), (g)(2), and (g)(3) of this AD. The initial compliance times for accomplishing the tasks are at the applicable times specified in the service information identified in paragraphs (g)(1), (g)(2), and (g)(3) of this AD, or within 90 days after the effective date of this AD, whichever occurs later.

(1) Airbus A330 Airworthiness Limitations Section (ALS) Part 1, Safe Life Airworthiness Limitation Items (SL–ALI), Revision 09, dated September 18, 2017.

(2) Airbus A330 ALS Part 1, SL-ALI, Variation 9.2, dated November 28, 2017.

(3) Airbus A330 ALS Part 1, SL–ALI, Variation 9.3, dated November 29, 2017.

(h) Terminating Actions for AD 2017-10-24

Accomplishing the actions required by paragraph (g) of this AD terminates all of the requirements of AD 2017–10–24.

(i) No Alternative Actions or Intervals

After the maintenance or inspection program, as applicable, has been revised as required by paragraph (g) of this AD, no alternative actions (*e.g.*, inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j)(1) of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

(ii) AMOCs approved previously for AD 2017–10–24 are not approved as AMOCs for this AD.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOAauthorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018–0034, February 5, 2018, for related information. This MCAI may be found in the AD docket on the internet at *http:// www.regulations.gov* by searching for and locating Docket No. FAA–2018–0759. (2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus A330 Airworthiness Limitations Section (ALS) Part 1, Safe Life Airworthiness Limitation Items (SL–ALI), Revision 09, dated September 18, 2017.

(ii) Airbus A330 ALS Part 1, SL–ALI, Variation 9.2, dated November 28, 2017.

(iii) Airbus A330 ALS Part 1, SL–ALI, Variation 9.3, dated November 29, 2017.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email *airworthiness.A330–A340@ airbus.com*; internet *http://www.airbus.com*.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http:// www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued in Des Moines, Washington, on November 8, 2018.

Chris Spangenberg

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018–25392 Filed 11–26–18; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0639; Product Identifier 2018-NM-058-AD; Amendment 39-19508; AD 2018-24-04]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT). **ACTION:** Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain

Airbus SAS Model A330-200 Freighter, A330-200, and A330-300 series airplanes. This AD was prompted by a revision of a certain airworthiness limitations item (ALI) document, which specifies new or more restrictive maintenance instructions and airworthiness limitations, and a determination that those maintenance instructions and airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive maintenance instructions and airworthiness limitations. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 2, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 2, 2019.

ADDRESSES: For service information identified in this final rule, contact Airbus SAS, Airworthiness Office-EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; internet http:// www.airbus.com. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at *http://www.regulations.gov* by searching for and locating Docket No. FAA-2018-0639.

Examining the AD Docket

You may examine the AD docket on the internet at *http:// www.regulations.gov* by searching for and locating Docket No. FAA-2018-0639; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800–647–5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229. SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus SAS Model A330-200 Freighter, A330-200, and A330–300 series airplanes. The NPRM published in the Federal Register on August 10, 2018 (83 FR 39633). The NPRM was prompted by a revision of a certain ALI document, which specifies new or more restrictive maintenance instructions and airworthiness limitations, and a determination that those maintenance instructions and airworthiness limitations are necessary. The NPRM proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive maintenance instructions and airworthiness limitations.

We are issuing this AD to address fatigue cracking, damage, and corrosion in principal structural elements; such fatigue cracking, damage, and corrosion could result in reduced structural integrity of the airplane.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018–0068, dated March 26, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for certain Airbus SAS Model A330–200 Freighter, A330–200, and A330–300 series airplanes. The MCAI states:

The airworthiness limitations for Airbus A330 and A340 aeroplanes, which are approved by EASA, are currently defined and published in the A330 and A340 [Airworthiness Limitations Section] ALS document(s). The Damage Tolerant Airworthiness Limitation Items (DT ALI) are specified in the ALS Part 2. These instructions have been identified as mandatory actions for continued airworthiness.

Failure to comply with these instructions could result in an unsafe condition [*i.e.*, fatigue cracking, damage, and corrosion in principal structural elements] which could result in reduced structural integrity of the airplane.

Previously, EASA issued AD 2016–0152 [which corresponds to FAA AD 2017–19–13, Amendment 39–19043 (82 FR 43837, September 20, 2017) ("AD 2017–19–13")] for A330 and A340 aeroplanes to require accomplishment of all maintenance tasks as described in ALS Part 2 Revision 01 (A330 aeroplanes) and Revision 02 (A340 aeroplanes).

Since that [EASA] AD was issued, Airbus published Revision 02 of the ALS Part 2 for A330 aeroplanes, including new and/or more restrictive items.

For the reason described above, this [EASA] AD takes over the requirements from EASA AD 2016–0152 for A330 aeroplanes, and requires accomplishment of all maintenance tasks as described in the ALS. EASA AD 2016–0152 has been revised accordingly, removing A330 aeroplanes from the Applicability.

You may examine the MCAI in the AD docket on the internet at *http://www.regulations.gov* by searching for and locating Docket No. FAA–2018–0639.

Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comment received on the NPRM and the FAA's response to that comment.

Request To Clarify or Remove Previously Approved Alternative Method of Compliance (AMOC)

American Airlines requested that we clarify the applicability of the AMOC approved in letter AIR-676-18-111 R1, dated January 29, 2018, or remove the previously approved AMOC from the proposed AD. The commenter stated that, as currently written, paragraph (i)(1)(ii) of the proposed AD is confusing because it states that the AMOC approved in letter AIR-676-18-111 R1, dated January 29, 2018, previously approved for AD 2017-19-13, would still be approved for the corresponding provisions of the final rule. The commenter explained that this AMOC is limited to a specific organization and is not applicable to all operators.

We agree with the commenter's request for the reasons provided by the commenter. AMOC letter AIR-676-18-111 R1, dated January 29, 2018, was issued specifically to Singapore Technologies Aerospace Limited and is not a global AMOC. We have revised paragraph (j)(1)(ii) of this AD to clarify that the AMOC granted in letter AIR-676-18-111 R1, dated January 29, 2018, is approved as an AMOC for Model A330–300 series airplanes modified from a passenger to freighter configuration under the provisions of FAA Supplemental Type Certificate ST04038NY.

Conclusion

We reviewed the relevant data, considered the comment received, and determined that air safety and the public interest require adopting this final rule with the change described previously and minor editorial changes. We have determined that these minor changes:

• Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and

• Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.

Related Service Information Under 1 CFR Part 51

Airbus SAS has issued Airbus A330 Airworthiness Limitations Section (ALS) Part 2—Damage Tolerant Airworthiness Limitation Items (DT– ALI), Revision 02, Issue 2, dated November 22, 2017. This service information describes maintenance instructions and airworthiness limitations applicable to the DT–ALI. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 105 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

We have determined that revising the existing maintenance or inspection program takes an average of 90 workhours per operator, although we recognize that this number may vary from operator to operator. In the past, we have estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), we have determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, we estimate the total cost per operator to be \$7,650 (90 work-hours \times \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a ''significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018–24–04 Airbus SAS: Amendment 39– 19508; Docket No. FAA–2018–0639; Product Identifier 2018–NM–058–AD.

(a) Effective Date

This AD is effective January 2, 2019.

(b) Affected ADs

This AD affects AD 2017–19–13, Amendment 39–19043 (82 FR 43837, September 20, 2017) ("AD 2017–19–13").

(c) Applicability

This AD applies to the Airbus SAS airplanes specified in paragraphs (c)(1), (c)(2), and (c)(3) of this AD, certificated in any category, with an original certificate of airworthiness or original export certificate of airworthiness issued on or before November 22, 2017.

(1) Model A330–223F and –243F airplanes. (2) Model A330–201, –202, –203, –223, and –243 airplanes.

(3) Model A330–301, –302, –303, –321, –322, –323, –341, –342, and –343 airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time Limits/Maintenance Checks.

(e) Reason

This AD was prompted by a revision of a certain airworthiness limitations item (ALI) document, which specifies new or more restrictive maintenance instructions and airworthiness limitations, and a determination that those maintenance instructions and airworthiness limitations are necessary. We are issuing this AD to address fatigue cracking, damage, and corrosion in principal structural elements; such fatigue cracking, damage, and corrosion could result in reduced structural integrity of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Maintenance or Inspection Program Revision

Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, to incorporate the information specified in Airbus A330 Airworthiness Limitations Section (ALS) Part 2-Damage Tolerant Airworthiness Limitation Items (DT-ALI), Revision 02, Issue 2, dated November 22, 2017. The initial compliance time for accomplishing the tasks is at the applicable times specified in Airbus A330 Airworthiness Limitations Section (ALS) Part 2—Damage Tolerant Airworthiness Limitation Items (DT-ALI), Revision 02, Issue 2, dated November 22, 2017, or within 90 days after the effective date of this AD, whichever occurs later.

(h) No Alternative Actions or Intervals

After the existing maintenance or inspection program has been revised, as required by paragraph (g) of this AD, no alternative actions (*e.g.*, inspections) or intervals may be used unless the actions or intervals are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j)(1) of this AD.

(i) Terminating Action for the Requirements of AD 2017–19–13

Accomplishing the action required by paragraph (g) of this AD terminates all requirements of AD 2017–19–13.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/ certificate holding district office.

(ii) The AMOC specified in letter AIR-676-18-111 R1, dated January 29, 2018, approved previously for AD 2017-19-13, is approved as an AMOC for the corresponding provisions of this AD for Model A330-300 series airplanes that have been modified from a passenger to freighter configuration under the provisions of FAA Supplemental Type Certificate ST04038NY.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOAauthorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018–0068, dated March 26, 2018, for related information. This MCAI may be found in the AD docket on the internet at *http:// www.regulations.gov* by searching for and locating Docket No. FAA–2018–0639.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Airbus A330 Airworthiness Limitations Section (ALS) Part 2—Damage Tolerant Airworthiness Limitation Items (DT–ALI), Revision 02, Issue 2, dated November 22, 2017.

(ii) [Reserved]

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email *airworthiness.A330-A340@ airbus.com;* internet *http://www.airbus.com.*

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202–741–6030, or go to: http:// www.archives.gov/federal-register/cfr/ibrlocations.html.

Issued in Des Moines, Washington, on November 15, 2018.

Dionne Palermo,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018–25663 Filed 11–26–18; 8:45 am] BILLING CODE 4910–13–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2018–0489; Product Identifier 2018–NM–001–AD; Amendment 39–19500; AD 2018–23–13]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT. **ACTION:** Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all The Boeing Company Model 747–8 and 747–8F series airplanes. This AD was prompted by a report that flightcrew oxygen masks did not function as designed during flight testing. This AD requires an inspection to determine if certain oxygen masks/regulators are installed, and replacement if necessary. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 2, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of January 2, 2019.

ADDRESSES: For service information identified in this final rule, contact Boeing Commercial Airplanes,

Attention: Contractual & Data Services (C&DS), 2600 Westminster Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet *https://www.myboeingfleet.com.* You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at *http://www.regulations.gov* by searching for and locating Docket No. FAA–2018– 0489.

Examining the AD Docket

You may examine the AD docket on the internet at http:// *www.regulations.gov* by searching for and locating Docket No. FAA-2018-0489; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

Susan L. Monroe, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206– 231–3570; email: *susan.l.monroe*@ *faa.gov.*

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all The Boeing Company Model 747–8 and 747–8F series airplanes. The NPRM published in the **Federal Register** on May 30, 2018 (83 FR 24688). The NPRM was prompted by a report that flightcrew oxygen masks did not function as designed during flight testing. The NPRM proposed to require an inspection to determine whether certain oxygen masks/regulators and stowage boxes are installed and replacement if necessary.

We are issuing this AD to address flightcrew oxygen masks/regulators that do not deploy correctly, which could result in a delay for the flightcrew to put on the masks, which may lead to hypoxia and loss of useful consciousness, potentially resulting in loss of control of the airplane.

Comments

We gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment.

Request To Include Training for Proper Mask-Packing

Zodiac Aerospace recommended that we revise paragraphs (g) and (h) to include training for proper maskpacking as an alternative to replacement. The commenter stated that if operators have followed proper packing procedures, no equipment change should be required.

Although we acknowledge Zodiac's recommendation, we note that the supplier had previously provided maskpacking training to Boeing, and that trained, certified mask packers had packed the masks that failed. We have determined that mandating a design change is necessary to effectively mitigate the unsafe condition. We have not changed this AD in this regard.

Request To Revise Proposed Parts Installation Limitation

Boeing requested that we revise paragraph (i) of the proposed AD to provide that subsequent changes or modifications may be handled by normal operator procedures without requiring approval of an alternative method of compliance (AMOC) as long as oxygen mask/regulator part number (P/N) MLD20–626–1 is not reintroduced as part of the subsequent change. Boeing considered paragraph (i)(3) of the proposed AD to be too restrictive because operators would be burdened with requests for AMOCs for each subsequent change or modification.

We partially agree with the commenter. We agree that options are warranted for operators because the proposed AD was highly restrictive, given the limited nature of the unsafe condition. Therefore, we have revised paragraph (g) of this AD to provide alternative actions to correct the unsafe condition, thereby reducing the need for AMOC requests. We also removed the requirement to inspect for the oxygen mask stowage box because that inspection is no longer needed based on these alternative actions.

However, we disagree with revising or deleting paragraph (i)(3) of this AD because the requirement refers to the dependent relationship between the new mask/regulator part number and the new oxygen mask stowage box part number required by the service information. The installation of oxygen mask/regulator P/N MLD20–726–1 with