

commands when the altitude climb field is edited or when the temperature compensation is activated. We are issuing this AD to prevent the FMC from issuing an incorrect turn direction command. The unsafe condition, if not addressed, could result in a collision or controlled flight into terrain.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Disable the Temperature Compensation

Within the next 12 months after the effective date of this AD, disable the automatic temperature compensation feature on the CSU by following steps (2) through (6) of the Instructions in Rockwell Collins Service Information Letter CSU-XX00-18-1, dated June 27, 2018.

#### (h) Revise the Airplane Flight Manual Limitations

Within the next 12 months after the effective date of this AD, revise the airplane flight manual by adding the information from step 2 of the Aircraft Flight Manual Recommendation in Rockwell Collins Service Information Letter FMC-XX00-18-1, dated June 27, 2018, into the Limitations section of the AFM.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ACO, send it to the attention of the person identified in paragraph (j)(1) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (j) Related Information

(1) For more information about this AD, contact Avi Acharya, Aerospace Engineer, Wichita ACO Branch, FAA, 1801 Airport Road, Room 100, Wichita, Kansas 67209; phone: 316-946-4192; fax: 316-946-4107; email: [avishek.acharya@faa.gov](mailto:avishek.acharya@faa.gov).

(2) For service information identified in this AD, contact Rockwell Collins, Inc., Collins Aviation Services, 400 Collins Road NE, M/S 164-100, Cedar Rapids, IA 52498-0001; telephone: 888-265-5467 (U.S.) or 319-265-5467; fax: 319-295-4941 (outside U.S.); email: [techmanuals@rockwellcollins.com](mailto:techmanuals@rockwellcollins.com); internet: [http://www.rockwellcollins.com/Services\\_and\\_Support/Publications.aspx](http://www.rockwellcollins.com/Services_and_Support/Publications.aspx). You may view this referenced service information at the FAA, Small Airplane Directorate, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued in Kansas City, Missouri, on November 26, 2018.

**Melvin J. Johnson,**

*Aircraft Certification Service, Deputy Director, Policy and Innovation Division, AIR-601.*

[FR Doc. 2018-26253 Filed 12-4-18; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

**[Docket No. FAA-2018-1003; Product Identifier 2018-NM-133-AD]**

**RIN 2120-AA64**

#### Airworthiness Directives; Airbus SAS Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for certain Airbus SAS Model A330-201, -202, and -203, and Model A330-301, -302, and -303 airplanes. This proposed AD was prompted by reports of damaged drain pipes located above the lower aft pylon fairing (LAPF), caused by a contact between the drain pipe and the two u-shape ribs of the LAPF. This proposed AD would require a special detailed inspection for damage and corrective actions, if necessary. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by January 22, 2019.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No. 2, 31700 Blagnac Cedex, France; phone: +33 5 61 93 36 96; fax: +33 5 61 93 45 80; email: [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com);

internet: <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-1003; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3229.

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2018-1003; Product Identifier 2018-NM-133-AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018-0198, dated September 6, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus SAS Model A330-201, -202, and -203, and Model A330-301, -302, and -303 airplanes. The MCAI states:

Some cases of damaged drain pipes, Part Number F7173000700000, located above the

Lower Aft Pylon Fairing (LAPF) and dedicated to drain pylon compartment A in case of hydraulic fluid leakage, were reported. Subsequent examination identified that the cracks were caused by a contact between the drain pipe and the two U-Shape Ribs of the LAPF. This interference condition can be present during the installation of the LAPF assembly to the pylon. The trailing edge assembly of the fairing has an internal frame bracket and shear clip which can cause chafing with the hydraulic drain pipes.

This condition, if not detected and corrected, combined with an additional independent failure as hydraulic leakage in pylon compartment A, could lead to hydraulic leakage in the LAPF box. In addition, the hydraulic fluid may flow forward of the LAPF and leak above engine hot surfaces, possibly resulting in a temporary uncontrolled fire in the pylon compartment A, and consequent reduced control of the aeroplane.

To address this unsafe condition, Airbus issued the inspection SB [Airbus Service Bulletin A330-54-3042, dated May 17, 2018] to provide instructions for a special detailed inspection (SDI) of the LAPF drain pipes.

For the reasons described above, this [EASA] AD requires a one-time SDI (borescope inspection method) of the LAPF of each pylon [for damage (including but not limited to cracks and leaks of the hydraulic drain pipe, and contact, interference, and chafing of the internal frame bracket and the shear clip of the trailing edge assembly of the LAPF with the aircraft hydraulic drain pipe)] and, depending on findings, replacement of

the LAPF drain pipes and clamp block, and rework of the U-shape ribs.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-1003.

**Related Service Information Under 1 CFR Part 51**

Airbus has issued the following service information.

- Airbus Service Bulletin A330-54-3041, dated May 17, 2018. This service information describes procedures for replacement of the hydraulic drain pipe clamp blocks of the LAPFs of the left-hand (LH) and right-hand (RH) pylons and modification of the LAPFs.
- Airbus Service Bulletin A330-54-3042, dated May 17, 2018. This service information describes procedures for a special detailed inspection for damage (including but not limited to cracks and leaks of the hydraulic drain pipe, and contact, interference, and chafing of the internal frame bracket and the shear clip of the trailing edge assembly of the LAPF with the aircraft hydraulic drain pipe), and corrective actions. Corrective actions include replacement of the hydraulic drain pipe at the LH or RH pylon.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**FAA's Determination**

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

**Proposed Requirements of This NPRM**

This proposed AD would require accomplishing the actions specified in the service information described previously.

**Costs of Compliance**

We estimate that this proposed AD affects 10 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = \$170 .....	\$0	\$170	\$1,700

We estimate the following costs to do any necessary on-condition actions that would be required based on the results

of any required actions. We have no way of determining the number of aircraft

that might need these on-condition actions:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS**

Labor cost	Parts cost	Cost per product
29 work-hours × \$85 per hour = \$2,465 .....	\$1,640	\$4,105

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage for affected individuals. As a result, we have included all known costs in our cost estimate.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of

the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive

Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

### Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);
3. Will not affect intrastate aviation in Alaska; and
4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Airbus SAS:** Docket No. FAA–2018–1003; Product Identifier 2018–NM–133–AD.

#### (a) Comments Due Date

We must receive comments by January 22, 2019.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to the Airbus SAS airplanes identified in paragraphs (c)(1) and (c)(2) of this AD, certificated in any category, all manufacturer serial numbers, except those on which Airbus modification 207430 has

been embodied in production, or Airbus Service Bulletin A330–54–3041 has been embodied in service.

(1) Model A330–201, –202, and –203 airplanes.

(2) Model A330–301, –302, and –303 airplanes.

#### (d) Subject

Air Transport Association (ATA) of America Code 54, Nacelles/pylons.

#### (e) Reason

This AD was prompted by reports of damaged drain pipes located above the lower aft pylon fairing (LAPF), caused by a contact between the drain pipe and the two u-shape ribs of the LAPF. We are issuing this AD to address damaged drain pipes located above the LAPF, which combined with an additional independent failure could lead to hydraulic leakage in the LAPF box, possibly resulting in a temporary uncontrolled fire and consequent reduced control of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) One-Time Inspections

Within 26 months after the effective date of this AD, accomplish a one-time special detailed inspection of the pylon drain pipes (inside and outside) on the left-hand and right-hand pylons, located above both LAPFs, for contact with the U-shaped ribs of the LAPF and damage (including but not limited to cracks and leaks of the pylon drain pipe, and contact, interference, and chafing of the internal frame bracket and the shear clip of the trailing edge assembly of the LAPF with the pylon drain pipe) in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330–54–3042, dated May 17, 2018.

#### (h) Corrective Actions

If, during any inspection required by paragraph (g) of this AD, any damage is found, at the applicable time specified in Airbus Service Bulletin A330–54–3042, dated May 17, 2018, accomplish the applicable corrective actions on the affected pylon in accordance with the Accomplishment Instructions of Airbus Service Bulletin A330–54–3042, dated May 17, 2018; and Airbus Service Bulletin A330–54–3041, dated May 17, 2018.

#### (i) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in

paragraph (j)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Airbus SAS’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC):* If any service information contains procedures or tests that are identified as RC, those procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

#### (j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018–0198, dated September 6, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–1003.

(2) For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3229.

(3) For service information identified in this AD, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; phone: +33 5 61 93 36 96; fax: +33 5 61 93 45 80; email: [airworthiness.A330-A340@airbus.com](mailto:airworthiness.A330-A340@airbus.com); internet: <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on November 23, 2018.

**John P. Piccola,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018–26360 Filed 12–4–18; 8:45 am]

**BILLING CODE 4910–13–P**