

Issued in Des Moines, Washington, on November 21, 2018.

Michael Kaszycki,

Acting Director, System Oversight Division,
Aircraft Certification Service.

[FR Doc. R1–2018–26365 Filed 12–7–18; 2:00 pm]

BILLING CODE 1301–00–C

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2018–0796; Product Identifier 2018–NM–104–AD; Amendment 39–19518; AD 2018–25–07]

RIN 2120–AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc., Model BD–700–1A10 and BD–700–1A11 airplanes. This AD was prompted by reports of drainage holes on the belly fairing forward and middle access panels being obstructed with sealant. This AD requires inspecting for and removing all sealant blocking the drainage holes on the belly fairing forward and middle access panels. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective January 15, 2019.

The Director of the Federal Register approved the incorporation by reference of certain publications listed in this AD as of January 15, 2019.

ADDRESSES: For service information identified in this final rule, contact Bombardier, Inc., 400 Côte Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514–855–5000; fax 514–855–7401; email thd.crj@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0796.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0796; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800–647–5527) is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516–228–7323; fax 516–794–5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc., Model BD–700–1A10 and BD–700–1A11 airplanes. The NPRM published in the *Federal Register* on September 18, 2018 (83 FR 47113). The NPRM was prompted by reports of drainage holes on the belly fairing forward and middle access panels being obstructed with sealant. The NPRM proposed to require inspecting for and removing all sealant blocking the drainage holes on the belly fairing forward and middle access panels.

We are issuing this AD to address fluid leakage that could lead to the accumulation of flammable fluids/vapors, beyond the design capacity of the belly fairing venting provisions, which could ignite if an ignition source (*i.e.*, spark, static discharge, heat, etc.) is present. Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian Airworthiness Directive CF–2018–14, dated May 1, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model BD–700–1A10 and BD–700–1A11 airplanes. The MCAI states:

Bombardier Aerospace (BA) has informed Transport Canada that the drainage holes on the belly fairing forward and middle access panels may be obstructed with sealant. The purpose of the drainage holes is to allow for drainage of a limited quantity of fluids due to any leaks, should they occur. This condition, if not corrected, may prevent the

timely detection of fluid leakage that could lead to the accumulation of flammable fluids/vapors, beyond the design capacity of the belly fairing venting provisions [which could ignite if an ignition source (*i.e.*, spark, static discharge, heat, etc.) is present].

This [Canadian] AD is issued to mandate the removal of all sealant blocking the drainage holes on the belly fairing forward and middle access panels.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0796.

Comments

We gave the public the opportunity to participate in developing this final rule. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 14 CFR Part 39

Bombardier has issued the following service information for Bombardier Model BD–700–1A10 airplanes.

- Service Bulletin 700–53–051, dated May 17, 2017.
- Service Bulletin 700–53–6009, dated May 17, 2017.

Bombardier has issued the following service information for Bombardier Model BD–700–1A11 airplanes.

- Service Bulletin 700–1A11–53–026, dated May 17, 2017.
- Service Bulletin 700–53–5010, dated May 17, 2017.

This service information describes procedures for inspecting for and removing sealant blocking the drainage holes on the belly fairing forward and middle access panels. These documents are distinct since they apply to different airplane models and configurations. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 376 airplanes of U.S. registry. We estimate

the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
6 work-hours × \$85 per hour = \$510	\$0	\$510	\$191,760

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national

government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2018–25–07 Bombardier, Inc.: Amendment 39–19518; Docket No. FAA–2018–0796; Product Identifier 2018–NM–104–AD.

(a) Effective Date

This AD is effective January 15, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model BD–700–1A10 and BD–700–1A11 airplanes, certificated in any category, serial numbers 9001 through 9707 inclusive, 9709 through 9717 inclusive, 9719 through 9726 inclusive, 9728, 9730, 9732 through 9734 inclusive, 9736 through 9740 inclusive, 9742 through 9745 inclusive, 9749, 9751, 9757, and 9998.

(d) Subject

Air Transport Association (ATA) of America Code 53, Fuselage.

(e) Reason

This AD was prompted by reports of drainage holes on the belly fairing forward and middle access panels being obstructed with sealant. We are issuing this AD to address fluid leakage that could lead to the accumulation of flammable fluids/vapors, beyond the design capacity of the belly fairing venting provisions, which could ignite if an ignition source (*i.e.*, spark, static discharge, heat, etc.) is present.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Sealant Removal

Within 375 flight hours or 12 months, whichever occurs first, after the effective date of this AD, do a general visual inspection for and remove all sealant blocking the drainage holes on the belly fairing forward and middle access panels, in accordance with the Accomplishment Instructions of the applicable service information listed in figure 1 to paragraph (g) of this AD.

Figure 1 to paragraph (g) of this AD – *Service bulletins*

Airplane Model	Bombardier Service Bulletin	Issue Date
BD-700-1A10	700-53-051	May 17, 2017
BD-700-1A10	700-53-6009	May 17, 2017
BD-700-1A11	700-1A11-53-026	May 17, 2017
BD-700-1A11	700-53-5010	May 17, 2017

(h) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the ACO Branch, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(i) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2018-14, dated May 1, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0796.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyacos@faa.gov.

(j) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this

paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 700-1A11-53-026, dated May 17, 2017.

(ii) Bombardier Service Bulletin 700-53-051, dated May 17, 2017.

(iii) Bombardier Service Bulletin 700-53-5010, dated May 17, 2017.

(iv) Bombardier Service Bulletin 700-53-6009, dated May 17, 2017.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte Vertu Road West, Dorval, Québec H4S 1Y9, Canada; telephone 514-855-5000; fax 514-855-7401; email thd.crj@aero.bombardier.com; internet <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on November 23, 2018.

John P. Piccola,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2018-26534 Filed 12-10-18; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA-2018-1013; Airspace Docket No. 18-ANE-7]

RIN 2120-AA66

Amendment of VOR Federal Airways V-318 and V-352; Northeastern United States

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action modifies the descriptions of VHF Omnidirectional Range (VOR) Federal airways V-318 and V-352 to reflect the removal of certain route segments within Canadian airspace that were deleted by NAV CANADA. This rule modifies the above airway descriptions to match the current configuration of the routes.

DATES: Effective date 0901 UTC, February 28, 2019. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

ADDRESSES: FAA Order 7400.11C, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at http://www.faa.gov/air_traffic/publications/. For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11C at NARA, call (202)