

Forward STA 328 Frame Assembly P/N	Aft STA 362 Frame Assembly P/N
92209-02106-042	92070-20097-062
92209-02106-043	92080-20047-051
92070-20097-041	92209-02109-043
92080-20047-041	92209-02109-044
	92070-20097-042
	92080-20047-042
	92070-20097-064
	92080-20047-052

Table 3 to Paragraph (e)(2)

Fwd STA 328 Frame Assembly P/N	Aft STA 362 Frame Assembly P/N
92209-02107-042	92209-02108-042
92209-02107-103	92209-02108-103

Table 4 to Paragraph (e)(2)

**(f) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Boston ACO Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Kristopher Greer, Aviation Safety Engineer, Boston ACO Branch, Compliance and Airworthiness Division, 1200 District Avenue, Burlington, Massachusetts 01803; telephone (781) 238-7799; email [Kristopher.Greer@faa.gov](mailto:Kristopher.Greer@faa.gov).

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

**(g) Additional Information**

Sikorsky S-92 Alert Service Bulletin (ASB) 92-53-008, Basic Issue, dated June 13, 2012; ASB 92-53-009, Basic Issue, dated December 6, 2012; ASB 92-53-012, Basic Issue, dated February 10, 2014, and Sikorsky Special Service Instructions No. 92-074-E, Revision E, dated April 9, 2014, and Sikorsky S-92A-AMM-000 Maintenance Manual, Chapter 53-20-00, Task 53-20-210-003, dated January 31, 2018, which are not incorporated by reference, contain additional information about the subject of this AD. For service information identified in this AD, contact Sikorsky Aircraft Corporation, Customer Service Engineering, 124 Quarry Road, Trumbull, CT 06611; telephone 1-800-Winged-S or 203-416-4299; email [wcs\\_cust\\_service\\_eng.gr-sik@lmco.com](mailto:wcs_cust_service_eng.gr-sik@lmco.com). You may view this information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

**(h) Subject**

Joint Aircraft System Component (JASC)  
Code: 5311 Fuselage Main, Frame.

Issued in Fort Worth, Texas, on December 13, 2018.

**Lance T. Gant,**

*Director, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2018-27713 Filed 12-21-18; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 39**

**[Docket No. FAA-2018-1011; Product Identifier 2018-NM-131-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; The Boeing Company Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for all The Boeing Company Model 767-200, -300, -300F, and -400ER series airplanes. This proposed AD was prompted by reports of uncommanded movements of the Captain's and First Officer's seats. This proposed AD would require an identification of the part number, and if applicable the serial number, of the Captain's and First Officer's seats, and applicable on-condition actions. This proposed AD would also require a one-time detailed inspection and repetitive checks of the horizontal movement system of the Captain's and First

Officer's seats, and applicable on-condition actions. This proposed AD would also provide an optional terminating action for the repetitive checks of the horizontal movement system for certain airplanes. We are proposing this AD to address the unsafe condition on these products.

**DATES:** We must receive comments on this proposed AD by February 11, 2019.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110-SK57, Seal Beach, CA 90740-5600; telephone 562-797-1717; internet <https://www.myboeingfleet.com>. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching

for and locating Docket No. FAA–2018–1011.

### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–1011; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800–647–5527) is in the **ADDRESSES** section. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3569; email: [Brandon.Lucero@faa.gov](mailto:Brandon.Lucero@faa.gov).

#### SUPPLEMENTARY INFORMATION:

### Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2018–1011; Product Identifier 2018–NM–131–AD” at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this proposed AD.

### Discussion

We have received reports indicating that there have been uncommanded movements of the Captain’s and First Officer’s seats. A Model 747 operator reported that during a takeoff, the First Officer’s seat unlocked from its seat tracks and moved aft. The First Officer was unable to control the airplane and the Captain took over the controls to avoid a rejected takeoff. The unlocking of the seat from the seat tracks was caused by actuator damage, which was a result of incorrect adjustment of the seat’s manual release lever cable, which allowed the clutch mechanism to only

partially engage. Captain’s and First Officer’s seats having the same part numbers are installed on both Model 747 and Model 767 airplanes. We are considering additional rulemaking to address the unsafe condition for Model 747 airplanes.

In addition, one operator reported that the Captain’s seat could not be locked in position after the horizontal position of the seat was adjusted in flight. The seat became unlocked from the track and moved freely forward and aft. Control was given to the First Officer for approach and landing. An inspection found that the horizontal actuator output shaft had broken. When a horizontal actuator output shaft breaks, the pilot cannot prevent seat movement in a forward and aft direction and cannot lock the seat in position. A broken horizontal actuator output shaft is the result of high loads that exceed the design limits that are caused by a stalled motor that can occur due to high mechanical resistance to motion during powered operation of the seat. Foreign object debris (FOD) in the seat tracks is another condition that can result in a stalled motor and cause the horizontal actuator output shaft to break.

An un-commanded seat movement during a critical part of a flight, such as take-off or landing, could cause a flight control obstruction or unintended flight control input, which could result in the loss of the ability to control the airplane.

#### Related Service Information Under 1 CFR Part 51

We reviewed Boeing Special Attention Service Bulletin 767–25–0539, Revision 1, dated July 17, 2018 (“BSASB 767–25–0539, Revision 1”). The service information describes procedures for identification of the part number, and, if applicable, the serial number of the Captain’s and First Officer’s seats, and applicable on-condition actions. The on-condition actions include an inspection of each seat’s fore/aft and vertical manual control levers for looseness, installation of serviceable seats, and a seat functional test after any cable adjustment.

We also reviewed Boeing Special Attention Service Bulletin 767–25–0549, Revision 1, dated August 10, 2018 (“BSASB 767–25–0549, Revision 1”). The service information describes procedures for a one-time detailed inspection and repetitive checks of the horizontal movement system of the Captain’s and First Officer’s seats for findings (e.g., evidence of cracks, scores, corrosion, dents, deformation or visible wear); and incorrectly assembled components (e.g., microswitch

assemblies, actuators, and limit switches), and applicable on-condition actions. The on-condition actions include overhaul of the horizontal movement system, clearing the seat tracks of FOD, replacement of the horizontal actuator, and replacement of the horizontal movement system. The service information also describes procedures for an optional terminating action for the repetitive checks by installing a serviceable Captain’s or First Officer’s seat.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

#### FAA’s Determination

We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

#### Proposed AD Requirements

This proposed AD would require accomplishment of the actions identified in the Accomplishment Instructions of BSASB 767–25–0539, Revision 1, described previously, except as discussed under “Differences Between this Proposed AD and the Service Information,” and except for any differences identified as exceptions in the regulatory text of this proposed AD.

This proposed AD would also require accomplishment of the actions identified as “RC” (Required for compliance) in the Accomplishment Instructions of BSASB 767–25–0549, Revision 1, described previously, except for any differences identified as exceptions in the regulatory text of this proposed AD.

For information on the procedures and compliance times, see this service information at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–1011.

#### Differences Between This Proposed AD and the Service Information

The effectivity of BSASB 767–25–0539, Revision 1; and BSASB 767–25–0549, Revision 1, is limited to Model 767–200, –300, –300F, and –400ER series airplanes with Ipeco part number series 3A090 and 3A258 Captain’s and First Officer’s powered seats installed, line numbers 161 and on. However, the applicability of this proposed AD includes all Model 767–200, –300, –300F, and –400ER series airplanes. Because the affected Captain’s and First Officer’s seats are rotatable parts, we have

determined that these seats could later be installed on airplanes that were initially delivered with acceptable seats, thereby subjecting those airplanes to the unsafe condition. The referenced service bulletins can be used on airplanes not included in the service bulletin effectivity. This difference has been coordinated with Boeing.

Where BSASB 767–25–0539, Revision 1, specifies to do the actions “within 72 months after the Original Issue date of this service bulletin,” this AD would require accomplishment of those actions “within 36 months after the effective date of this AD.” The 36-month compliance time corresponds with the compliance time in BSASB 767–25–0549, Revision 1. We have determined

a 36-month compliance time is appropriate for doing the actions specified in this proposed AD. We have coordinated this difference with Boeing.

**Costs of Compliance**

We estimate that this proposed AD affects 90 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Identification, seat .....	1 work-hour × \$85 per hour = \$85 ..	\$0	\$85 .....	\$7,650 per seat.
Detailed inspection, horizontal movement system.	1 work-hour × \$85 per hour = \$85, per seat.	0	\$85 per seat .....	\$7,650 per seat.
Checks, horizontal movement system.	2 work-hour × \$85 per hour = \$170 per seat, per check cycle.	0	\$170 per seat, per check cycle.	\$15,130 per seat, per check cycle.

We estimate the following costs to do any necessary on-condition actions that would be required. We have no way of

determining the number of aircraft that might need these on-condition actions:

**ESTIMATED COSTS OF ON-CONDITION ACTIONS \***

Action	Labor cost	Parts cost	Cost per product
Adjustment, control lever cable .....	1 work-hour × \$85 per hour = \$85, per seat ..	\$0 .....	\$85 per seat.
Overhaul or replacement, horizontal movement system.	Up to 15 work-hours × \$85 per hour = \$1,275, per seat.	Up to \$6,400 per seat	Up to \$7,675 per seat.
Inspection of each seat’s fore/aft and vertical manual control levers.	1 work-hour × \$85 per hour = \$85, per seat ..	\$0 .....	\$85 per seat.
Installation of serviceable seats .....	1 work-hour × \$85 per hour = \$85, per seat ..	\$0 .....	\$85 per seat.
Clearing FOD .....	1 work-hour × \$85 per hour = \$85, per seat ..	\$0 .....	\$85 per seat.
Replacement of the horizontal actuator .....	1 work-hour × \$85 per hour = \$85, per actuator.	\$205 .....	\$290, per actuator.
Functional test, adjusted control lever cable ..	1 work-hour × \$85 per hour = \$85, per seat ..	\$0 .....	\$85, per seat.

\* The estimated cost for tooling to align an affected seat for adjustment of the control lever cable is up to \$46,064.

We have received no definitive data that would enable us to provide cost estimates for the optional terminating action for the on-condition repetitive checks specified in this proposed AD.

**Authority for This Rulemaking**

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority

because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes to the Director of the System Oversight Division.

**Regulatory Findings**

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the

distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator,

the FAA proposes to amend 14 CFR part 39 as follows:

## **PART 39—AIRWORTHINESS DIRECTIVES**

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### **§ 39.13 [Amended]**

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**The Boeing Company:** Docket No. FAA–2018–1011; Product Identifier 2018–NM–131–AD.

#### **(a) Comments Due Date**

We must receive comments by February 11, 2019.

#### **(b) Affected ADs**

None.

#### **(c) Applicability**

This AD applies to all The Boeing Company Model 767–200, –300, –300F, and –400ER series airplanes, certificated in any category.

#### **(d) Subject**

Air Transport Association (ATA) of America Code 25, Equipment/Furnishings.

#### **(e) Unsafe Condition**

This AD was prompted by reports of uncommanded movements of the Captain's and First Officer's seats. We are issuing this AD to address uncommanded movement of the Captain's and First Officer's seats. An uncommanded seat movement during a critical part of a flight, such as take-off or landing, could cause a flight control obstruction or unintended flight control input, which could result in the loss of the ability to control the airplane.

#### **(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

#### **(g) Seat Identification and On-Condition Actions**

Within 36 months after the effective date of this AD, do an inspection to determine the part number, and serial number as applicable, of the Captain's and First Officer's seats, and do all applicable on-condition actions, in accordance with the Accomplishment Instructions of Boeing Special Attention Service Bulletin 767–25–0539, Revision 1, dated July 17, 2018.

#### **(h) Detailed Inspection and Repetitive Checks of Horizontal Movement System and On-Condition Actions**

Except as specified in paragraph (i) of this AD: At the applicable times specified in paragraph 1.E., "Compliance," of Boeing Special Attention Service Bulletin 767–25–0549, Revision 1, dated August 10, 2018 ("BSASB 767–25–0549, Revision 1"), do all applicable actions identified as "RC"

(required for compliance) in, and in accordance with, the Accomplishment Instructions of BSASB 767–25–0549, Revision 1.

#### **(i) Exceptions to Service Information Specifications**

For purposes of determining compliance with the requirements of this AD: Where BSASB 767–25–0549, Revision 1, uses the phrase "the original issue date of this service bulletin," this AD requires using "the effective date of this AD."

#### **(j) Optional Terminating Action for Repetitive Checks**

(1) For Group 1, Configuration 2 and 4 airplanes identified in BSASB 767–25–0549, Revision 1: Installation of a serviceable Captain's seat, as specified in, and in accordance with, the Accomplishment Instructions of BSASB 767–25–0549, Revision 1, terminates the repetitive checks of the Captain's seat as required by paragraph (h) of this AD for that airplane only.

(2) For Group 1, Configuration 3 and 4 airplanes: Installation of a serviceable First Officer's seat BSASB 767–25–0549, Revision 1, as specified in, and in accordance with, the Accomplishment Instructions of BSASB 767–25–0549, Revision 1, terminates the repetitive checks of the First Officer's seat as required by paragraph (h) of this AD for that airplane only.

#### **(k) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (l)(1) of this AD. Information may be emailed to: *9-ANM-Seattle-ACO-AMOC-Requests@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by the Boeing Commercial Airplanes Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (k)(4)(i) and (k)(4)(ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled "RC Exempt," then the RC requirement is removed from that step or

substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

#### **(l) Related Information**

(1) For more information about this AD, contact Brandon Lucero, Aerospace Engineer, Cabin Safety and Environmental Systems Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3569; email: *Brandon.Lucero@faa.gov*.

(2) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet *https://www.myboeingfleet.com*. You may view this referenced service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

Issued in Des Moines, Washington, on December 13, 2018.

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2018–27882 Filed 12–21–18; 8:45 am]

**BILLING CODE 4910–13–P**

## **DEPARTMENT OF TRANSPORTATION**

### **Federal Aviation Administration**

#### **14 CFR Part 39**

**[Docket No. FAA–2018–1058; Product Identifier 2018–CE–051–AD]**

**RIN 2120–AA64**

#### **Airworthiness Directives; Pilatus Aircraft Ltd. Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** We propose to adopt a new airworthiness directive (AD) for Pilatus Aircraft Ltd. Model PC–6, PC–6/350, PC–6/350–H1, PC–6/350–H2, PC–6/A, PC–6/A–H1, PC–6/A–H2, PC–6/B–H2, PC–6/B1–H2, PC–6/B2–H2, PC–6/B2–H4, PC–6/C–H2, PC–6/C1–H2, PC–6–H1, and PC–6–H2 airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify