

| Document | ADAMS Accession No./ Web link/Federal Register Citation |
|---|---|
| Letter from Holtec International dated November 19, 2018, Submitting Request for Amendment No. 13 to Certificate of Compliance No. 1014 | ML18325A154 |
| Proposed Certificate of Compliance No. 1014 Amendment No. 13, Certificate of Compliance for Spent Fuel Storage Casks | ML18351A173 |
| Proposed Certificate of Compliance No. 1014 Amendment No. 13, Technical Specifications, Appendix A | ML18351A174 |
| Proposed Certificate of Compliance No. 1014 Amendment No. 13, Technical Specifications, Appendix B | ML18351A175 |
| Proposed Certificate of Compliance No. 1014 Amendment No. 13, Technical Specifications, Appendix A-100U | ML18351A176 |
| Proposed Certificate of Compliance No. 1014 Amendment No. 13, Technical Specifications, Appendix B-100U | ML18351A177 |
| Certificate of Compliance No. 1014 Amendment No. 13, Preliminary Safety Evaluation Report | ML18351A178 |

The NRC may post materials related to this document, including public comments, on the Federal Rulemaking website at <http://www.regulations.gov> under Docket ID NRC-2019-0030. The Federal Rulemaking website allows you to receive alerts when changes or additions occur in a docket folder. To subscribe: (1) Navigate to the docket folder (NRC-2019-0030); (2) click the "Sign up for Email Alerts" link; and (3) enter your email address and select how frequently you would like to receive emails (daily, weekly, or monthly).

List of Subjects in 10 CFR Part 72

Administrative practice and procedure, Hazardous waste, Indians, Intergovernmental relations, Nuclear energy, Penalties, Radiation protection, Reporting and recordkeeping requirements, Security measures, Whistleblowing.

For the reasons set out in the preamble and under the authority of the Atomic Energy Act of 1954, as amended; the Energy Reorganization Act of 1974, as amended; the Nuclear Waste Policy Act of 1982, as amended; and 5 U.S.C. 552 and 553; the NRC is adopting the following amendments to 10 CFR part 72:

PART 72—LICENSING REQUIREMENTS FOR THE INDEPENDENT STORAGE OF SPENT NUCLEAR FUEL, HIGH-LEVEL RADIOACTIVE WASTE, AND REACTOR-RELATED GREATER THAN CLASS C WASTE

■ 1. The authority citation for part 72 continues to read as follows:

Authority: Atomic Energy Act of 1954, secs. 51, 53, 57, 62, 63, 65, 69, 81, 161, 182, 183, 184, 186, 187, 189, 223, 234, 274 (42 U.S.C. 2071, 2073, 2077, 2092, 2093, 2095, 2099, 2111, 2201, 2210e, 2232, 2233, 2234, 2236, 2237, 2238, 2273, 2282, 2021); Energy Reorganization Act of 1974, secs. 201, 202, 206, 211 (42 U.S.C. 5841, 5842, 5846, 5851); National Environmental Policy Act of 1969 (42 U.S.C. 4332); Nuclear Waste Policy Act of 1982, secs. 117(a), 132, 133, 134, 135, 137, 141, 145(g), 148, 218(a) (42 U.S.C. 10137(a), 10152, 10153, 10154, 10155, 10157, 10161,

10165(g), 10168, 10198(a)); 44 U.S.C. 3504 note.

■ 2. In § 72.214, Certificate of Compliance 1014 is revised to read as follows:

§ 72.214 List of approved spent fuel storage casks.

* * * * *

- Certificate Number:* 1014.
- Initial Certificate Effective Date:* May 31, 2000.
- Amendment Number 1 Effective Date:* July 15, 2002.
- Amendment Number 2 Effective Date:* June 7, 2005.
- Amendment Number 3 Effective Date:* May 29, 2007.
- Amendment Number 4 Effective Date:* January 8, 2008.
- Amendment Number 5 Effective Date:* July 14, 2008.
- Amendment Number 6 Effective Date:* August 17, 2009.
- Amendment Number 7 Effective Date:* December 28, 2009.
- Amendment Number 8 Effective Date:* May 2, 2012, as corrected on November 16, 2012 (ADAMS Accession No. ML12213A170); superseded by Amendment 8, Revision 1 Effective Date: February 16, 2016.
- Amendment Number 8, Revision 1 Effective Date:* February 16, 2016.
- Amendment Number 9 Effective Date:* March 11, 2014, superseded by Amendment Number 9, Revision 1, on March 21, 2016.
- Amendment Number 9, Revision 1, Effective Date:* March 21, 2016, as corrected (ADAMS Accession No. ML17236A451).
- Amendment Number 10 Effective Date:* May 31, 2016, as corrected (ADAMS Accession No. ML17236A452).
- Amendment Number 11 Effective Date:* February 25, 2019.
- Amendment Number 12 Effective Date:* February 25, 2019.
- Amendment Number 13 Effective Date:* May 13, 2019.
- Safety Analysis Report (SAR) Submitted by:* Holtec International.
- SAR Title:* Final Safety Analysis Report for the HI-STORM 100 Cask System.

Docket Number: 72-1014.
Certificate Expiration Date: May 31, 2020.

Model Number: HI-STORM 100.
* * * * *

Dated at Rockville, Maryland, this 14th day of February, 2019.

For the Nuclear Regulatory Commission.

Margaret M. Doane,
Executive Director for Operations.

[FR Doc. 2019-02886 Filed 2-25-19; 8:45 am]

BILLING CODE 7590-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0643; Product Identifier 2018-NM-084-AD; Amendment 39-19572; AD 2019-03-20]

RIN 2120-AA64

Airworthiness Directives; Dassault Aviation Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Dassault Aviation Model FALCON 7X airplanes. This AD was prompted by a determination that new and more restrictive maintenance requirements and airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new and more restrictive maintenance requirements and airworthiness limitations for airplane structures and systems. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 2, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 2, 2019.

ADDRESSES: For service information identified in this final rule, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; phone: 201-440-6700; internet: <http://www.dassaultfalcon.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0643.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0643; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3226.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Dassault Aviation Model FALCON 7X airplanes. The NPRM published in the **Federal Register** on August 10, 2018 (83 FR 39630). The NPRM was prompted by a determination that new and more restrictive maintenance requirements and airworthiness limitations are necessary. The NPRM proposed to require revising the existing maintenance or inspection program, as applicable, to incorporate new and more restrictive maintenance requirements and airworthiness limitations for airplane structures and systems.

We issued a supplemental NPRM (SNPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Dassault Aviation Model FALCON 7X airplanes. The SNPRM published in the **Federal Register** on

November 15, 2018 (83 FR 57364). We issued the SNPRM to require the incorporation of revised and more restrictive airworthiness limitations than those proposed in the NPRM.

We are issuing this AD to address reduced structural integrity and reduced control of airplanes due to the failure of system components.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018-0101, dated May 3, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Dassault Aviation Model FALCON 7X airplanes. The MCAI states:

The airworthiness limitations and certification maintenance instructions for Dassault Falcon 7X aeroplanes, which are approved by EASA, are currently defined and published in Dassault Falcon 7X AMM [airplane maintenance manual], Chapter 5-40. These instructions have been identified as mandatory for continued airworthiness.

Failure to accomplish these instructions could result in an unsafe condition [*i.e.*, reduced structural integrity and reduced control of these airplanes due to the failure of system components].

Previously, EASA issued AD 2015-0095 [which corresponds to FAA AD 2016-16-09, Amendment 39-18607 (81 FR 52752, August 10, 2016) (“AD 2016-16-09”)] to require accomplishment of the maintenance tasks, and implementation of the airworthiness limitations, as specified in Dassault Falcon 7X AMM, Chapter 5-40, at Revision 4.

Since that [EASA] AD was issued, Dassault issued the ALS [airworthiness limitations section], which introduces new and more restrictive maintenance requirements and/or airworthiness limitations.

For the reason described above, this [EASA] AD retains the requirements of EASA AD 2015-0095, which is superseded, and requires accomplishment of the actions specified in the ALS.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0643.

Comments

We gave the public the opportunity to participate in developing this final rule. We received no comments on the SNPRM or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the SNPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the SNPRM.

Related Service Information Under 1 CFR Part 51

Dassault Aviation has issued Chapter 5-40-00, Airworthiness Limitations, DGT 107838, Revision 7, dated August 24, 2018, of the Dassault Falcon 7X Maintenance Manual (MM). This service information introduces new and more restrictive maintenance requirements and airworthiness limitations for airplane structures and systems. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 67 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

We have determined that revising the existing maintenance or inspection program takes an average of 90 work-hours per operator, although we recognize that this number may vary from operator to operator. In the past, we have estimated that this action takes 1 work-hour per airplane. Since operators incorporate maintenance or inspection program changes for their affected fleet(s), we have determined that a per-operator estimate is more accurate than a per-airplane estimate. Therefore, we estimate the total cost per operator to be \$7,650 (90 work-hours × \$85 per work-hour).

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on

products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019–03–20 Dassault Aviation:

Amendment 39–19572; Docket No. FAA–2018–0643; Product Identifier 2018–NM–084–AD.

(a) Effective Date

This AD is effective April 2, 2019.

(b) Affected ADs

This AD affects AD 2014–16–23, Amendment 39–17947 (79 FR 52545, September 4, 2014) (“AD 2014–16–23”) and AD 2016–16–09, Amendment 39–18607 (81 FR 52752, August 10, 2016) (“AD 2016–16–09”).

(c) Applicability

This AD applies to Dassault Aviation Model FALCON 7X airplanes, certificated in any category, with an original certificate of airworthiness or original export certificate of airworthiness issued on or before August 24, 2018.

Note 1 to paragraph (c) of this AD: Model FALCON 7X airplanes with modifications M1000 and M1254 incorporated are commonly referred to as “Model FALCON 8X” airplanes as a marketing designation.

(d) Subject

Air Transport Association (ATA) of America Code 05, Time limits/maintenance checks.

(e) Reason

This AD was prompted by a determination that new and more restrictive maintenance requirements and airworthiness limitations are necessary. We are issuing this AD to address reduced structural integrity and reduced control of airplanes due to the failure of system components.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revise the Existing Maintenance or Inspection Program

Within 90 days after the effective date of this AD, revise the existing maintenance or inspection program, as applicable, by incorporating the information specified in Chapter 5–40–00, Airworthiness Limitations, DGT 107838, Revision 7, dated August 24, 2018, of the Dassault Falcon 7X Maintenance Manual (MM). The initial compliance times for the tasks specified in Chapter 5–40–00, Airworthiness Limitations, DGT 107838, Revision 7, dated August 24, 2018, of the Dassault Falcon 7X MM are at the applicable compliance times specified in Chapter 5–40–00, Airworthiness Limitations, DGT 107838, Revision 7, dated August 24, 2018, of the Dassault Falcon 7X MM, or within 90 days after the effective date of this AD, whichever occurs later.

(h) Terminating Action for Other ADs

(1) Accomplishing the actions required by paragraph (g) of this AD terminates the requirements of paragraph (q) of AD 2014–16–23.

(2) Accomplishing the actions required by paragraph (g) of this AD terminates all requirements of AD 2016–16–09.

(i) No Alternative Actions, Intervals, and Critical Design Configuration Control Limitations (CDCCLs)

After the maintenance or inspection program, as applicable, has been revised as required by paragraph (g) of this AD, no alternative actions (e.g., inspections), intervals, or CDCCLs may be used unless the actions, intervals, and CDCCLs are approved as an alternative method of compliance (AMOC) in accordance with the procedures specified in paragraph (j)(1) of this AD.

(j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the European Aviation Safety Agency (EASA); or Dassault Aviation’s EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(k) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) EASA AD 2018–0101, dated May 3, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2018–0643.

(2) For more information about this AD, contact Tom Rodriguez, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3226.

(l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Chapter 5–40–00, Airworthiness Limitations, DGT 107838, Revision 7, dated August 24, 2018, of the Dassault Falcon 7X Maintenance Manual (MM).

(ii) [Reserved]

(3) For service information identified in this AD, contact Dassault Falcon Jet Corporation, Teterboro Airport, P.O. Box 2000, South Hackensack, NJ 07606; phone: 201-440-6700; internet: <http://www.dassaultfalcon.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on February 14, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-03122 Filed 2-25-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0964; Product Identifier 2018-NM-127-AD; Amendment 39-19571; AD 2019-03-19]

RIN 2120-AA64

Airworthiness Directives; Saab AB, Saab Aeronautics (Formerly Known as Saab AB, Saab Aerosystems) Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for all Saab AB, Saab Aeronautics Model SAAB 2000 airplanes. This AD was prompted by reports that certain fuel probes indicated misleading fuel quantities on the engine indicating and crew alerting system (EICAS). This AD requires a functional check of certain fuel probes, and replacement with a serviceable part if necessary. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 2, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of April 2, 2019.

ADDRESSES: For service information identified in this final rule, contact Saab AB, Saab Aeronautics, SE-581 88,

Linköping, Sweden; telephone +46 13 18 5591; fax +46 13 18 4874; email saab2000.techsupport@saabgroup.com; internet <http://www.saabgroup.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0964.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0964; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Shahram Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3220.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Saab AB, Saab Aeronautics Model SAAB 2000 airplanes. The NPRM published in the **Federal Register** on November 26, 2018 (83 FR 60374). The NPRM was prompted by reports that certain fuel probes indicated misleading fuel quantities on the EICAS. The NPRM proposed to require a functional check of certain fuel probes, and replacement with a serviceable part if necessary.

We are issuing this AD to address deteriorated capacity of the fuel probes, which could lead to incorrect fuel reading, possibly resulting in fuel starvation and uncommanded engine in-flight shutdown, and consequent reduced control of the airplane.

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Union, has issued EASA Airworthiness Directive 2018-0187, dated August 29, 2018 (referred to after this as the

Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Saab AB, Saab Aeronautics Model SAAB 2000 airplanes. The MCAI states:

Occurrences were reported that certain fuel probes, installed on SAAB 2000 aeroplanes, indicated misleading fuel quantities on the engine indicating and crew alerting system (EICAS). The investigation results suggest that this may be an aging phenomenon, leading to deteriorated capacity of the fuel probes.

This condition, if not detected and corrected, could lead to incorrect fuel reading, possibly resulting in fuel starvation and uncommanded engine in-flight shutdown, with consequent reduced control of the aeroplane.

To address this potential unsafe condition, SAAB issued the SB [service bulletin] to provide instructions for a functional check.

For the reason described above, this [EASA] AD requires a one-time functional check of the fuel quantity system and the fuel low level EICAS warnings to determine whether any affected parts are out of tolerance and, depending on findings, replacement of those affected parts.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0964.

Comments

We gave the public the opportunity to participate in developing this final rule. We received no comments on the NPRM or on the determination of the cost to the public.

Clarification of Paragraph (g)(2) of This AD

We have removed the words “has reached” from the definition in paragraph (g)(2) of this AD for clarity and to match the MCAI.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this final rule with the change described previously and minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

We also determined that these changes will not increase the economic burden on any operator or increase the scope of this final rule.