

procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(I) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2018-26, dated October 5, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0186.

(2) For more information about this AD, contact Darren Gassetto, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7323; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on May 3, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-09643 Filed 5-13-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0256; Product Identifier 2019-NM-027-AD]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for all Bombardier, Inc., Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes; Model CL-600-2C10 (Regional Jet Series 700, 701 & 702) airplanes; Model CL-600-2D15 (Regional Jet Series 705) airplanes; Model CL-600-2D24 (Regional Jet Series 900) airplanes; and Model CL-600-2E25 (Regional Jet Series 1000) airplanes. This proposed AD was prompted by a report that during Automatic Flight Control System (AFCS) ALTS CAP or (V) ALTS CAP mode the flight guidance/autopilot does not account for engine failure while capturing an altitude. This proposed AD would require revising the airplane flight manual (AFM) to include a limitation and abnormal operating procedure for the AFCS. We are proposing this AD to address the unsafe condition on these products.

DATES: We must receive comments on this proposed AD by June 28, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email

ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0256; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Steven Dzierzynski, Aerospace Engineer, Avionics and Electrical Systems Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7367; fax 516-794-5531; email 9-avs-nyaco-cos@faa.gov.

SUPPLEMENTARY INFORMATION:

Comments Invited

We invite you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include "Docket No. FAA-2019-0256; Product Identifier 2019-NM-027-AD" at the beginning of your comments. We specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. We will consider all comments received by the closing date and may amend this NPRM because of those comments.

We will post all comments we receive, without change, to <http://www.regulations.gov>, including any personal information you provide. We will also post a report summarizing each substantive verbal contact we receive about this NPRM.

Discussion

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2018-32, dated December 10, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or "the MCAI"), to correct an unsafe condition for all Bombardier, Inc., Model CL-600-2B19 (Regional Jet Series 100 & 440) airplanes; Model CL-

600-2C10 (Regional Jet Series 700, 701 & 702) airplanes; Model CL-600-2D15 (Regional Jet Series 705) airplanes; Model CL-600-2D24 (Regional Jet Series 900) airplanes; and Model CL-600-2E25 (Regional Jet Series 1000) airplanes. The MCAI states:

It was determined that during ALTS CAP or (V) ALTS CAP mode, the flight guidance/autopilot does not account for engine failure while capturing an altitude. If an engine failure occurs during or before a climb while in ALTS CAP or (V) ALTS CAP mode, the airspeed may drop significantly below the safe operating speed. Prompt crew intervention may be required to maintain a safe operating speed.

This [Canadian] AD mandates the introduction of a Limitation and Abnormal procedure to the [airplane flight manual] AFM to address the above mentioned unsafe condition.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0256.

Related Service Information Under 1 CFR Part 51

Bombardier has issued the following service information, which describes procedures for revising the AFM by including a warning for the AFCS and procedures if an engine failure occurs during or before a climb while in ALTS CAP mode or if an engine failure occurs during or before a climb while in (V) ALTS CAP mode. These documents are distinct since they apply to different airplane models.

- Subject 2—AFCS, of Section 02-08, “System Limitations,” of Chapter 2, “LIMITATIONS,” and Subject C, “Engine Failure in Climb During ALTS CAP,” of Section 05-02, “In-flight Engine Failures,” of Chapter 5, “ABNORMAL PROCEDURES,” of the Bombardier CRJ Regional Jet AFM, CSP A-012, Revision 70, dated July 13, 2018.

- Subject 2—AFCS, of Section 02-08, “System Limitations,” of Chapter 2, “LIMITATIONS,” and Subject C, “Engine Failure in Climb During ALTS CAP” and “Engine Failure in Climb During (V) ALTS CAP,” of Section 05-02, “In-flight Engine Failures,” of Chapter 5, “ABNORMAL PROCEDURES,” of the Bombardier CRJ Regional Jet AFM CSP B-012, Revision 24, dated May 11, 2018.

- Subject 2—AFCS, of Section 02-08, “System Limitations,” of Chapter 2, “LIMITATIONS,” and Subject C, “Engine Failure in Climb During ALTS CAP” and “Engine Failure in Climb During (V) ALTS CAP,” of Section 05-02, “In-flight Engine Failures,” of Chapter 5, “ABNORMAL PROCEDURES,” of the Bombardier CRJ Regional Jet AFM CSP C-012, Revision 19A, dated August 17, 2018.

- Subject 2—AFCS, of Section 02-08, “System Limitations,” of Chapter 2, “LIMITATIONS,” and Subject C, “Engine Failure in Climb During ALTS CAP” and “Engine Failure in Climb During (V) ALTS CAP,” of Section 05-02, “In-flight Engine Failures,” of Chapter 5, “ABNORMAL PROCEDURES,” of the Bombardier CRJ

Regional Jet AFM CSP D-012, Revision 20, dated September 28, 2018.

This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to our bilateral agreement with the State of Design Authority, we have been notified of the unsafe condition described in the MCAI and service information referenced above. We are proposing this AD because we evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop on other products of the same type design.

Proposed Requirements of This NPRM

This proposed AD would require revising the AFM by including a warning for the AFCS and procedures if an engine failure occurs during or before a climb while in ALTS CAP mode and if an engine failure occurs during or before a climb while in (V) ALTS CAP mode.

Costs of Compliance

We estimate that this proposed AD affects 985 airplanes of U.S. registry. We estimate the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
1 work-hour × \$85 per hour = \$85	\$0	\$85	\$83,725

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation

is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

We determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

1. Is not a “significant regulatory action” under Executive Order 12866;
2. Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979);

- 3. Will not affect intrastate aviation in Alaska; and
- 4. Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

Bombardier, Inc.: Docket No. FAA–2019–0256; Product Identifier 2019–NM–027–AD.

(a) Comments Due Date

We must receive comments by June 28, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to the Bombardier, Inc. airplanes identified in paragraphs (c)(1) through (c)(5) of this AD, certificated in any category, all manufacturer serial numbers.

(1) Model CL–600–2B19 (Regional Jet Series 100 & 440) airplanes.

(2) Model CL–600–2C10 (Regional Jet Series 700, 701 & 702) airplanes.

(3) Model CL–600–2D15 (Regional Jet Series 705) airplanes.

(4) Model CL–600–2D24 (Regional Jet Series 900) airplanes.

(5) Model CL–600–2E25 (Regional Jet Series 1000) airplanes.

(d) Subject

Air Transport Association (ATA) of America Code 22, Auto flight.

(e) Reason

This AD was prompted by a report that during Automatic Flight Control System

(AFCS) ALTS CAP or (V) ALTS CAP mode the flight guidance/autopilot does not account for engine failure while capturing an altitude. We are issuing this AD to address an engine failure that occurs during or before a climb while in ALTS CAP or (V) ALTS CAP mode, which may cause the airspeed to drop significantly below the safe operating speed, possibly resulting in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Revision of the Airplane Flight Manual (AFM)

Within 30 days after the effective date of this AD: Revise the AFM to include the information in Subject 2, “Automatic Flight Control System (AFCS),” of Section 02–08, “System Limitations,” of Chapter 2, “LIMITATIONS,” and Subject C, “Engine Failure in Climb During ALTS CAP,” or “Engine Failure in Climb During (V) ALTS CAP,” of Section 05–02, “In-flight Engine Failures,” of Chapter 5, “ABNORMAL PROCEDURES,” as applicable, of the applicable AFM identified in figure 1 to paragraph (g) of this AD.

BILLING CODE 4910–13–P

Figure 1 to paragraph (g) of this AD – AFM Revision

Bombardier Airplane Model	AFM Number	AFM Revision
CL-600-2B19	CSP A-012	AFM Revision 70, dated July 13, 2018.
CL-600-2C10	CSP B-012	AFM Revision 24, dated May 11, 2018.
CL-600-2D15 CL-600-2D24	CSP C-012	AFM Revision 19A, dated August 17, 2018.
CL-600-2E25	CSP D-012	AFM Revision 20, dated September 28, 2018.

(h) Credit for Previous Actions

This paragraph provides credit for actions required by paragraph (g) of this AD, if those

actions were performed before the effective date of this AD using the applicable AFM

specified in figure 2 to paragraph (h) of this AD.

Figure 2 to paragraph (h) of this AD – Credit for Previous AFM Revision

Bombardier Airplane Model	AFM Number	AFM Revision
CL-600-2B19	CSP A-012	AFM Revision 68, dated August 04, 2017; or AFM Revision 69, dated January 05, 2018.
CL-600-2C10	CSP B-012	AFM Revision 22, dated September 15, 2017; or AFM Revision 22A, dated January 03, 2018; or AFM Revision 23, dated March 02, 2018; or AFM revision 23A, dated April 30, 2018.
CL-600-2D15 CL-600-2D24	CSP C-012	AFM Revision 17, dated October 13, 2017; or AFM Revision 17A, dated November 15, 2017; or AFM Revision 17B, dated January 03, 2018; or AFM Revision 18, dated March 29, 2018; or AFM Revision 18A, dated April 30, 2018; or AFM Revision 19, dated June 15, 2018.
CL-600-2E25	CSP D-012	AFM Revision 17, dated June 16, 2017; or AFM Revision 18, dated November 10, 2017; or AFM Revision 18A, dated January 03, 2018; or AFM Revision 19, dated April 27, 2018.

BILLING CODE 4910-13-C**(i) Other FAA AD Provisions**

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by

the DAO, the approval must include the DAO-authorized signature.

(j) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2018-32, dated December 10, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0256.

(2) For more information about this AD, contact Steven Dzierzynski, Aerospace Engineer, Avionics and Electrical Systems Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7367; fax 516-794-5531; email 9-avs-nyacos@faa.gov.

(3) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; fax 514-855-7401; email ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

Issued in Des Moines, Washington, on April 25, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-09806 Filed 5-13-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2019-0323; Product Identifier 2019-NM-026-AD]

RIN 2120-AA64

Airworthiness Directives; The Boeing Company Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: We propose to adopt a new airworthiness directive (AD) for certain The Boeing Company Model 737-800 series airplanes. This proposed AD was