

Rules and Regulations

Federal Register

Vol. 84, No. 103

Wednesday, May 29, 2019

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

NATIONAL MEDIATION BOARD

5 CFR Chapter CI

[Docket No. C-7188]

RIN 3209-AA47

Supplemental Standards of Ethical Conduct for Employees of the National Mediation Board

AGENCY: National Mediation Board.

ACTION: Final rule.

SUMMARY: The National Mediation Board (NMB or Board), with the concurrence of the U.S. Office of Government Ethics (OGE), is issuing a final rule for employees of the NMB that supplements the executive branch-wide Standards of Ethical Conduct (Standards) issued by OGE. The supplemental regulation requires NMB employees to obtain approval before engaging in outside employment.

DATES: This final rule is effective May 29, 2019.

FOR FURTHER INFORMATION CONTACT: Mary Johnson, General Counsel, National Mediation Board, 202-692-5050, infoline@nmb.gov.

SUPPLEMENTARY INFORMATION:

I. Background

On November 1, 2018, the NMB, with OGE's concurrence, published an interim final rule in the **Federal Register**, 83 FR 54861, adopting agency-specific supplemental regulations requiring NMB employees to obtain approval before engaging in outside employment. The interim final rule provided a 60 day comment period, which ended on December 31, 2018. The NMB did not receive any comments. The rationale for the interim final rule, which the NMB is now adopting as final, is explained in the preamble at: [https://www.federalregister.gov/documents/2018/11/01/2018-23548/supplemental-standards-of-ethical-conduct-for-](https://www.federalregister.gov/documents/2018/11/01/2018-23548/supplemental-standards-of-ethical-conduct-for-employees-of-the-national-mediation-board)

employees-of-the-national-mediation-board.

II. Matters of Regulatory Procedure

Executive Order 12866

This rule is not a significant rule for purposes of Executive Order 12866 and has not been reviewed by the Office of Management and Budget.

Regulatory Flexibility Act

As required by the Regulatory Flexibility Act, the NMB certifies that these regulatory changes will not have a significant impact on small business entities. This rule will not have any significant impact on the quality of the human environment under the National Environmental Policy Act.

Paperwork Reduction Act

The NMB has determined that the Paperwork Reduction Act does not apply because this regulation does not contain any information collection requirements that require the approval of the Office of Management and Budget.

List of Subjects in 5 CFR Part 10101

Conflicts of interests, Government employees.

Dated: May 1, 2019.

By direction of the Board.

Mary Johnson,

General Counsel, National Mediation Board.

Emory A. Rounds, III,

Director, U.S. Office of Government Ethics.

Chapter CI—National Mediation Board

PART 10101—SUPPLEMENTAL STANDARDS OF ETHICAL CONDUCT FOR EMPLOYEES OF THE NATIONAL MEDIATION BOARD

■ Accordingly, the interim rule adding 5 CFR chapter CI, consisting of part 10101, which was published at 83 FR 54861 on November 1, 2018, is adopted as final without change.

[FR Doc. 2019-11163 Filed 5-28-19; 8:45 am]

BILLING CODE 7550-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 25

[Docket No. FAA-2019-0235; Special Conditions No. 25-747-SC]

Special Conditions: Airbus Model A330 Series Airplanes; Seats With Inertia Locking Devices

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final special conditions.

SUMMARY: These special conditions are issued for the Airbus Model A330 series airplane. These airplanes will have a novel or unusual design feature when compared to the state of technology envisioned in the airworthiness standards for transport-category airplanes. This design feature is seats with inertia locking devices. The applicable airworthiness regulations do not contain adequate or appropriate safety standards for this design feature. These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

DATES: Effective May 29, 2019.

FOR FURTHER INFORMATION CONTACT: Shannon Lennon, Cabin and Airframe Safety Section, AIR-675, Transport Standards Branch, Policy and Innovation Division, Aircraft Certification Service, Federal Aviation Administration, 2200 South 216th Street, Des Moines, Washington 98198; telephone and fax 206-231-3209; email shannon.lennon@faa.gov.

SUPPLEMENTARY INFORMATION:

Background

On February 13, 2019, Airbus applied for a change to Type Certificate No. A46NM for seats with inertia locking devices in Model A330 series airplanes. The Model A330 series airplane is a twin-engine, transport-category airplane with a maximum takeoff weight of 533,518 pounds and seating for 440 passengers.

Type Certification Basis

Under the provisions of title 14, Code of Federal Regulations (14 CFR) 21.101, Airbus must show that the Model A330

series airplanes, as changed, continue to meet the applicable provisions of the regulations listed in Type Certificate No. A46NM, or the applicable regulations in effect on the date of application for the change, except for earlier amendments as agreed upon by the FAA.

If the Administrator finds that the applicable airworthiness regulations (*i.e.*, 14 CFR part 25) do not contain adequate or appropriate safety standards for Airbus Model A330 series airplanes because of a novel or unusual design feature, special conditions are prescribed under the provisions of § 21.16.

Special conditions are initially applicable to the model for which they are issued. Should the type certificate for that model be amended later to include any other model that incorporates the same novel or unusual design feature, or should any other model already included on the same type certificate be modified to incorporate the same novel or unusual design feature, these special conditions would also apply to the other model under § 21.101.

In addition to the applicable airworthiness regulations and special conditions, Airbus Model A330 series airplanes must comply with the fuel-vent and exhaust-emission requirements of 14 CFR part 34, and the noise-certification requirements of 14 CFR part 36.

The FAA issues special conditions, as defined in 14 CFR 11.19, in accordance with § 11.38, and they become part of the type certification basis under § 21.101.

Novel or Unusual Design Features

Airbus Model A330 series airplanes will incorporate the following novel or unusual design features:

Seats with inertia locking devices (ILD).

Discussion

Airbus will install, in Model A330 series airplanes, Thompson Aero Seating Ltd. passenger seats that can be translated in the fore and aft direction by an electrically powered motor (actuator) that is attached to the seat primary structure. Under typical service-loading conditions, the motor internal brake is able to translate the seat and hold the seat in the translated position. However, under the inertial loads of emergency-landing loading conditions specified in 14 CFR 25.562, the motor internal brake may not be able to maintain the seat in the required position. The ILD is an “active” device intended to control seat movement (*i.e.*, a system that mechanically deploys

during an impact event) to lock the gears of the motor assembly in place. The ILD mechanism is activated by the higher inertial load factors that could occur during an emergency landing event. Each seat place incorporates two ILDs, one on either side of the seat pan. Only one ILD is required to hold an occupied seat in position during worst-case dynamic loading specified in § 25.562.

The ILD will self-activate only in the event of a predetermined airplane loading condition such as that occurring during crash or emergency landing, and will prevent excessive seat forward translation. A minimum level of protection must be provided if the seat-locking device does not deploy.

The normal means of satisfying the structural and occupant protection requirements of § 25.562 result in a non-quantified, but nominally predictable, progressive structural deformation or reduction of injury severity for impact conditions less than the maximum specified by the rule. A seat using ILD technology, however, may involve a step change in protection for impacts below and above that at which the ILD activates and deploys to retain the seat pan in place. This could result in structural deformation or occupant injury output being higher at an intermediate impact condition than that resulting from the maximum impact condition. It is acceptable for such step-change characteristics to exist, provided the resulting output does not exceed the maximum allowable criteria at any condition at which the ILD does or does not deploy, up to the maximum severity pulse specified by the requirements.

The ideal triangular maximum severity pulse is defined in Advisory Circular (AC) 25.561–1B. For the evaluation and testing of less-severe pulses for purposes of assessing the effectiveness of the ILD deployment setting, a similar triangular pulse should be used with acceleration, rise time, and velocity change scaled accordingly. The magnitude of the required pulse should not deviate below the ideal pulse by more than 0.5g until 1.33 t_1 is reached, where t_1 represents the time interval between 0 and t_1 on the referenced pulse shape as shown in AC 25.561–1B. This is an acceptable method of compliance to the test requirements of the special conditions.

Conditions 1 through 5 address ensuring that the ILD activates when intended, to provide the necessary protection of occupants. This includes protection of a range of occupants under various accident conditions. Conditions 6 through 10 address maintenance and reliability of the ILD, including any

outside influences on the mechanism, to ensure it functions as intended.

These special conditions contain the additional safety standards that the Administrator considers necessary to establish a level of safety equivalent to that established by the existing airworthiness standards.

Discussion of Comments

The FAA issued Notice of Proposed Special Conditions No. 25–19–02–SC for the Airbus Model A330 series airplane. This document was published in the **Federal Register** on April 16, 2019 (84 FR 15531). No comments were received, and the special conditions are adopted as proposed.

Applicability

As discussed above, these special conditions are applicable to Airbus Model A330 series airplanes. Should Airbus apply at a later date for a change to the type certificate to include another model incorporating the same novel or unusual design feature, these special conditions would apply to that model as well.

Conclusion

This action affects only one novel or unusual design feature on one model series of airplanes. It is not a rule of general applicability.

List of Subjects in 14 CFR Part 25

Aircraft, Aviation safety, Reporting and recordkeeping requirements.

Authority Citation

The authority citation for these special conditions is as follows:

Authority: 49 U.S.C. 106(f), 106(g), 40113, 44701, 44702, 44704.

The Special Conditions

Accordingly, pursuant to the authority delegated to me by the Administrator, the following special conditions are issued as part of the type certification basis for Airbus Model A330 series airplanes.

In addition to the requirements of § 25.562, passenger seats incorporating inertia locking devices (ILD)s must meet the following:

1. *Level of Protection Provided by ILD*—It must be demonstrated by test that the seats and attachments, when subject to the emergency-landing dynamic conditions specified in § 25.562, and with one ILD not deployed, do not experience structural failure that could result in:

- a. Separation of the seat from the airplane floor.
- b. Separation of any part of the seat that could form a hazard to the seat

occupant or any other airplane occupant.

c. Failure of the occupant restraint or any other condition that could result in the occupant separating from the seat.

2. *Protection Provided Below and Above the ILD Actuation Condition*—If step-change effects on occupant protection exist for impacts below and above that at which the ILD deploys, tests must be performed to demonstrate that the occupant is shown to be protected at any condition at which the ILD does or does not deploy, up to the maximum severity pulse specified by § 25.562. Test conditions must take into account any necessary tolerances for deployment.

3. *Protection Over a Range of Crash Pulse Vectors*—The ILD must be shown to function as intended for all test vectors specified in § 25.562.

4. *Protection During Secondary Impacts*—The ILD activation setting must be demonstrated to maximize the probability of the protection being available when needed, considering a secondary impact that is above the severity at which the device is intended to deploy up to the impact loading required by § 25.562.

5. *Protection of Occupants other than 50th Percentile*—Protection of occupants for a range of stature from a two-year-old child to a ninety-five percentile male must be shown.

6. *Inadvertent Operation*—It must be shown that any inadvertent operation of the ILD does not affect the performance of the device during a subsequent emergency landing.

7. *Installation Protection*—It must be shown that the ILD installation is protected from contamination and interference from foreign objects.

8. *Reliability*—The performance of the ILD must not be altered by the effects of wear, manufacturing tolerances, aging or drying of lubricants, and corrosion.

9. *Maintenance and Functional Checks*—The design, installation, and operation of the ILD must be such that it is possible to functionally check the device in place. Additionally, a functional-check method and a maintenance-check interval must be included in the seat installer's instructions for continued airworthiness (ICA) document.

10. *Release Function*—If a means exists to release an inadvertently activated ILD, the release means must not introduce additional hidden failures that would prevent the ILD from functioning properly.

Issued in Des Moines, Washington, on May 22, 2019.

Victor Wicklund,

Manager, Transport Standards Branch, Policy and Innovation Division, Aircraft Certification Service.

[FR Doc. 2019-11071 Filed 5-28-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0726; Product Identifier 2017-SW-097-AD; Amendment 39-19638; AD 2019-09-04]

RIN 2120-AA64

Airworthiness Directives; Leonardo S.p.A. (Type Certificate Previously Held by Finmeccanica S.p.A., AgustaWestland S.p.A.) Helicopters

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Leonardo S.p.A. (Type Certificate previously held by Finmeccanica S.p.A., AgustaWestland S.p.A.) Model AW109SP helicopters. This AD requires inspecting and altering the rescue hoist. This AD was prompted by a report of a damaged hoist cable that detached after load application. The actions of this AD are intended to address an unsafe condition on these products.

DATES: This AD is effective July 3, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain document listed in this AD as of July 3, 2019.

ADDRESSES: For service information identified in this final rule, contact Leonardo S.p.A. Helicopters, Matteo Ragazzi, Head of Airworthiness, Viale G. Agusta 520, 21017 C. Costa di Samarate (Va) Italy; telephone +39-0331-711756; fax +39-0331-229046; or at <https://www.leonardocompany.com/en/home>. You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0726.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for

and locating Docket No. FAA-2018-0726; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the European Aviation Safety Agency (EASA) AD, any incorporated-by-reference service information, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT:

David Hatfield, Aviation Safety Engineer, Safety Management Section, Rotorcraft Standards Branch, FAA, 10101 Hillwood Pkwy., Fort Worth, TX 76177; telephone (817) 222-5110; email david.hatfield@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Leonardo S.p.A. (formerly Finmeccanica S.p.A., AgustaWestland S.p.A.) Model AW109SP helicopters. The NPRM published in the **Federal Register** on August 21, 2018 (83 FR 42230). The NPRM was prompted by a report of a damaged hoist cable that detached after load application. The NPRM proposed to require inspecting and altering the rescue hoist.

We are issuing this AD to address chafing of a rescue hoist cable. This condition could result in detachment of an external load and subsequent injury to persons being lifted.

EASA, which is the Technical Agent for the Member States of the European Union, has issued AD No. 2017-0025, dated February 14, 2017, to correct an unsafe condition for certain Leonardo S.p.A. (formerly Finmeccanica S.p.A. and AgustaWestland S.p.A.) Model AW109SP helicopters. EASA advises that a hoist cable became snagged behind a hoist handle assembly nut and broke during a dummy load application. EASA further advises that this condition could result in detachment of an external load, and subsequent personal injury or injury to persons on the ground. To address this unsafe condition, the EASA AD requires inspecting the hoist cable, modifying the rescue hoist handle, and amending the rescue hoist pre-flight inspection described in the rotorcraft flight manual.