

(i) Bombardier REO 601R-53-61-1230, dated February 10, 2005.

(ii) Bombardier REO 601R-53-61-1230, Revision A, dated November 6, 2009.

(iii) Bombardier REO 601R-53-61-1230, Revision B, dated October 5, 2005.

(iv) Bombardier REO 601R-53-61-1230, Revision C, dated November 10, 2005.

(v) Bombardier REO 601R-53-61-1230, Revision D, dated July 19, 2006.

(vi) Bombardier REO 601R-53-61-1230, Revision E, dated August 18, 2011.

(3) This paragraph provides credit for the actions required by paragraph (k)(2) of this AD, if those actions were performed before the effective date of this AD using the service information specified in paragraph (p)(3)(i), (p)(3)(ii), (p)(3)(iii), (p)(3)(iv), or (p)(3)(v) of this AD, provided that the maintenance or inspection program is revised by incorporating the inspection requirements at the threshold and repetitive inspection times specified in the SDIR of Bombardier REO 601R-53-61-1285, Revision E, date October 31, 2016.

(i) Bombardier REO 601R-53-61-1285, dated March 24, 2005.

(ii) Bombardier REO 601R-53-61-1285, Revision A, dated November 6, 2009.

(iii) Bombardier REO 601R-53-61-1285, Revision B, dated April 14, 2010.

(iv) Bombardier REO 601R-53-61-1285, Revision C, dated August 19, 2011.

(v) Bombardier REO 601R-53-61-1285, Revision D, dated October 31, 2011.

(4) This paragraph provides credit for the actions required by paragraph (k)(2) of this AD if those actions were performed before the effective date of this AD using the service information specified in paragraph (p)(4)(i), (p)(4)(ii), (p)(4)(iii), (p)(4)(iv), (p)(4)(v), or (p)(4)(vi) of this AD, provided that the maintenance or inspection program is revised by incorporating the inspection requirements at the threshold and repetitive inspection times specified in the SDIR of Bombardier REO 601R-53-61-1541, Revision F, dated November 12, 2014.

(i) Bombardier REO 601R-53-61-1541, dated November 27, 2005.

(ii) Bombardier REO 601R-53-61-1541, Revision A, dated February 8, 2008.

(iii) Bombardier REO 601R-53-61-1541, Revision B, dated March 16, 2009.

(iv) Bombardier REO 601R-53-61-1541, Revision C, dated August 19, 2011.

(v) Bombardier REO 601R-53-61-1541, Revision D, dated October 31, 2011.

(vi) Bombardier REO 601R-53-61-1541, Revision E, dated November 5, 2013.

(5) This paragraph provides credit for the actions required by paragraph (m) of this AD, if those actions were performed before the effective date of this AD using Bombardier REO 601R-53-61-5828, dated November 1, 2016, provided that the maintenance or inspection program is revised by incorporating the inspection requirements at the threshold and repetitive inspection times specified in the SDIR of Bombardier REO 601R-53-61-5828, Revision A, dated March 16, 2017.

#### (q) Other FAA AD Provisions

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO

Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: 516-228-7300; fax: 516-794-5531.

(i) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(ii) AMOCs approved previously for AD 2012-25-02 are approved as AMOCs for the corresponding provisions in paragraphs (g), (h), and (i) of this AD.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or TCCA; or Bombardier Inc.'s TCCA DAO. If approved by the DAO, the approval must include the DAO-authorized signature.

#### (r) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian Airworthiness Directive CF-2011-30R2, dated June 12, 2017, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0794.

(2) For more information about this AD, contact Aziz Ahmed, Aerospace Engineer, Airframe and Mechanical Systems Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7329; fax 516-794-5531.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (s)(5) and (s)(6) of this AD.

#### (s) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(3) The following service information was approved for IBR on July 12, 2019.

(i) Bombardier Repair Engineering Order 601R-53-61-1230, Revision F, dated October 31, 2011.

(ii) Bombardier Repair Engineering Order 601R-53-61-1240, Revision D, dated October 31, 2016.

(iii) Bombardier Repair Engineering Order 601R-53-61-1285, Revision E, dated October 31, 2016.

(iv) Bombardier Repair Engineering Order 601R-53-61-1541, Revision F, dated November 12, 2014.

(v) Bombardier Repair Engineering Order 601R-53-61-5828, Revision A, dated March 16, 2017.

(4) The following service information was approved for IBR on January 16, 2013 (77 FR 73902, December 12, 2012).

(i) Bombardier Temporary Revision 2B-2187, dated June 22, 2011, to Appendix B-Airworthiness Limitations, of Part 2 of the Bombardier CL-600-2B19 Maintenance Requirements Manual.

(ii) [Reserved]

(5) For service information identified in this AD, contact Bombardier, Inc., 400 Côte-Vertu Road West, Dorval, Québec H4S 1Y9, Canada; Widebody Customer Response Center North America toll-free telephone 1-866-538-1247 or direct-dial telephone 514-855-5000; fax 514-855-7401; email [ac.yul@aero.bombardier.com](mailto:ac.yul@aero.bombardier.com); internet <http://www.bombardier.com>.

(6) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(7) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on April 19, 2019,

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019-11956 Filed 6-6-19; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2018-0696; Product Identifier 2017-SW-101-AD; Amendment 39-19650; AD 2019-11-04]

**RIN 2120-AA64**

#### Airworthiness Directives; Airbus Helicopters Deutschland GmbH Helicopters

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** We are adopting a new airworthiness directive (AD) for certain Airbus Helicopters Deutschland GmbH (Airbus Helicopters) Model MBB-BK 117 D-2 helicopters. This AD requires replacing the rescue hoist cable cut pushbutton flip guard (flip guard). This AD was prompted by reports of unintended lifting of several flip guards.

We are issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective July 12, 2019.

**ADDRESSES:** For service information identified in this final rule, contact Airbus Helicopters, 2701 N. Forum Drive, Grand Prairie, TX 75052; phone: (972) 641-0000 or (800) 232-0323; fax: (972) 641-3775; or at [http://www.helicopters.airbus.com/website/en/ref/Technical-Support\\_73.html](http://www.helicopters.airbus.com/website/en/ref/Technical-Support_73.html). You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy, Room 6N-321, Fort Worth, TX 76177.

#### Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0696; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the European Aviation Safety Agency (EASA) AD, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:** Clark Davenport, Flight Test Engineer, Flight Test Branch, Compliance and Airworthiness Division, FAA, 10101 Hillwood Parkway, Fort Worth, TX 76177; phone: 817-222-5151; email: [clark.davenport@faa.gov](mailto:clark.davenport@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Airbus Helicopters Model MBB BK 117 D 2 helicopters. The NPRM published in the **Federal Register** on August 27, 2018 (83 FR 43559). The NPRM was prompted by reports of unintended lifting of several flip guards. The NPRM proposed to require replacing the flip guard with flip guard part number (P/N) 79553511 on the collective lever switch unit.

We are issuing this AD to address unintended lifting of a flip guard. This condition could result in inadvertent cutting of the rescue hoist cable and subsequent personal injury.

EASA, which is the Technical Agent for the Member States of the European Union, issued EASA AD No. 2017-0038, dated February 22, 2017 (EASA AD No.

2017-0038), to correct an unsafe condition for certain Airbus Helicopters Models MBB-BK 117 D-2 and MBB-BK 117 D-2m helicopters. EASA advises that multiple events were reported of unintended lifting of the flip guard and that the flip guard has two stable positions, open and closed. EASA AD No. 2017-0038 states that if the unintended lifting is not detected, the requirement for dual action when activating the rescue hoist cable cut is not guaranteed. According to EASA, this condition, if not corrected, could result in inadvertent cutting of the rescue hoist cable and subsequent personal injury.

EASA further advises that Airbus Helicopters has developed an improved mono-stable (closed) flip guard, and EASA AD No. 2017-0038 requires installing the new flip guard and re-identifying the collective lever switch unit.

#### Comments

We gave the public the opportunity to participate in developing this final rule, but we did not receive any comments on the NPRM.

#### FAA's Determination

These helicopters have been approved by EASA and are approved for operation in the United States. Pursuant to our bilateral agreement with the European Union, EASA has notified us of the unsafe condition described in the EASA AD. We are issuing this AD because we evaluated all information provided by EASA and determined the unsafe condition exists and is likely to exist or develop on other helicopters of these same type designs and that air safety and the public interest require adopting the AD requirements as proposed.

#### Differences Between This AD and the EASA AD

The EASA AD applies to Airbus Helicopters Model MBB-BK 117 D-2m helicopters, whereas this AD does not since these models are not type certificated in the U.S. Also, the EASA AD requires compliance within 440 hours time in service (TIS), however, this AD requires compliance before the next hoist operation or within 440 hours TIS, whichever occurs first. Finally, the EASA AD requires identifying the collective lever switch unit with the service information number; this AD does not.

#### Related Service Information

Airbus Helicopters has issued Alert Service Bulletin No. MBB-BK117 D-2-67A-002, Revision 0, dated January 23, 2017. This service information contains procedures for replacing flip guard P/N

79552176 with improved flip guard P/N 79553511 and for identifying the collective lever switch unit with the alert service bulletin number.

#### Costs of Compliance

We estimate that this AD affects 21 helicopters of U.S. Registry. At an average labor rate of \$85 per hour, we estimate that operators may incur the following costs in order to comply with this AD.

Replacing the flip guard requires about 14 hours, and required parts cost \$735, for a cost per helicopter of \$1,925 and a cost of \$40,425 to the U.S. fleet.

According to Airbus Helicopter's service information, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. We do not control warranty coverage by Airbus Helicopters. Accordingly, we have included all costs in our cost estimate.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

#### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

(1) Is not a "significant regulatory action" under Executive Order 12866,

(2) Is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),

(3) Will not affect intrastate aviation in Alaska, and

(4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

#### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

#### 2019-11-04 Airbus Helicopters

**Deutschland GmbH:** Amendment 39-19650; Docket No. FAA-2018-0696; Product Identifier 2017-SW-101-AD.

#### (a) Applicability

This AD applies to Airbus Helicopters Deutschland GmbH Model MBB-BK 117 D-2 helicopters, certificated in any category, with a cable cut flip guard (flip guard) part number (P/N) 79552176 installed.

#### (b) Unsafe Condition

This AD defines the unsafe condition as unintended lifting of a flip guard. This condition could result in inadvertent cutting of the rescue hoist cable and subsequent personal injury.

#### (c) Effective Date

This AD is effective July 12, 2019.

#### (d) Compliance

You are responsible for performing each action required by this AD within the specified compliance time unless it has already been accomplished prior to that time.

#### (e) Required Actions

Before the next hoist operation or within 440 hours time in service, whichever occurs first, remove flip guard P/N 79552176 from service and install flip guard P/N 79553511 on the collective lever switch unit.

#### (f) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Safety Management Section, Rotorcraft Standards Branch, FAA, may approve AMOCs for this AD. Send your proposal to: Clark Davenport, Flight Test Engineer, Flight Test Branch, Compliance and Airworthiness Division, FAA, 10101

Hillwood Parkway, Fort Worth, TX 76177; telephone 817-222-5151; email 9-ASW-FTW-AMOC-Requests@faa.gov.

(2) For operations conducted under a 14 CFR part 119 operating certificate or under 14 CFR part 91, subpart K, we suggest that you notify your principal inspector, or lacking a principal inspector, the manager of the local flight standards district office or certificate holding district office before operating any aircraft complying with this AD through an AMOC.

#### (g) Additional Information

(1) Airbus Helicopters Alert Service Bulletin No. MBB-BK117 D-2-67A-002, Revision 0, dated January 23, 2017, which is not incorporated by reference, contains additional information about the subject of this AD. For service information identified in this AD, contact Airbus Helicopters, 2701 N Forum Drive, Grand Prairie, TX 75052; phone: (972) 641-0000 or (800) 232-0323; fax: (972) 641-3775; or at [http://www.helicopters.airbus.com/website/en/ref/Technical-Support\\_73.html](http://www.helicopters.airbus.com/website/en/ref/Technical-Support_73.html). You may review the referenced service information at the FAA, Office of the Regional Counsel, Southwest Region, 10101 Hillwood Pkwy., Room 6N-321, Fort Worth, TX 76177.

(2) The subject of this AD is addressed in European Aviation Safety Agency (EASA) AD No. 2017-0038, dated February 22, 2017. You may view the EASA AD on the internet at <http://www.regulations.gov> in Docket No. FAA-2018-0696.

#### (h) Subject

Joint Aircraft Service Component (JASC) Code: 6700 Rotorcraft Flight Control.

Issued in Fort Worth, Texas, on May 31, 2019.

#### Lance T. Gant,

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2019-11993 Filed 6-6-19; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 71

[Docket No. FAA-2019-0206; Airspace Docket No. 19-ASO-6]

RIN 2120-AA66

#### Amendment of Class E Airspace; Monroe, GA

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends Class E airspace extending upward from 700 feet above the surface in Monroe-Walton County Airport, Monroe, GA, to accommodate airspace reconfiguration due to the decommissioning of the Monroe non-directional radio beacon

and cancellation of the NDB approach. Controlled airspace is necessary for the safety and management of instrument flight rules (IFR) operations at this airport. This action also updates the geographic coordinates of this airport.

**DATES:** Effective 0901 UTC, August 15, 2019. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11C, Airspace Designations and Reporting Points, and subsequent amendments can be viewed on line at [http://www.faa.gov/air\\_traffic/publications/](http://www.faa.gov/air_traffic/publications/). For further information, you can contact the Airspace Policy Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11C at NARA, call (202) 741-6030, or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**FOR FURTHER INFORMATION CONTACT:** John Fornito, Operations Support Group, Eastern Service Center, Federal Aviation Administration, 1701 Columbia Ave., College Park, GA 30337; telephone (404) 305-6364.

#### SUPPLEMENTARY INFORMATION:

#### Authority for This Rulemaking

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it amends Class E airspace extending upward from 700 feet above the surface for Monroe-Walton County Airport, Monroe, GA, due to the decommissioning of the Monroe non-directional radio beacon and cancellation of the NDB approach.