

Rules and Regulations

Federal Register

Vol. 84, No. 114

Thursday, June 13, 2019

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0024; Product Identifier 2018-NM-138-AD; Amendment 39-19640; AD 2019-10-01]

RIN 2120-AA64

Airworthiness Directives; Bombardier, Inc., Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: We are adopting a new airworthiness directive (AD) for certain Bombardier, Inc., Model CL-600-2A12 (601) airplanes. This AD was prompted by a report of damage to the anti-rotation tab on a main landing gear (MLG) side brace fitting due to the installation of an incorrect side brace fitting shaft. This AD requires an inspection of the MLG side brace fitting for damage, a verification of the side brace fitting shaft part number, and replacement of the side brace fitting shaft if necessary. It also requires the installation of an anti-rotation bracket. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective July 18, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of July 18, 2019.

ADDRESSES: For service information identified in this final rule, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone 1-866-538-1247 or direct-dial telephone 1-514-855-2999; email ac.yul@aero.bombardier.com; internet <http://www.bombardier.com>. You may view this service information at the FAA, Transport Standards Branch, 2200

South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0024.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0024; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations (phone: 800-647-5527) is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Aziz Ahmed, Aerospace Engineer, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: 516-287-7329; fax: 516-794-5531; email: Aziz.Ahmed@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

We issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain Bombardier, Inc., Model CL-600-2A12 (601) airplanes. The NPRM published in the **Federal Register** on February 28, 2019 (84 FR 6705). The NPRM was prompted by a report of damage to the anti-rotation tab on an MLG side brace fitting due to the installation of an incorrect side brace fitting shaft. The NPRM proposed to require an inspection of the MLG side brace fitting for damage, a verification of the side brace fitting shaft part number, and replacement of the side brace fitting shaft if necessary. It also proposed to require the installation of an anti-rotation bracket.

We are issuing this AD to address premature cracking of the MLG side brace fitting. This condition, if not corrected, could lead to the collapse of the MLG, resulting in structural damage to the wing spar and fuel tank.

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2018-19, dated July 20, 2018 (referred to after this as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Bombardier, Inc., Model CL-600-2A12 (601) airplanes. The MCAI states:

There has been a report of damage to the anti-rotation tab on a Main Landing Gear (MLG) Side Brace fitting. Investigation of the report revealed that a Challenger model CL600 MLG Side Brace shaft had been installed on a Challenger model CL601 Side Brace fitting. Due to the difference in size, this will result in changes to the way the load is transferred between the shaft and the MLG Side Brace fitting and may result in premature cracking of the MLG Side Brace fitting. This condition, if not corrected, could lead to the collapse of the MLG resulting in structural damage to the wing spar and fuel tank.

This [Canadian] AD mandates an inspection of the MLG Side Brace fitting and shaft to verify that the correct shaft part number (P/N) is installed and the fitting is not damaged [damage includes cracking, scratches, gouges, corrosion, defects, and incorrect inner diameter tolerance]. If the Challenger CL600 shaft is installed, this AD mandates replacement with the correct Challenger model CL601 part. If the correct P/N is found installed, this [Canadian] AD also mandates the installation of a bracket to prevent the incorrect part from being installed in the future.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0024.

Comments

We gave the public the opportunity to participate in developing this final rule. We received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

We reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. We have determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related Service Information Under 1 CFR Part 51

Bombardier has issued Service Bulletin 601-0624, Revision 02, dated January 29, 2018. This service information describes procedures for inspecting the MLG side brace fitting

and side brace fitting shaft, installing a replacement side brace fitting shaft if necessary, and installing an anti-rotation bracket.

This service information is reasonably available because the interested parties have access to it through their normal

course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

We estimate that this AD affects 9 airplanes of U.S. registry. We estimate the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
4 work-hours × \$85 per hour = \$340	\$397	\$737	\$6,633

We estimate the following costs to do any necessary on-condition actions that would be required based on the results

of any required actions. We have no way of determining the number of aircraft

that might need these on-condition actions:

ESTIMATED COSTS OF ON-CONDITION ACTIONS

Labor cost	Parts cost	Cost per product
8 work-hours × \$85 per hour = \$680	\$7,989	\$8,669

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

We are issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Is not a “significant rule” under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979),
- (3) Will not affect intrastate aviation in Alaska, and
- (4) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:
Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019-10-01 Bombardier, Inc.: Amendment 39-19640; Docket No. FAA-2019-0024; Product Identifier 2018-NM-138-AD.

(a) Effective Date

This AD is effective July 18, 2019.

(b) Affected ADs

None.

(c) Applicability

This AD applies to Bombardier, Inc., Model CL-600-2A12 (601) airplanes, certificated in any category, serial numbers (S/N) 3001 through 3009 inclusive and 3011 through 3029 inclusive.

(d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

(e) Reason

This AD was prompted by a report of damage to the anti-rotation tab on a main landing gear (MLG) side brace fitting due to the installation of an incorrect side brace fitting shaft. We are issuing this AD to address premature cracking of the MLG side brace fitting. This condition, if not corrected, could lead to the collapse of the MLG, resulting in structural damage to the wing spar and fuel tank.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Inspection for Damage and Identification of the Side Brace Fitting Shaft Part Number

Within 400 flight cycles or 12 months, whichever occurs first, after the effective date of this AD, do the actions specified in paragraphs (g)(1) and (g)(2) of this AD.

(1) Identify the part number of the installed side brace fitting shaft.

(2) Do a detailed visual inspection (DVI) of the side brace fitting for signs of damage, including cracking and gouges, in accordance with paragraph 2.B. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(h) Installation of Anti-Rotation Bracket

(1) For airplanes on which a side brace fitting shaft having P/N 600-10237-3 is installed and the actions required by paragraph (g) of this AD are done on or after the effective date of this AD: Before further flight, modify the MLG side brace fitting by installing the anti-rotation bracket in accordance with paragraph 2.C. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(2) For airplanes on which a side brace fitting shaft having P/N 600-10237-3 is installed and the actions required by paragraph (g) of this AD were done before the effective date of this AD: Within 6 months after the effective date of this AD, modify the MLG side brace fitting by installing the anti-rotation bracket in accordance with paragraph 2.C. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(i) Replacement of the Side Brace Fitting Shaft and Installation of the Anti-Rotation Bracket

(1) For airplanes on which a side brace fitting shaft having P/N 600-10237-1 or 600-10237-5 is installed and damage is found during the DVI of the side brace fitting: Before further flight, do a DVI of the anti-rotation tab and side brace fitting aft bushing for cracking, scratches, gouges, corrosion, and inner diameter tolerance, and a special detailed inspection (SDI) of the side brace fitting aft bore for cracks and defects; perform applicable repairs; replace the side brace fitting shaft with a side brace fitting shaft having P/N 600-10237-3; and install the anti-rotation bracket in accordance with paragraph 2.D. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(2) For airplanes on which a side brace fitting shaft having P/N 600-10237-1 or 600-10237-5 is installed and no damage is found during the DVI of the side brace fitting: Within 300 flight cycles or 12 months, whichever occurs first, after the inspection required by paragraph (g)(2) of this AD, do a DVI of the anti-rotation tab and side brace fitting aft bushing for cracking, scratches,

gouges, corrosion, and inner diameter tolerance, and an SDI of the side brace fitting aft bore for cracks and defects; perform applicable repairs; replace the side brace fitting shaft with a side brace fitting shaft having P/N 600-10237-3; and install the anti-rotation bracket in accordance with paragraph 2.D. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(j) Exceptions to Service Information

Where Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018, specifies contacting Bombardier's Customer Support Engineering for repair instructions: This AD requires doing the repair before further flight using a method approved in accordance with the procedures specified in paragraph (l)(2) of this AD.

(k) Credit for Previous Actions

(1) For an airplane on which a side brace fitting shaft having P/N 600-10237-3 is installed: This paragraph provides credit for actions required by paragraphs (g) and (h) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 601-0624, dated October 1, 2012; or Bombardier Service Bulletin 601-0624, Revision 01, dated March 29, 2017.

(2) This paragraph provides credit for actions required by paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 601-0624, dated October 1, 2012; or Bombardier Service Bulletin 601-0624, Revision 01, dated March 29, 2017, provided that the side brace fitting shaft was identified as having P/N 600-10237-3 and within 6 months after the effective date of this AD, the MLG side brace fitting is modified by installing the anti-rotation bracket in accordance with paragraph 2.C. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(3) This paragraph provides credit for actions required by paragraphs (g) and (i) of this AD, if those actions were performed before the effective date of this AD using Bombardier Service Bulletin 601-0624, Revision 01, dated March 29, 2017, provided that any side brace fitting shaft having P/N 600-10237-1 or P/N 600-10237-5 was identified and replaced with a side brace fitting shaft having P/N 600-10237-3, and the anti-rotation bracket was installed in accordance with paragraph 2.D. of the Accomplishment Instructions of Bombardier Service Bulletin 601-0624, Revision 01, dated March 29, 2017.

(l) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly

to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone 516-228-7300; fax 516-794-5531. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain corrective actions from a manufacturer, the action must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada Civil Aviation (TCCA); or Bombardier, Inc.'s TCCA Design Approval Organization (DAO). If approved by the DAO, the approval must include the DAO-authorized signature.

(m) Related Information

(1) Refer to Mandatory Continuing Airworthiness Information (MCAI) Canadian AD CF-2018-19, dated July 20, 2018, for related information. This MCAI may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0024.

(2) For more information about this AD, contact Aziz Ahmed, Aerospace Engineer, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, New York 11590; telephone: 516-287-7329; fax: 516-794-5531; email: Aziz.Ahmed@faa.gov.

(3) Service information identified in this AD that is not incorporated by reference is available at the addresses specified in paragraphs (n)(3) and (n)(4) of this AD.

(n) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) Bombardier Service Bulletin 601-0624, Revision 02, dated January 29, 2018.

(ii) [Reserved]

(3) For service information identified in this AD, contact Bombardier, Inc., 200 Côte-Vertu Road West, Dorval, Québec H4S 2A3, Canada; North America toll-free telephone: 1-866-538-1247 or direct-dial telephone: 1-514-855-2999; email: ac.yul@aero.bombardier.com; internet: <http://www.bombardier.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, call 202-741-6030, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on May 29, 2019.

Michael Kaszycki,

*Acting Director, System Oversight Division,
Aircraft Certification Service.*

[FR Doc. 2019-12351 Filed 6-12-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2019-0405; Product Identifier 2019-NM-003-AD; Amendment 39-19647; AD 2019-11-01]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: We are superseding Airworthiness Directive (AD) 2018-25-12, which applied to certain Airbus SAS Model A350-941 airplanes. AD 2018-25-12 required modifying the vertical tail plane (VTP) tension bolts connection by adding sealant and protective treatment to the head of the connection, at the barrel nut cavities, and in the surrounding area. Since we issued AD 2018-25-12, it was determined that the instructions for certain airplanes are unclear for proper accomplishment of the required modification. This AD, for certain airplanes, requires accomplishing a revised modification and, for certain other airplanes, retains the modification required by AD 2018-25-12, as specified in an European Aviation Safety Agency (EASA) AD, which will be incorporated by reference. We are issuing this AD to address the unsafe condition on these products.

DATES: This AD becomes effective June 28, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of June 28, 2019.

We must receive comments on this AD by July 29, 2019.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <http://www.regulations.gov>. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations,

M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

• *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material incorporated by reference (IBR) in this AD, contact the EASA, at Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email: ADs@easa.europa.eu; internet: www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available in the AD docket on the internet at <http://www.regulations.gov>.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0405; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations (phone: 800-647-5527) is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT: Kathleen Arrigotti, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3218.

SUPPLEMENTARY INFORMATION:

Discussion

We issued AD 2018-25-12, Amendment 39-19523 (83 FR 64230, December 14, 2018) (“AD 2018-25-12”), which applied to certain Airbus SAS Model A350-941 airplanes. AD 2018-25-12 required modifying the VTP tension bolts connection by adding sealant and protective treatment to the head of the connection, at the barrel nut cavities, and in the surrounding area. AD 2018-25-12 resulted from a determination that certain holes for the VTP tension bolts connection are not properly protected against corrosion. We issued AD 2018-25-12 to address corrosion of the VTP tension bolts

connection, which could reduce the structural integrity of the VTP, and could ultimately lead to reduced controllability of the airplane.

Actions Since AD 2018-25-12 Was Issued

Since we issued AD 2018-25-12, it was determined that the instructions for certain airplanes (Group 2 airplanes as identified in the EASA AD identified below), are unclear for proper accomplishment of the required modification.

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2018-0290, dated December 21, 2018 (“EASA AD 2018-0290”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Airbus SAS Model A350-941 airplanes. The MCAI states:

It was identified that the section 19 holes for the Vertical Tail Plane (VTP) tension bolts connection are not properly protected against corrosion.

This condition, if not corrected, could reduce the structural integrity of the VTP.

To address this unsafe condition, Airbus developed production mod 108307 and mod 110696 to improve protection against corrosion, and issued the SB [service bulletin] to provide in-service modification instructions. Consequently, EASA issued AD 2018-0045 [which corresponds to FAA 2018-25-12] to require a modification by adding sealant and protective treatment to the head of the section 19 VTP tension bolts connection, at the barrel nut cavities and in the surrounding area.

Since that [EASA] AD was issued, it was identified that the instructions for Group 2 aeroplanes, as identified in the SB, were not clear enough for proper accomplishment. Consequently, Airbus published Revision 01 of the SB to clarify those instructions for Group 2 aeroplanes.

For the reasons described above, this [EASA] AD retains the requirements of EASA AD 2018-0045, which is superseded, and requires, for Group 2 aeroplanes, accomplishment of the modification in accordance with the instructions of Revision 01 of the SB.

You may examine the MCAI in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0405.

Explanation of Retained Requirements

Although this AD does not explicitly restate the requirements of AD 2018-25-12, this AD retains certain requirements of AD 2018-25-12 with clarified instructions. Those requirements are referenced in EASA AD 2018-0290, which, in turn, is referenced in paragraph (g) of this AD.